

ASS. REC. BY:

REF:

CS3/ASM19022703/T1+03^{SP}

Special Instruction:

Surveyor: Tau Ahn

ASSIGNMENT (Office)

From (Person): Yvonne Ang

of

ASM (AXA)

Date/Time: 24/12/19 @ 4:08pm

Estimated Cost:

Bill to:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 8461S

Insured:

SMQ 1723Y

at Workshop in/s

My Car Consultant

Tel:

8866 8832

of

53 ubi Avenue 1 #01-33

Policy No:

Claim No:

SQM 02AZP

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:36am @ 26/12/19

Person Contacted:

Hui Gin

Vehicle:

IN/OUT

Date/Time

Action/Instruction

Exchange (X)

SLC 8461S - NA/INC19022425/24

DJA: 21/12/19

SMQ 1723Y - NA/INC19022425/24

DJA: 21/12/2019

9/11-

Sent preli advise via sm smart claim

ASS. REC. BY:

Taylin

REF:

ASM(CAXA)

ASSIGNMENT

From:

Date:

7/1/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLC 84615

at Workshop m/s

My Car Consultant

of

53 Ubi Ave 1 # 01-33

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

957K. X

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Imp - PKS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLC 84615

Yr Regn:

246, May

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Forte K3

c.c 1591

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

137473

T/Radio:

Insured / Std / NI / NA

Eng/No:

KNAFZ411MF5537887

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

P: 215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

7/1/2020

Survey held at

My Car Consultant

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 8 MV

#2800 - #3500

Resurvey - a/i

After repair - 10/1

8/1/2020

RECEIVED 21 JAN 2020

Date/Time, File Pass to?

☐

: Preli. Report

1) 21/1 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Pins

Others

TOTAL

Report Format:

PRS

Lump Sum / L&I: (\$



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

Date: 09/01/2019

To : AXA Insurance Pte Ltd

Survey details

Date of loss	21-Dec-19
Date of appointment	7-Jan-20
Date of survey	20-Dec-19
Location of survey	My Car Consultant

Vehicle Details:

Claim Type:	Third Party
Vehicle number	SLC 8461S
Make and Model	FORTE K3 1.6A SX
Date of registration	27/5/2016
Excess	
Market Value	\$57,000
Part Rebate	\$43,026
Nett Loss	\$13,974

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
Check item	
Labour	
Total	
Lump Sum(if applicable)	

Number of days of repair	4
--------------------------	---

Remarks:

The Estimated Repair Cost of the
Damaged vehicle is in the region of
\$2800 - \$3500




Service Request Details

Claim

S9M02AZP

Reference

None 

Loss Date

December 21, 2019

Report Date

Dec 24, 2019 9:36:00 AM

Request Date

December 24, 2019

Due Date

January 2, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLC84615

Model

FORTE K3 1.6A SX

Service Address

...

Primary Contact/Insured

KONG KUM WAH
BLK 540 JELAPANG ROAD, #10-32, 670540, Singapore
96869676

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

WS : My Car Consultant Pte Ltd

Messages

Invoices

History

Documents

5

Assessment

Metrics

Notes

[New Message](#)

Summer Lee (LKK Auto)

From: My Car Consultant <admin@mycar.sg>
Sent: Monday, 23 December, 2019 4:28 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] OUR REF: SLC8461S YOUR REF: SMQ1723Y PRE-REPAIR INSPECTION FOR SLC8461S
Attachments: SLC8461S_21122019.pdf
Categories: Santosh

WITHOUT PREJUDICE

OUR REF: SLC8461S

YOUR REF: SMQ1723Y

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SLC8461S

ACCIDENT INVOLVING SLC8461S AND SMQ1723Y

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd



+65 88668832

Admin@mycar.sg

Mycar.sg

53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/12/2019 15:22
Date Of Accident	21/12/2019 02:30
Exact Location Of Accident	WOODLANDS CROSSING BEFORE JOHOR CUSTOMS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC8461S
Insured/Policyholder	
Name Of Registered Owner	SG VEHICLE RENTAL PRIVATE LIMITED
Co Reg No	2XXXXXX198R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-899999999

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3 1.6A SX
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100303665-01
Cover Note Number	

Driver

Name of Driver	LIANG HOWE VEE (LIAN HAOWEI)
NRIC No	SXXXX259F
Date Of Birth	12/09/1975
Occupation	OUTDOOR
Date Of Driving Pass	19/08/2016
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98212088
Fax Number	
Contact Number	OFFICE-98212088
Email Address	NOEMAIL

Address

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

Vehicle A: 922 B4619
Vehicle B: SMQ 1328Y



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20191221/2021

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No. 1800-8486999

2 of 3

Report No. T/20191221/2021

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIANG HOWE-VEE	ID No	S7527259F
Related Vehicle	SLC8461S (Car)	Contact No	98212088
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 21/12/19 around 0230hrs, I was driving towards Malaysia via Woodlands. Whilst along Johor Causeway, after Woodlands Checkpoint, I came to a complete stop due to a heavy traffic along Johor Causeway. Suddenly I heard and felt an impact coming from the rear of my vehicle. After which I exited my vehicle and did a visual check and saw that my rear bumper had scratches and was dented. I then approached the driver of, SMQ1723Y, Silver Mercedes convertible, the driver then told me to meet up with him ahead at the nearest patrol station and I acknowledged and did not managed to get his particulars.

Subsequently the other driver managed to clear customs first and proceeded forward and I lost sight of him. Thereafter I cleared the customs, I then went around to look for him at around the vicinity and the nearest, Shell petrol station and the next, Petronas petrol station, however there was no sign of him. I am lodging this report for company record purposes.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	198R
Vehicle Details	
Vehicle No.:	SLC84615
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jan 2020
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A SX
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	G4FGFH600829
Chassis No.:	KNAFZ411MF5537887
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$17,376.00
Original Registration Date:	27 May 2016
First Registration Date:	27 May 2016
Transfer Count:	1
Actual ARF Paid:	\$17,376.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2026
PARF Rebate Amount:	\$13,032.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$29,994.00
Total Rebate Amount:	\$43,026.00

The information contained herein is correct as at 09 Jan 2020

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM19022703/T1td3s2

8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE Date: 24-01-2020

068811



ATTN: YVONNE ANG

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMQ 1723Y	Veh. Inspected	SLC 8461S
Policy No.		Coverage (\$)	0.00
Claim No.	S9M02AZP	Excess (\$)	0.00
Assign From	YVONNE ANG	Assign Date	24/12/2019

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNAFZ411MF5537887	Colour	GREY
Odometer	137473 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/45 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	--

5. General Information

Accident Date	21/12/2019	Inspect Date / Time	07/01/2020 (12:00 PM)
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800-\$3,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

Report Ref No. CS3/ASM19022703/T1td3s2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.