

ASS. REC. BY:

REP: 033/III 19022704/Qty d307

Special Instructions:

Assigner: Sun Pm

ASSIGNMENT (Office)

From (Person): Meimner Stanley fai

of III

Date/Time: 28/12/19 @ 11:26am

Estimated Cost:

Bill to:

OD/TP/WB/TP RES / OD RES / KVA / INV / MV / CS

To Inspect Vehicle No: SLG 85242

Insured: SHC 83914

at Workshop n/s Legacy Technical

Tel: 8858 8851

of 39 woodlands close # 01-08

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:16pm @ 26/12/19

Person Contacted:

ERIC

Vehicle IN OUT

Date/Time	Action/Instruction
	<u>1. Initials +</u>
	<u>SLG 85242 - X</u>
	<u>SHC 83914 - (CL) / III 18022704 / 1/2/2020</u>
	<u>20A: 8/10/2018</u>

ASS. REC. BY: Sun Pin.

REF: III

PRS

ASSIGNMENT

From: Date: 30/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 8524Z

at Workshop m/s Legacy technical

of 39 woodlands close # 01-08 MEGA

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 2pm
GUC@ 8858 8851

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
XX	

Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLG 8524Z Yr Regn: 14/10/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit 1.3 G. cc 1317

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 77380 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GK 31211610

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14

R: 175/70 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 20/12/2019 D.O.I: 30/12/2019

Survey held at Legacy

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 46,726

PV: 41,661

NV: 5,065

Repair Range
2k - 3k

Repair day
5 days

26/2/2020

RECEIVED 27 FEB 2020

Date/Time, File Pass to?

☐: Prel. Report

Days Of Repair: 5

1)

☐: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

26/2/20 Typist

Add Fee: ☐: Site Insp (\$)

☐: Interview (\$)

☐: Tech. Insp (\$)

☐: Weekend (\$)

Survey Fee

Transportation

S + PS \$

Photos

Claims

TOTAL

Report Format:

Lump Sum (LBJ): \$3150/- PRS

PRSK PS

290
11
261

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 26 December 2019 11:26 AM
To: 'sur@lkkauto.com'; Nivitha (LKK Auto)
Cc: jiapei@kscgp.com; Accident@kscgp.com; Zuhaidah Samsuri
Subject: RE: URGENT PLEASE - 2nd Notice to Conduct Pre-Repair Survey - Yourinsured: SHC 8391H; Our ref: SLG 8524Z/LT/jp/sl
Attachments: 2nd PRS (reject) SLG 8524Z.PDF; 1st PRS -SLG 8524Z_20191224121215.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLG8524Z
III INSURED VEHICLE NO. : SHC8391H
DATE OF LOSS : 20.12.2019

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor **LKK AUTO CONSULTANTS** to conduct the pre-repair survey.

This claim is handled by **AIDA**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

We have started using Audatex since 1st Dec 2019. Please do adjustments through Audatex and upload the report onto Merimen.

Thank You.

Warmest regards,

Stanley Lai

**Motor & Work Injury Claims Department
India International Insurance Pte Ltd**

64 Cecil Street, IOB Building, Level 5

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Tuesday, 24 December, 2019 4:28 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: jiapei@kscgp.com

Subject: RE: URGENT PLEASE - 2nd Notice to Conduct Pre-Repair Survey - Yourinsured: SHC 8391H; Our ref: SLG 8524Z/LT/jp/sl

Dear Sirs,

We refer to the matter above and your email of even date.

Please see enclosed our 2nd Notice to Conduct Pre- Repair Survey. Our client is not agreeable to your proposed motor surveyors as a Single Joint Expert.

The workshop details as follows:

Legacy Technica Motorsports

39 Woodlands Close

#01-08 MEGA @ @Woodlands

Singapore 737856

Contact person:

Mr Eric Wong (8858 8851)

Thank you.

Regards,

Sharon

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0983 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

To: Accident@kscgp.com

Cc: jiapei@kscgp.com

Sent: Tue, 24 Dec 2019 07:27:40 +0000

Subject:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

We started using audatex since 1st dec 2019. Please submit your estimate/quotation through Audatex so that our surveyors can make the adjustments according.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: 24 December, 2019 12:23 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: jiapei@kscgp.com

Subject: URGENT PLEASE - 1st Notice to Conduct Pre-Repair Survey - Your insured: SHC 8391H; Our ref: SLG 8524Z/LT/jp/sl

Dear Sirs,

Please find enclosed the 1st Notice to Conduct Pre-Repair Survey for your attention/action.

Thank you.

Regards,

Sharon

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0983 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located

both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Your Ref : SHC 8391H
Our Ref : SLG 8524Z/LT/jp/sl
Date : 24 December 2019

Fax : 6538 3708
Tel : 3152 0985
Email : jiapei@kscgp.com

India International Insurance Pte. Ltd.

BY EMAIL ONLY

DATE OF ACCIDENT: 20 DECEMBER 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email dated 24 December 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor
1	Richard Wong of RW Automotive Appraisers Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Legacy Tecnica Motorsports
39 Woodlands Close
#01-08, MEGA @ Woodlands
Singapore 737856

Contact Person/Tel : Mr Eric Wong / 8858 8851

Yours faithfully,

SL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	898C
Vehicle Details	
Vehicle No.:	SLG8524Z
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G F PACKAGE CVT ABS D/AIRBAG 2WD
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	L13B1312878
Chassis No.:	GK31211610
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$13,953.00
Original Registration Date:	14 Oct 2016 / 6 yrs 9 mths / 81 mths
First Registration Date:	14 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$8,953.00 / 4,476.5
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2026
PARF Rebate Amount:	\$6,714.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$34,947.00
Total Rebate Amount:	\$41,661.00

The information contained herein is correct as at 31 Dec 2019

$$7,000 / 12 = 583.33 \quad \text{OK}$$

$$81 \text{ mths} \times 583.33 = 42,249.73$$

$$42,249.73 + 4,476.5 \\ = 46,726.23$$

$$MV = 46,726$$

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available [adversely](https://www.gia.com.sg).

ACCIDENT STATEMENT

Date Of Report	21/12/2019 10:47
Date Of Accident	20/12/2019 14:55
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE EXIT 15
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG8524Z
Insured/Policyholder	
Name Of Registered Owner	LIM BEI SHAN
NRIC No	SXXXX898C
Email Address	SHEREEN@HMWORLDGROUP.COM
Mobile Phone No	(LOCAL) +65-92387924
Alternative Phone No	OTHERS-92387924
Vehicle Particulars	
Manufacturer	HONDA
Model	FIT 1.3G F PACKAGE CVT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PVT USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DNPCSN1763121902
Cover Note Number	14/10/19-13/10/20

Driver

Name of Driver	LIM BEI SHAN
NRIC No	SXXXX898C
Date Of Birth	24/05/1989
Occupation	INDOOR
Date Of Driving Pass	15/09/2008
Driving Experience	11 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92387924
Fax Number	
Contact Number	OTHERS-92387924
EMail Address	SHEREEN@HMWORLDGROUP.COM



Address	BLK 256A SUMANG WALK #03-607
Postcode	821256
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK DIVISION HQ
Police Station Address	ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8391H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LEE TONG BIING
NRIC/Passport Number	SXXXX093I
Contact Number	
Address	BLK 255 ANG MO KIO AVE 4 #04-117
Postcode	2056
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM BEI SHAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLG8524Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of any insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Road Risk Management Centre established by the General Insurance Association of Singapore (GIA) for archiving with that copies of this report will for a fee be made available upon request to its interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer(s), my work(s) and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer said Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes of:
 - (i) assessing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions in responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or letters to me, which could involve disclosure of certain personal data about me to bring about delivery of the claim as well as in the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, assessing, handling and/or dealing with my claims collectively and "Purposes").
- (b) If insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/ran be disclosed by, any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claim's history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, compiling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated in;
 - (iii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not the policyholder)
Date & Time

 24/12/19

Reporting Centre Personnel's Signature
Name: 
NIC/FIN No. (91)

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 20/12/2019 Time: 1455hrs

Location: P.E. towards Changi, before Exit 15 (KPE/Amn) & Upper Selegie Road at Lane 3.


I was driving along the mentioned location, Date & Time. As I was going to Marina via KPE, I was driving in Lane 3. As the car in front stopped, I slow down and stop my vehicle (SL688524Z). A Combi/Delgo taxi SLR8591H collide onto the rear of my car, the impact was huge and my car is badly damaged.

DECLARATION

(I declare and this foregoing particulars are true & correct)


Driver's Signature
Date & Time


Driver's Signature
Of document and the policyholder
Date & Time

 21/12/19
Reporting Officer's Signature
Date
Signature (19/12)

POLICE REPORT



**SINGAPORE
POLICE FORCE**



G/20191220/7044

1 of 2

POLICE REPORT (NP299)

Report No. G/20191220/7044

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469676
Tel No 1800-2440000

Date/Time Report Made 20/12/2019 17:14	Vide Report No	Station Diary No
Name Of Informant LIM BEI SHAN	Address APT BLK 256A SUMANG WALK #03-607 SINGAPORE 821250	
ID Type / ID No. NRIC NO / S8917898C	Contact No. Home/Office	Mobile 92367924
Nationality SINGAPORE CITIZEN	Email Address inquiry@legacysystems.com	
Occupation Administration manager	Sex Female	Age 30
Institution/School Name	Date of Birth 24/05/1989	Race Chinese
Date/Time Of Incident 20/12/2019 14:55 - 20/12/2019 15:00	Location Of Incident PAN ISLAND EXPRESSWAY	

Brief details:

On the above mentioned date, time and location along PIE towards Changi, before exit to serangoon & CTE expressway after a Chinese temple on my left hand side, I was driving my vehicle SLG85242 at lane 3 and proceeding towards changi direction to KPE, the traffic was slow, and the vehicle in front stopped. I slow down and stopped my vehicle, however, a comfort Delgo taxi SHC8391H collide onto the rear of my vehicle, and hence, my vehicle was damaged, the impact was so huge that my back was having very bad aching, and hence, I proceed to clinic for check up and examine. I am making this police report for future reference.

Signature Of Officer Recording The Report Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required. Date/Time: 20/12/2019 17:14
Signature Of Interpreter: Not applicable	
Officer In-Charge Of Case:	Classification Of Case

Authentication Stamp

Identification Card



**SINGAPORE
POLICE FORCE**



62201191220/7044

POLICE REPORT (NP299)

CONTINUATION OF REPORT

2 of 2

Report No. G/20191220/7044

Subjects involved			
Suspect			
Person Name	LEE TING BING		
ID Type	NRIC NO		
Gender	Male	ID No	S1467093
Language	Chinese	Race	Chinese
		Occupation	Taxi driver
Victim			
Person Name	LIM BEI SHAN		
ID Type	NRIC NO		
Gender	Female	ID No	S8917898C
Race	Chinese	Age	30
Occupation	Administration manager	Language	English
Address	APT BLK 256A SUMANG WALK #03-607 SINGAPORE		Address Type
	821258	Mobile No	92387924
Is Informant A	Yes		
Victim?			
Person Name	LIM BEI SHAN (Informant)		

Signature Of Officer Recording The Report

Not applicable

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required

Date/Time

20/12/2019 17:14

Classification Of Case:



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal COE Toyota Wish 2.5A



2.88% P.A. \$0 Admin, Monthly
From \$588, 2 Years Warranty
Engine And Gearbox,
GV Credit [View Ad](#)


[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

3 vehicles

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Fit		Any	Any	2016	Any	Any	Any	Available
	Honda Fit 1.3A G		\$53,800	\$8,260 /yr	22-Jan-2016	1,317 cc	48,768 km	Hatchback	Available
Stylish Sporty Black H/Back Fit For Your Work, Fit For Your Family Leisure! Smooth Drive And Good Acceleration With Honda I/TEC Engine, Economical, Fuel Efficiency, Practical, Money Saver! Owned By IT Engineer Who Taken Care Of This Baby Meticulously To Be In...									
Car House Pte Ltd									
Posted: 10-Nov-2019 Tags: 2016 Honda Fit, 2016 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda									
	Honda Fit 1.3A G		\$54,800	\$7,700 /yr	17-Jun-2016	1,317 cc	53,201 km	Sedan	Available
Best Fuel Efficient Hatchback! 1 Owner With Free 6 Months Extended Warranty For A Peace OF Mind. 100% Loan With 100% Approval With Our In House Loan. Low Interest For Bank. View To Appreciate, Call Now!									
Starise Automobile									
Posted: 20-Dec-2019 Tags: 2016 Honda Fit, 2016 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda									
	Honda Fit Hybrid 1.5A		\$58,500	\$8,190 /yr	01-Nov-2016	1,496 cc	-	Hatchback	Available
Fuel Type: Petrol-Electric									
Elegant Black, One Owner Only, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained, Easy Financing. Flexible In- House Loan Packages Available.									
Prime Motor & Leasing									
Posted: 27-Dec-2019 Tags: 2016 Honda Fit, 2016 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Fit, Honda Fit Singapore, used Honda Fit Singapore, used Honda Fit, used vehicles Singapore or even buy used Honda Fit Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Nivitha (LKK Auto)

From: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Sent: Sunday, 12 January 2020 3:23 PM
To: Hsiao Tong (LKKAuto); assignments; Admin A
Subject: FW: MCT19120490

SI 485242

From: Mekavathanan Sarangapani
Sent: Sunday, 12 January 2020 3:22:51 PM (UTC+08:00) Kuala Lumpur, Singapore
To: KKLau; Hsiao Tong (LKKAuto); Olivia Lau (LKKAuto)
Cc: Zuhaidah Samsuri; Stanley Lai
Subject: MCT19120490

LKK team

Please carry out paper survey please

Meka

**RW AUTOMOTIVE APPRAISERS SERVICES**

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

INVOICE

Legacy Tecnica Motorsports
38, Woodlands Close
#01-08, MEGA@Woodlands
Singapore 737856
On behalf of Lim Bei Shan

Invoice No : 190105

Date : 06.01.2020

Being:		
Survey Fees (including 64 photographs and transport charges)		\$ 464.00
S'pore Dollars	: Four Hundred and Sixty-Four only.	<u>\$ 464.00</u>
Our Reference No.	: RW/0105/19TP	
Vehicle No.	: SLG 8524 Z	

SURVEYED WITHOUT PREJUDICE

RICHARD WONG
(Licensed Appraiser)



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)
 256 Bishan St. 22 #12-472 Singapore 570256
 Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912
 Reg. No. 52821270B

Lim Bei Shan
 c/o Legacy Tecnica Motorsports
 38, Woodlands Close
 #01-08, MEGA@Woodlands
 Singapore 737856

Report No : RW/0105/19TP
 Date : 06.01.2020

VEHICLE INSPECTION REPORT

REFERENCE

Requested by : Workshop, owner's behalf
 Date of Request : 30.12.2019
 Date of Accident : 20.12.2019
 Date of Inspection : 30.12.2019
 Inspected at : Legacy Tecnica Motorsports
 38, Woodlands Close, MEGA@Woodlands
 #01-08, Singapore 737856

VEHICLE DETAILS

Vehicle No.	: SLG 8524 Z	Make & Model	: Honda Fit
Year Make	: 2015	Colour	: Red
Engine No.	: L13B1312878	Chassis No.	: GK31211610
Engine Capacity	: 1317 cc	Mileage	: 77,380 km
Air-Con	: Yes	Radio/CD/Cassette	: Yes
Seat Belt	: Yes	Rims	: Sport

GENERAL CONDITION OF VEHICLE

General Condition	: Good	Modification	: Nil
Brakes	: Serviceable	Handbrake	: Serviceable
Steering	: Serviceable		

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Rim</u>	<u>Tread Balance</u>
Front Right	Dunlop	175/70 R14	Sport	6 mm
Front Left	Dunlop	175/70 R14	Sport	6 mm
Rear Right	Dunlop	175/70 R14	Sport	6 mm
Rear Left	Dunlop	175/70 R14	Sport	6 mm

ASSESSMENT

	<u>Repairer's Estimate</u>	<u>Recommendation</u>
Spare Parts	\$ 3,495.68	\$ 2,925.68
Labour Charges	\$ 2,680.00	\$ 2,170.00
Paint Work	\$ 1,600.00	\$ 1,400.00
Towing Charges	\$ -	\$ -
Total	<u>\$ 7,775.68</u>	<u>\$ 6,495.68</u>
Recommend lump sum repairs		\$ 5,190.00
Reduction		<u>\$ 2,585.68</u>
Estimated Period Required for Repair		<u>7 days</u>

**RW AUTOMOTIVE APPRAISERS SERVICES**

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: +65 6553 3912

Reg. No. 528212708

Page : 1

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLG 8524 Z

Report No.: RW/0105/19TP

<u>S/No</u>	<u>QTY</u>	<u>Description</u>		<u>Condition/ Remarks</u>	<u>Repairer's Estimates</u>	<u>My Recommendation</u>
<u>REPLACEMENT OF DAMAGED PARTS</u>						
1)	1	Rear bumper	/ PD	Cracked	\$ 575.00	\$ 575.00 ✓
2)	1set	Rear bumper clips	/ NRC	Necessary	\$ 30.00	\$ 30.00 ✓
3)	2	Rear bumper side holders	/ BR	Necessary	\$ 48.20	\$ 48.20 24.1
4)	1	Rear bumper side grille LH	/ MIB	Missing	\$ 48.20	\$ 48.20 ✓
5)	1	Rear end panel	/ DD	Dented	\$ 391.80	\$ 391.80 ✓
6)	1	Rear end panel top garnish	X SVC	Distorted	\$ 90.30	\$ 90.30 X
7)	1	Rear tail lamp LH	/ SCH	Cracked	\$ 287.20	\$ 287.20 ✓
8)	1	Rear tail gate	/ DD	Dented/Bent	\$ 814.20	\$ 814.20 694
9)	1	Rear tail gate lock	X SVC	Dented	\$ 175.20	\$ 175.20 X
10)	1	Rear tail gate weatherstripe	X SVC	Necessary	\$ 92.30	\$ 92.30 X
11)	1	Rear tail gate inner trim board	X SVC	Distorted	\$ 225.40	\$ 225.40 X
12)	1set	Rear tail gate inner trim board clips	X SVC	Necessary	\$ 30.00	\$ 30.00 X
13)	1	Rear tail gate glass moulding	/ NRC	Necessary	\$ 85.00	\$ 85.00 ✓
14)	1	Rear 'Honda' logo	/ NRC	Necessary	\$ 35.40	\$ 35.40 ✓
15)	1	Rear 'Fit' emblem	/ NRC	Necessary	\$ 38.90	\$ 38.90 ✓
16)	1	Rear end panel antenna sensor	X SVC	Failed	\$ 85.00	\$ 85.00 X
17)	1	Rear end panel antenna buzzer	X SVC	Failed	\$ 105.00	\$ 105.00 X
					\$ 3,157.10	\$ 3,157.10 2209.6
Less 20%					\$ 631.42	\$ 631.42 -20%
					\$ 2,525.68	\$ 2,525.68 1,767.68
18)	1	Rear reverse sensors	/ Short	Failed	\$ 350.00	SN \$ 280.00 200
19)	1	Rear end panel sealant	/ NRC	Necessary	\$ 60.00	SN \$ 60.00 30
20)	1	Rear tail gate glass sealant	/ NRC	Necessary	\$ 60.00	SN \$ 60.00 30
21)	1	Rear camera	X SVC	Serviceable	\$ 500.00	SN \$ -
Total (Parts):					\$ 3,495.68	\$ 2,925.68 260

LABOUR CHARGES

22)	Cut out, replace and weld rear end panel. Panel beat rear fender and rear left door. Straighten rear left chassis. Remove and replace all damaged parts.	\$ 1,600.00	\$ 1,400.00 800
23)	Check wiring and lightings.	\$ 60.00	\$ 30.00 ✓
24)	Remove and reinstall rear windscreen glass.	\$ 180.00	\$ 140.00 120
		<u>\$ 5,335.68</u>	<u>\$ 4,495.68</u>



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

Page : 2

Vehicle No: SLG 8524 Z

Report No.: RW/0105/19TP

Balance brought forward	\$ 5,335.68	\$ 4,495.68
25) Remove and reinstall rear upholstery, cushion seats and roof lining to enable repair.	\$ 150.00	\$ 120.00 50
26) Transfer rear tail gate fittings.	\$ 150.00	\$ 100.00 60
27) Remove and replace rear reverse sensors.	\$ 100.00	\$ 60.00 30
28) Remove and reinstall rear camera.	\$ 120.00	\$ 80.00 X
29) Conduct waterproof test after repair.	\$ 120.00	\$ 80.00 X
30) Rust proofing treatment on affected area.	\$ 200.00	\$ 160.00 30
31) Spray painting on affected area. Tailgate, bumper, end panel, fender	\$ 1,600.00	\$ 1,400.00 800
Total (Labour):	\$ 4,280.00	\$ 3,570.00 1,920
Total:	\$ 7,775.68	\$ 6,495.68

Repair days - 5 days

L/S

\$ 3,150

P = 1,767.68

N = 260

L = 1,920

3,947.68

- 208

3,158.14



RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

Page : 3

Vehicle No: SLG 8524 Z

Report No.: RW/0105/19TP

POINT OF IMPACT

At the rear portion of the vehicle.

RECOMMENDATION

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$6,495.68.

CONCLUSION

The repairer has agreed to undertake repairs at a lump sum of \$5,190.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE



RICHARD WONG
(Licensed Appraiser)



INDIA
INTERNATIONAL
INSURANCE
SINGAPORE
Serving the region since 1987

INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 148707292K (Lyt. Reg. No. 912-0078806-K)
64 Cantonment Street #04-01 #05-10B Building Singapore 049711

Office (65) 63476100 Email insure@iil.com.sg
Fax (65) 62244174 Website www.iil.com.sg

PRESERVE

MCT/19/20490/01/28

UNINSURED LOSS

PRESERVE

4HC Re.

SUBRO

PRESERVE

702

34

LPPN

PC-DC

1

INVESTIGATION FEE

SURVEY FEES

P-S

300

LEGAL FEES

CLL

OTHERS

FRAUD CHECK

UPLOAD TO MERIMEN

GRANT RIGHTS

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO 2875
 RECIPIENT ADDRESS 65383708
 DESTINATION ID
 ST. TIME 13/01 09:52
 TIME USE 00'29
 PAGES SENT 2
 RESULT OK



GUN P SINGH SEKHON
 CHIA HOK SENG
 REY FOO JONG HAN
 GOH LAM CHUAN
 NAVINDER SINGH
 P. PADMAN
 KWEH SOON HAN
 FAIZAL MOHAMED ASHRAF
 LUE JIAPEI
 TAN XIN ER
 LIM YUN HENG
 JEREMY CHIEW YIEN MING
 FARAH NAZURA BINTE ZAINUDDIN

KSCGP
 JURIS LLP

Advocates & Solicitors • Commissioners for Oaths
 Notary Public

*Celebrating 27 Years of
 Professional and Personalized
 Legal Service*

MAIN OFFICE:

10 Hoe Chiang Road, #13-03A
 Keppel Towers,
 Singapore 089315
 Tel: 6538 3611
 Fax: 6538 3708

Website: www.kscgp.com

(Fax/Email not for service of court documents)

Registered in Singapore with limited liability
 as a Limited Liability Partnership
 Registration Number T10LL1855L

Your Ref: SHC 8391H

Our Ref: GS/20/2036/LT/jp/cl

Date: 10 January 2020

India International Insurance Pte Ltd
 64 Cecil Street
 Level 5
 IOB Building
 Singapore 049711

Dear Sirs,

LIM BEI SHAN

C/o 10 Hoe Chiang Road #13-03A Keppel Towers Singapore 089315

ACCIDENT INVOLVING SLG 8524Z AND SHC 8391H ALONG PAN-ISLAND EXPRESSWAY ("PIE") TOWARDS CHANGI BEFORE EXIT 15 ON 20.12.2019

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 20 December 2019 along Pan-Island Expressway ("PIE") towards Changi before Exit 15, involving our client's motor vehicle bearing registration number SLG 8524Z and the motor vehicle bearing registration number SHC 8391H, which was insured by you at the material time.

We are instructed that the accident was caused by the negligent driving and/or management of the authorised driver of SHC 8391H. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

(1) Cost of repairs	-	\$ 5,190.00
(2) Loss of use	-	\$ 800.00
(3) Survey fee	-	\$ 464.00
(4) LTA search	-	\$ 10.00



DID: 3152 0985

Email: jiapei@kscgp.com

BY HAND

MCT/19/20490

Aid 13/1/2020

PC

GUH ... P SINGH SEKHON
CHIA KOK SENG
REY FOO JONG HAN
GOH LAM CHUAN
NAVINDER SINGH
P. PADMAN
KWEH SOON HAN
FAIZAL MOHAMED ASHRAF
JUE JIAPEI
TAN XIN ER
LIM YUN HENG
JEREMY CHIEW YIEN MING
FARAH NAZURA BINTE ZAHUDIN

KSCGP

JURIS LLP

Advocates & Solicitors • Commissioners for Oaths
Notary Public

*Celebrating 27 Years of
Professional and Personalised
Legal Service*

MAIN OFFICE:

10 Hoe Chiang Road, #13-03A
Keppel Towers,
Singapore 089315
Tel: 6538 3611
Fax: 6538 3708

Website: www.kscgp.com

(Fax/Email not for service of court documents)

Registered in Singapore with limited liability
as a Limited Liability Partnership
Registration Number T10LL1855L

Your Ref : SHC 8391H
Our Ref : GS/20/2036/LT/jp/cl
Date : 10 January 2020



DID: 3152 0985

Email: jiapei@kscgp.com

India International Insurance Pte Ltd
64 Cecil Street
Level 5
IOB Building
Singapore 049711

BY HAND

Dear Sirs,

LIM BEI SHAN

C/o 10 Hoe Chiang Road #13-03A Keppel Towers Singapore 089315

ACCIDENT INVOLVING SLG 8524Z AND SHC 8391H ALONG PAN-ISLAND EXPRESSWAY ("PIE") TOWARDS CHANGI BEFORE EXIT 15 ON 20.12.2019

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 20 December 2019 along Pan-Island Expressway ("PIE") towards Changi before Exit 15, involving our client's motor vehicle bearing registration number SLG 8524Z and the motor vehicle bearing registration number SHC 8391H, which was insured by you at the material time.

We are instructed that the accident was caused by the negligent driving and/or management of the authorised driver of SHC 8391H. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

(1) Cost of repairs	-	\$ 5,190.00
(2) Loss of use	-	\$ 800.00
(3) Survey fee	-	\$ 464.00
(4) LTA search	-	\$ 10.00
(5) GIA search	-	\$ 29.00
(6) Incidentals	-	\$ 100.00
(7) Costs	-	\$ 900.00
(8) GST on items (6) & (7)	-	\$ 70.00
		\$ 7,563.00

BRANCH: PRIVATE PROPERTY CONVEYANCING
400 Lorong 6 Toa Payoh Biz 3 Lobby 2
#09-18 HDB Hub
Singapore 310490
Tel: 6591 7696 Fax: 6258 1825

BRANCH: HDB CONVEYANCING
400 Lorong 6 Toa Payoh Biz 3 Lobby 2
#09-18 HDB Hub
Singapore 310490
Tel: 6591 7696 Fax: 6258 1409

BRANCH: SHIPPING/ADMIRALTY & COMMERCIAL
92 Arab Street #03-01 & #03-02
Singapore 199788
Tel: 6634 1346 Fax: 6634 1356

BRANCH: CORPORATE & LITIGATION
51 Robinson Road
#15-02 Robinson Centre
Singapore 068893
Tel: 6817 8795 Fax: 6224 1612

The information contained in this letter / facsimile message is CONFIDENTIAL and may also be LEGALLY PRIVILEGED, intended only for the individual or entity named above. If you are not the intended recipient, you are hereby notified that any use, revelation, dissemination, distribution or copying of this document is strictly prohibited. If you have received this document in error, please notify us immediately by telephone (call the number above) and destroy the original message.

A copy each of the supporting documents are enclosed.

<u>S/NO.</u>	<u>AVAILABLE DOCS</u>	<u>PARTICULARS</u>
<u>Client's Documents</u>		
1.	21.12.2019, 20.12.2019	GIA Statement / Traffic Police report
2.		Witness(es) Statement
3.		Accident site photographs
4.		Video footage / CCTV / CD recording
5.		Repair bill / invoice / Excess Tax invoice
6.		Rental bill / invoice and agreement / receipts
7.		Vehicle Entry Permit receipt / E-day license for off-peak vehicle
8.		Towing fees / receipt (Singapore / Malaysia)
9.		Client sold off vehicle and produce letter from LTA
10.		Spare Part Ordering Form
11.		Levy at Custom / receipts
12.	06.01.2020	Survey invoice and surveyor's report
13.	06.01.2020	64 Original / Copies of damage photographs
14.		Enquire PARF / COE Rebate for Registered Vehicle
15.		Enquire Transfer fee
16.		Certificate of Insurance / Motor Cover Note / New Policy Schedule / Registration Card / Grant / Road Tax
17.	24.12.2019	Pre-repair Inspection Notices
18.		Traffic Police investigation results
19.		Estimated agreement between surveyor and repairer
20.	30.12.2019	Tax invoices and search results from General Insurance Association of Singapore (GIA) and Traffic Police search fees
<u>Third Party's Documents</u>		
21.	20.12.2019	GIA Statement / Traffic Police report
22.		Admission Note
23.	24.12.2019	LTA search / receipt / tax invoice
24.		Malaysia Vehicles Searches / service
25.		RCB / ACRA search
26.		Enhanced Individual search / receipt
27.		Property tax search / receipt
<u>Others (Apply only in chain collisions and/or any other documents)</u>		
28.		

We have on 24 December 2019 notified you of the accident and a pre-repair inspection of our client's motor vehicle was carried out by the appointed surveyors.


Subject to our client's instructions, please confirm in writing within 7 days hereof if you or your insured wish to inspect our client's vehicle or conduct a second re-inspection.

Please note that you or your insured should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured. In this event, you will be liable for any and all legal costs incurred.

Please also note that if your insured has a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter, which we will then forward to our client and/or the insurers for consideration on a without prejudice basis.

For avoidance of doubt, kindly note that this claim is made without prejudice to our client's personal injury claim.

Yours faithfully,



(Main Office)

Enc.

Cc client

Cc owner – Comfort Transportation Pte Ltd

Cc driver – Lee Tong Bing

Address: BLK 296A SUMANG WALK #03-607
 Postcode: 821258
 Is this driver an employee of the Insurer's Company? NO
 Relationship of the Driver with the Insured: OWNERS
 Motor Vehicle Registration Number of Driver's Own Vehicle: -
 Make/Model: -

Insurer's Company of Driver's Own Vehicle:

Accident Information at the Accident

Accident Description: COLLISION - HEAD TO HEAD
 Direction of Movement: CLEAR
 Road Condition: DRY
 Other Information:

Was there more than 1 vehicle involved in this accident? NO

Number of Vehicles (including own vehicle) involved in this accident: 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance: NO

Number of Passengers (including Driver): 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station:

Police Station Name: BEDOK DIVISION HQ

Police Station Address: ROAD 30 BEDOK NORTH ROAD, POSTCODE: 469676, COUNTRY SINGAPORE

Police Station Contact: TEL NO - FAX NO

Was action of Intended Prosecution given? NO

If yes, against whom?

Circumstances of Accident

REPORT AT SCENES

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number: SHC8391H

Vehicle Make/Model/Colour:

Details Of Properties

Vehicle Category: TAXI

Name of Driver: LEE TONG BIING

NRIC/Passport Number: SX0000931

Contact Number:

Address: BLK 255 ANG MO KIO AVE 4 #04-117

Postcode: 2056

Insurer's Company Name:

DETAILS OF INJURED PERSON 1

Name UM DEE SHAM

Approximate Age

Reason Sustain

Injured person in which vehicle? SLG8524Z

Wearing seat belts worn?

Was the injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please read out loudly the details of the accident involved in the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may render insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of any liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the G.A. Road Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you agree to assist in the archiving of this report at the centre and to assist in the report being made available afterwards.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) I/We, my/ourself/ours, the General Insurance Association of Singapore (GIA) or anyone permitted to sign on my/our behalf and/or process my personal data (personal information put out in this form) and any other personal information provided by me or possessed by my insurer collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in the accident (insurers) who have insured vehicle(s) involved in the accident. Such shall be subject to my/our consent to the "Insured", the Insurers' Association of Singapore (GIA) and the Ministry of Transport of Singapore and to consent agreement, such as the policy for the purpose of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my investigations responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, claims, reports or forms to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as my own later external cover of employer/s or a foreigner/s); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) I/We (PQ) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including those who follow them), which may be able to obtain of Singapore for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used by a complete claim's history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing claims;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with legal obligations with my employer/s and/or agent/s.


 Name: Mr. Lim Jia Hui
 Date: 10/10/2018


 Name: Mr. Lim Jia Hui
 (If driver is not the policyholder)
 Date: 10/10/2018


 Name: Mr. Lim Jia Hui
 Date: 10/10/2018

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date 7/12/2019 Time 18:55hrs
 Location P.T.E. Towards change, lanes (2 & 3) (C/E/ARM) &
 before seeing a hand at lane 3.

I was driving along the mentioned location on 2 lane
 the road is 2 lanes in each direction. I was driving on lane 3.
 As the car in front stopped, I slowed down and saw my
 vehicle (2019 2019 2019). A white Volvo car 2019 2019
 collide with the rear of my car. The 1st part was
 huge and my car is badly damaged.

DECLARATION

I hereby declare that the above information is true and correct.


 Name: [Signature]
 Date: 7/12/2019


 Name: [Signature]
 Date: 7/12/2019


 Name: [Signature]
 Date: 7/12/2019

POLICE REPORT

SINGAPORE
POLICE FORCE

REP-1011-01-0000

1 of 1

POLICE REPORT (NP288)

Rep. No. G201912207044

Police Station Of Origin
 Benish Division H3
 30 Indok North Road SINGAPORE 489478
 Tel No 1800 2440000

Date/Time Report Made 22/12/2019 17:14	Video Report No.	Station Copy No.
Name Of Informant LIM HUI SHAN	Address APT BLK 255A SUMMIT WALK #03-607 SINGAPORE 621256	
ID Type / ID No. NRIC NO / S19116380	Contact No. Home/Office	Mobile 92387924
Nationality SINGAPORE CITIZEN	Email Address inquiry@legabytechnica.com	
Occupation Administration manager	Sex Female	Age 23
Initiation/School Name	Date of Birth 24/05/1996	Race Chinese
Date/Time Of Incident 20/12/2019 14:55 - 20/12/2019 15:00	Location Of Incident PAN ISLAND EXPRESSWAY	
Brief details		

On the above mentioned date, time and location along PIE towards Changi, before exit to Selegieon & CTE expressway after a Chinese temple on my left hand side, I was driving my vehicle SLC85242 at lane 3 and proceeding towards changi direction to KPE, the traffic was slow, and the vehicle in front stopped, I slow down and stopped my vehicle, however, a comfort Drive taxi SHC8121H collide onto the rear of my vehicle, and hence, my vehicle was damaged, the impact was so huge that my back was having very bad aching, and hence, I proceed to clinic for check up and examine. I am making this police report for future reference.

Signature Of Officer Recording The Report Not available	Signature Of Informant The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter Not available	Date/Time 20/12/2019 17:14
Officer In Charge Of Case	Classification Of Case
Authentication Stamp	

Identification Card



SINGAPORE
POLICE FORCE

POLICE REPORT (NP288)

CONTINUATION OF REPORT



620114172017044

2 of 2

Report No. G2019122017044

Subjects Involved			
Suspect			
Person Name	LEE TING BING		
ID Type	NRIC NO		
Gender	Male	ID No	S1467093
Language	Chinese	Race	Chinese
		Occupation	Taxi driver
Victim			
Person Name	LIM BEI SHAN		
ID Type	NRIC NO		
Gender	Female	ID No	S6917898C
Race	Chinese	Age	30
Occupation	Administration manager	Language	English
Address	APT BLK 258A SUMANGI	Address Type	
	WALK #03-607 SINGAPORE	Mobile No	92387921
	821256		
Is Informant A Victim?	Yes		
Person Name	LIM BEI SHAN (Informant)		

Signature of Officer Recording The Report

Not applicable

Signature of Interpreter

Not applicable

Officer In Charge Of Case

Authentication Stamp

Signature Of Informant

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time

20/12/2019 17:14

Classification Of Case

Your Ref : SHC 8391H
Our Ref : SLG 8524Z/LT/jp/sl
Date : 24 December 2019

Fax : 6538 3708
Tel : 3152 0985
Email : jiapei@kscgp.com

India International Insurance Pte. Ltd.

BY EMAIL ONLY

DATE OF ACCIDENT: 20 DECEMBER 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of SLG 8524Z to notify you of a road traffic accident on 20 December 2019 at about 2.55 pm along Pan-Island Expressway ('PIE') towards Changi before Exit 15, involving our client's vehicle registration number SLG 8524Z and vehicle registration number **SHC 8391H** which was managed by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

f SL

Enc.

Your Ref : SHC 8391H
Our Ref : SLG 8524Z/LT/jp/sl
Date : 24 December 2019

Fax : 6538 3708
Tel : 3152 0985
Email : jiapei@kscgp.com

India International Insurance Pte. Ltd.

BY EMAIL ONLY

DATE OF ACCIDENT: 20 DECEMBER 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email dated 24 December 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor
1	Richard Wong of RW Automotive Appraisers Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Legacy Tecnica Motorsports
39 Woodlands Close
#01-08, MEGA @ Woodlands
Singapore 737856

Contact Person/Tel : Mr Eric Wong / 8858 8851

Yours faithfully,

SL

Your Ref : SHC 8391H
Our Ref : SLG 8524Z/LT/jp/sl
Date : 24 December 2019

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-19-213893

Date of Request: 30/12/2019

Your Ref No: GS/20/2036/LT/JP/SL

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 20/12/2019

Place of Accident: PIE TOWARDS CHANGI BEFORE EXIT

Client Vehicle No: SLG8524Z

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHC8391H	PIE TWDS AIRPORT CHANGI.	20/12/2019 15:00

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

TAX INVOICE

Our Ref No: GR-19-213893

Date of Request: 30/12/2019

Your Ref No: GS/20/2036/LT/JP/SL

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 20/12/2019

Place of Accident: PIE TOWARDS CHANGI BEFORE EXIT

Client Vehicle No: SLG8524Z

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-213902
Date of Request: 30/12/2019

Your Ref No: GS/20/2036/LT/JP/SL

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Date of Accident: 20/12/2019
Vehicle No: SLG8524Z
Place of Accident: PIE TOWARDS CHANGI BEFORE EXIT 15
Involving Vehicle No: SHC8391H

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHC8391H	PIE TOWARDS CHANGI BEFORE EXIT 15	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/12/2019 16:25
Date Of Accident	20/12/2019 15:00
Exact Location Of Accident	PIE TWDS AIRPORT CHANGI.
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC8391H
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	LEE TONG BIING
NRIC No	S1467093I
Address	BLK 255 ANG MO KIO AVENUE 4 #04-117
General Information of the Accident	
Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Other Information	
Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	3
Circumstances of Accident	
REFER ATTACHED	
Attachment(s)	
Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG8524Z
Vehicle Make/Model/Colour	
Name of Driver	LIM BEI SHAN
Insurance Company Name	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
100, JALAN KEMAS, SINGAPORE 115

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON. 20 Dec. 2012 @ 1200 hrs I

veh (A) cannot stop in time and

hit veh (B) (Rev.) @ the turn point

of accident veh (A) ferry two persons

was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



SCENE



SCENE



20/12/2019 16:48

SCENE



SCENE



SCENE



SCENE



2012/12/20 18:46

Enquire Vehicle & Owner Information (Vehicle No. SHC8391H As At 20 Dec 2019 / 14:55:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SLG8524Z/LT/JP/SL

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHC8391H

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2019 16:25
Date Of Accident	20/12/2019 15:00
Exact Location Of Accident	PIE TWDS AIRPORT CHANGI.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8391H
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	LEE TONG BIING
NRIC No	S1467093I
Date Of Birth	02/08/1961
Occupation	OUTDOOR
Date Of Driving Pass	03/10/1983
Driving Experience	36 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90056131
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 255 ANG MO KIO AVENUE 4 #04-117
Postcode	560255
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG8524Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM BEI SHAN
NRIC/Passport Number	S8917898C
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
GO, REG. NO. 13001821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 20 Dec 2011 @ 1500 hrs I

veh (A) cannot stop in time and

hit veh (B) (Rev.) @ the turn point

of accident. veh (A) ferry two passengers

was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SCENE



SCENE



SCENE



SCENE



SCENE



SCENE



...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey PR1

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2020 Edit Reg		26 Dec 2019 00:00 Edit Adj Rpt	\$3,150.00 Edit Estimates	\$3,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SLG8524Z	Date of Loss:	20/12/2019 14:00 - :59 [38 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19120490	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC8391H	Policy No. (Claimant):							
		Excess:							
Repairer:	Legacy Technica Motorsports (woodlands) (HQ) 39 WOODLANDS CLOSE, #01-08 MEGA @ WOODLANDS, 737856 Woodlands - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 07/01/2020]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG8524Z (MCT19120490)

[SHC8391H]

TP





























-

Dec 20 2019 2:00PM

[-]

Legacy Technica Motorsports (woodlands)

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	14/01/20 10:00	Chassis Number					Load JPG	<input checked="" type="checkbox"/>	
2	14/01/20 10:00	Odometer Reading					Load JPG	<input checked="" type="checkbox"/>	
3	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
4	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
5	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
6	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
7	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
8	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
9	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
10	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
11	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
12	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
13	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
14	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
15	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
16	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
17	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
18	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
19	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
20	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
21	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
22	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
23	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
24	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
25	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
26	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
27	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
28	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
29	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
30	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
31	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
32	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
33	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
34	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
35	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
36	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	
37	14/01/20 10:00	General View					Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/01/20 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/01/20 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
43	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
44	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/01/20 10:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/19 16:51	EMAIL FROM III TO ARRANGE FOR SURVEY	 Load PDF	
2	26/12/19 16:51	TP GIA REPORT	 Load PDF	
3	04/03/20 09:58	Colour Photo	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	30/12/19 11:46	Singapore Accident Statement	 Load PDF	
2	05/02/20 10:40	Letter of Demand from Third Party TPD LOD FROM KSCGP JURIS LLP (SLG85242) PT 1	 Load PDF	
3	05/02/20 10:40	Letter of Demand from Third Party TPD LOD FROM KSCGP JURIS LLP (SLG85242) PT 2	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19022704/QYD3E2

Date: 04/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : SLG8524Z **Insured Vehicle No :** SHC8391H
 Date of Loss: 20/12/2019 Nature of Claim: TP Claim No: MCT19120490

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG8524Z**
 Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1312878
 Reg. Date: 14/10/2016 (Man. Year: 2015) Chassis No: GK31211610
 Colour: Red Odometer: 77380 km
 Engine Capacity: 1317 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
 Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,495.68	2,027.68	1,468.00	41.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	1,920.00	2,360.00	55.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,775.68	3,947.68	3,828.00	49.23
Approved Total (Overridden) (S\$)		3,150.00		
Nett Amount (S\$)	7,775.68	3,150.00	4,625.68	59.49

INSPECTION

Date of Assignment: 26/12/2019
 Date Inspected: 30/12/2019 Inspected At: Legacy Technical Motorsports (woodlands) (HQ)
 39 WOODLANDS CLOSE, #01-08 MEGA @ WOODLANDS
 Singapore 737856
 Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2020)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG8524Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	575.00 FL	*575.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDERS (2PCS)	Broken (1Pc only)	48.20 FL	*24.10 FL
4	1		*REAR BUMPER SIDE GRILLE LH	Missing	48.20 FL	*48.20 FL
5	1		*REAR END PANEL	Dented	391.80 FL	*391.80 FL
6	1		*REAR END PANEL TOP GARNISH	Serviceable	90.30 FL	*- FL
7	1		*REAR TAIL LAMP LH	Scratched	287.20 FL	*287.20 FL
8	1		*REAR TAIL GATE	Dented	814.20 FL	*694.00 FL
9	1		*REAR TAIL GATE LOCK	Serviceable	175.20 FL	*- FL
10	1		*REAR TAIL GATE WEATHERSTRIPE	Serviceable	92.30 FL	*- FL
11	1		*REAR TAIL GATE INNER TRIM BOARD	Serviceable	225.40 FL	*- FL
12	1		*SET REAR TAIL GATE INNER TRIM BOARD CLIPS	Serviceable	30.00 FL	*- FL
13	1		*REAR TAIL GATE GLASS MOULDING	Necessary	85.00 FL	*85.00 FL
14	1		*REAR HONDA LOGO	Necessary	35.40 FL	*35.40 FL
15	1		*REAR FIT EMBLEM	Necessary	38.90 FL	*38.90 FL
16	1		*REAR END PANEL ANTENNA SENSOR	Serviceable	85.00 FL	*- FL
17	1		*REAR END PANEL ANTENNA BUZZER	Serviceable	105.00 FL	*- FL
18	1		*REAR REVERSE SENSORS	Shorted	350.00 FS	*200.00 FS
19	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
20	1		*REAR TAIL GATE GLASS SEALANT	Necessary	60.00 FS	*30.00 FS
21	1		*REAR CAMERA	Serviceable	500.00 FS	*- FS
					Sub Total (\$\$)	4,127.10 2,469.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	831.42 441.92
					Total Parts (\$\$)	3,495.68 2,027.68

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUT OUT, REPLACE AND WELD REAR END PANEL. PANEL BEAT REAR FENDER AND REAR LEFT DOOR. STRAIGHTEN REAR LEFT CHASSIS. REMOVE AND REPLACE ALL DAMAGED PARTS	New	1,600.00	800.00
2	CHECK WIRING AND LIGHTINGS	New	60.00	30.00
3	REMOVE AND REINSTALL REAR WINDSCREEN GLASS	New	180.00	120.00
4	REMOVE AND REINSTALL REAR UPHOLSTERY, CUSHION SEATS AND ROOF LINING TO ENABLE REPAIR	New	150.00	50.00
5	TRANSFER REAR TAIL GATE FITTINGS	New	150.00	60.00
6	REMOVE AND REPLACE REAR REVERSE SENSORS	New	100.00	30.00
7	REMOVE AND REINSTALL REAR CAMERA	New	120.00	0.00
8	CONDUCT WATERPROOF TEST AFTER REPAIR	New	120.00	0.00
9	RUST PROOFING TREATMENT ON AFFECTED AREA	New	200.00	30.00
10	SPRAY PAINTING ON AFFECTED AREA	New	1,600.00	800.00
Gross Labour Cost (S\$)			4,280.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >