

ASS. REC. BY:

REF: CS/EG1219022762/EG d3n2

Special Instruction:

Surname: Steve

ASSIGNMENT (Office)

From (Person): Jacelyn Foo of EGP Date/Time: 26/12/19 @ 4:36pm

Estimated Cost: _____ Bill to: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 49 66E Insured: GBA 8759Mat Workshop m/s Southern Motor Tel: 6273 0369.of Blk 1006 Bukit Merah lane 2# 01-10Policy No: _____ Claim No: CDMCG19002333

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 4/12/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 11:16am @ 29/12/19 Person Contacted: Mr Lim H.O.D. Endorsement: _____Vehicle IN OUT

Date/Time	Action/Instruction
	<u>Vehicle ✓</u>
	<u>GBA 8759M X</u>
	<u>FBK 4966E CS/INCD/UNRES/24HRS/26/12/19</u>
<u>30/12/19 @ 2:38pm</u>	<u>revised to Jacelyn Foo via Messenger.</u>

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/c

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBK 4966E

Yr Regn:

18/9/15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make:

Honda CB400SF

c.c

399

Colour

Black

AC:

Insured / Std / NI / NA

Sp. Reading

43909

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/N:

NC 421603494

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / 9/Rim / STD A/Rim or

Tyre Size:

F:

120/60ZR17

R:

160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FKR

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

4/2/19

D.O.A.

27/12/19

Survey held at

Shadham Mdr

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt, LH

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-13K

6/2/20

Finalize \$7450, 3 days (Lim)
Chkd @ 3634.20, 33.1

RECEIVED 08 FEB 2020

Date/Time, File Pass to?

☐

Prall. Report

1) 27/12/19

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

350

1) S + RS - SI

2) Plate

3) Others

4) -

TOTAL

11

361

Report Format :

MEP-T1

Lump Sum / L.B.:

7450

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Dec 2019

Preliminary Advice

Insured Vehicle No	: GBA8759M	Accident Date	: 04/12/2019
TP Vehicle No	: FBK4966E	Assignment Date	: 27/12/2019
Make	: HONDA CB400SF	Est. Duration of Repair	: 3.00
Date of Inspection	: 27/12/2019		
Inspection At	: SOUTHERN MOTOR (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10 SINGAPORE 159762		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,084.20
Revised Amount	:S\$	9,539.50
Check Items (Estimated)	:S\$	1,260.00
Total	:S\$	10,799.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

ASS. REC. BY:

REF: CS/EG19022762/Eg d3n2

Special Instructions:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person):

Jacelyn Foo

of

EGL

Date/Time:

26/12/19 @ 4:36pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FBK 49 66E

Insured:

GBA 8759M

at Workshop m/s

Southern Motor

Tel:

6273 0369.

of

Blk 1006 Bukit Merah Lane 2# 01-10

Policy No:

Claim No:

CDMCG19002333

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/12/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

11:16am @ 27/12/19

Person Contacted:

Mr Lim

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction

30/12/19 ✓GBA 8759M XFBK 4966E CDMCG19002333/2019/12/26/1930/12/19 @ 2:38pm revised to Jacelyn Foo via Messenger.

Signature Steve

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: FBK 4966E

Yr Regn: 18/9/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB400SF

c.c. 399

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

43009

T/Radio: Insured / Std / NI / NA

Eng/No:

C/N:

NC 421603494

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / 9/Rim / STD A/Rim or

Tyre Size:

F: 120/60ZR17

R: 160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FKR

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

4/2/19

D.O.I.

27/12/19

Survey held at

Shadham Motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt, LH

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-13K

6/2/20

Finalize \$7450, 3 days (Lim)
Red to 3634.20, 33%

RECEIVED FEB 2020

30/12

Date/Time, File Pass to?

☐

: Proll. Report

1) 27/2/20

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ - RS. - SI

Billable

Others

1

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Weekend (\$

Report Format:

MER-11

Lump Sum / L.B. (\$

7450

350

11

361

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Dec 2019

Preliminary Advice

Insured Vehicle No	: GBA8759M	Accident Date	: 04/12/2019
TP Vehicle No	: FBK4966E	Assignment Date	: 27/12/2019
Make	: HONDA CB400SF	Est. Duration of Repair	: 3.00
Date of Inspection	: 27/12/2019		
Inspection At	: SOUTHERN MOTOR (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10 SINGAPORE 159762		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,084.20
Revised Amount	:S\$	9,539.50
Check Items (Estimated)	:S\$	1,260.00
Total	:S\$	10,799.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: Jacelyn Foo <jacelyn.foo@ergo.com.sg>
Sent: Thursday, 26 December 2019 4:36 PM
To: admin-d@lkkauto.com; admin-a@lkkauto.com; Meikwan@lkkauto.com
Cc: Southern Motor
Subject: RE: ERGO Claims Ref: CDMCG19002333 (GBA8759M) | Your Ref: FBK4966E
Attachments: Estimate.pdf

Data Classification: Confidential, C3

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest Regards,
Jacelyn Foo
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID: +65 6829 9258
jacelyn.foo@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference. ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Southern Motor [mailto:soumotor@hotmail.com]
Sent: Thursday, December 26, 2019 4:17 PM
To: Jacelyn Foo
Subject: Re: ERGO Claims Ref: CDMCG19002333 (GBA8759M) | Your Ref: FBK4966E

Dear Jacelyn Foo,

We select LKK Auto Consultancy Pte Ltd
as our surveyor.

Thank you.

From Southern Motor

From: Jacelyn Foo <jacelyn.foo@ergo.com.sg>
Sent: Thursday, December 26, 2019 2:08 PM
To: soumotor@hotmail.com <soumotor@hotmail.com>
Subject: ERGO Claims Ref: CDMCG19002333 (GBA8759M) | Your Ref: FBK4966E

Data Classification: Confidential, C3

Dear Southern Motor,

Please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPk	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Thanks!

Warmest Regards,
Jacelyn Foo
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID: +65 6829 9258
jacelyn.foo@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	282C
Vehicle Details	
Vehicle No.:	FBK4966E
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400SF MANUAL
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	NC42E1203498
Chassis No.:	NC421603494
Maximum Power Output:	-
Open Market Value:	\$7,306.00
Original Registration Date:	18 Sep 2015
First Registration Date:	18 Sep 2015
Transfer Count:	2
Actual ARF Paid:	\$1,096.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Sep 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,512.00
COE Rebate Amount:	\$3,727.00
Total Rebate Amount:	\$3,727.00

The information contained herein is correct as at 27 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/12/2019 21:29
Date Of Accident	04/12/2019 08:40
Exact Location Of Accident	SLE TOWARDS JOHOR AT 4.4KM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK4966E
Insured/Policyholder	
Name Of Registered Owner	JOSE GEORGE
NRIC No	S7967282C
Email Address	JOSEGEORGEUAE@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97109545
Alternative Phone No	OTHERS-97109545

Vehicle Particulars

Manufacturer	HONDA
Model	CB400SF MANUAL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	SI19V09598
Cover Note Number	N.A

Driver

Name of Driver	JOSE GEORGE
NRIC No	S7967282C
Date Of Birth	05/08/1979
Occupation	INDOOR
Date Of Driving Pass	16/12/2010
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97109545
Fax Number	
Contact Number	OTHERS-97109545
Email Address	JOSEGEORGEUAE@YAHOO.COM

Address NA
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : SHAFIQ AYMAN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO.T/20191206/2031: ON THE ABOVE MENTION TIME AND PLACE, I WAS RIDING MY MOTORCYCLE FBK4966E WITH MY PILLION SHAFIQ. WE WERE ON OUR WAY BACK TO JOHORE. I WAS RIDING ON LANE 1/3 ALONG SLE TOWARDS BKE WHEN I NOTICED A LORRY GBA8759M ON LANE 2/3 TRAVELLING SLOWLY AND SUDDENLY FILTERED TO THE RIGHT INTO MY TRAVEL PATH. I WAS THEN UNABLE TO STOP OR AVOID IN TIME AND THUS THE LORRY'S RIGHT SIDE CENTRE PORTION SIDE SWIPPED MY HANDLE BAR PORTION. IMPACT THEN CAUSED MY MOTORCYCLE TO FALL THUS CAUSED BOTH MYSELF AND PILLION TO LAND ON THE GROUND. THE LORRY THEN IMMEDIATELY STOPPED AND RENDERED ASSISTANCE. AMBULANCE WERE THEN CALLED IN AND BOTH MYSELF AND PILLION WERE CONVEYED TO KTPH. WE WERE BOTH CONSCIOUS AFTER THE ACCIDENT TOOK PLACE. WE WERE BOTH DISCHARGED SAME DAY. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBA8759M
 Vehicle Make/Model/Colour MITSUBISHI / FB70BB1SRDEA
 Details Of Properties N.A

Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name JOSE GEORGE
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBK4966E
Were seat belts worn? NO
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name SHAFIQ AYMAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBK4966E
Were seat belts worn? NO
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. This report is to be completed by the Policyholder and/or the Authorized Officer.
2. A truthful and accurate report is essential and accurate as possible. Any dishonest or fraudulent information provided may result in the insurance company's right to repudiate policy liability.
3. Any loss and damage to the property, contents or belongings may not be covered or partly covered, but not part of the insurance claimable.
4. Any false reporting may be referred to the Police for investigation.
5. The report will be forwarded to the insurers of the Ajax Mars Management Corporation Limited by the General Insurance Association of Singapore (GIA) for checking and they reserve the right to report you to the relevant authorities and investigation as warranted.
6. By the signing of this report to the insurers, you hereby consent to the signing of this report to the insurers and its copies of the report being made available elsewhere.
7. **Consent under the Personal Data Protection Act (PDPA)**
I/We hereby acknowledge, agree and consent that:
 - (i) My/ourself, my/ourself and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and/or share such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insured who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers, insurance firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (a) processing, handling and/or dealing with my claims involving the settlement of the claims and any necessary investigations relating to the claims;
 - (b) investigating the accident and/or my claims;
 - (c) carrying out and/or dealing with my instructions or requesting to any insurers to me;
 - (d) administering my claims (including the issuing of correspondence, statements, insurers' reports in relation to me, which could involve disclosure of certain personal data about me to bring about delivery of the claim as well as on the external cover of email/printout packages); and/or
 - (e) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes";
 - (ii) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawfully/legally firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may/can be disclosed by any of the insurers and/or link to third third party service providers or administering their insurers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
 - (iv) my Personal Information will not be collected and used to compile claims history for the purpose of fraud detection, investigation and management to present and all future claims;
 - (v) the information so collected under (ii) above may be shared / disclosed:
 - (a) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (b) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
WONG EUN KEAT

Policyholder's Signature
Date & Time:

9/12/2019

Insurer's Signature
(If insurer is not the policyholder)
Date & Time:

Reporting Officer (Insurance Firm)'s Signature
Name:
Specimen No:

DATE: 10/10/2010

1. T-1000-1011

2. 1000-1011



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION:

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

VERIFY BY AJAX MARS (ARC)

REPORTING OFFICER

WONG JUN KEAT

Reporting Officer's Signature

Name

NRIC/IN No.



**SINGAPORE
POLICE FORCE**



T/20191206/2031

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20191206/2031

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/12/2019 10:24		Vide Report No.: L/20191204/0062		Station Diary No.:	
Informant's Particulars					
Name of Informant: JOSE GEORGE			Address: APT BLK 131B KIM TIAN ROAD #07-175 KIM TIAN VISTA SINGAPORE 162131		
ID Type / ID No.: NRIC NO / S7967282C			Contact No.: Home/Office: Mobile: 97109545		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 40	Date of Birth:	Type of Informant: Rider		
Race: Indian			Language:		Institution / School Name:
Occupation: Architectural draughtsman			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 04/12/2019 08:40	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY 4.4KM				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
FBK4966E	Motorcycle				Slightly Damaged	1
GBA8759M	Lorry				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20191206/2031

CONTINUATION OF REPORT

Rider			
Name	JOSE GEORGE		ID No. S7967282C
Related Vehicle	FBK4966E (Motorcycle)		Contact No. 97109545
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date Class: 2B Date of Expiry: NIL
Date Treatment	04/12/2019	Date Discharge	04/12/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Pillion			
Name	SHAFIQ AYMAN		ID No. 880702566235
Related Vehicle	FBK4966E (Motorcycle)		Contact No. NIL
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	04/12/2019	Date Discharge	04/12/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTION TIME AND PLACE, I WAS RIDING MY MOTOR CYCLE FBK4966E WITH MY PILLION SHAFIQ. WE WERE ON OUR WAY BACK TO JOHORE. I WAS RIDING ON LANE 1/3 ALONG SLE TOWARDS BKE WHEN I NOTICED A LORRY GBA8759M ON LANE 2/3 TRAVELLING SLOWLY AND SUDDENLY FILTERED TO THE RIGHT INTO MY TRAVEL PATH. I WAS THEN UNABLE TO STOP OR AVOID IN TIME AND THUS THE LORRY'S RIGHT SIDE CENTRE PORTION SIDE SWIPPED MY HANDLE BAR PORTION. IMPACT THEN CAUSED MY MOTORCYCLE TO FALL THUS CAUSED BOTH MYSELF AND PILLION TO LAND ON THE GROUND. THE LORRY THEN IMMEDIATELY STOPPED AND RENDERED ASSISTANCE. AMBULANCE WERE THEN CALLED IN AND BOTH MYSELF AND PILLION WERE CONVEYED TO KTPH. WE WERE BOTH CONCIIOUS AFTER THE ACCIDENT TOOK PLACE. WE WERE BOTH DISCHARGED SAME DAY. THAT'S ALL.



**SINGAPORE
POLICE FORCE**



T/20191206/2031

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No: T/20191206/2031

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD
YUSOF

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /

Contact No.:

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
06/12/2019 10:24

Classification Of Case:



南方摩哆

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

20th December 2019

Engo Insurance Pte Ltd

5 Temasek Boulevard #04-05

Suntec Tower Five

Singapore (038985)

Dear Sirs,

RE: Cost of repair to Honda CB400SF - FBK4966E

1pc of Front Mudguard / DR
 1pc of Meter Complete / DR
 1pc of Head Lamp Complete / DO
 1pc of Front Signal / LUT (LH)
 1pc of Handle Bar / BT
 1pc of Front Fork Complete / DO
 1pc of Front Sport Rim / DO
 1pc of Front Tyre / TN (-70%)
 2pcs of Front Brake Disc / ? / BT
 1pc of Steering Cone Stand / APC
 1pc of Fuel Tank / DO
 1pc of Cylinder Head Cover / DO
 1pc of Cylinder Head Cover Rubber / APC
 1pc of Magneto Cover / CUT
 1pc of Magnet Gasket / APC
 1pc of Handle Balancer / CUT
 1pc of Radiator / DO
 1pc of Front Footrest / MIS
 1pc of Rear Footrest / MIS
 1pc of Gear Lever Complete / BT/CUT
 1pc of Clutch Lever / MIS
 1pc of Mirror / CUT
 1pc of Lamp Stay Bracket / CUT
 1pc of Clutch Cable X NM
 1pc of Handle Grip / TN

P-8599-50

L-724

9323-50

L/S - 7458-80

= 7450

Yours Faithfully,
Southern Motor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S\$ 165.00 ✓
 1,650.00 1480 ✓
 480.00 ✓
 95.00 ✓
 165.00 ✓
 1,800.00 ✓
 1,250.00 850 ✓
 160.00 112 ✓
 1,400.00 1000 ✓
 380.00 150 ✓
 1,600.00 1180 ✓
 325.00 ✓
 95.00 ✓
 185.00 ✓
 18.00 ✓
 70.00 50 ✓
 850.00 ✓
 45.00 ✓
 45.00 ✓
 165.00 ✓
 65.00 ✓
 85.00 ✓
 120.00 ✓
 35.00 X
 30.00 ✓

11,278.00

1,127.80

10,150.20

Less 10%

Nett

Transport

Fork Oil

Steering Cone

Coolant

Engine Oil

IU Unit

Labor

\$11,084.20

Tel 62299189
 Fax 62299247

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG19022762/EQD3N2
Date: 07/02/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No: FBK4966E Insured Vehicle No: GBA8759M
Date of Loss: 04/12/2019 Nature of Claim: TP Claim No: CDMCG19002333

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBK4966E Engine No: NC42E1203498
Make & Model: HONDA CB400SF, 399cc Chassis No: NC421603494
Reg. Date: 18/09/2015 (Man. Year: 2015) Odometer: 43009 km
Colour: Black
Engine Capacity: 399 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60 ZR17 Rear Tyre Size: 160/60 R17
Front Left Side: FKR 5 mm Rear Left Side: FKR 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,399.20	8,818.50	1,580.70	15.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	685.00	505.00	180.00	26.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,084.20	9,323.50	1,760.70	15.88
Approved Total (Overridden) (S\$)		7,450.00		
(S\$)	11,084.20	7,450.00	3,634.20	32.79
+ GST 7.00/7.00% (S\$)	775.89	521.50	254.39	32.79
Nett Amount (S\$)	11,860.09	7,971.50	3,888.59	32.79

INSPECTION

Date of Assignment: 26/12/2019
Date Inspected: 27/12/2019 Inspected At: Southern Motor (HQ)
BLK 1006 BUKIT MERAH LANE 2, #01-10
Singapore 159762
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Feb 2020)	
Parts:	N/A	HONDA CB400SF 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK4966E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Broken	165.00 FL	*165.00 FL
2	1		*METER COMPLETE	Broken	1,650.00 FL	*1,480.00 FL
3	1		*HEAD LAMP COMPLETE	Dented	480.00 FL	*480.00 FL
4	1		*FRONT SIGNAL LH	Cut	95.00 FL	*95.00 FL
5	1		*HANDLE BAR	Bent	165.00 FL	*165.00 FL
6	1		*FRONT FORK COMPLETE	Dented	1,800.00 FL	*1,800.00 FL
7	1		*FRONT SPORT RIM	Dented	1,250.00 FL	*850.00 FL
8	2		*FRONT BRAKE DISC	Bent	1,400.00 FL	*1,000.00 FL
9	1		*STEERING CONE STAND	Necessary	380.00 FL	*150.00 FL
10	1		*FUEL TANK	Dented	1,600.00 FL	*1,180.00 FL
11	1		*CYLINDER HEAD COVER	Dented	325.00 FL	*325.00 FL
12	1		*CYLINDER HEAD COVER RUBBER	Necessary	95.00 FL	*95.00 FL
13	1		*MAGNETO COVER	Cut	185.00 FL	*185.00 FL
14	1		*MAGNET GASKET	Necessary	18.00 FL	*18.00 FL
15	1		*HANDLE BALANCER	Cut	70.00 FL	*50.00 FL
16	1		*RADIATOR	Dented	850.00 FL	*850.00 FL
17	1		*FRONT FOOTREST	Missing	45.00 FL	*45.00 FL
18	1		*REAR FOOTREST	Missing	45.00 FL	*45.00 FL
19	1		*GEAR LEVER COMPLETE	Bent/Cut	165.00 FL	*165.00 FL
20	1		*CLUTCH LEVER	Missing	65.00 FL	*65.00 FL
21	1		*MIRROR	Cut	85.00 FL	*85.00 FL
22	1		*LAMP STAY BRACKET	Cut	120.00 FL	*120.00 FL
23	1		*CLUTCH CABLE	Not Necessary	35.00 FL	*- FL
24	1		*HANDLE GRIP	Torn	30.00 FL	*30.00 FL
25	1		*FORK OIL	Necessary	24.00 FS	*24.00 FS
26	1		*COOLANT	Necessary	45.00 FS	*45.00 FS
27	1		*STEERING CONE	Necessary	120.00 FS	*120.00 FS
28	1		*ENGINE OIL	Necessary	60.00 FS	*30.00 FS
29	1		*FRONT TYRE	Torn	160.00 FL	*112.00 FL

F=Franchise part, S=SpicNett, L=ListItemDisc.

Sub Total (\$\$)	11,527.00	9,774.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,127.80	955.50
Total Parts (\$\$)	10,399.20	8,818.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	35.00	35.00
2	IU UNIT	New	170.00	170.00
3	LABOR	New	480.00	300.00
Gross Labour Cost (S\$)			685.00	505.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >