

ASS. REC. BY:

REF:

CS3/AUG19022765/Byd302

Special Instruction:

Surveyor: Mr. Jim

ASSIGNMENT (Office)

From (Person): Winnie Fan

of

AIG

Date/Time:

26/12/19 @ 4:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 5237R

Insured:

SLX 4703K

at Workshop m/s

Kumchew

Tel:

64536259

of

160 Sin Ming Drive # 05-08

Policy No:

0999994491

Claim No:

638481145286

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:46am @ 27/12/19

Person Contacted:

Mdm. Hun

Vehicle

IN / OUT

Date/Time	Action/Instruction
	Johnnot? (X)
	SLX 4703K: X
	GBG 5237R: X

ASS. REC. BY: Mr Lim

REF: AIG

PRS

ASSIGNMENT

From: \_\_\_\_\_ Date: 27/12/19

Estimated Cost: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBG 5237R

at Workshop m/s Kum Chew

of 160 Sin Ming Drive # 05-08

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: look for mdm. Lim

Veh No: GBG 5237R Yr Regn: 28/8/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Nissan 350 Panel van c.c 2,488

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 85701 T/Radio: Insured / Std / NI / NA

Eng/No: YD25422211A

C/No: JN1MC2E26Z0008536

Gen. Cond: Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 195/15 Luxofix

R: 195/15 BS

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 47,000/2

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>Wp</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Luxotin fit / BS rear

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. 21/12/19	D.O.I. 27/12/19

Survey held at Kum Chew

Des. of Damages:  Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
5/2/20	Submit PRS
RECEIVED 06 FEB 2020	
MV	47,000/2
PV	28,244/2
NV	18,756/2

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? 5/2/20 Typist

Report Format: \_\_\_\_\_

Lump Sum / L.B.I: (\$) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$) )

: Interview (\$) )

: Tech. Invs (\$) )

: Weekend (\$) )

Survey Fee:	180
Transportation:	_____
Photos	_____
Others	11
TOTAL	191

TTCM Lim  
30/12/19

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Dec 2019 <a href="#">Edit Reg</a>		27 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>MICROCREDIT CAR LEASING PTE LTD</b> , Co. Reg. No.: 200910504E								
Main Claimant:	-								
Vehicle Reg. No.:	<b>GBG5237R</b>	Date of Loss:	21/12/2019 11:00 - :59						
Claim Type:	<b>TP / 6384811452SG</b>	Policy/Cover Note No.:	0999994191 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLX4703K</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Kum Chew Motor Workshop (160 Sin Ming) (HQ)</b> 160 Sin Ming Drive, #05-08 Sin Ming Autocity, 575722 Sin Ming - Tel: 6456 3715								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ] Kianmeng.Chan1@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Final Rpt due 08/01/2020]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLX4703K AND GBG5237R ON 21/12/2019**

\* From: Fan, Winnie-LW  
To: Admin A, assignments  
Cc: Fong, Andy-SY  
Sent: 12/26/2019 4:22:34 PM

---

Hi LKK,

Kindly assist to survey.

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you

-----Original Message-----

From: kumchew1 [mailto:kumchew1@singnet.com.sg]

Sent: Monday, December 23, 2019 3:31 PM

To: 'Hor, Yinrul'

Subject: FW: ACCIDENT INVOLVING GBG 5237 R & SLX 4703 K ON 21/12/2019.

Dear Sir,

We are acting on behalf of M/s. Acepac Rental the owner of GBG 5237 R in the above matter.

Kindly arrange for pre-repair with the following details;

Venue : Kum Chew Motor Workshop  
160, Sin Ming Drive #05-08  
Sin Ming Autocity  
Singapore 575722.

Contact No. : 64536256.

Thank & Best Regards,  
Mdm Lim

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	615A
Vehicle Details	
Vehicle No.:	GBG5237R
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5AT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	YD25422211A
Chassis No.:	JN1MC2E26Z0008536
Maximum Power Output:	-
Open Market Value:	\$26,142.00
Original Registration Date:	28 Aug 2017
First Registration Date:	28 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$1,308.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$28,244.00
<b>Total Rebate Amount:</b>	<b>\$28,244.00</b>

The information contained herein is correct as at 30 Dec 2019

OK

Dep 6,70/yr  
514/mth

MV 47,000/2  
PV 28,244/2  
NV 18,756/2

Tam   
30/12/19



## BIDDED CARPLATE NUMBERS FOR SALE

*Find and buy your favourite car plate number here!*

START  
SEARCH  
NOW!

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal COE Toyota Vios 1.5A.



2.98% P.A, \$0 Down, \$0 Admin,  
Monthly From \$438. 2 Yrs  
Warranty Engine/Gearbox  
GV Credit StarAxi

ABWIN ONE-STOP

MOTORING SOLUTIONS



VIEW OUR PROFILE


Browse by Category ▾

Sort by Reg. Date ▾ 20 results/page ▾

8 vehicles

Nissan NV350

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Nissan NV350		Any	Any	2017	Any	Any	Any	Available
	Nissan NV350	2.5M	\$46,800	\$5,860 /yr	22-Dec-2017	2,488 cc	52,000 km	Van	Available
	<b>Fuel Type:</b> Diesel								
	Lowest In The Market! Well Maintained By 1 Owner Only!No Waiting Time Needed. Save Up The Hassle From Registration Of New Car. Bank Loan At Promotional Rate, 100% Loan Available. We Also Offer Various In House Loan With Flexible Finance Package. Trade In W...								
	Posted: 18-Dec-2019 Tags: 2017 Nissan NV350, 2017 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan								
	Nissan NV350	2.5A	\$50,800	\$6,460 /yr	10-Nov-2017	2,488 cc	-	Van	Available
	<b>Fuel Type:</b> Diesel								
	Low Mileage, Under Warranty By Tan Chong. Call Us Now To Make Appointment For Viewing.								
	Posted: 31-Oct-2019 Tags: 2017 Nissan NV350, 2017 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan								
	Nissan NV350	2.5M	\$47,800	\$6,170 /yr	29-Sep-2017	2,488 cc	36,000 km	Van	Available
	<b>Fuel Type:</b> Diesel								
	1 Ownership,Under Utilised,almost As Good As New YET Lower Depreciation=cost Savings.Bank And In House Loan Available! Trade In Welcome.So Hurry Come And View, Test Drive Now! Make An Appointment With Any Of Hong Wei Vehicle Salespersons Now!								
	Posted: 15-Dec-2019 Tags: 2017 Nissan NV350, 2017 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan								
	Nissan NV350	2.5A	\$52,800	\$6,890 /yr	30-Aug-2017	2,488 cc	1,800 km	Van	Available
	<b>Fuel Type:</b> Diesel								
	1 Owner, Super Rarely Used That's Why Super Low Mileage, As Good As Driving A New Van, No Accidents Before, Still Under Agent Warranty.								
	Posted: 21-Dec-2019 Tags: 2017 Nissan NV350, 2017 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan								
	<b>Magic Car 2 Way Security Alarm</b>								
	Korean Top Security Alarm , Magic Car Has Arrived   2 way alarm with auto start. More than 15 years in Car Security system.								
	More info about this product								
	Nissan NV350	2.5M	\$48,800	\$6,510 /yr	29-Jun-2017	2,488 cc	-	Van	Available
	<b>Fuel Type:</b> Diesel								
	New Euro 6 From Agent Tan Chong. Latest Facelift. Call To Enquire Or Viewing!								
	ABWIN (1994) Pte Ltd								
	Posted: 27-Dec-2019 Tags: 2017 Nissan NV350, 2017 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan								
	Nissan NV350	2.5M	\$48,800	\$6,520 /yr	22-Jun-2017	2,488 cc	-	Van	Available
	<b>Fuel Type:</b> Diesel								
	1 Direct Owner, Regularly Maintain, Practical 5 Door And Low Maintenance Popular Vehicle. Call For A Test Drive Now.								
	Posted: 04-Dec-2019 Tags: 2017 Nissan NV350, 2017 nissan nv350, Nissan NV350, nissan nv350, Nissan, NV350, nv350, Used Nissan								
	Nissan NV350	2.5A	\$47,800	\$6,450 /yr	30-May-2017	2,488 cc	60,082 km	Van	Available
	<b>Fuel Type:</b> Diesel								
	Tip Top Condition Like New, Very Careful 1 Owner, Low Mileage, Low Depreciation, In House Loan Available, Loan Easy Approval. Trade In Welcome!								

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/12/2019 10:57
Date Of Accident	21/12/2019 11:30
Exact Location Of Accident	ALONG CLEMENTI AVENUE 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG5237R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ACEPAC RENTAL
Co Reg No	5XXXX615A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64536256

### Vehicle Particulars

Manufacturer	NISSAN
Model	NV350
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999993983/100832936-00000
Cover Note Number	

### Driver

Name of Driver	NUR ADLY BIN SULAIMAN
NRIC No	SXXXX805C
Date Of Birth	11/09/1995
Occupation	OUTDOOR
Date Of Driving Pass	24/11/2016
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97770824
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 107 SIMEI STREET 1  
#06-836  
Postcode 520107  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - HIRER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - MAJOR/MINOR RD  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? YES  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name CHANGI N.P.C  
Police Station Address ROAD: 9 SIMEI STREET 2 , POSTCODE: 529914 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: - FAX NO:  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20191223/2022.

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLX4703K  
Vehicle Make/Model/Colour HONDA SHUTTLE  
Details Of Properties  
Vehicle Category PRIVATE HIRE  
Name of Driver ONG KA YONG  
NRIC/Passport Number SXXXX488F  
Contact Number 94758032  
Address  
Postcode  
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	NUR ADLY BIN SULAIMAN
Approximate Age	24
Injuries Sustain	BACK AND SHOULDER
Injured person in which vehicle?	GBG5237R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 107 SIMEI STREET 1 #06-836
Postcode	520107

**DETAILS OF INJURED PERSON 2**

Name	
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLX4703K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time

23 DEC 2019

10:57am

Signature of Insurer

Insurer's Signature

(If not the policyholder)

Date & Time

23 DEC 2019


10:57am

Favoring Service Personnel's Signature

Name:

ORCID ID No.: Poh Kwee Choo

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT  
T/20191223/2022

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time: 23 DEC 2019



  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 23 DEC 2019

  
Reporting Centre Personnel's Signature  
Name: Poh Kwee Choo  
NRIC/FIN No.



**SINGAPORE  
POLICE FORCE**



T/20191223/2022

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

1 of 3

Report No. T/20191223/2022

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/12/2019 09:21	Vide Report No.: T/20191221/7011	Station Diary No.: 13
--	-------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: NUR ADLY BIN SULAIMAN		Address: APT BLK 107 SIMEI STREET 1 #06-836 SINGAPORE 520107	
ID Type / ID No.: NRIC NO / S9531805C		Contact No.: Home/Office:                      Mobile: 97770824	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 24	Date of Birth: 11/09/1995	Type of Informant: Driver
Race: Boyanese		Language:	Institution / School Name:
Occupation: Other electrical engineering technicians		Driving Licence Information: Class: 3,4                      Date of Expiry: .	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 21/12/2019 11:30	Type of Location: Straight Road
Location: Along Road 1 CLEMENTI AVENUE 2				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBG5237R	Van	NISSAN	NV350 PANEL VAN 2.5 5AT 5DR EURO V	Red	Slightly Damaged	0
SLX4703K	Car	HONDA	SHUTTLE HYBRID 1.5 AUTO	Black	Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20191223/2022

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

2 of 3

Report No. T/20191223/2022

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NUR ADLY BIN SULAIMAN	ID No.	S9531805C
Related Vehicle	GBG5237R (Van)	Contact No.	97770824
Hospital/Clinic	KINGS MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	22/12/2019	Date Discharge	22/12/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

I was driving my vehicle, GBG5237E travelling straight along Clementi Avenue 2 towards Clementi. On the right lane, SLC4703K was about to exit the carpark Block 331 and wanted to turn right at a junction that did not have a traffic light. The driver did not see me coming and made the right turn as I was going straight. As such, I collided into his vehicle on the right side driver door.

I then got out of my vehicle and called for ambulance and the driver was then conveyed to the hospital. I had also went clinic as I was not feeling well. I was then given 3 days of Medical Leave.



SINGAPORE  
POLICE FORCE



T/20191223/2022

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999


3 of 3  
Report No. T/20191223/2022

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 MUHAMAD ZHAFRI BIN REJAB	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 23/12/2019 09:21
Officer In Charge Of Case: TP / GIT / Sgt 3 RASHID BIN AZMAN Contact No.: 65476216	Classification Of Case:
Authentication Stamp NP168 	



**...CLAIM SUBFOLDER...(Pending for Survey Report)**

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Dec 2019 <a href="#">Edit Reg</a>		26 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	<b>MICROCREDIT CAR LEASING PTE LTD</b> , Co. Reg. No.: 200910504E								
Main Claimant:	-								
Vehicle Reg. No.:	<b>GBG5237R</b>	Date of Loss:	21/12/2019 11:00 - :59 <b>[27 Months and 23 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 6384811452SG</b>	Policy/Cover Note No.:	0999994191 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLX4703K</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Kum Chew Motor Workshop (160 Sin Ming) (HQ)</b> 160 Sin Ming Drive, #05-08 Sin Ming Autocity, 575722 Sin Ming - Tel: 6456 3715								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Final Rpt due 08/01/2020]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*GBG5237R (6384811452SG)  
[SLX4703K]  
TP

-  
Dec 21 2019 11:00AM  
[MICROCREDIT CAR LEASING PTE LTD]  
Kum Chew Motor Workshop (160 Sin Ming)

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View In Browser"/>	
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
2	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
3	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
4	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
5	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
6	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
7	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
8	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
9	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
10	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
11	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
12	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
13	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
14	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
15	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
16	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
17	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
18	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
19	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
20	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
21	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
22	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
23	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
24	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
25	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
26	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
27	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
28	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
29	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
30	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
31	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
32	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
33	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
34	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
35	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
36	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
37	13/01/20 16:56	General View						 Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
39	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
40	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
41	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
42	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
43	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
44	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
45	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
46	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>
47	13/01/20 16:56	General View		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	31/12/19 14:17	OI Accident Statement		Load PDF <input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG19022765/BYD3E2  
**Date:** 07/02/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 0999994191	
Claimant Vehicle No : GBG5237R	Insured Vehicle No : SLX4703K	
Date of Loss: 21/12/2019	Nature of Claim: TP	Claim No: 6384811452SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG5237R		
Make & Model:	NISSAN NV350, 2.5 D Panel Van (M)	Engine No:	YD25422211A
Reg. Date:	28/08/2017 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0008536
Colour:	White	Odometer:	85701 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Luxotik 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Luxotik 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	26/12/2019	
Date Inspected:	27/12/2019 Inspected At:	Kum Chew Motor Workshop (160 Sin Ming) (HQ) 160 Sin Ming Drive, #05-08 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	5.0 days	

**Adjuster:** Lim Teow Guan

**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT BUMPER	Broken	0.00 F	*- F
3	1		*FRT RH BUMPER FOG LAMP COVER	Missing	0.00 F	*- F
4	1		*FRT RH BUMPER FOG LAMP	Missing	0.00 F	*- F
5	1		*FRT GRILLE	Missing	0.00 F	*- F
6	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
7	1		*FRT APRON PANEL	Bent	0.00 F	*- F
8	1		*FRT CORNER PANEL	Dented	0.00 F	*- F
9	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
10	1		*BONNET	Dented	0.00 F	*- F
11	1		*BONNET LOCK	Jammed	0.00 F	*- F
12	1		*BONNET HINGE	* Check	0.00 F	*- F
13	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
14	1		*AIR CON FAN ASSY	* Check	0.00 F	*- F
15	1		*RADIATOR COWLING	* Check	0.00 F	*- F
16	1		*RADIATOR FAN ASSY	* Check	0.00 F	*- F
17	1		*RADIATOR HOSE TOP	* Check	0.00 F	*- F
18	1		*RADIATOR EXPANSION TANK	* Check	0.00 F	*- F
19	1		*OIL COOLER	* Check	0.00 F	*- F
20	1		*FRT RH DOOR	Bent	0.00 F	*- F
21	1		*RH INTERCOOLER	Bent	0.00 F	*- F
22	1		*FRT PANEL	Bent	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >