

ASS. REC. BY: STNR REF: C93 / SMO18020245 / E48-1/2 Special Instructions:

Supervisor: Muhammad ASSIGNMENT (Office)

From (Person): Gmoh Pau Leang of SMO Date/Time: 30/12/19 4:40pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 4464D Insured: GBF 2329J

at Workshop n/s: Orion Autoclinic Tel: 9444476

of No. 25 Kaki Bukit Rd 4 #D3-32. Synergy

Policy No: D18MTPCYE002784 Claim No: OMT01804876

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07-11-2018

(Client's Record) 07-11-2018 @ after 11am

CA / REV / REP. / REV 24 HRS' Wp. H.O.D. Endorsement: _____

Date/Time: 09/11/2018 4:53pm Person Contacted: Kenneth Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJW 4464D - x</u>
	<u>GBF 2329J x</u>
	<u>Dismantle: 12/11/2018</u>
	<u>After repair: 14/11/2018</u>

Repair 7 day
 31/12/19 L/S \$4000/- (Red \$3390-00, 45%)
 31/12/19 Typist

[Signature]
 31/12/2019

490 - 220 = 270

YRS
Hwee Jie

REF: SMO

Mufman

ASSIGNMENT

From: Date: 19.11.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Trailed Vehicle No: SJW 4464D

at Workshop no: Orion Autodinic

at: 25 Kaki Bukit Rd 4 #10-32

Insured: C Synergy

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

After 11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

But. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GA : FR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

GA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT

Ins No: SJW 4464D

Type: Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: (A)

Make: Honda fit

Colour: Red

Sp Reading: 113848

Eng No: L13A4202373

C/Ns: GE61184575

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Type Size: F: 195/55 R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / OKM or

Front: R/Bal: 6 mm L/Bal: 6 mm D.O.A: 7/11/18

Rear: R/Bal: 6 mm L/Bal: 6 mm D.O.I: 9/11/18

Survey held at: @ 1330

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front / Rear

The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

Page: 1 of 1
Range: \$4000 - \$5000
6 days

[Signature]
15/11/2018

Case/Time: File Pass to: ☐ Prel. Report

Case/Time: File Return to: ☐ Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp: \$5

☐ Interview: \$5

☐ Tech. Serv: \$5

☐ Workshop: \$5

Survey Fee: 100

Insurance: 60460

100
60460
10
220

Report Format: PRS

Lump Sum / L.B. / \$

Nivitha (LKK Auto)

From: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Sent: Friday, 6 September 2019 5:26 PM
To: Yvonne
Cc: Admin-D <admin-d@lkkauto.com> (admin-d@lkkauto.com);
'assignments@lkkauto.com'; sur@lkkauto.com
Subject: RE: CMTD1804876/GPL \ Yr Ref: 2018.6043.EA.MK.ya - 2D/ GBF2329J & SJW4464D
ACC ON 07.11.18

Importance: High

Without Prejudice

Dear Yvonne,

With reference to the captioned, we acknowledge receipt of your letter of demand and we note that our surveyor, M/s LKK AUTO had conducted post repair inspection and we will be carrying out the paper resurvey for this case.

In the meantime, please hold hands and we will revert to you as soon as possible, thank you.

By copy to M/s LKK AUTO (your ref : CS3/SMO18020245/JCBE2) ,

Please assist for the above and do notify us once your report is uploaded in Merimen, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 20 August, 2019 10:22 AM
To: Yvonne <yvonne@ealc.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1804876/GPL \ Yr Ref: 2018.6043.EA.MK.ya - 2D/ G8F2329J & SJW4464D ACC ON 07.11.18

Without Prejudice

Our Reference: CMTD1804876/GPL
Your Reference: 2018.6043.EA.MK.ya

Hi Yvonne,

We acknowledged receipt of your claim documents.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 217.

Aside to Pau Loong,

Please assist.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Yvonne [<mailto:yvonne@ealc.com.sg>]
Sent: Monday, August 19, 2019 1:55 PM

To: Claims - Motor Survey

Subject: Our Ref: 2018.6043.EA.MK.ya Your Ref: GBF2329J

Dear Sir/Madam,

We enclose herewith our letter dated 19 August 2019. Thank you.

Regards,

Yvonne Ang

East Asia Law Corporation

No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413

Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2018 17:00
Date Of Accident	07/11/2018 16:30
Exact Location Of Accident	BLK 546A MSCP SERANGOON NORTH AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW4464D
Insured/Policyholder	
Name Of Registered Owner	ROSMAH BINTE RASID
NRIC No	S1559694E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90050095
Alternative Phone No	OFFICE-90050095

Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3G A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-004426
Cover Note Number	

Driver

Name of Driver	ROSMAH BINTE RASID
NRIC No	S1559694E
Date Of Birth	25/05/1962
Occupation	INDOOR
Date Of Driving Pass	22/05/1998
Driving Experience	20 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90050095
Fax Number	
Contact Number	OFFICE-90050095

Address	BLK 279A SENGKANG EAST AVENUE #07-517
Postcode	541279
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF2329J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KER HUI CHONG
NRIC/Passport Number	
Contact Number	92983234
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A
MY VEHICLE WAS STATIONARY IN THE MULTISTORY CARPARK.
VEHICLE B, WHO WAS MAKING A RIGHT TURN COLLIDED INTO MY
FRONT RIGHT OF MY VEHICLE A. THE IMPACT WAS SO HARD THAT IT
CAUSED THE VEHICLE TO MOVED. THE REAR LEFT OF MY VEHICLE
GRAZED ONTO THE WALL DUE TO THE FORCEFUL IMPACT FROM
VEHICLE B.
TRAFFIC POLICE REPORT NO: A120181107 0095

DECLARATION

I/We declare the foregoing particulars are true in every respect.

ROSM
Policyholder's Signature
Date & Time:

ROSM
Driver's Signature
(If driver is not the policyholder)
Date & Time:

CH
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Robert

Policyholder's Signature
Date & Time:

Robert

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2018 11:08
Date Of Accident	07/11/2018 16:30
Exact Location Of Accident	SERANGOON NORTH AVENUE 3 BLK 546A CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF2329J
Insured/Policyholder	
Name Of Registered Owner	LIAN LEE WOODEN CASE MAKER CO PTE LTD
Co Reg No	2XXXXX347k
Email Address	NBC@LIANLEEWODEN.COM.SG
Mobile Phone No	(LOCAL) +65-92983234
Alternative Phone No	Office-63681787

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER-3.0 D FEA01BR2SDEB (CBU) (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPCVE002784
Cover Note Number	

Driver

Name of Driver	KER HUI CHING
NRIC No	SXXXX189H
Date Of Birth	12/08/1950
Occupation	OUTDOOR
Date Of Driving Pass	16/11/1977

Driving Experience	40 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92983234
Fax Number	
Contact Number	
EEmail Address	D_KER@YAHOO.COM
Address	APT BLK 247 BUKIT BATOK EAST AVENUE 5 #06-80 SINGAPORE
Postcode	650247
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	Name: : NGUYEN TIEN LOC Gender: : Male
Passenger 2	Name: : DUONG DUC HUY Gender: : Male

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
POLICE STATION NAME [OTHER]	TRAFFIC POLICE DIVISION HQ 10 UBI AVENUE 3 SINGAPORE 408865
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

KINDLY REFER TO ATTACHED POLICE REPORT NO T/20181107/7018

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW4464D
Vehicle Make/Model/Colour	HONDA FIT /JAZZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLE8836J
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 08/11/18



Driver's Signature

(If driver is not the policyholder)

Date & Time: 08/11/18

Signature of Reporting Centre Personnel



Reporting Centre Personnel's Signature

Name: BOON LEE KEON

NRIC/FIN No.: S7882145J

Sketch Plan #2

SKETCH PLAN

A - GIBF2329J
B - SJW446AD
C - SLE8836J

LOCATION: SERANGAP NORTA AVE 3 RUK 546A CAR PARK

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

KINDLY FIND THE ATTACHED POLICE REPORT NO:- T/2018 1107/7018

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 02/11/2018

GABAYC SketchPlanForm_V3




Driver's Signature

(If driver is not the policyholder)

Date & Time: 02/11/2018

Signature of Reporting Centre Personnel



Reporting Centre Personnel's Signature

Name: BOI LEE KEDAK

NRIC/FIN No: 57482143J

Certificate of insurance



Sompo Insurance Singapore Pte. Ltd.

30 Raffles Place, #05-01/02 Singapore Land Tower, Singapore 048629 -
Tel: 6451 6555 | Fax: 6321 8333 | Website: www.sompo.sg
Co. Reg. No.: 19880540001 | GST Reg. No.: A020000198

Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 180)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1990
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1958 (MALAYSIA)**

Car No./Policy No. : D18MTPCVE002794
1. Registration No. : GBF2329J
2. Insured Name : LIAN LEE WOODEN CASE MAKER CO PTE LTD
3. Commencement Date : 19 AUGUST 2018 00:00
4. Expiry Date : 18 AUGUST 2019 23:59
5. Coverage : Market value at time of loss - Comprehensive
6. Excess : \$300 - Section I

7. Persons or Classes of Persons entitled to drive*

b) Any person who is driving on the Insured's order or with their permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

8. Limitations as to use*

- 1) Use in connection with the insured's business.
- 2) Use for the carriage of passengers (other than for hire or reward) in connection with the policyholder's business.
- 3) Use for social, domestic or pleasure purposes.

The Policy does not cover

- 1) Use for hire or reward or racing, pace-making, reliability trial or speed-testing.
- 2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

9. ExcelDrive Workshops & Accident Reporting

It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereafter.

It is compulsory to have the accident repairs to the insured vehicle carried out at ExcelDrive Workshops, otherwise claim is not payable.

In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline : (65) 6481 6555

Visit www.sompo.com.sg for list of ExcelDrive Workshops and Accident Reporting Centers.

We HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 180) and Part IV of the Road Transport Act, 1987 (Malaysia).

Sompo Insurance Singapore Pte. Ltd.

Date/Time of Issue : 30 JULY 2018 12:10

*Limitation restricted inoperative by section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 180) and section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

IMPORTANT NOTICE

1. Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 180), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
2. Insureds are further warned that on the sale of a motor vehicle or if for any reason the insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 180).
3. The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle.
4. Please note that this Insurance is subject to the premium being paid and received in full by the Company (s) before the inception date where the Policy is to be issued to an individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.
5. Insurance coverage under this Policy is subject to the terms and conditions as stipulated in the Motor Insurance Policy.

Intermediary Code & Name : 11C18805 & CHEN KIN NAM CI Code: 300 X30D894KJP8ZAN

Police report



SINGAPORE POLICE FORCE



T/20181107/7018

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20181107/7018

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/11/2018 23:06		Vide Report No.: A/20181107/0095		Station Diary No.:	
Informant's Particulars					
Name of Informant: KER HUI CHING			Address: APT BLK 247 BUKIT BATOK EAST AVENUE 5 #06-80 SINGAPORE 650247		
ID Type / ID No.: NRIC NO / S0215189H			Contact No.: Home/Office: Mobile: 92983234		
Nationality: SINGAPORE CITIZEN			Email: d_ker@yahoo.com		
Sex: Male	Age: 68	Date of Birth: 12/08/1950	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 07/11/2018 16:30	Type of Location: Car Park
Location: SERANGOON NORTH AVENUE 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF2329J	Lorry					0
SJW4464D	Car	HONDA	Fit / Jazz	Red	Slightly Damaged	0
SLE8836J	Car	MERCEDES BENZ	GLA	Grey	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20181107/701B

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20181107/701B

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KER HUI CHING	ID No.	S0215189H
Related Vehicle	GBF2329J (Lorry)	Contact No.	92983234
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was driving my company lorry (GBF 2329 J) in the multistorey carpark at Serangoon North Ave 3 BLK 546A.

While driving down the ramp to level 2A, the lorry engine suddenly died off and the power steering stopped functioning.

As a result of that, I'm unable to negotiate the right turn after the ramp in time to avoid a collision into the parked vehicle A (SJW 4464 D).

Due to the impact of the collision, parked vehicle A (SJW 4464D) knocked onto the adjacent parked vehicle B (SLE 8836 J).



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20181107/7018

3 of 3

Report No. T/20181107/7018

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
YAN MINGSHENG DANIEL
Contact No.: 65476252

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
07/11/2018 23:06

Classification Of Case:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 5722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0161118

Date of Report: 28/12/2018

To: Ms Rosmah Binte Rasid
C/o: 25 Kaki Bukit Road 4
Synergy@KB #03-31
Singapore 417800

Date of Assignment: 08/11/2018
Report requested by: Ms Rosmah Binte Rasid
Date of Accident: 07/11/2018
Date of Inspection: 08/11/2018
Claim No.: Third Party Claim
Policy No.: -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.: SJW4464D
Make & Model: Honda Fit
Date of Registration: 25/03/2010
Colour: Red

Engine Capacity (cc): 1339cc
Mileage (km): 113845km
Chassis - Frame No.: GE61184575
Engine No.: L13A4202373

TYRE CONDITION

Front LH	6 mm	Front RH	6 mm
Make	Yokohama	Make	Yokohama
Rear LH	6 mm	Rear RH	6 mm
Make	Yokohama	Make	Yokohama

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork	Good
Paintwork	Good
Handbrake	Serviceable
Footbrake	Serviceable
Steering	Serviceable
Apparent Engine Modification	Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location: M/s. Orion Autocline Pte Ltd
25, Kaki Bukit Road 4, Synergy@KB, #03-31, Singapore 417800

ASSESSMENT

Repairer's Estimate	\$ 11,253.84
Revised Amount	\$ 9,245.36
Less Excess	\$ -
Recommended Reserve	\$ 7,390.00 (Lump Sum)

Estimated Normal Period of Repairs: 12 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S1529890

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 2014044340

Vehicle No : SJW4464D

Report No. : PAS/TP/0161118

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M's. Orion Autoclinic Pte Ltd, 25, Kaki Bukit Road 4, Synergy@KB, #03-31, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front RH, LHF and rear LH portions.

DAMAGES

The bonnet, front bumper, front support panel, front fenders, front apron panels, headlamps, tailgate, rear bumper, rear end panel, rear floor panel, LHR chassis member, LHR fender, LH taillamp, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$9,245.36.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$7,390.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

Vehicle No.: SJW4464D

Report No.: PAS/TP/0161118

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$S)	Our Assessment (\$S)
1	2 pcs	Headlamp R.L.	Cracked Broken	\$ 410.60	\$ 821.20	\$ 821.20 /
2	1 pc	Frt grille	Cracked		\$ 178.20	\$ 178.20 /
3	1 pc	Frt grille emblem	Necessary		\$ 22.90	\$ 22.90 /
4	1 pc	Frt bumper	Dented		\$ 523.50	\$ 523.50 /
5	6 pcs	Frt bumper clip	Necessary	\$ 3.80	\$ 22.80	\$ 22.80 /
6	2 pcs	Frt bumper retainer R.L.	Broken Necessary	\$ 15.30	\$ 30.60	\$ 30.60 /
7	2 pcs	Frt bumper bracket R.L.	Cracked	\$ 27.50	\$ 55.00	\$ 55.00 X Svc
8	1 pc	Frt bumper reinforcement	Dented		\$ 253.90	\$ 253.90 X Svc
9	1 pc	Frt bumper grille	Cracked		\$ 96.50	\$ 96.50 /
10	1 pc	Frt support panel	Dented Repair		\$ 381.90	\$ -
11	1 pc	Frt fender RH	Dented Distorted		\$ 375.60	\$ 375.60 X Svc
12	1 pc	Washer tank	Dented		\$ 82.90	\$ 82.90 X Svc
13	1 pc	Tailgate	Dented Distorted		\$ 736.60	\$ 736.60 /
14	1 pc	Rr no plate lamps garnish	Refit		\$ 145.20	\$ -
15	1 pc	Tailgate emblem (Logo)	Not necessary		\$ 26.50	\$ -
16	1 pc	Tailgate emblem (Fit)	Necessary		\$ 22.80	\$ 22.80 /
17	1 pc	Rr windscreen moulding	Necessary		\$ 120.40	\$ 120.40 /
18	1 pc	Rr windscreen A dam rubber	Necessary		\$ 35.80	\$ 35.80 /
19	1 pc	Rr windscreen B dam rubber	Necessary		\$ 31.00	\$ 31.00 /
20	2 pcs	Rr windscreen D dam rubber	Necessary	\$ 4.70	\$ 9.40	\$ 9.40 /
21	1 pc	Tailgate inner trim	Cracked Deformed		\$ 265.20	\$ 265.20 X Svc
22	10 pcs	Tailgate inner trim clip	Necessary	\$ 3.20	\$ 32.00	\$ 32.00 X Svc
23	1 pc	Tailgate lock	Dented Damaged		\$ 263.90	\$ 263.90 X Svc
24	1 pc	Tailgate lock striker	Bent		\$ 26.70	\$ 26.70 X Svc
25	1 pc	Taillamp LH	Cracked		\$ 296.20	\$ 296.20 /
26	1 pc	Taillamp panel LH	Dented Distorted		\$ 183.50	\$ 183.50 X Svc
27	1 pc	Rr bumper	Dented		\$ 573.20	\$ 573.20 /
28	6 pcs	Rr bumper clip	Necessary	\$ 3.80	\$ 22.80	\$ 22.80 /
29	2 pcs	Rr bumper retainer R.L.	Cracked Necessary	\$ 28.90	\$ 57.80	\$ 57.80 /
30	1 pc	Rr end panel	Dented Distorted		\$ 386.50	\$ 386.50 X Svc
31	1 pc	Rr end panel garnish	Dented Deformed		\$ 140.80	\$ 140.80 X Svc
32	1 pc	Rr weatherstrip	Torn Necessary		\$ 122.30	\$ 122.30 X Svc
33	1 pc	Rr fender LH	Dented Repair		\$ 682.00	\$ -
34	1 pc	Rr fender trim LH	Cracked Deformed		\$ 320.70	\$ 320.70 X Svc
35	6 pcs	Rr fender trim clip LH	Necessary	\$ 3.50	\$ 21.00	\$ 21.00 X Svc
36	1 pc	Bonnet	Dented Repair			(Refer labour no. 2 & 3)
37	1 pc	Frt support panel	Dented Repair			(Refer labour no. 2 & 3)
38	1 pc	Frt fender LH	Dented Repair			(Refer labour no. 2 & 3)
39	2 pcs	Frt apron panel R.L.	Dented Repair			(Refer labour no. 2 & 3)
40	1 pc	Rr fender LH	Dented Repair			(Refer labour no. 7, 9 & 10)
41	1 pc	Rr floor panel	Dented Repair			(Refer labour no. 7, 9 & 10)
42	1 pc	Rr chassis member LH	Dented Repair			(Refer labour no. 7, 9 & 10)
					\$ 7,367.30	\$ 6,131.70
Less Discount : 20%					\$ 1,473.46	20% \$ 1,226.34
List Parts Sub-Total :					\$ 5,893.84	\$ 4,905.36
1	1 pc	Rr windscreen sealant	Necessary	S N	\$ 50.00	\$ 40.00 /
2	1 pc	Reverse sensor	Dented Damaged	S N	\$ 250.00	\$ 220.00 200 /
Parts Total :					\$ 6,193.84	\$ 5,165.36

240



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Seres St #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@fho.com

Business Reg: 2014044340

Vehicle No.: SJW4464D

Report No.: PAS/TP/0161118

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check front electrical system and focus headlamp.	\$ 60.00	\$ 50.00 30/
2	To straighten, repair, realign on front affected area and replace damaged parts.	\$ 800.00	\$ 550.00 400/
3	To spray painting, blending on front affected and adjacent area.	\$ 1,200.00	\$ 1,000.00 400/
4	To check rear electrical wiring system.	\$ 50.00	\$ 30.00 /
5	To transfer tailgate component parts to new tailgate.	\$ 100.00	\$ 80.00 50/
6	To transfer rear windscreen to new tailgate.	\$ 120.00	\$ 120.00 /
7	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 150.00	\$ 120.00 X
8	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 60.00	\$ 50.00 20/
9	To straighten, repair, realign on rear affected area and replace damaged parts.	\$ 1,200.00	\$ 990.00 400/
10	To spray painting, blending on rear affected and adjacent area.	\$ 1,200.00	\$ 1,000.00 400/
11	To spray anti-rust coating on new and affected panels.	\$ 120.00	\$ 90.00 30/
P- 2881.36 M- 240 L- 1880 5001.36		L/S - 4001.08 = 4900 Labour Total : Total (Parts & Labour) : 7 repair days	\$ 5,060.00 \$ 11,253.84 \$ 4,080.00 \$ 9,245.36 1880

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is **\$ 7,390.00**

Under normal circumstances, the repairs should be completed within a reasonable period of **12 Working Days**. (Exclude waiting days of PRL, Sunday, Public Holiday and awaiting of shipment for spare parts)

132 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18020245/Eyf3e2-1		
50 RAFFLES PLACE		Date : 02-01-2020		
#05-01/06		Code : SMO		
SINGAPORE LAND TOWERSINGAPORE 048623				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 2329J	Veh. Inspected	SJW 4464D	
Policy No.	D18MTPCVE002784	Coverage (\$)	0.00	
Claim No.	CMTD1804876	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	30/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	GE61184575	Colour	RED	
Odometer	113848	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/55 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/55 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/55 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/11/2018	Inspection Date	09/11/2018	
Survey held at	ORION AUTOCLINIC-NO 25 KAKI BUKIT RD 4 #03-32			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 4464D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	HEADLAMP R/L @\$410.60	CRACKED / BROKEN	821.20	821.20
1	FRT GRILLE	CRACKED	178.20	178.20
1	FRT GRILLE EMBLEM	NECESSARY	22.90	22.90
1	FRT BUMPER	DENTED	523.50	523.50
6	FRT BUMPER CLIP @\$3.80	NECESSARY	22.80	22.80
2	FRT BUMPER RETAINER R/L @15.30	BROKEN / NECESSARY	30.60	30.60
2	FRT BUMPER BRACKET R/L @\$27.50	SERVICEABLE	55.00	-
1	FRT BUMPER REINFORCEMENT	SERVICEABLE	253.90	-
1	FRT BUMPER GRILLE	CRACKED	96.50	96.50
1	FRT SUPPORT PANEL	TO REPAIR SEE LABOUR	381.90	-
1	FRT FENDER RH	SERVICEABLE	375.60	-
1	WASHER TANK	SERVICEABLE	82.90	-
1	TAILGATE	DENTED / DISTORTED	736.60	736.60
1	RR NO. PLATE LAMPS GARNISH	REFIT	145.20	-
1	TAILGATE EMBLEM (LOGO)	NOT NECESSARY	26.50	-
1	TAILGATE EMBLEM (FIT)	NECESSARY	22.80	22.80
1	RR WINDSCREEN MOULDING	NECESSARY	120.40	120.40
1	RR WINDSCREEN A DAM RUBBER	NECESSARY	35.80	35.80
1	RR WINDSCREEN B DAM RUBBER	NECESSARY	31.00	31.00
2	RR WINDSCREEN D DAM RUBBER @\$4.70	NECESSARY	9.40	9.40
1	TAILGATE INNER TRIM	SERVICEABLE	265.20	-
10	TAILGATE INNER TRIM CLIP @\$3.20	SERVICEABLE	32.00	-
1	TAILGATE LOCK	SERVICEABLE	263.90	-
1	TAILGATE LOCK STRIKER	SERVICEABLE	26.70	-
1	TAILLAMP LH	CRACKED	296.20	296.20
1	TAILLAMP PANEL LH	SERVICEABLE	183.50	-
1	RR BUMPER	DENTED	573.20	573.20
6	RR BUMPER CLIP @\$3.80	NECESSARY	22.80	22.80

Report Ref No. CS3/SMO18020245/Eyf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RR BUMPER RETAINER R/L @\$28.90	CRACKED / NECESSARY	57.80	57.80
1	RR END PANEL	SERVICEABLE	386.50	-
1	RR END PANEL GARNISH	SERVICEABLE	140.80	-
1	RR WEATHERSTRIP	SERVICEABLE	122.30	-
1	RR FENDER LH	TO REPAIR SEE LABOUR	682.00	-
1	RR FENDER TRIM LH	SERVICEABLE	320.70	-
6	RR FENDER TRIM CLIP LH @\$3.50	SERVICEABLE	21.00	-
1	BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
2	FRT APRON PANEL R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR CHASSIS MEMBER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-1,473.46	-720.34
			5,893.84	2,881.36
	SPECIAL NETT ITEMS			
1	RR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REVERSE SENSOR (SN)	DENTED / DAMAGED	250.00	200.00
			300.00	240.00
	LABOUR			
	TO CHECK FRONT ELECTRICAL SYSTEM AND FOCUS HEADLAMP.		60.00	30.00
	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT SUPPORT PANEL, FRT FENDER LH AND FRT APRON PANEL R/L.		800.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING, BLENDING ON FRONT AFFECTED AND ADJACENT AREA.	NOT NECESSARY	1,200.00	400.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		50.00	30.00
	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE		100.00	50.00
	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE.		120.00	120.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS.		150.00	-
	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT.		60.00	20.00
	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR FENDER LH, BONNET, RR FLOOR PANEL AND RR CHASSIS MEMBER LH.		1,200.00	400.00
	TO SPRAY PAINTING, BLENDING ON REAR AFFECTED AND ADJACENT AREA.		1,200.00	400.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		120.00	30.00
			5,060.00	1,880.00
GRAND TOTAL			11,253.84	5,001.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS3/SMO18020245/Eyf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.