gringth: -			NMENT (Office)		1.1	
From (Person	i): Gerald poh	of	+DC	De	e/Time: 27/12/	1903.20
Estimated Co	Annual Control of the		Bill to:			
	STTP RES / OD RE	S/EVA/INV/M	V /·CS		Nie 77	
To Inspect V		GBE		Insured;	FF 9Y	-99 C
at Workshop		Ann 300	The second secon	Tel:	6455 0	747
of	BIK 176	I paily all	Vive # 01-1	7		
Policy No:		9	Claim No:	19/19/	20/400/0	122819
Sum Insured:			Excess:			
Sum Insured: Make of Veh (Client's Recor			Excess;	D.	A 26/2	2019
Make of Veh (Client's Recor	ત્રી)	RS		1	IOD Endotvement	2019
Make of Veh (Client's Recor CA / REV					IOD Endotvement	2019
Make of Veh (Client's Recor CA / REV	1)   REP.   REV 24 H   9:3901113   30   12   1	Person Contac	ted: Yuwn	1	IOD Endotvement	2019
Make of Veh (Client's Recor CA / REV Date/Time:	/ REP. / REV 24 H	Person Contac	ted: Yuwn	1	IOD Endotvement	2019
Make of Veh (Client's Recor CA / REV Date/Time:	REP. / REV 24 H 9:39am 301211 Action/Instruction	Person Contac Tolymoly (×	ted: Yuwn	1	IOD Endotvement	2019
Make of Veh (Client's Recor CA / REV Date/Time:	Action/Instruction  846 63215	Person Contac Tolymoly (×	ted: Yuwn	1	IOD Endotvement	2019

.

#### Nivitha (LKK Auto)

From:

GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent:

Friday, 27 December 2019 3:22 PM

To:

'assignments@lkkauto.com'

Cc:

MT\_Claim\_SG

Subject:

PRE-REPAIR SURVEY - BGE6321J [External Confidential]

Attachments:

27122019151753.pdf

### Lonpac External - Confidential

Our Ref

: 19/19/20/VC00/022819

Dear Nivitha,

Kindly see attached and proceed with the pre-repair survey.

Best Regards Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555


Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

# K. K. CHENG & CO

Advocates and Solicitors 101 Upper Cross Street #05-21 People's Park Centre Singapore 058357 Tel: 6227 1272 Fax: 6227 5563



Our Ref:

AJ/GBE 6321J

Your Ref.

YP 7799C

(Please quote our reference number when replying)

27 December 2019

# LONPAC INSURANCE BERHAD

Singapore

By fax only: 6296 3767

Attention: Motor Claims Department

Dear Sirs

NOTICE OF ACCIDENT

TS ENGINEERING WORKS PTE LTD Claimant:

Pre-nction Protocol for Non-injury Motor Accident Cases involving motor accident occurring on or after 1st April 2016 ["Protocol"]

We refer to your letter dated 27 December 2019

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 26 December 2019.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 26 December 2019.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the prerepair survey had been done by your appointed surveyor.

Fourthly, for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:-

Name of Workshop

Ann Joo Motor Ptc Ltd

Address

Blk 176 Sin Ming Drive #01-17

Sin Ming Autocare Singapore 575721

Telephone No

64550747

Contact person

Yiwen

Your faithfully

CHENG KIM KUAN cc Workshop (Ref: GBF 6321J)

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company		
Owner ID:	159K		
Vehicle No.:	GBE6321J		
Vehicle to be Exported:	No		
Intended Deregistration Date:	02 Jan 2020		
Vehicle Make:	TOYOTA		
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY		
Primary Colour:	Silver		
Manufacturing Year:	2015		
Engine No.:	1KD2570844		
Chassis No.:	KDY2318022499		
Maximum Power Output:	35		
Open Market Value:	\$32,419.00		
Original Registration Date:	29 Jan 2016		
First Registration Date:	29 Jan 2016		
Transfer Count:	2		
Actual ARF Paid:	\$1,621.00		
PARF Eligibility:	No		
PARF Eligibility Expiry Date:			
PARF Rebate Amount:	\$0.00		
COE Expiry Date:	28 Jan 2026		
COE Category:	C - Goods Vehicle & Bus		
COE Period(Years):	10		
PQP Paid:	\$4,840.00		
COE Rebate Amount:	\$2,937.00		
Total Rebate Amount:	\$2,937.00		

The information contained herein is correct as at 02 Jan 2020



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

#### PRE-REPAIR INSPECTION REPORT CS3/LPC19022861/Gtd3s2 LONPAC INSURANCE BHD 03-02-2020 Date: 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 Code: LPC2 Policy Particulars :- (THIRD PARTY CLAIM) GBE 6321J YP 7799C Veh. Inspected Insured Veh. 0.00 Coverage (\$) Policy No. 19/19/20/VC00/022819 0.00 Excess (\$) Claim No. 27/12/2019 GERALD POH Assign Date Assign From Vehicle Particulars & Condition 2982 TOYOTA DYNA 3.0 Make & Model C.C HIDDEN Year of Reg. 2016 Engine No. SILVER KDY2318022499 Colour Chassis No. Steering IN ORDER 169600 KM Odometer NIL IN ORDER Modification Brakes GOOD General **Conditions of Tyres** Make Balance Size GT RADIAL 5 mm 195 R15 R/H Front Tyre 195 R15 GT RADIAL 5 mm L/H Front Tyre MAXMILER 5 mm R/H Rear Tyre 155 R13 MAXMILER 5 mm 155 R13 L/H Rear Tyre **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. **General Information** 5. 02/01/2020 ( 05:30 PM ) Inspect Date / Time **Accident Date** 26/12/2019 ANN JOO MOTOR PL Survey held at BLK 176 SIN MING DRIVE #01-17 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS

Report Ref No. CS3/LPC19022861/Gtd3s2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A Automotive Assessor Tu

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.