

ASS. REC. BY:

REF: CS/FCI 19022864/K9 f3 112

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

MAY CHUA

of

FCI

Date/Time:

30.12.11 3:44 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMK 4226C

Insured:

SH 9260P

at Workshop m/s

EM Solution

Tel:

64560226

of

160 SM Ming Drive #03-18/19

Policy No:

Claim No:

D20000038 MP54

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 30.12.11 3:44 p.m

Person Contacted:

Bernard

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (V) Estimate

SMK 4226C - X

SH 9260P - AS/INCL 30/4005 / R/H 12

PCA - 31/12/2013

46/01/2013 11.55am revised to May Chua by email.

17/1 L1 Rep @ 13501 email & confirmed (Red \$ 3830.80, 74%)

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKM 4226 Yr Regn: 10/4/19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: 1 Honda Avaru S.C. 1591

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 138075 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM1HD841CMK4884340

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 24/12/19 D.O.I. 13/1/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 GIA not ready

RECEIVED 20 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format: 7P

Lump Sum / I.B.I. (\$) 1350

140
50
50
17
257



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D20000038MFSH

Date: 16th January 2020

Our Ref: CS/FCI19022864/Kqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMK 4226C

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/01/2020 at the premises of M/s E M SOLUTION and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 5,180.80</u>
Revised Estimate Amount	: <u>S\$ 420.00</u>
"Check" Items Amount	: <u>S\$ 1,754.40</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages
at the front o/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	27-12-2019	Our Ref No. D20000038MFSH
Accident Date	24-12-2019	Claim Type. Third Party
Insured Vehicle	SH9260P	Third Party Vehicle. SMK4226C
Survey Location	160, SIN MING DRIVE, #03-18/19, SIN MING AUTOCITY	
Contact Person.	BERNARD	
Contact No.	64560226/ 91018302	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	E M SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 16 January 2020 11:55 AM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'May Chua'
Subject: RE: SURVEY ASSESSMENT - D20000038MFSH/1
Attachments: CSFCI19022864Kqf3.pdf

Dear May,

Enclosed herewith preliminary advice of SMK 4226C.

"Wishing you a Happy and Prosperous Lunar New Year"

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 30 December 2019 3:45 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'May Chua' <maychua@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D20000038MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Monday, 30 December, 2019 3:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D20000038MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	011I
Vehicle Details	
Vehicle No.:	SMK4226C
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A) S
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	G4FGKU116213
Chassis No.:	KMHD841CMKU884340
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,582.00
Original Registration Date:	10 Apr 2019
First Registration Date:	10 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$14,582.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Apr 2029
PARF Rebate Amount:	\$10,936.00
Intended COE Rebate Details	
COE Expiry Date:	09 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,309.00
COE Rebate Amount:	\$24,288.00
Total Rebate Amount:	\$35,224.00

The information contained herein is correct as at 16 Jan 2020

OK

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

13.01.2020

Kong Chun Yuen

REPAIR ESTIMATE FOR HYUNDAI AVANTE - SMK 4226 C

1 pc	front bumper	522.30			my car	574.00	✓
1 pc	front bumper RH side retainer				sm	36.00	X
1 pc	front bumper RH fog lamp				sm	285.00	X
2 pcs	headlamps assy	1080.50	nls sux	1,298.00		2,596.00	c/s? my car
1 pc	RH front fender				sm	986.00	X
1 pc	RH front fender inner shield				sm	98.00	X
1 pc	RH front fender lamp				sm	76.00	X
						4,651.00	
				Less 20%		930.20	
						3,720.80	
1)	Check electrical wirings.					60.00	20%
2)	Repair damages and renew above parts					680.00	20%
3)	Spray paint on accident affected portions.					680.00	20%
4)	Tuff kote on affected portions.					40.00	X
						<u>\$ 5,180.80</u>	

Not Withheld

61/2y 81350k

LKK Auto Consultants hereby notify the Reparer of the following:

- To reserve unallocated repair amount
- To display damaged parts clearly reserved
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No direct modification to claims
- Supplementary items must be re-approved and is subject to final approval from Insurance Company

Acknowledged by Reparer:

Signature: _____

Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19022864/Kqf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-01-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 9260P	Veh. Inspected	SMK 4226C
	Policy No.		Coverage (\$)	0.00
	Claim No.	D20000038MFSH	Excess (\$)	0.00
	Assign From	MAY CHUA	Assign Date	30/12/2019
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI AVANTE S (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHD841CMKU884340	Colour	METALLIC SILVER
	Odometer	138075	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	FIRENZA	8 mm
	L/H Front Tyre	205/55 R16	FIRENZA	8 mm
	R/H Rear Tyre	205/55 R16	FIRENZA	8 mm
	L/H Rear Tyre	205/55 R16	FIRENZA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/12/2019	Inspection Date	13/01/2020
	Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 4226C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	MTG CRACKED	574.00	522.30
1	FRONT BUMPER RH SIDE RETAINER	SERVICEABLE	36.00	-
1	FRONT BUMPER RH FOG LAMP	SERVICEABLE	285.00	-
2	HEADLAMPS ASSY @\$1298.00	O/S MTG CRACKED / N/S SERVICEABLE	2,596.00	1,080.50
1	RH FRONT FENDER	TO REPAIR SEE LABOUR	986.00	-
1	RH FRONT FENDER INNER SHIELD	SERVICEABLE	98.00	-
1	RH FRONT FENDER LAMP	SERVICEABLE	76.00	-
	LESS 20% DISCOUNT		-930.20	-320.56
			3,720.80	1,282.24
	LABOUR			
	CHECK ELECTRICAL WIRINGS.		60.00	20.00
	REPAIR DAMAGES AND RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF RH FRONT FENDER.		680.00	200.00
	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS.		680.00	200.00
	TUFF KOTE ON AFFECTED PORTIONS.	NOT NECESSARY	40.00	-
			1,460.00	420.00
	GRAND TOTAL		5,180.80	1,702.24
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,350.00

Report Ref No. CS/FC119022864/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.