

2200292

ASS. REC. BY

REF: CS3/CTI 19022868/Gqd352

Special Instruction:

Surveyor: Chong

ASSIGNMENT (Office)

From (Person) Chong Boon Sen

of CTI

Date/Time: 30/12/19 @ 8:32am

Estimated Cost:

Bill to:

Minim

OP / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FX 9492G

Insured:

SKX 1117J

at Workshop m/s

Speedy Motor

Tel:

6481 5567

of

Blk 10 Ank Rd. Park 2A #05-21

Policy No:

DMPCSN30804019044

Claim No:

SNM19 D206127/SKX1117J/CBS Co2

Sum Insured:

Excess:

Make of Veh:

D.O.A

2/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:02am @ 30/12/19

Person Contacted:

Ms. Tan

Vehicle IN OUT

Date/Time

Action/Instruction Estimate (X)

SKX 1117J X

FX 9492G X

08/1/20


Submit PPS.

PRs *PRs* *CTi*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: *Speedy Motor*
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: **Yes** or No
 GIA / PR Seen: _____ Consistent?: **Yes** or No
 Est. Repairs: 3 days Res.: **Yes** or No
 Lum Sum: _____ % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *FX 9492 G* yr Regn: *14/04/04*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: *Piaggio Beverly* *200A*
 Colour: *Red* A/C: *Insured / Std / NI / NA*
 Sp. Reading: *-* T/Radio: *Insured / Std / NI / NA*

Eng/No: _____
 C/No: *ZAPM2820000047189*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *110/90-16 (IRC)*
 R: *140/70-16 (SHINKO)*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *IRC*

Front _____ Rear _____
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. _____ D.O.I. *30-12-19*

Survey held at W/S
 Des. of Damages: Rear / O/S / N/S / UIC / Rooftop or *5x40pm*

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>\$2000 - \$3000</i>

RECEIVED D 8 JAN 2020

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to? _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invt (\$)
 : (Asst) Eng (\$)

Survey Fee:	
Transportation:	
S + RS, SI	
Fines	
Other:	
TOTAL	

Report Format: *PRs*
 Emp. Sign / M.B. / C.K.

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 30 December 2019 8:32 AM
To: zul
Cc: 'assignments'
Subject: RE: OUR REF: SNM19D206127/SKX1117J/CBS & YOUR REF:JEQ/FX9492G/SM (zl)-PRS -Accident involving FX9492G & SKX1117J on 21.12.2019

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: zul [mailto:zul@juseq.com.sg]

Sent: Friday, December 27, 2019 4:59 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D206127/SKX1117J/CBS & YOUR REF:JEQ/FX9492G/SM (zl)-PRS -Accident involving FX9492G & SKX1117J on 21.12.2019

We refer to your email dated today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) **UNITED Appraisal And Management Pte Ltd**
- 2) **SK Auto Consultants**

- 3) Chartered Auto Assessors
- 4) LCW APPRAISER PTE LTD
- 5) Sincere Appraisal Services
- 6) Pal's Appraisal Pte Ltd
- 7) Mc-Coy Appraiser Pte Ltd
- 8) CM Automotive Consultancy

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

Speedy Motor Cycle Service Centre

Blk 10 Ang Mo Kio Industrial Park 2A

#05-21 Singapore 568047

Person In-Charge: Mr Lim Sam Hee at Tel: 6481 5567 / 9388 6867

Fax No. 6482 5567

*Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

Regards,

Zul

JusEquity Law Corporation

133 New Bridge Road #10-03

Chinatown Point

Singapore 059413

Tel: 6536 9339

Fax: 6536 5368

E-mail: zul@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Friday, 27 December, 2019 4:45 PM

To: zul@juseq.com.sg

Subject: RE: OUR REF: SNM19D206127/SKX1117J/CBS & YOUR REF:JEQ/FX9492G/SM (zl)-PRS -Accident involving FX9492G & SKX1117J on 21.12.2019

Without prejudice

Dear Sir,

LKK

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Friday, December 27, 2019 2:58 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; zul@juseq.com.sg

Subject: OUR REF: SNM19D206127/SKX1117J/CBS & YOUR REF:JEQ/FX9492G/SM (zl)-PRS -Accident involving FX9492G & SKX1117J on 21.12.2019

Dear Boon Sen,

Please conduct PRS- FX9492G soonest possible.

File with officer in charge –Chong Boon Sen –DID: 6389 6171

Dear Zul,

**** kindly quote our reference number when replying.*

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: zul [<mailto:zul@juseq.com.sg>]

Sent: Thursday, December 26, 2019 2:14 PM

To: Claims Dept of CTI

Subject: Accident involving FX9492G & SKX1117J on 21.12.2019 O ref: JEQ/FX9492G/SM (zl)

Dear Sir/Madam,

Please refer to our notice of accident.

Regards,

Zul

JusEquity Law Corporation

133 New Bridge Road #10-03

Chinatown Point

Singapore 059413

Tel: 6536 9339

Fax: 6536 5368

E-mail: zul@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2019 14:15
Date Of Accident	21/12/2019 12:45
Exact Location Of Accident	57 GRANGE ROAD GRAMERCY PARK CONDO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FX9492G
Insured/Policyholder	
Name Of Registered Owner	SAHLAN BIN SENAN
NRIC No	SXXXX009B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93657650
Alternative Phone No	Office-93657650
Vehicle Particulars	
Manufacturer	PIAGGIO
Model	BEVERLY-198CC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5064021213-06
Cover Note Number	
Driver	
Name of Driver	SAHLAN BIN SENAN
NRIC No	SXXXX009B
Date Of Birth	28/05/1966
Occupation	INDOOR
Date Of Driving Pass	15/08/1989
Driving Experience	30 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93657650

Fax Number	
Contact Number	OFFICE-93657650
E-Mail Address	NOEMAIL
Address	BLK 848 ADMIRALTY LINK #02-67
Postcode	750848
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	RIVER VALLEY NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT : T/20191221/2078

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX1117J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	90108526
Address	

1/8/2020

E-FILE

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: ESTHER LIM
 NRIC/FIN No.:


 CYS Automobile Services Pte Ltd
 38 Woodlands Industrial Park East, #07-17A
 Singapore 757700
 Tel: 6219 2098 (3lines) Fax: 6219 2096

57 GRANGE ROAD, GRAMERCY PARK CONDO

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


REFER to police Report:
T/20191221/2078.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: ESTHER LIM
 NRIC/FIN No.:

SHARDE StreetPlanForm_V01


**SINGAPORE
POLICE FORCE**


T/20191221/2078

1 of 3

Report No. T/20191221/2078

Police Station Of Origin:
River Valley NPP
4 Delta Avenue #01-02 SINGAPORE 161004
Tel No: 1800-2789999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/12/2019 14:59	Vide Report No.:	Station Diary No.: 41
Informant's Particulars		
Name of Informant: SAHLAN BIN SENAN	Address: APT BLK 484 ADMIRALTY LINK #02-67 SINGAPORE 750484	
ID Type / ID No.:	Contact No.:	Mobile: 93657650
NRIC NO / S1754009B	Home/Office:	
Nationality: SINGAPORE CITIZEN	Email:	
Sex: Male	Age: 53	Date of Birth: 28/05/1966
Race: Malay	Type of Informant: Rider	Institution / School Name:
Occupation: Building technician	Language:	
	Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury	Drink Drive: No	Date/Time of Accident: 21/12/2019 12:45	Type of Location: Straight Road
Location: Along Road 1 GRANGE ROAD			
57 Grange Road, near Gramercy park.			Road Speed Limit:
Weather: Clear	Road Surface: Wet	Traffic Volume:	
Traffic Flow: One Way	Traffic Control: Not Controlled	Anyone conveyed by ambulance: No	
Type of Collision: Between Moving Vehicles - Head To Rear			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FX9492G	Motorcycle	PIAGGIO	BEVERLY20 0 A	Silver	Seriously Damaged	0
SKX1117J	Car				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FX9492G	NTUC Income Insurance Co-Operative Limited	5064021213-06	10/10/2019	09/10/2020



**SINGAPORE
POLICE FORCE**



T/20191221/2078

2 of 3

Report No. T/20191221/2078

Police Station Of Origin:
River Valley NPP
4 Delta Avenue #01-02 SINGAPORE 161004
Tel No: 1800-2789999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	SAHLAN BIN SENAN	ID No.	S1754009B
Related Vehicle	NIL	Contact No.	93657650
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 21/12/2019 at around 1245hrs, I was riding at the above mentioned address. I was riding (FX9492G) on a slope exiting a carpark when I came to a hump.

Subsequently, I slowed down and a vehicle (SKX1117J) hit me from the rear. I did not fell and no one was injured. However, my motorbike suffered several damages and the car suffered some scratches on the bumper.

I am lodging this report for insurance claim purposes.



**SINGAPORE
POLICE FORCE**



T/20191221/2078

3 of 3

Report No. T/20191221/2078

Police Station Of Origin:
River Valley NPP
4 Delta Avenue #01-02 SINGAPORE 161004
Tel No: 1800-2789999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 1 CHAN JUN MIN, STANLEY 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 21/12/2019 14:59
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case: <div style="border: 1px solid black; padding: 2px; display: inline-block;">SN 069</div>
Authentication Stamp NP168	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	009B
Vehicle Details	
Vehicle No.:	FX9492G
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2020
Vehicle Make:	PIAGGIO
Vehicle Model:	BEVERLY200 A
Primary Colour:	Silver
Manufacturing Year:	2003
Engine No.:	M282M52119
Chassis No.:	ZAPM2820000047189
Maximum Power Output:	-
Open Market Value:	\$3,348.00
Original Registration Date:	14 Apr 2004
First Registration Date:	14 Apr 2004
Transfer Count:	9
Actual ARF Paid:	\$503.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Feb 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,952.00
COE Rebate Amount:	\$808.00
Total Rebate Amount:	\$808.00

The information contained herein is correct as at 08 Jan 2020

OK

> [Back to OneMotoring](#)

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
FX9492G

Make / Model
PIAGGIO / BEVERLY200 A

Vehicle Type :
P01 - Passenger Scooter

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
ZAPM2820000047189

Propellant :
Petrol

Engine No. :
M282M52119

Motor No. :
-

Engine Capacity :
198 cc

Power Rating :
-

Maximum Power Output :
-

Maximum Laden Weight :

-

Unladen Weight :

149 kg

Year Of Manufacture :

2003

Original Registration Date :

14 Apr 2004

Lifespan Expiry Date :

-

COE Category :

D - Motorcycle

PQP Paid :

\$1,952.00

COE Expiry Date :

29 Feb 2024

Road Tax Expiry Date :

09 Apr 2020

PARF Eligibility Expiry Date :

-

Inspection Due Date :

09 Oct 2020

Intended Transfer Date :

08 Jan 2020

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission:

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
---------------	---------

Print

OK →

Save as PDF

Copy as Text

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jan 2020		08 Jan 2020 11:49 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	SAHLAN BIN SENAN, ID: S17540098		
Vehicle Reg. No.:	FX9492G	Date of Loss:	21/12/2019 12:00 - :59 [188 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D206127C02	Policy/Cover Note No.:	DMPCSN30804019044
Vehicle Reg. No. (Insured):	SKX1117J	Policy No. (Claimant):	5064021213-06
		Excess:	S\$0.00
Repairer:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/01/2020]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FX9492G (SNM19D206127C02)
[SKX1117J]**

TP

SAHLAN BIN SENAN

Dec 21 2019 12:00PM

[-]

Speedy Motor Cycle Service Centre

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼
Video			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail Print
1	23/12/19 16:18	Video - Accident [Linked Accident Report Documents]	 Load MP4 <input type="checkbox"/>
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail Print
1	23/12/19 16:21	Accident Statement	 Load HTM <input type="checkbox"/>
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail Print
1	23/12/19 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>
2	23/12/19 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>
3	23/12/19 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>
4	23/12/19 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>
5	23/12/19 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>
6	23/12/19 16:17	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
2	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
3	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
4	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
5	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
6	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
7	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
8	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
9	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
10	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
11	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
12	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
13	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
14	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
15	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
16	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
17	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
18	08/01/20 11:57	General View	 Load JPG <input checked="" type="checkbox"/>
19	08/01/20 11:57	General View	Load JPG <input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
20	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/01/20 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/01/20 11:57	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
53	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
68	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	13/01/20 10:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
91	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
96	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
99	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
100	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
110	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
111	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
112	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
114	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
115	13/01/20 10:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
116	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
117	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
118	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
119	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
120	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
121	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
122	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
123	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
124	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
125	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
126	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
127	13/01/20 10:21	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	23/12/19 16:20	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	23/12/19 16:21	sketch 2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	23/12/19 16:21	P1 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	23/12/19 16:21	P2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	23/12/19 16:21	P3 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	23/12/19 16:18	Video - Accident	Load MP4	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	23/12/19 16:21	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	23/12/19 16:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	23/12/19 16:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	23/12/19 16:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	23/12/19 16:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	23/12/19 16:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	23/12/19 16:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	CYS Automobile Services Pte Ltd (Woodlands)	Thumbnail	Print
1	23/12/19 16:20	Sketch Plan	Load TIF	
2	23/12/19 16:21	sketch 2	Load JPG	<input checked="" type="checkbox"/>
3	23/12/19 16:21	P1	Load JPG	<input checked="" type="checkbox"/>
4	23/12/19 16:21	P2	Load JPG	<input checked="" type="checkbox"/>
5	23/12/19 16:21	P3	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19022868/GQD3S2
Date: 20/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30804019044
Claimant Vehicle No :	FX9492G	Insured Vehicle No :	SKX1117J
Date of Loss:	21/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D206127C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FX9492G	Engine No:	M282M52119
Make & Model:	PIAGGIO BEVERLY, 198cc	Chassis No:	ZAPM2820000047189
Reg. Date:	14/04/2004 (Man. Year: 2003)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/90-16	Rear Tyre Size:	140/70-16
Front Left Side:	IRC 4 mm	Rear Left Side:	Shinko 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/01/2020		
Date Inspected:	30/12/2019	Inspected At:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21 Singapore 568047
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jan 2020)

Parts: N/A PIAGGIO BEVERLY 198cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FX9492G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >