

ASSIGNMENT

ASS. REC. BY:

REP:

CS/SMO19022871/Dydt362

Special Instructions:

Surveyor: Brylin

ASSIGNMENT (Office)

From (Person): Cince Teo

of

SMO

Date/Time: 30/12/19 @ 8:58am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

AR 4104 B

Insured:

SLD 23619

at Workshop in/a

SG 98 Motor

Tel:

6452 4898

of

BLK 4001 # 01-21 AMK Ind. Park I

Policy No:

Claim No:

CMTD1906002 / AGC

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:06am @ 30/12/19

Person Contacted:

Rose

Vehicle IN/OUT


Date/Time	Action/Instruction
	<u>Estimate /</u>
	<u>SLD 23619 X</u>
	<u>AR 4104 B X</u>
<u>13/1</u>	<u>Sent Preli by email to Insurance</u>

7000 Desc: BY: Bryan

ref:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Item Sum: 20 % 3 Val.: Yes or No

CA / REV / REP: / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: AR 4104B Regn: Jan 2019
 Type: M/Car / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha GDR 155 CC: 155
 Colour: Black A/C: Insured / Std / NI / NA
 Sp Reading: H.A. T/Radio: Insured / Std / NI / NA
 Eng/No: G358E008812
 C/No: MH3SG4640KJ049099
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Ins / Jammed / Leaked / Burnt or
 Brake: Ins / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 110/80 R14
 R: 140/70 R14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Bridgestone
 Front: _____ Rear: _____
 R/Bal: 3 mm R/Bal: 3 mm
 L/Bal: _____ mm L/Bal: _____ mm
 D.O.A: 20/12/2019 D.O.I: 30/12/2019
 Survey held at: 3698 Manu
 Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or
Rnd y 0/8 Rnd y 1/8 Rnd.
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Empo SLD 2361 G.

MV 8.5K
 LIA 2.3K
 ML 6.2K

RECEIVED 3 JAN 2020

30/01/2020 Inspected 2/5 2600/- with 4 days repair (Red \$1768-70, 40%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 3

Date/Time, File Return to?

31/1/20 Typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

S + RS: \$1

Photos

Office

TOTAL

290

290

Report Formed:

Uniq Sum ME: \$2600f

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, January 13, 2020 1:27 PM
To: Ye, Yong Kang Melvin
Cc: 'Chan, Shu Hui Agnes'
Subject: RE: CMTD1906002/AGC - PRI(LKK)/ SLD2361G & AR4104B ACC ON 20.12.19
Attachments: AR4104B PRELI ADVISE.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle AR4104B
Date of survey : 30/12/2019
Number of days : 4 days
Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, December 30, 2019 11:09 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1906002/AGC - PRI(LKK)/ SLD2361G & AR4104B ACC ON 20.12.19

Dear Sir/Mdm,

Thank you for the assignment.

Wishes you a Merry Christmas & Happy New Year 2020



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref:

Date: 13 Jan 2020

Our Ref: CS/SMO19022871/Dyd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. AR4104B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/12/2019 at the premises of M/s SG98 MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,368.70</u>
Revised Estimate Amount	: S\$ <u>2,635.76</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the front n o/s front & front n n/s front.



Yours faithfully

Bryan Ang
Licensed Appraiser

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 30 December 2019 8:58 AM
To: Sg Motor; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Ye, Yong Kang Melvin; Chan, Shu Hui Agnes
Subject: CMTD1906002/AGC - PRI(LKK)/ SLD2361G & AR4104B ACC ON 20.12.19
Attachments: AR 4104B PRI.pdf

Our Reference : CMTD1906002/AGC
Your Reference: AR4104B

Without Prejudice
EMAIL ONLY

Date: 30.12.2019

OUR Email: motorsurvey@sompo.com.sg

Attention:
SG 98 MOTOR PTE LTD

Dear Rose,

ACCIDENT INVOLVING SLD2361G & AR4104B ON 20.12.2019

We refer to your email reply of 28/12/19.

We will appoint LKK Auto Consultants to conduct the survey.

Hi LKK Auto,

Please refer to the email below and make the arrangement to survey for **AR4104B** on a without prejudice basis and revert with your report upon completion of survey to my colleague, **Ms. Agnes**.

Thank You.

Our office will be closed on New Year's Eve (31/12/19) and New Year Day (01/01/20). Business will resume on 2nd January 2020.

We wish you a Happy New Year!

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



or



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sg Motor <sgmotor2000@yahoo.com.sg>

Sent: Saturday, December 28, 2019 1:05 PM

To: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: CMTDD1906002/AGC - PRI/ SLD2361G & AR4104B ACC ON 20.12.19

Hi all,

pls arrange LKK to survey the bike AR 4104B.

Thank You
rose

Regards

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park I

Singapore 569622

Tel: 64524898 Fax: 64526898

On Friday, 27 December 2019, 05:46:17 pm GMT+8, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference : CMTD1906002/AGC

Your Reference: AR4104B

Without Prejudice

EMAIL ONLY

Date: 27.12.2019

OUR Email: motorsurvey@sompo.com.sg

Attention:

SG 98 MOTOR PTE LTD

Dear Leena,

ACCIDENT INVOLVING SLD2361G & AR4104B ON 20.12.2019

We refer to your Notice of Accident dated 27.12.2019.

Please be informed that **Ms. Agnes Chan** the handler of this case who can be contacted at 63295 327/ agnes.chan@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.

We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sg Motor <sgmotor2000@yahoo.com.sg>

Sent: Friday, December 27, 2019 3:07 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>; Sg Motor <sg_motor_enterprise@yahoo.com.sg>

Subject: Plse arrange PRI on bike AR 4104B as per attached.

Attn: Motor Claims Dept

Plse arrange PRI on bike AR 4104B as per attached.

Thank You

Regards

Leena

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 27 December 2019

Sompo Insurance Singapore Pte Ltd
50 Raffles Place #05-01/06
Singapore Land Tower
SINGAPORE 048623

Attn: Motor Claims Dept
Fax No: 6221 3147 / 6226 6318
Email: motorsurvey@sompo.com.sg

Dear Sir/Mdm,

PRE-REPAIR INSPECTION

Accident between AR 4104B and SLD 2361G on 20 December 2019 at 1720 hrs
Location: Tampines Street 83

- 1 We hereby give you NOTICE that we are claiming against your insured motor Vehicle No : SLD 2361G damages to our client's Motor Vehicle No : AR 4104B
- 2 Plse provide a list of surveyors and their respective company name.
- 3 Kindly let us know if you wish to conduct a pre-repair inspection only after 11.30am at Blk 4001 Ang Mo Kio Industrial Park 1 #01-21 Singapore 569622. (Tel: 6452 4898, HP: 9171 1655)
- 4 If we do not hear from you within the next two (2) working days, we shall advise our clients to proceed with their own inspection and repairs.

Hope you are able to assist us on the above matter soonest.

Yours faithfully,


Rose
S9 Motor Trading Pte Ltd
Tel: 6452 4898

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2019 11:17
Date Of Accident	20/12/2019 17:20
Exact Location Of Accident	TAMPINES STREET 83
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	AR4104B
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD WAFIY BIN JAINI
NRIC No	SXXXX342H
Email Address	WAFIY_1991@ICLOUD.COM
Mobile Phone No	(LOCAL) +65-82015797
Alternative Phone No	OTHERS-82015797

Vehicle Particulars

Manufacturer	YAMAHA
Model	GDR155A (AEROX)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5107253337
Cover Note Number	

Driver

Name of Driver	MUHAMMAD WAFIY BIN JAINI
NRIC No	SXXXX342H
Date Of Birth	18/01/1991
Occupation	OUTDOOR
Date Of Driving Pass	01/01/2000
Driving Experience	19 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82015797
Fax Number	
Contact Number	OTHERS-82015797
Email Address	WAFIY_1991@ICLOUD.COM

Address	BLK 855 #04-254 TAMPINES STREET 83
Postcode	520855
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20191221/7009;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	SEAN
Phone Number	98362003
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD2361G
Vehicle Make/Model/Colour	TOYOTA / CAMRY 2.0 AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NEO WEE HOCK
NRIC/Passport Number	SXXXX394E
Contact Number	82004514

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD WAFIY BIN JAINI
Approximate Age	28
Injuries Sustain	
Injured person in which vehicle?	AR4104B
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 855 #04-254 TAMPINES STREET 83
Postcode	520855

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/12/19

@1500h.

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@vicom.com.sg


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:

Date & Time: 23/11/19

© 502415

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (YAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature

Signature: _____

NRIC/FIN No.



SINGAPORE POLICE FORCE



T/20191221/7009

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20191221/7009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/12/2019 12:06		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MUHAMMAD WAFIY BIN JAINI			Address: 855 TAMPINES STREET 83 #04-254 SINGAPORE 520855		
ID Type / ID No.: NRIC NO / S9101342H			Contact No.: Home/Office: Mobile: 82015797		
Nationality: SINGAPORE CITIZEN			Email: WAFIY_1991@HOTMAIL.COM		
Sex: Male	Age: 28	Date of Birth: 18/01/1991	Type of Informant: Rider		
Race: Javanese			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/12/2019 17:20	Type of Location: Car Park
Location: TAMPINES STREET 83				
Weather: Sunny		Road Surface: Dry		Road Speed Limit: 15 Km/h
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
AR4104B	Motorcycle	YAMAHA	Aerox	Black	Seriously Damaged	1
SLD2361G	Car	TOYOTA	Altis	Black	Slightly Damaged	3

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
AR4104B	NTUC Income Insurance Co-Operative Limited		24/01/2018	24/01/2020



SINGAPORE POLICE FORCE



T/20191221/7009

2 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191221/7009

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Rider			
Name	MUHAMMAD WAFIY BIN JAINI	ID No.	S9101342H
Related Vehicle	AR4104B (Motorcycle)	Contact No.	82015797
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	20/12/2019	Date Discharge	20/12/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Rider			
Name	MUHAMMAD WAFIY	ID No.	S9101342H
Related Vehicle	AR4104B (Motorcycle)	Contact No.	82015797
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/12/2019	Date Discharge	20/12/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	NEO WEE HOCK	ID No.	S7320394E
Related Vehicle	SLD2361G (Car)	Contact No.	82004514
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

The vehicle bearing registration number SLD2361G was turning into the carpark. Driver made a wide turn and he was not focussing on the road as i saw he was looking to the left side where the void deck was. I then sound my horn but he was driving at quiet a speed but i am not sure how fast was he travelling but he was not able to stop his vehicle in time and hit head on to my motor bike. There is a witness by the name of Sean contact no. 98362003 whom was on his way back from work and he saw the incident happened. He assisted me to pick up my bike and called for the ambulance. I would wish to add that the driver have a in car camera installed in his car.



**SINGAPORE
POLICE FORCE**



T/20191221/7009

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20191221/7009

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20191221/7009

4 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191221/7009

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
MUHAMMAD RIZWAN BIN KAMALUDIN
Contact No.: 65476185

Authentication Stamp

NP168

Signature Of Informant:

The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
21/12/2019 12:06

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	342H
Vehicle Details	
Vehicle No.:	AR4104B
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	YAMAHA
Vehicle Model:	GDR155A (AEROX)
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	G3J8E0088112
Chassis No.:	MH3SG4640KJ049099
Maximum Power Output:	-
Open Market Value:	\$2,379.00
Original Registration Date:	25 Jan 2019
First Registration Date:	25 Jan 2019
Transfer Count:	1
Actual ARF Paid:	\$357.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,889.00
COE Rebate Amount:	\$2,608.00
Total Rebate Amount:	\$2,608.00

The information contained herein is correct as at 13 Jan 2020

OK

TRANSACTION REPORT

27-DEC-2019 FRI 08:55

FOR:

SEND(M)

DATE	START	RECEIVER	TX TIME	PAGES	NOTE	M#	SENDER
27-DEC	08:55	68547648	11"	0	COM. E-16	910	

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 30 December 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : AR 4104B

Yamaha Aerox 155

ACCIDENT DATE: 20 December 2019

Description	Qty	Quotation \$
1 Handle Bar <i>cut</i>	1	165.00 ✓
2 Brake Lever <i>cut</i>	1	75.00 ✓
3 Balancer <i>cut o/s n/g n/w</i>	1 set	150.00 75.00 ✓
4 Front Panel <i>cut</i>	1	210.00 ✓
5 Head Lamp Assy <i>crack</i>	1	490.00 ✓
6 Front Mudguard <i>broken</i>	1	135.00 ✓
7 Front RH Side Panel <i>cut/broken</i>	1	155.00 ✓
8 Front RH Side Fairing <i>broken</i>	1	180.00 ✓
9 RH Fairing Top Guard <i>broken</i>	1	168.00 ✓
10 L/RH Leg Shield <i>n/w</i>	1 set	265.00 X
11 Lower Panel <i>cut</i>	1	165.00 ✓
12 Fork Tube <i>distorted</i>	1 set	480.00 X
13 Fork Under Bracket <i>dam</i>	1	135.00 X
14 Fork Guard LH <i>n/w</i>	1	125.00 X
15 Front RH Signal <i>n/w</i>	1	165.00 ✓
16 Front Side Garnish Panel <i>broken</i>	1	250.00 ✓
17 Compartment Centre <i>mostly broken</i>	1	185.00 ✓
18 Compartment Lid Cover <i>defunct</i>	1	125.00 ✓
19 Front Rim <i>n/w</i>	1	320.00 X

Sub-Total 3,943.00

Less 10% 394.30

Sub-Total 3,548.70

① Headlamp Assy *cut* \$105.

② Front mudguard - Rear pce. *broken* \$85.00

3183.00

1070 2864.70

VEHICLE NO : AR 4104B

Yamaha Aerox 155

Nett Items

- | | |
|--|----------------------------------|
| 1 Towing fee <i>NH</i> | 40.00 <i>X</i> |
| 2 Remove & replace new parts, align & etc | 260.00 <i>200/-</i> |
| 3 Remove & replace rim, fork assy, top up fork oil | <i>430.00</i> 120.00 <i>80/-</i> |
| 4 Putty & respray touch up paint work | 250.00 <i>150/-</i> |
| 5 Supply decal sticker - original | 150.00 <i>NH</i> |

Sub-Total 820.00

Nett Total 4,368.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

3294.70

4/s 2600/-

1599.70


S9 MOTOR TRADING PTE LTD

LG

30/12/2019 @ 1800m

N/A Auction

2/sun 4 days.



LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19022871/Dyd3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 03-02-2020	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLD 2361G	Veh. Inspected	AR 4104B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1906002/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	30/12/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA GDR155A	c.c	155
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3SG4640KJ049099	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/80 R14	BRIDGESTONE	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R14	BRIDGESTONE	3 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, O/S FRONT AND N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/12/2019	Inspection Date	30/12/2019
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AR 4104B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	165.00	165.00
1	BRAKE LEVER	CUT	75.00	75.00
1	SET BALANCER	O/C CUT / N/S NOT NECESSARY	150.00	75.00
1	FRONT PANEL	CUT	210.00	210.00
1	HEAD LAMP ASSY	CRACKED	490.00	490.00
1	FRONT MUDGUARD	BROKEN	135.00	135.00
1	FRONT RH SIDE PANEL	CUT / BROKEN	155.00	155.00
1	FRONT RH SIDE FAIRING	BROKEN	180.00	180.00
1	RH FAIRING TOP GUARD	BROKEN	168.00	168.00
1	SET L/RH LEG SHIELD	NOT NECESSARY	265.00	-
1	LOWER PANEL	CUT	165.00	165.00
1	SET FORK TUBE	DISTORTED	480.00	480.00
1	FORK UNDER BRACKET	DAMAGED	135.00	135.00
1	FORK GUARD LH	NOT NECESSARY	125.00	-
1	FRONT RH SIGNAL	NOT NECESSARY	165.00	-
1	FRONT SIDE GARNISH PANEL	BROKEN	250.00	250.00
1	COMPARTMENT CENTRE	MOUNTING BROKEN	185.00	185.00
1	COMPARTMENT LID COVER	DEFORMED	125.00	125.00
1	FRONT RIM	NOT NECESSARY	320.00	-
1	HEADLAMP STAY	BENT	105.00	105.00
1	FRONT MUDGUARD-REAR	BROKEN	85.00	85.00
	LESS 10% DISCOUNT		-413.30	-318.30
			3,719.70	2,864.70
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NEW PARTS, ALIGN & ETC.		260.00	200.00
	REMOVE & REPLACE RIM, FORK ASSY, TOP UP FORK OIL		120.00	80.00
	PUTTY & RESPRAY TOUCH UP PAINT WORK.		250.00	150.00

Report Ref No. CS/SMO19022871/Dyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY DECAL STICKER-ORIGINAL	NOT NECESSARY	150.00	-
			820.00	430.00
	GRAND TOTAL		4,539.70	3,294.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/SMO19022871/Dyd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.