

CC31 A1914022880/Asf302

ASSIGNMENT

minim

SLT6893C

2017 Nov

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

At Workshop no.

of

Insured

Policy No.

Claims No.

Sub Insured

Excess

\$0/-

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection



Est. or Market Value

IDAC Accident Report

Consistent? Yes or No

QIA / PR Seen

Consistent? Yes or No

Est. Repair

09/88

days

Res.

Yes or No

Ltho Sinc

%

3 Val

Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Type

SLT6893C

M.Cycle / Bus / Van / Lorry / Taxi / Private Motor

Truck / Trailer

Make

Audi A3.SB

999

Colour

Black

Insured / Std / N / NA

Sp. Reading

45894

13.4k Insured / Std / N / NA

Eng No

Chassis

WAUZZ28V8JA040904

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt

Brake: Good / Jammed / Leaked / Burnt

Modi: Nil / Rims / STD A/Rim or

Tyre Size

F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

06

mm

R/Bal

06

mm

L/Bal

06

mm

L/Bal

06

mm

D.O.A

D.O.A

30/12/19

Survey held at

Premium

Des. of Damage

Fr

Rear / OS / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

OD AIG

SLT 6893C - NA / EQ 119022760/24

DOR - 27/12/2019

30/12/19 @ 17:45 pm revised PA to AIG via minim

MV: 851K

PV: 44.7K

Nett: 40.3K

30/12/19 @ 17:20 pm mandate request received again to AIG via minim

Date / Time / File Photo



Prelim. Report



Final Report

Typ: 44
Cost / Time / File Photo

Days Of Repair:

9

Resurvey No. of Trip:

2

Survey / Fee

Examination

Site / Fee

Site / Fee

Site / Fee

Site / Fee

Site / Fee

200

11

211

\$16,089.84 r/p