

ASS. REC. BY:

REF: CS/MSG NO228851 AAT f306

Special Instructions:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

30.12.19 15:45 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 591M

Insured:

GBD 9687P

at Workshop m/s:

CAS Garage

Tel:

97916119

of

No 1 Kaki Bukit Ave 6 #02-22 Autobay

Policy No:

29131179MFC

Claim No:

609539

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31.8.2019

CA / REV / REP. / REV 24 HRS

31.12.2019

H.O.D. Endorsement:

Date/Time:

30.12.19 4.58 PM

Person Contacted:

Nichole

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 591M - X

GBD 9687P - X

02/1/20 @ 10.40am Informed Christina Wong, we are pending estimate from repairer.

Finalize lump sum \$2,800 (Red: 7512.32! 72%)

ASS. REC. BY:

REF: MSIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: 31.12.2019

Estimated Cost: \_\_\_\_\_

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 591Mat Workshop n/s CAS Garageof NO 1 Kaki Bukit Ave 6 #02-21 Autobay

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLA591M Yr Regn: 2016 FebType: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra cc 1591Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 45123 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH D H 41 C M 64 653714Gen. Cond: Good / Fair / Poor / BurntSteering: Insured / Jammed / Leaked / Burnt orBrake: Insured / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 31/12/19Survey held at CAS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or •


Front N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSIG

RECEIVED 11 MAR 2020

  
11/3/2020

Date/Time, File Pass in?

☐ : Prel. Report11/3 Typist☒ : Final Report

Date/Time, File Return in?

3

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Wheel and (\$)Survey Fee: 900

Transportation: \_\_\_\_\_

Photos \_\_\_\_\_

Others 11

TOTAL

911Rep. Format: TPLump Sum / F.B. / F: 2800

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Modified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2019		30 Dec 2019 15:45 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	COPE SYSTEM ENGINEERING SERVICE PRIVATE LIMITED, Co. Reg. No.: 52790300X		
Main Claimant:	NG YONG SHENG, ID: S7819313A		
Vehicle Reg. No.:	SLA591M	Date of Loss:	31/08/2019 21:00 - :59 [42 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 609539	Policy/Cover Note No.:	29131179MKC (Comprehensive) Coverage: 03/08/2019 - 02/08/2020
Vehicle Reg. No. (Insured):	GBD9687P	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/12/2019]		
Driver/Custodian (Insured):	CHAU THIAM SUNG (43 / Male), NRIC: S75602203, Tel: +6597892171 Email:		
Adj Asg. Remarks:	on WP. Liab: clear, use IHS, car in? Nicole 9791 6119/6484 2220		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Thursday, 2 January 2020 10:40 AM  
**To:** do-not-reply@merimen.com  
**Cc:** SUR  
**Subject:** TP VEHICLE SLA 591M (YOUR REF: 609539)

This mail is associated with :

**\*SLA591M (609539)**

**[GBD9687P]**

TP

NG YONG SHENG

Aug 31 2019 9:00PM

[COPE SYSTEM ENGINEERING SERVICE PRIVATE LIMITED]

Cas Garage Pte Ltd

Dear Christina,

Please be informed that we have inspected the vehicle SLA 591M on 31/12/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/09/2019 17:13
Date Of Accident	31/08/2019 21:30
Exact Location Of Accident	BLK 802 TAMPINES AVENUE 4
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA591M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG YONG SHENG
NRIC No	S7819313A
Email Address	RAIN2FALL4EVER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96722504
Alternative Phone No	OTHERS-96722504

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1725625
Cover Note Number	

### Driver

Name of Driver	NG YONG SHENG
NRIC No	S7819313A
Date Of Birth	09/07/1978
Occupation	INDOOR
Date Of Driving Pass	25/11/1998
Driving Experience	20 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96722504
Fax Number	
Contact Number	OTHERS-96722504
Email Address	RAIN2FALL4EVER@GMAIL.COM

Address	752 BEDOK RES ROAD #03-10
Postcode	479257
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PAX 1 GENDER: : MALE
Passenger 2	NAME: : PAX 2 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9687P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHAU THIAM SUNG
NRIC/Passport Number	S7560220J
Contact Number	97892171
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 2/9/19

1622 hr

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



## Sketch Plan #2

### SKETCH PLAN

Vehicle  
A - SLA 491 M.  
B - GBD9687P

Legend

Vehicle      Motorcycle

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I went off to buy food after parking my car.  
When I returned, my boys in the car told me the borry that  
just reversed into the lot on my left knocked into my car.  
The driver just got off the borry and I confronted him.  
Driver offered to pay me on the spot but I wanted to find out how much  
with it cost for the repair.  
\* attached is the video from my car cam and the hp recording of  
a conversation between the driver and me

### DECLARATION

I/We declare the foregoing particulars are true in every respect.  
Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against your policy must be made within the stipulated timeframe  
from the day of occurrence. Kindly check your policy for more details.

<p><u>Y/L</u></p> <p>Policyholder's Signature</p> <p>Date &amp; Time: 2/8/19 1622 hrs</p>	<p>Driver's Signature (If driver is not the policyholder)</p> <p>Date &amp; Time:</p>	<p><u>[Signature]</u></p> <p>Reporting Centre Personnel's Signature</p> <p>Name:</p> <p>NRIC/PRN No.:</p>
---	---	---

**CAS GARAGE PTE LTD**

(Reg No. 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

**VEHICLE REPAIR ESTIMATE**

Insurance Company: MSIG INSURANCE SINGAPORE PTE LTD

MOTOR CLAIMS DEPARTMENT

Address: NO 4 SHENTON WAY, #21-01, SGX CENTRE  
S(068807)

Telephone: 68277888

Fax: 68277800

Email: [motorsurvey@sg.msia.com](mailto:motorsurvey@sg.msia.com)

Make/ Model : HYUNDAI ELANTRA

Date: 30.12.2019

Chassis No : KMHDH41CMGU653714

Vehicle No: SLA591M

Date/Time of Accide 31.08.2019/2130

Date of Reg : 20.02.2016

**Materials Cost/ Spare Parts Cost****TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	FRONT BONNET <i>green</i>	1	\$ 1,443.60	\$ 1,443.60
2	FRONT BONNET INSULATOR	1	\$ 285.90	\$ 285.90
3	FRONT BUMPER <i>broken</i>	1	\$ 598.70	\$ 598.70
4	FRONT BUMPER SIDE RETAINERS LH <i>new</i>	1	\$ 65.80	\$ 65.80
5	FRONT BUMPER REINFORCEMENT <i>broken</i>	1	\$ 456.20	\$ 456.20
6	FRONT BUMPER SPONGE	1	\$ 256.80	\$ 256.80
7	FRONT BUMPER LOWER GRILLE <i>green</i>	1	\$ 245.60	\$ 245.60
9	FRONT BUMPER FOGLAMPS LH	1	\$ 265.90	\$ 265.90
10	FRONT BUMPER FOGLAMPS COVER LH <i>new</i>	1	\$ 95.80	\$ 95.80
11	FRONT ENGINE UNDERCOVER <i>new</i>	1	\$ 158.90	\$ 158.90
12	FRONT RADIATOR GRILLE <i>new</i>	1	\$ 205.60	\$ 205.60
13	FRONT RADIATOR GRILLE CHROME MOLDING <i>new</i>	1	\$ 125.60	\$ 125.60
14	FRONT RADIATOR GRILLE LOGO <i>new</i>	1	\$ 78.90	\$ 78.90
15	FRONT HEADLAMP LH <i>cracked</i>	1	\$ 1,850.10	\$ 1,850.10
16	FRONT HEADLAMPS LOWER BRACKET LH <i>new</i>	1	\$ 58.90	\$ 58.90
17	FRONT FENDER LH <i>Dented</i>	1	\$ 547.30	\$ 547.30
18	FRONT FENDER INNER COWLING LH <i>new</i>	1	\$ 85.90	\$ 85.90
19	SIDE MIRROR LH <i>green</i>	1	\$ 458.60	\$ 458.60
20	FRONT DOOR LH	1	\$ 1,456.30	\$ 1,456.30

**Total List Price Cost**

PARTS DISCOUNT 20%

**\$ 8,740.40****\$ 6,992.32**

314780

251824

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
3	FRONT SENSOR <i>new</i>	1 SET	\$ 250.00	\$ 250.00
4	FRONT FENDER INNER COWLING CLIPS SET <i>new</i>	2 SET	\$ 60.00	\$ 60.00
<b>Total Special Nett Items</b>				<b>\$ 390.00</b>

60

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 1,000.00
<i>450</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00
<i>400</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00
TO CONDUCT CHECK ON HEADLAMPS AND SETTLING	\$ 180.00
TO REMOVE/ REPLACE FRONT SENSORS AND DISTANCE SETTLING	\$ 150.00
<b>Total Others Cost</b>	<b>\$ 530.00</b>
<b>GRAND TOTAL</b>	
	<b>\$ 10,312.32</b>

930

## CAS GARAGE PTE LTD

UEN 201828067M  
1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,  
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan  
Direct Contact: +65 8782 7171  
Email: allan@casgarage.sg  
Fax: +65 6509 9501

Adrian Lj  
4/3 31/12/19

04 Days

total: 3508.24

4/5: 28K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

As acknowledged by Repairer

/EC

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2019		30 Dec 2019 15:45 <a href="#">Edit Adj Rpt</a>	<b>S\$2,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>








  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	COPE SYSTEM ENGINEERING SERVICE PRIVATE LIMITED, Co. Reg. No.: 52790300X								
Main Claimant:	NG YONG SHENG, ID: S7819313A								
Vehicle Reg. No.:	SLA591M	Date of Loss:	31/08/2019 21:00 - :59 [42 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 609539	Policy/Cover Note No.:	29131179MKC (Comprehensive) Coverage: 03/08/2019 - 02/08/2020						
Vehicle Reg. No. (Insured):	GBD9687P	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 5, #02-22 Autobay, 417883 Kaki Bukit - Tel: 9090 1222								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/01/2020]								
Driver/Custodian (Insured):	CHAU THIAM SUNG (43 / Male), NRIC: S7560220J, Tel: +6597892171 Email:								
Adj Asg. Remarks:	on WP. Liab: clear, use IHS, car in? Nicole 9791 6119/6484 2220								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLA591M (609539)  
 [GBD9687P]  
 TP  
 NG YONG SHENG  
 Aug 31 2019 9:00PM  
 [COPE SYSTEM ENGINEERING SERVICE PRIVATE LIMITED]  
 Cas Garage Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print	
1	29/10/19 16:26	Video - Accident Third party video					Load MP4			
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	11/03/20 14:28	Adjuster Immediate Advice					Load HTM			
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
2	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
3	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
4	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
5	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
6	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
7	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
8	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
9	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
10	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
11	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
12	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
13	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
14	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
15	09/03/20 18:25	General View					Load JPG		<input checked="" type="checkbox"/>	
16	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
17	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
18	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
19	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
20	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
21	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
22	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
23	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
24	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
25	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
26	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
27	09/03/20 18:25	Reinspection Photo					Load JPG		<input checked="" type="checkbox"/>	
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/10/19 16:23	<b>TPD SLA591M GIA REPORT</b> From: SC - Reg. No: GBD9687P, Claimant: COPE SYSTEM ENGINEERING SERVICE PRIVATE LIMITED	 Load PDF	
2	25/10/19 16:24	<b>TPD SLA591M - PRI</b>	 Load PDF	
3	17/12/19 16:45	<b>CRM - 1105809</b>	 Load PDF	
4	18/12/19 12:32	<b>Waiting for further evidence from TP workshop</b>	 Load PDF	
5	20/12/19 14:44	<b>CRM 1109532</b>	 Load PDF	
6	20/12/19 18:41	<b>agreed on direct settlement</b>	 Load PDF	
7	30/12/19 12:47	<b>EMAIL TO IHS</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div> <div></div> <div> ^ v </div> </div> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19022885/AGTF3

Date: 16/03/2020

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29131179MKC

Claimant Vehicle No : SLA591M

Insured Vehicle No : GBD9687P

Date of Loss: 31/08/2019

Nature of Claim: TP

Claim No: 609539

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLA591M

Make &amp; Model: HYUNDAI ELANTRA, 1.6 AD (A)

Engine No: G4FGFU060434

Reg. Date: 20/02/2016 (Man. Year: 2015)

Chassis No: KMHDH41CMGU653714

Colour: Grey

Odometer: 45123 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,382.32	2,578.24	4,804.08	65.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	930.00	2,000.00	68.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,312.32	3,508.24	6,804.08	65.98
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	10,312.32	2,800.00	7,512.32	72.85

## INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 31/12/2019 Inspected At:

Cas Garage Pte Ltd (HQ)

No. 1, Kaki Bukit Ave 6, #02-22 Autobay

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)
<b>Parts:</b> 143	HYUNDAI ELANTRA 1.6 AD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLA591M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	1,443.60 FL	*- FL
2	1		*FRONT BONNET INSULATOR	Not Necessary	285.90 FL	*- FL
3	1		*FRONT BUMPER	Torn	598.70 FL	*598.70 FL
4	1		*FRONT BUMPER SIDE RETAINERS LH	Necessary	65.80 FL	*65.80 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	456.20 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	256.80 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	245.60 FL	*- FL
8	1		*FRONT BUMPER FOGLAMPS LH	Not Necessary	265.90 FL	*- FL
9	1		*FRONT BUMPER FOGLAMPS COVER LH	Not Necessary	95.80 FL	*- FL
10	1		*FRONT ENGINE UNDERCOVER	Not Necessary	158.90 FL	*- FL
11	1		*FRONT RADIATOR GRILLE	Not Necessary	205.60 FL	*- FL
12	1		*FRONT RADIATOR GRILLE CHROME MOULDING	Not Necessary	125.60 FL	*- FL
13	1		*FRONT RADIATOR GRILLE LOGO	Not Necessary	78.90 FL	*- FL
14	1		*FRONT HEADLAMP LH	Cracked	1,850.10 FL	*1,850.10 FL
15	1		*FRONT HEADLAMPS LOWER BRACKET LH	Not Necessary	58.90 FL	*- FL
16	1		*FRONT FENDER LH	Dented	547.30 FL	*547.30 FL
17	1		*FRONT FENDER INNER COWLING LH	Torn	85.90 FL	*85.90 FL
18	1		*SIDE MIRROR LH	Not Necessary	458.60 FL	*- FL
19	1		*FRONT DOOR LH	Not Necessary	1,456.30 FL	*- FL
20	1		*SET FRONT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
21	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
22	1		*SET FRONT SENSOR	Not Necessary	250.00 FS	*- FS
23	2		*SET FRONT FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*30.00 FS
					<b>Sub Total (S\$)</b>	<b>9,130.40 3,207.80</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>1,748.08 629.56</b>
					<b>Total Parts (S\$)</b>	<b>7,382.32 2,578.24</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALIGNE ALL PARTS	New	1,000.00	450.00
2	TO RESPRAY AFFECTED AREAS	New	1,400.00	400.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	0.00
4	TO CONDUCT CHECK ON HEADLAMPS AND SETTLING	New	180.00	30.00
5	TO REMOVE/REPLACE FRONT SENSORS AND DISTANCE SETTLING	New	150.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>2,930.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >