

ASS. REC. BY:

REF: CS/SPF19022896/GV1392

Special Instruction:

Envelope: GQ

ASSIGNMENT (Office)

From (Person): Funkie Thay of SPF Date/Time: 30/12/19 @ 3:33pm

Estimated Cost: Bill to:

OD/FF/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 6598P

Insured: QX 1634L

at Workshop m/s

Kon Poole Sing

Tel: 67479560

of

61 Defu lane 12

Policy No:

Claim No:

AEMD / 105 / 009 / 2019 / 14

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 27/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4.53pm @ 30/12/19

Person Contacted:

Mr. Tan

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SLW 6598P: X		
21/1/2020	Submit \$ 1895, 2 days		

Do Not Finalise

INS. REC. BY:

Enl.

REF:

SPF

ASSIGNMENT

From:

Date: 13/1/2019

Veh No:

SLW6598P

Yr Regn:

27 Feb 2018

Estimated Cost:

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SLW 6598P

Make:

Citroen Picasso <sup>h2</sup> c.c. 1199

at Workshop m/s

Ken Hook Siney

Colour:

Red

A/C: Insured / Std / NI / NA

of

61 De Fu Lane 12

Sp. Reading:

41649

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

VF73AHNY THJ 860397

Claims No.

Gen. Cond:  Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering:  In order / Jammed / Leaked / Burnt or

(Client's Record)


Brake:  In order / Jammed / Leaked / Burnt or

Make of Veh:

2pm

Modi:  Nil / S/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F: 205/55 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA /  MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5 mm

R/Bal.

5 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5 mm

L/Bal.

5 mm

Est. Repairs:

2 days Res.: Yes or No

D.O.A.

D.O.I.

13-01-20

Lum Sum:

% 3 Val.: Yes or No

Survey held at

w/s

2pm

CA / REV / REP. / 24 HRS

1up

Des. of Damages:  Frt /  Rear / O/S / N/S / UIC / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$1800 - \$2000 (EST) upper range

RECEIVED 21 JAN 2020

Do Not Finalise

Date/Time, File Pass to?

: Preli. Report  
 : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 2

Survey Fee: 220

220

Date/Time, File Return to?

21/1 - typist

Add Fee:

: Site Insp (\$)   
 : Interview (\$)   
 : Tech. Invs (\$)   
 : Weekend (\$)

Transportation:

S + RS \$

Photos

Other:

TOTAL

Report Format:

TP

Lump Sum / R.E.I. (\$) :

1895 f

## Nivitha (LKK Auto)

---

**From:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Sent:** Monday, 30 December 2019 3:33 PM  
**To:** 'assignments'; Veron Chen (LKKAuto)  
**Cc:** Swee Kok KANG (SPF); Hafizul Farhan RAHMAT (SPF); Cui Fen ENG (SPF)  
**Subject:** RE : Pre-Repair Inspection for vehicle SLW6598P

Your reference: SLW 6598P

Our reference: aemd/105/009/2019/119

Veron,

Please conduct Pre-repair Inspection for vehicle SLW 6598P at the address below, please liaise with Mr Tan for appointment.

Kan Fook Sing Motor Worksop

No: 61 Defu Lane 12

Singapore 539147

Tel : 67479560

Person-in-charge: Mr Tan

Thanks.

Frankie Thay (Mr)  
1 Logistics Services Executive  
Logistics Support & Services Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 68428435



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/12/2019 10:46
Date Of Accident	27/12/2019 09:15
Exact Location Of Accident	SLIP ROAD OF BARTLEY RD TO AIRPORT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW6598P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ZHANG ZHEWEI DYAN
NRIC No	SXXXX160Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91905097
Alternative Phone No	OTHERS-91905097
<b>Vehicle Particulars</b>	
Manufacturer	CITROEN
Model	GC4 PICASSO 1.2 PURETECH 130 EAT6
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800018972-01
Cover Note Number	
<b>Driver</b>	
Name of Driver	LUO YANYU
NRIC No	SXXXX334E
Date Of Birth	08/02/1981
Occupation	INDOOR
Date Of Driving Pass	13/08/2005
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81265251
Fax Number	
Contact Number	
EEmail Address	YANYUL@GMAIL.COM

Address APT BLK 315A ANG MO KIO ST 31 #25-337 (S) 562315  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name ANG MO KIO POLICE DIVISIONAL HQ (F DIVISION)  
 Police Station Address ROAD: 51 ANG MO KIO AVENUE 9 , POSTCODE: 569929 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-2180000 - FAX NO: 64814246  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

refer with attach.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number QX1634L  
 Vehicle Make/Model/Colour HYUNDAI  
 Details Of Properties  
 Vehicle Category GOVERNMENT  
 Name of Driver TARA BAHADUR SARTUNGE  
 NRIC/Passport Number GXXXX093U  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

)

)

SKETCH PLAN

A: SLW 6598P

B: QX 1634L

airport rd ←



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer with anttech police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]* 27/12/19  
11.15am

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







**SINGAPORE  
POLICE FORCE**



F/20191227/7015

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20191227/7015

Subjects Involved			
Victim			
Person Name	LUO YANYU		
ID Type	NRIC NO	ID No	S8104334E
Gender	Male	Age	38
Race	Chinese	Language	English
Occupation	SAF REGULAR	Address Type	
Address	APT BLK 315A ANG MO KIO STREET 31 #25-337 SINGAPORE 562315	Mobile No	81265251
Is Informant A Victim?	Yes		
Person Name	LUO YANYU (Informant)		

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In-Charge Of Case:

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 27/12/2019 11:07
Classification Of Case:

Authentication Stamp

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	160Z
Vehicle No.:	SLW6598P
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	CITROEN
Vehicle Model:	GC4 PICASSO 1.2 PURETECH 130 EAT6
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	10XTA40847137
Chassis No.:	VF73AHNYTHJ860397
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,954.00
Original Registration Date:	27 Feb 2018
First Registration Date:	27 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$24,136.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2028
PARF Rebate Amount:	\$18,102.00
COE Expiry Date:	26 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,810.00
COE Rebate Amount:	\$29,892.00
<b>Total Rebate Amount:</b>	<b>\$47,994.00</b>

The information contained herein is correct as at 13 Jan 2020

OK



# 簡福星噴多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147  
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428  
 E-mail: ryan@kanfs.net/ patricia@kanfs.net  
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883  
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

SPF ACCIDENTS CLAIMS SECTION

DATE : 27-12-2019

AUTOMOTIVE ENGG & MGNT DIV  
 POLICE LOGISTICS DEPARTMENT  
 NO: 1 MOUNT PLEASANT ROAD  
 NEBBERS RD POLICE ACADEMY #02-12 SINGAPORE 298333  
 ACCIDENT DATE : 27-12-2019 09:15  
 THIRD PARTY REF. : QX1634L

ATTN: SPF ACCIDENTS CLAIMS SECTION

ESTIMATE COST OF REPAIR TO VEICLE SLW6598P CITROEN GC4 PICASSO 1.2 PURETECH

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BUMPER / C/A	980.00
2	10	REAR BUMPER CLIP @\$5.00 / MCL.	50.00
			<hr/>
			1,030.00
			<hr/>
			LESS 10 %
			<hr/>
			103.00
			<hr/>
			TOTAL ( A )
			<hr/>
			927.00

### LABOUR CHARGES

1	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	480.00	200
2	1	SPRAYPAINTING CHARGES	480.00	300
			<hr/>	
			TOTAL ( D )	960.00
			<hr/>	
			ESTIMATE TOTAL	3355
			<hr/>	
				1,887.00

*[Signature]*  
 14/1/2020

2 Days.

P/P ~~before~~ repair  
 before paint  
 After repair photos.

Guo Qiang - 82880282

13/01/2020.

1895

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



# 簡福星嘍王廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147  
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428  
 E-mail: ryan@kanfs.net/ patricia@kanfs.net  
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883  
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

SPF ACCIDENTS CLAIMS SECTION

DATE : 13-01-2020

AUTOMOTIVE ENGG & MGNT DIV  
 POLICE LOGISTICS DEPARTMENT  
 NO:1 MOUNT PLEASANT ROAD  
 BECKERLE RD POLICE ACADEMY #02-12 SINGAPORE 298333  
 ACCIDENT DATE : 27-12-2019 09:15  
 THIRD PARTY REF. : QX1634L

ATTN: SPF ACCIDENTS CLAIMS SECTION

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SLW6598P CITROEN GC4 PICASSO 1.2 PURETECH

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BUMPER REINFORCEMENT / <i>bt</i>	350.00 —
1	REAR BUMPER REINFORCEMENT PLASTIC / <i>ll</i>	170.00 —
		<hr/> 520.00
	LESS 10 %	52.00
	TOTAL (A)	<hr/> 468.00
	SUPPLEMENTARY TOTAL	<hr/> 468.00



# 簡福星摩呀工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147  
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428  
 E-mail: ryan@kanfs.net/ patricia@kanfs.net  
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883  
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

SPF ACCIDENTS CLAIMS SECTION

DATE : 27-12-2019

AUTOMOTIVE ENGG & MGNT DIV  
 POLICE LOGISTICS DEPARTMENT  
 NO:1 MOUNT PLEASANT ROAD  
 VEHICLE REG POLICE SLD6598P #02-12 SINGAPORE 298333  
 ACCIDENT DATE : 27-12-2019 09:15  
 THIRD PARTY REF. : QX1634L

ATTN: SPF ACCIDENTS CLAIMS SECTION

ESTIMATE COST OF REPAIR TO VEICLE SLW6598P CITROEN GC4 PICASSO 1.2 PURETECH

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1 REAR BUMPER / OA	980.00 -
2	10 REAR BUMPER CLIP@5.00 / MCL	50.00 -
		<hr/>
		1,030.00
		<hr/>
LESS 10 %		103.00
		<hr/>
TOTAL (A)		927.00

### LABOUR CHARGES

1	1 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	480.00 200-
2	1 SPRAYPAINTING CHARGES	480.00 300-
		<hr/>
TOTAL (D)		960.00
		<hr/>
ESTIMATE TOTAL		1,887.00

2 Days.  
 Lump sum repair.  
 After repair photos.  
 Guo Qiang - 82880282  
 13/01/2020.

简福星摩哆工廠  
 KAN FOOK SING MOTOR WORKSHOP  
 61 DEFU LANE 12  
 SINGAPORE 539147  
 TEL: 67479560, 68582126, 68584361  
 FAX: 67481006, 62818428

SPF ACCIDENTS CLAIMS SECTION

AUTOMOTIVE ENGG & MGNT DIV  
 POLICE LOGISTICS DEPARTMENT

NO:1 MOUNT PLEASANT ROAD

VEHICLE NO: POLICE ACCEP#02-12 SINGAPORE 298333

ACCIDENT DATE : 27-12-2019 09:15

THIRD PARTY REF. : QX1634L

INVOICE NO : TEST

DATE : 17-01-2020

ATTN: SPF ACCIDENTS CLAIMS SECTION

INVOICE COST OF REPAIRS TO VEHICLE SLW6598P CITROEN GC4 PICASSO 1.2 PURETECH

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BUMPER	980.00
10	REAR BUMPER CLIP @\$5.00	50.00
1	REAR BUMPER REINFORCEMENT	350.00
1	REAR BUMPER REINFORCEMENT PLASTIC	170.00
		<u>1,550.00</u>
	LESS 10 %	155.00
	TOTAL ( A )	<u>1,395.00</u>

LABOUR CHARGES

1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	200.00
1	SPRAYPAINTING CHARGES	300.00
	TOTAL ( D )	<u>500.00</u>
	TOTAL REPAIR COST :	<u>1,895.00</u>
	G S T % :	132.65
	INVOICE AMOUNT :	<u>2,027.65</u>

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 21 January 2020 11:20 AM  
**To:** alicechau@kanfs.net; Guo Qiang (LKKAuto); SUR  
**Subject:** RE: SLW6598P (TP) - Finalization & Photo (1-15)  
**Attachments:** MARKING.pdf

Dear Alice,

WITHOUT PREJUDICE

For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** alicechau <alichechau@kanfs.net>  
**Sent:** Monday, 20 January 2020 12:58 PM  
**To:** Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** SLW6598P (TP) - Finalization & Photo (1-15)

Dear Sir,

With reference to the mentioned vehicle, kindly confirm and finalise.

Thank you.

Regards,  
Alice  
Kan Fook Sing Motor Workshop  
Tel:6747 9560  
Fax:6748 1006



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF19022896/Gvd3s2

ACCIDENT CLAIMS SECTION (SPORE POLICE  
FORCE) POLICE LOGISTICS BASE (PLB) 1  
HEMMANT ROAD SINGAPORE 438675

Date : 24-01-2020



ATTN: FRANKIE THAY

Code : SPF

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 1634L	Veh. Inspected	SLW 6598P
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/119	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	30/12/2019

## 2. Vehicle Particulars & Condition

Make & Model	CITROEN PICASSO 1.2	c.c	1199
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VF73AHNYTHJ860397	Colour	RED
Odometer	41649	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R17	MICHELIN	5 mm
L/H Front Tyre	205/55 R17	MICHELIN	5 mm
R/H Rear Tyre	205/55 R17	MICHELIN	5 mm
L/H Rear Tyre	205/55 R17	MICHELIN	5 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	27/12/2019	Inspection Date	13/01/2020
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 6598P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	CRACKED	980.00	980.00
10	REAR BUMPER CLIP @ \$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	BENT	350.00	350.00
1	REAR BUMPER REINFORCEMENT PLASTIC (ADDITIONAL)	DEFORMED	170.00	170.00
	LESS 10% DISCOUNT		-155.00	-155.00
			1,395.00	1,395.00
<b>LABOUR</b>				
	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS.		480.00	200.00
	SPRAY PAINTING CHARGES.		480.00	300.00
			960.00	500.00
<b>GRAND TOTAL</b>			<b>2,355.00</b>	<b>1,895.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,895.00</b>

Report Ref No. CS/SPF19022896/Gvd3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 - \$2,000.00 (EST)

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.