

ASS. REC. BY:

REF: CS/ C1119022907/ Hs f30k Special Instruction:

SURVIVOR: Hock Ann ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping of CTI Date/Time: 30.12.19 17.09pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SGU 7095L Insured: PC 1057A

at Workshop m/s FI Garage Tel: 96311088

of 2 Kaki Bukit Bkt 4 #03-88

Policy No: DMB JSN 30845219000 Claim No: SVM1912206143202

Sum Insured: Excess:

Make of Veh: D.O.A 03.12.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS mp"

Date/Time: 31.12.2019 9.03am Person Contacted: Ah Hao H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGU 7095L - NA/IN (V621797/h4) DOA - 03/12/2019
	PC 1057A - VA/TIN (19021793/h4) DOA - 03/12/2019
	SGU 7095L Finalised amt 4/5-p car \$2200 DOA 3 days
	Agree by workshop invoice from (Ah Hao)
	(\$ 922.21 Red - 30%)

Shin

Surveyor

REF: CT1

ASSIGNMENT

2/000

Date: 13-Jan-2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGU 7095L

at Workshop n/s: FI Garage

at 8 kaki Bukit Ave 4 #03-33 premier

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res: Yes or No

Lump Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

emp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGU 7095L

Vr Regt:

23/105/2017

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

T. Vios

cc 1497

Colour:

Black

A/C Insured / Std / NI / NA

Sp. Reading:

342.210 km

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053 HY 730500 1407

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rip / ☐ STD A/Rim or

Tyre Size:

F:

185 / 60 / R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal:

37 mm

R/Bal:

47 mm

L/Bal:

3 mm

L/Bal:

4 mm

D.O.A:

3/12/19

D.O.A:

13/1/20

Survey held at

FI Garage

Des. of Damages: Frt / Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* Shortage Police Report &

* not to hand charges unless (same) officer

* SGU 7095L

no driver seen
his return.

RECEIVED 30 JAN 2020

MV - 12000

PV - 11931

NV - 5000

30/1/2020

A4 400 → 9631/008

Date/Time, File Pass to?

30/01/20

Type

Type

Date/Time, File Return to?



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

770

Transportation:

S + RS, SI

Photo:

Others:

TOTAL

770

Report Format:

Lump Sum / I.B.I: (\$) 2,200/- 45

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Dec 2019		30 Dec 2019 17:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	TOP NOTCH SERVICES			
Vehicle Reg. No.:	SGU7095L	Date of Loss:	03/12/2019 21:00 - :59	
Claim Type:	TP / SNM19D206143C02	Policy/Cover Note No.:	DMB15N30845719000	
Vehicle Reg. No. (Insured):	PC1057A	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	F1 Garage (HQ) 8 KAKI BUKIT AVENUE 4, #03-33, PREMIER@KAKI BUKIT, 415875 Kaki Bukit - Tel: 96311088			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/01/2020]			
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 30 December 2019 4:56 PM
To: alfred_ng@juseq.com.sg
Cc: Admin A; 'assignments'
Subject: RE: OUR REF: SNM19D206143/PC1057A/IRENE & YOUR REF: JEQ/191277/1219/FI - SGU7095L -PRS -NOTICE OF ACCIDENT

Dear Sir/Mdm (LKK),

We refer to the above matter .

Please get your surveyor to liaise with F1 Garage to conduct survey.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: alfred_ng@juseq.com.sg [mailto:alfred_ng@juseq.com.sg]
Sent: Monday, December 30, 2019 4:54 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D206143/PC1057A/IRENE & YOUR REF: JEQ/191277/1219/FI -SGU7095L -PRS -NOTICE OF ACCIDENT

Dear Irene,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

Mr. Marcus Chua

Please be informed that our client's vehicle is available for inspection at the under stated workshop:-

F1 GARAGE
8 Kaki Bukit Ave 4
#03-33 Premier@Kaki
Singapore 415875
Contact person: Ah Hao

Mobile : 9631-1088.

With Regards

Alfred Ng
Executive
Legal Division
On behalf of Mr. Michael Yap
M/s JusEquity Law Corporation
No. 133 New Bridge Road
Chinatown Point
#10-03 Singapore 059413
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

From: Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]

Sent: Monday, December 30, 2019 4:12 PM

To: alfred_ng@juseq.com.sg; juseq@singnet.com.sg

Subject: RE: OUR REF: SNM19D206143/PC1057A/IRENE & YOUR REF: JEQ/191277/1219/FI -SGU7095L -PRS -NOTICE OF ACCIDENT

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING

Kelvin Ang

SEE CHEW SENG

MOHD FADHILAH BIN OSMAN

XING QUO QIANG

KENNETH KONG

SIMON HO

CHUA WEIJIE

MARCUS CHUA

HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Irene Tay

Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, December 30, 2019 3:54 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>; alfred_ng@juseq.com.sg; juseq@singnet.com.sg
Subject: OUR REF: SNM19D206143/PC1057A/IRENE & YOUR REF: JEQ/191277/1219/FI -SGU7095L -PRS -NOTICE OF ACCIDENT

Dear Irene,

Please conduct PRS –SGU7095L –soonest possible and our Insured has not filed SAS Report.

File with officer in charge –Irene Tay –DID: 6389 6192.

Dear Alfred,

*** kindly quote our reference number when replying ***

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6116
Fax (65) 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: alfred_ng@juseq.com.sg [mailto:alfred_ng@juseq.com.sg]
Sent: Monday, 30 December, 2019 11:27 AM
To: Claims Dept of CTI
Subject: NOTICE OF ACCIDENT

Your ref: PC1057A
Our ref: JEQ/191277/1219/F1

Dear Sirs,

Kindly refer to our attachment

With Regards

Alfred Ng

Executive

Legal Division

On behalf of Mr. Michael Yap

M/s JusEquity Law Corporation

No. 133 New Bridge Road

Chinatown Point

#10-03 Singapore 059413

Tel : 6536 9339

Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.



8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT SINGAPORE 415875
Co.Reg No. 201905076M TEL: 96311088
GST Reg. No. 201905076M E-MAIL: sales@F1GarageSG.com

Attendance Form

Car Plate: SGU7095L
Accident Date: 3/12/19
Other Party Vehicle: PC1057A

1st

Surveyor Name: H. ANN
Surveyor Company: LKL
Contact: 85311883 / 67418454 - 08pm
Signature: [Signature]
Date of Survey: 13/1/20

2nd

Surveyor Name: H. ANN
Surveyor Company: LKL
Contact: 85311883 / 67418454
Signature: [Signature]
Date of Survey: 14/1/20 3.50pm

3rd

Surveyor Name: _____
Surveyor Company: _____
Contact: _____
Signature: _____
Date of Survey: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Business
Owner ID:	322B

Vehicle Details

Vehicle No.:	SGU7095L
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	1NZX545299
Chassis No.:	MR053HY9305001407
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,878.00
Original Registration Date:	23 May 2007
First Registration Date:	23 May 2007
Transfer Count:	1
Actual ARF Paid:	\$14,166.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	22 May 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,333.00
COE Rebate Amount:	\$11,931.00
Total Rebate Amount:	\$11,931.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Jan 2020

OK



Toyota Vios 1.5A E (COE till 05/2022)

Price Range

Depreciation

Year Reg

Vehicle Type

Home » Used Cars » Boeki Auto Pte Ltd » Toyota Vios 1.5A E (COE till 05/2022)

Toyota Vios 1.5A E (COE till 05/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



BOEKI AUTO PTE LTD



Price \$16,800

Depreciation \$7,060 /yr

Reg Date 15-Jun-2007
(2yrs 4mths 17days COE left)

Mileage N.A.

Manufactured 2007

Road Tax \$889 /yr

Transmission Auto

Dereg Value \$12,049 as of today (change)

OMV \$12,607

COE \$25,333

ARF \$13,868

Engine Cap 1,497 cc

Power 80.0 kW (107 bhp)

Curb Weight 1,095 kg

No. of Owners 1

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Toyota Vios (2007-2013)

Description

Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more




Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location

Price Chart



Shortlist

Compare

Add to

Report Error

More Actions

Seller Information

Boeki Auto Pte Ltd

37 vehicles for sale. 65 sold in past 3 mths

49 Sungei Kadut Loop

Tel: 67555005

Search cars nearby

Boeki

82180500

Posted on: 1

ated on: 27-Dec-2019

Compare

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Thursday, 23 January, 2020 8:31 AM
To: Lai ZhengHao
Cc: Shirley Hiew (LKK Auto)
Subject: RE: FINALIZED SGU 7095L

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear hao ,

Good day, o.k will be process base on finalized total amount COR \$ 2200 L/sump REPAIR and DOR 3 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need send direct (china taiping insurance) claim dept .

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lai ZhengHao [mailto:lai@f1tpt.com]
Sent: Wednesday, 22 January, 2020 4:38 PM
To: Hock Ann (LKK Auto)
Subject: Re: FINALIZED SGU 7095L

Hi, we accept this offer.
Thanks

On Wed, 22 Jan 2020 at 4:20 PM, Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear hao ,

Good day , Kindly attached refer SGU 7095L finalized updated calculate adjustment on 22.1.2020

COR - \$ 2200

DOR – 3 DAYS

Please refer adjustment updated total L/SUMP amount \$ 2200 if agree total L/SUMP amount and repair days, will be to close case.

Please update soon asap.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, [Ubi Avenue 1, #02-25](#) | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and the copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated above.

ACCIDENT STATEMENT

Date Of Report 11/12/2019 10:37
 Date Of Accident 03/12/2019 21:40
 Exact Location Of Accident BLK 302 UBI AVE 1 OPEN CARPARK
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGU7095L
 Insured/Policyholder
 Name Of Registered Owner TOP NOTCH SERVICES
 Co. Reg No 53330322B
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-84884426

Vehicle Particulars

Manufacturer TOYOTA
 Model VIOS
 Exact Purpose for which vehicle was being used at time of accident PARKED

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken. THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5111689210
 Cover Note Number

Driver

Name of Driver LIONG SIN YEONG
 NRIC No S8672597E
 Date Of Birth 04/09/1988
 Occupation INDOOR
 Date Of Driving Pass 12/06/2009
 Driving Experience 10 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-94884426
 Fax Number
 Contact Number NOEMAIL
 EMail Address

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident as given on this form provided.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy benefits**.
4. The issue and withdrawal of this form by insurance companies are an admission of policy liability on the part of the insurance companies.
5. Any claim reporting may be referred to the Police for investigation.
6. This report will be forwarded to the insurers at the GIC Claims Management Centre established by the General Insurance Association of Singapore (GIA) for processing and that copies of this report will for a fee be made available upon application to the insurer's claims.
7. By the completion of this report to the insurers, you hereby consent to the processing of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)

(understand, acknowledge, agree and consent that)

- (a) My insurer, its authorised agent the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers) who have insured vehicles involved in this accident and/or individuals referred to as the "Insured" (the insurers' lawyers/law firms, the Ministry, Authorities of Singapore and any relevant government agency/authority such as the police, for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claim;
 - (iii) processing and/or dealing with my instructions or regarding claims enquiries to me;
 - (iv) processing my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as the externalisation of envelopes that packages apply;
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes".
- (b) all insurers who have insured vehicles involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may then be disclosed to any of the insurers and/or GIA to their third party service providers or approximating their lawyers/law firms, which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that would be evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
NIC/FIN No.

address BLK 280D BUKIT BATOK ST 25 #06-50
 postcode 653288
 Was driver an employee of the Insured's Company NO
 If no, Relationship of the Driver with the Insured OWNER
 vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station.
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD 10 UBI AVENUE 3, POSTCODE: 408565, COUNTRY SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT T/20191203/2181

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC1057A
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

Accident Sketch Plan

SKETCH PLAN

DIR 2-2 For Reg 2 open Capital A = 1607-321
B = PC 1752A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report 7/2019 (203/219)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/YPN No.



SINGAPORE POLICE FORCE

Police Station / Sub-Station
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65473000



T/20191203/2181

1 of 3

Report No: T/20191203/2181

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made
03/12/2019 21:40

Station Diary No.

Informant's Particulars

Name of Informant
LIONG SIN YEONG

ID Type / ID No
NRIC NO / 25672597E

Nationality
SINGAPORE CITIZEN

Sex
Male

Age
32

Race
Chinese

Occupation
FINANCE

Address
APT BLK 288D BUKIT BATOK STREET 25 #06-50 NATURE

VIEW SINGAPORE 653288

Contact No.:

Mobile: 94584426

Home/Office:

Email:

Type of Informant:

Driver

Institution / School Name:

Driving Licence Information:

Class: 2B,3,4

Date of Expiry:

General Information of the Accident

Type of Accident

Non-Injury
Hit and Run

Drink

Drive:

No

Date/Time of Accident:

03/12/2019 21:40

Type of Location:
Car Park

Location:

Along Road 1
UBI AVENUE 1

BLK 302 OPEN SPACE CARPARK

Weather:

Clear

Road Speed Limit:

Traffic Flow:

Road Surface:

Dry

Traffic Volume:

Traffic Control:

Anyone conveyed by ambulance:

No

Type of Collision:

Moving Vehicle Against - Parked Vehicle

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC1057A	Van	TOYOTA	HIACE COMMUTER GL 3.0 A	Silver		0
SGU7095L	Car	TOYOTA	VIOS E AUTO	Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



1-201912052181

2 00

Report No: 1-201912052181

Police Station Of Origin
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408885
Tel No: 65470000

CONTINUATION OF REPORT

Driver Name	LIONG SIN YEONG	ID No.	S8672597E
Related Vehicle	SGU7095L (Car)	Contact No.	94884426
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION.

I JUST ENDED WORK AND I AM GOING TO HEAD BACK HOME. THEN WHEN I WENT TO THE CARPARK I REALIZED THAT MY CAR HAD A DENT AND SCRATCHES ON THE DRIVER'S SIDE DOOR. THERE IS A WITNESS OF THE INCIDENT, HE CALLED ME OVER AND TOLD ME HE HAD WITNESS THE ENTIRE INCIDENT WHILE WASHING THE DISHES. HE SAID THAT THE VAN PC1057A JUST HIT THE CAR AND SIMPLY DROVE OFF WITHOUT STOPPING. SO I REALIZED THAT IT IS AN HIT AND RUN ACCIDENT. NO ONE WAS INJURED.

THAT IS ALL.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408565
Tel No: 65470000



Report No: TCR000000000000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474685 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /

WINSTON KOH WEN ZHONG

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

03/12/2019 23:00

Classification Of Case:

Officer In Charge Of Case:

TP / HRT /

SI KALESWARI PALANI

Contact No.: 65476902



**SINGAPORE
POLICE FORCE**

Authentication Stamp

NP168

Signature:

F1 Garage Pte Ltd

8 Kaki Bukit Ave 4, #03-33
Premier @ Kaki Bukit, Singapore 415875
H/P: 96311088 / 91188490
Email: sales@F1garageSG.com

Vehicle number: SGU7095L
Make and model: Toyota Vios

Parts 2487.84
Paint 2500
1865.88
Spec 120
Labour 750
2735.88
H/s less 20%
2188.70
Total
H/s → \$2200
Net.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

No. Parts

List price

1 RH front door ✓ B+ \$
1 RH front door outer handle ✓ CRA \$
1 RH front door outer moulding ✓ SCR \$
1 RH front door frame black tape ✓ all \$
1 RH front door inner trim board ✓ CRA \$
1set RH front door inner trim board clips ✓ all \$
1 RH front door lock ✓ Jm \$
1 RH Power Window Motor \$320 X (svc) \$
1 RH Power window Regulator \$220 ✓ -25% \$
1 RH Side Mirror whole Assy \$460 ✓ CRA \$

1,013.40 979.80 ✓
84.30 ✓
112.00 85.80 ✓
45.64 ✓
505.30 400.80 ✓
35.00 20 ✓
247.30 191.50 ✓

2,042.94
510.74
1,532.21

Special nett

1 RH front door protector ✓ SCR \$
1 RH rear door protector X (svc) \$

120.00 ✓
120.00

Labour / Painting + side mirror RH

Labour charges

Putty and re-spray affected areas

Check wirings and lightings on affected areas

Spray rust coating on affected areas

Remove and replace RH front door inner parts to new door X

Labour charges

Putty and re-spray affected areas

Check wirings and lightings on affected areas

Spray rust coating on affected areas

Remove and replace RH front door inner parts to new door X

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

500.00 350 ✓

600.00 350 ✓

50.00 30 ✓

100.00 70 ✓

100.00

3,122.21

3892.21

14/1/2020

14/1/2020

14/1/2020

14/1/2020

14/1/2020

14/1/2020

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Dec 2019		30 Dec 2019 17:09 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	TOP NOTCH SERVICES								
Vehicle Reg. No.:	SGU7095L	Date of Loss:	03/12/2019 21:00 - :59 [150 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D206143C02	Policy/Cover Note No.:	DMBISN30845719000						
Vehicle Reg. No. (Insured):	PC1057A	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	F1 Garage (HQ) 8 KAKI BUKIT AVENUE 4, #03-33, PREMIER@KAKI BUKIT, 415875 Kaki Bukit - Tel: 96311088								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 09/01/2020]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGU7095L (SNM19D206143C02)
[PC1057A]
TP
TOP NOTCH SERVICES
Dec 3 2019 9:00PM
[-]
F1 Garage

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/20 11:51	Chassis Number	 Load JPG	☒
2	14/01/20 11:51	Odometer Reading	 Load JPG	☒
3	14/01/20 11:51	General View	 Load JPG	☒
4	14/01/20 11:51	General View	 Load JPG	☒
5	14/01/20 11:51	General View	 Load JPG	☒
6	14/01/20 11:51	General View	 Load JPG	☒
7	14/01/20 11:51	General View	 Load JPG	☒
8	14/01/20 11:51	General View	 Load JPG	☒
9	14/01/20 11:51	General View	 Load JPG	☒
10	14/01/20 11:51	General View	 Load JPG	☒
11	14/01/20 11:51	General View	 Load JPG	☒
12	14/01/20 11:51	General View	 Load JPG	☒
13	14/01/20 11:51	General View	 Load JPG	☒
14	14/01/20 11:51	General View	 Load JPG	☒
15	14/01/20 11:51	General View	 Load JPG	☒
16	14/01/20 11:51	General View	 Load JPG	☒
17	14/01/20 11:51	General View	 Load JPG	☒
18	14/01/20 11:51	General View	 Load JPG	☒
19	14/01/20 11:51	General View	 Load JPG	☒
20	14/01/20 11:51	General View	 Load JPG	☒
21	14/01/20 11:51	General View	 Load JPG	☒
22	14/01/20 11:51	General View	 Load JPG	☒
23	14/01/20 11:52	General View	 Load JPG	☒
24	14/01/20 11:52	General View	 Load JPG	☒
25	14/01/20 11:52	General View	 Load JPG	☒
26	14/01/20 11:52	General View	 Load JPG	☒
27	14/01/20 11:52	General View	 Load JPG	☒
28	14/01/20 11:52	General View	 Load JPG	☒
29	14/01/20 11:52	General View	 Load JPG	☒
30	14/01/20 11:52	General View	 Load JPG	☒
31	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
32	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
33	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
34	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
35	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
36	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
37	17/01/20 09:56	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
39	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
40	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
41	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
42	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
43	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
44	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
45	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
46	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
47	17/01/20 09:56	Reinspection Photo	 Load JPG	☒
48	23/01/20 08:38	After Repair Photo	 Load JPG	☒
49	23/01/20 08:38	After Repair Photo	 Load JPG	☒
50	23/01/20 08:38	After Repair Photo	 Load JPG	☒
51	23/01/20 08:38	After Repair Photo	 Load JPG	☒
52	23/01/20 08:38	After Repair Photo	 Load JPG	☒
53	23/01/20 08:38	After Repair Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022907/ASF3E2

Date: 03/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMBISN30845719000
Claimant Vehicle No :	SGU7095L	Insured Vehicle No :	PC1057A
Date of Loss:	03/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D206143C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGU7095L	Engine No:	1NZX545299
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305001407
Reg. Date:	23/05/2007 (Man. Year: 2007)	Odometer:	342210 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	CROSSWIND 3 mm	Rear Left Side:	CROSSWIND 4 mm
Front Right Side:	CROSSWIND 3 mm	Rear Right Side:	CROSSWIND 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,522.20	1,985.88	536.32	21.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	750.00	600.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,872.20	2,735.88	1,136.32	29.35
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	3,872.20	2,200.00	1,672.20	43.18
+ GST 7.00/7.00% (S\$)	271.05	154.00	117.05	43.18
Nett Amount (S\$)	4,143.25	2,354.00	1,789.25	43.18

INSPECTION

Date of Assignment: 30/12/2019
Date Inspected: 13/01/2020 Inspected At:

F1 Garage (HQ)
8 KAKI BUKIT AVENUE 4, #03-33,
PREMIER@KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2020)
Parts: 143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU7095L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Bent	1,013.40 FL	*979.80 FL
2	1		*RH FRONT DOOR OUTER HANDLE	Cracked	84.30 FL	*84.30 FL
3	1		*RH FRONT DOOR OUTER MOULDING	Scratched	112.00 FL	*85.80 FL
4	1		*RH FRONT DOOR FRAME BLACK TAPE	Necessary	45.64 FL	*45.64 FL
5	1		*RH FRONT DOOR INNER TRIM BOARD	Cracked	505.30 FL	*400.80 FL
6	1		*SET RH FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	35.00 FL	*20.00 FL
7	1		*RH FRONT DOOR LOCK	Jammed	247.30 FL	*191.50 FL
8	1		*RH POWER WINDOW MOTOR	Serviceable	320.00 FL	*- FL
9	1		*RH POWER WINDOW REGULATOR	Crumpled	220.00 FL	*220.00 FL
10	1		*RH SIDE MIRROR WHOLE ASSY	Cracked	460.00 FL	*460.00 FL
11	1		*RH FRONT DOOR PROTECTOR	Scratched	120.00 FS	*120.00 FS
12	1		*RH REAR DOOR PROTECTOR	Serviceable	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,282.94	2,607.84
- List Item Discount on L Items 25.00/25.00% (S\$)	760.74	621.96
Total Parts (S\$)	2,522.20	1,985.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES }	New	500.00	350.00
2	REMOVE AND REPLACE RH FRONT DOOR INNER PARTS TO NEW DOOR }	New	100.00	0.00
3	PUTTY & RE-SPRAY AFFECTED AREAS	New	600.00	350.00
4	CHECK WIRINGS AND LIGHTINGS ON AFFECTED AREAS	New	50.00	30.00
5	SPRAY RUST COATING ON AFFECTED AREAS	New	100.00	20.00
Gross Labour Cost (\$\$)			1,350.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >