

ASS. REC. BY

REF: CS/MSG 19022922/ Ktf3n2 Special Instructions

Surveyor

Kinuth

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSIG

Date/Time:

31.12.19 10.45 AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 5841K

Insured:

GBG 477E

at Workshop n/s

Massive Trading

Tel:

9108 2728

of

BIC 5038 #01-405 Amc Industrial pt 2

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vels:

D.O.A.

28.12.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

31.12.2019 1100AM

Person Contacted:

Anthony

Vehicle:

IN/OUT

Date/Time

Action/Instruction (v) Estimate

SKC 5841K - X

GBG 477E - X

01/01/2020 2:55pm revised to Christina Wong via message.

ISS REC BY:

REF: MJG/1

Heath

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s Massive

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Basic Market Value: 825k

IDAC Accident Report: _____ Consistent?: Yes or No

GDH / PR / Leon: _____ Consistent?: Yes or No

Est. Repair: 08 Feb days Res.: Yes or No

Lumsum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Day: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKC 5841K 'Yr Regn: 09, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: NIS Sylphy c.c. 1498

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 73.730 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BAAG11Z0111428

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 28/12/19

Rear R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 31/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

None of

The U/C / Chassis frame / Body Structure affected due to collision.

Action / Instruction

File pass to

30/1 C1 Pump @ 4300k email & confirm (red: 5430.52, 570/0)

RECEIVED 6 5 FEB 2020

Handwritten signature and date 4/2/2020

Date/TIME File Pass to: 14/2 Typist

: Prel. Report
 : Final Report

Days Of Repair: 8
Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	150
\$ + RS. Sl	11
Fuel	
Others	
TOTAL	161

Report Format

Lump Sum / B.I. AS: 4300/-

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 02 Jan 2020

Preliminary Advice

Insured Vehicle No	: GBG4777E	Accident Date	: 28/12/2019
TP Vehicle No	: SKC5841K	Assignment Date	: 31/12/2019
Make	: NISSAN SYLPHY	Est. Duration of Repair	: 9.00
Date of Inspection	: 31/12/2019		
Inspection At	: MASSIVE TRADING & AUTO BLK 5038 #01-405, ANG MO KIO INDUSTRIAL PK 2 SINGAPORE 569541		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,450.52
Revised Amount	:S\$	3,798.84
Check Items (Estimated)	:S\$	2,704.47
Total	:S\$	6,503.31

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Dec 2019 09:38		31 Dec 2019 10:45 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	FRONTIER MAINTENANCE & CONTRACTORS PTE LTD, Co. Reg. No.: 201508717D		
Main Claimant:	PHUA HWEE NGOH, ID: S0918630A		
Vehicle Reg. No.:	SKC5841K	Date of Loss:	28/12/2019 12:00 - :59 [99 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	B29088834MKC (Comprehensive) Coverage: 15/08/2019 - 14/08/2020
Vehicle Reg. No. (Insured):	GBG4777E	Policy No. (Claimant):	5103347767-01
		Excess:	
Repairer:	Massive Trading & Auto () Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/01/2020]		
Driver/Custodian (Insured):	TUN AUNG CHO (39 / Male) , NRIC: G7378628U, Tel: +6592234004 Email: NOEMAIL		
Adj Asg. Remarks:	on WP. Lab: clear. Choose LKK. Anthony 91082728		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	630A
Vehicle Details	
Vehicle No.:	SKC5841K
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	HR15005705C
Chassis No.:	JN1BAAG11Z0111428
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,077.00
Original Registration Date:	12 Sep 2011
First Registration Date:	12 Sep 2011
Transfer Count:	2
Actual ARF Paid:	\$18,077.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2021
PARF Rebate Amount:	\$9,942.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$8,627.00
Total Rebate Amount:	\$18,569.00

The information contained herein is correct as at 02 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/12/2019 11:41
Date Of Accident	28/12/2019 12:10
Exact Location Of Accident	UPP BT TIMAH RD TWDS WOODLANDS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC5841K
Insured/Policyholder	
Name Of Registered Owner	PHUA HWEE NGOH
NRIC No	SXXXX630A
Email Address	MASSIVETRD@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92783363
Alternative Phone No	OFFICE-92783363

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103347767-01
Cover Note Number	

Driver

Name of Driver	PHUA HWEE NGOH
NRIC No	SXXXX630A
Date Of Birth	11/09/1952
Occupation	INDOOR
Date Of Driving Pass	15/12/1986
Driving Experience	33 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92783363
Fax Number	
Contact Number	OFFICE-92783363
E-Mail Address	MASSIVETRD@GMAIL.COM

Address	BLK 275 BT BATOK EAST AVE 4 #01-130
Postcode	650275
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 28/12/19 @ 1210HRS, I WAS TRAVELLING ALONG UPP BUKIT TIMAH RD TOWARDS WOODLANDS RD. JUST BEFORE THE JUNCTION OF CHOA CHU KANG RD, I SAW A BARRELL LYING ON THE LANE SO I SLOWED DOWN MY VEHICLE TRYING TO AVOID IT. SUDDENLY I FELT AN STRONG IMPACT FROM THE REAR OF MY VEHICLE. I GOT OUT OF MY VEHICLE AND REALISED THAT VEH B (GBG 4777 E) HAD COLLIDED INTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG4777E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TUN AUNG CHO
NRIC/Passport Number	GXXXX628U
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Phua
 Policyholder's Signature
 Date & Time:

Phua
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28/12/2019 @ ard 12:10hrs, I was travelling along Upp Bukit Timah Rd towards Woodland Rd. Just before the junction of Chua Chu Kang Rd, I saw a barrel ~~was~~ lying on the lane so I slowed down my vehicle trying to avoid it. Suddenly, I felt an strong impact from the rear of my vehicles. I got out of my vehicle and realised that veh B (G3G4777E) had collided into my vehicle rear portion.

Claim OD/TP at Su Brothers Claim OD/TP at other workshop Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop : massive Trading 3 A-to

Email address : massivetrade@gmail.com

& myself : massivetrade@gmail.com

Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

/We declare the foregoing particulars are true in every respect.

Phua
 Policyholder's Signature
 Date & Time:

Phua
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 SIC/FIN No:

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Handwritten signature
2/1/2020

Phua Hwee Ngoh
Blk 275B Bukit Batok East Ave 4
#01-130
Singapore 650275

Not Authorised
U1 Per @ 4300/-
Returning After Point
8 - days

Vehicle No : SKC 5841 K
Make : Nissan Sylphy 1.5
Year : 2009

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid	<i>810.90</i>	<i>Per</i> \$890.90	<i>✓</i>
1 pc	Rear boot lid inner insulator		<i>Per</i> \$175.80	<i>X</i>
1 pc	Rear boot lid top chrome moulding		<i>Per</i> \$287.50	<i>X</i>
1 pc	Rear end panel	<i>491.80</i>	<i>Per</i> \$521.80	<i>✓</i>
1 pc	Rear o/s fender	<i>957.30</i>	<i>Per</i> \$987.20	<i>✓</i>
2 pcs	Rear fender inner insulator		<i>old reform</i> \$282.40	<i>✓</i>
1 pc	Rear spare tyre cover board		<i>Per</i> \$615.20	<i>X</i>
1 pc	Rear spare spool sponge compartment		<i>Per</i> \$175.30	<i>X</i>
1 pc	Rear bumper	<i>660.60</i>	<i>Per</i> \$713.60	<i>✓</i>
1 pc	Rear bumper sponge		<i>Per</i> \$105.10	<i>X</i>
2 pcs	Rear bumper bracket		<i>old rd</i> \$55.90	<i>✓</i>
2 pcs	Rear bumper side retainer		<i>old rd</i> \$55.10	<i>✓</i>
1 pc	Rear bumper moulding		<i>Per</i> \$176.70	<i>✓</i>
			\$5,836.90	<i>5435.90</i>
			Less 30 %	\$1,750.77
			List total	\$4,085.13

Nett Item

1 pc	Rear boot lid inner lock (top)		<i>Per</i> \$107.90	<i>X</i>
1 pc	Rear boot lid inner lock (lower)		<i>Per</i> \$60.50	<i>X</i>
1 pc	Rear boot lid emblem " Logo "		<i>Per</i> \$45.20	<i>✓</i>
1 pc	Rear boot lid emblem " Sylphy "		<i>Per</i> \$76.50	<i>✓</i>
1 pc	Rear boot lid lower chrome moulding		<i>Per</i> \$135.20	<i>X</i>
2 pcs	Rear boot lid reflector		<i>old sem</i> \$96.40	<i>✓</i>
2 pcs	Rear no plate lamp		\$64.20	<i>Per</i> \$128.40
1 pc	Rear antenne sensor		<i>Per</i> \$85.60	<i>So far</i>
1 pc	Rear boot rubber		<i>old rd</i> \$97.10	<i>502in</i>
1 pc	Rear end panel inner garnish		<i>old rd</i> \$176.80	<i>✓</i>
2 pcs	Rear tail-lamp assy		<i>old rd</i> \$192.70	<i>✓</i>
			Nett c/f	\$1,491.40

LN Auto Components hence notify the Receiver of the following:

- To returny defective parts only please
- To display damaged parts during returny
- Parts return are subject to confirmation
- Third party survey is in a "limited freedom" task
- No recall notification is allowed
- Customer's survey results may vary and will be subject to confirmation from the Supplier

Approved Signature: _____

SJW 2959 G

- 1 pc Rear o/s fender air duct
- 2 pcs Rear bumper reflector
- 1 pc Rear exhaust silencer

Nett b/f	\$1,491.40
<i>o/s Av</i>	
	<i>in</i> \$53.90 <i>R</i>
\$51.60	\$103.20 <i>L</i>
	<i>n</i> \$568.60 <i>X</i>
	<u>\$2,217.10</u>
Less 10 %	\$221.71
Nett total	<u>\$1,995.39</u>

S Nett Item

- 1 pc Rear no plate
- 1 set Rear reverse sensor
- 1 pc Rear windscreen sealant

	<i>in</i> \$40.00 <i>X</i>
	<i>short</i> \$200.00 <i>✓</i>
	<i>no</i> \$40.00 <i>✓</i>
S Nett total	<u>\$280.00</u>

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,400.00 *90d*

To putty & spray paint on rear accident affected portion.

\$1,200.00 *90d*

Check/reconnect wiring.

\$40.00 *2d*

To spray anti rust on accident affected portion.

\$180.00 *6d*

Remove/refit rear boot upholstery to facilitate repair.

\$150.00 *10d*

Remove/renew rear exhaust silencer.

nn \$150.00 *X*

Remove/refit rear windscreen to facilitate repair

\$100.00 *✓*

Remove/refit roof lining to facilitate repair

nn \$150.00 *X*

Total \$9,730.52

9450.52

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19022922/KTF3N2
Date: 05/02/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29088834MKC
Claimant Vehicle No :	SKC5841K	Insured Vehicle No :	GBG4777E
Date of Loss:	28/12/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC5841K	Engine No:	HR15005705C
Make & Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Chassis No:	JN1BAAG11Z0111428
Reg. Date:	12/09/2011 (Man. Year: 2010)	Odometer:	73730 km
Colour:	Metallic Silver		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 8 mm	Rear Left Side:	Maxxis 8 mm
Front Right Side:	Maxxis 8 mm	Rear Right Side:	Maxxis 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,080.52	3,307.32	2,773.20	45.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	2,080.00	1,290.00	38.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,450.52	5,387.32	4,063.20	42.99
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	9,450.52	4,300.00	5,150.52	54.50

INSPECTION

Date of Assignment:	31/12/2019	
Date Inspected:	31/12/2019	Inspected At: Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Feb 2020)

Parts: 143 NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKC5841K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	890.90 FL	*810.90 FL
2	1		*REAR BOOT LID INNER INSULATOR	Serviceable	175.80 FL	*- FL
3	1		*REAR BOOT LID TOP CHROME MOULDING	Serviceable	287.50 FL	*- FL
4	1		*REAR END PANEL	Bent	521.80 FL	*491.80 FL
5	1		*REAR O/S FENDER	Buckled	987.20 FL	*957.30 FL
6	1		*REAR FENDER INNER INSULATOR	O/s Deformed	564.80 FL	*282.40 FL
7	1		*REAR SPARE TYRE COVER BOARD	Serviceable	615.20 FL	*- FL
8	1		*REAR SPARE SPOOL SPONGE COMPARTMENT	Serviceable	175.30 FL	*- FL
9	1		*REAR BUMPER	Bent	713.60 FL	*660.60 FL
10	1		*REAR BUMPER SPONGE	Serviceable	105.10 FL	*- FL
11	1		*REAR BUMPER BRACKET	O/s Dented	111.80 FL	*55.90 FL
12	1		*REAR BUMPER SIDE RETAINER	O/s Distorted	110.20 FL	*55.10 FL
13	1		*REAR BUMPER MOULDING	Necessary	176.70 FL	*176.70 FL
14	1		*REAR BOOT LID INNER LOCK (TOP)	Repair	107.90 FN	*- FN
15	1		*REAR BOOT LID INNER LOCK (LOWER)	Repair	60.50 FN	*- FN
16	1		*REAR BOOT LID EMBLEM LOGO	Necessary	45.20 FN	*45.20 FN
17	1		*REAR BOOT LID EMBLEM SYLPHY	Necessary	76.50 FN	*76.50 FN
18	1		*REAR BOOT LID LOWER CHROME MOULDING	Serviceable	135.20 FN	*- FN
19	1		*REAR BOOT LID REFLECTOR	O/s Cracked	192.80 FN	*96.40 FN
20	2		*REAR NO PLATE LAMP	Serviceable	128.40 FN	*- FN
21	1		*REAR ANTANNE SENSOR	Serviceable	85.60 FN	*- FN
22	1		*REAR END PANEL INNER GARNISH	Mtg Cracked	176.80 FN	*176.80 FN
23	1		*REAR TAIL-LAMP ASSY	O/s Broken	385.40 FN	*192.70 FN
24	1		*REAR O/S FENDER AIR DUCT	Serviceable	53.90 FN	*- FN
25	1		*REAR BUMPER REFLECTOR	O/s Broken	103.20 FN	*51.60 FN
26	1		*REAR EXHAUST SILENCER	Repair	568.60 FN	*- FN
27	1		*REAR BOOT RUBBER (50%)	Dented/Distorted	87.39 FS	*48.55 FS
28	1		*REAR NO PLATE	Serviceable	40.00 FS	*- FS
29	1		*SET REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
30	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

	Sub Total (\$)	7,923.29	4,418.45
	- List Item Discount on L Items 30.00/30.00% (\$)	1,630.77	1,047.21
	- Nett Item Discount on N Items 10.00/10.00% (\$)	212.00	63.92
	Total Parts (\$)	6,080.52	3,307.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	1,400.00	900.00
2	TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION	New	1,200.00	900.00
3	CHECK/RECONNECT WIRING	New	40.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	180.00	60.00
5	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR)	New	150.00	100.00
6	REMOVE/REFIT ROOF LINING TO FACILITATE REPAIR)	New	150.00	0.00
7	REMOVE/RENEW REAR EXHAUST SILENCER	New	150.00	0.00
8	REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	100.00	100.00
Gross Labour Cost (\$\$)			3,370.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >