

A.S.S. BY:

REF: CS/CTI 19022923 /Uy-f3

Special Instruction:

Survivor:

Marius

ASSIGNMENT (Office)

From (Person):

Irene Tay Hui Ping

of

CTI

Date/Time:

31.12.19 10.48 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 687M

Insured:

GBG 6034C

at Workshop m/s

Kan Poo C Sng

Tel:

67 479560

of 61 Defu Lane 12

Policy No:

Claim No:

SNM19b 206154102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21.12.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

31.12.19 10.58 a.m

Person Contacted:

Patricia

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	XD 687M - x
	GBG 6034C - CS/CTI 19022769/ kyds Dat - 24/12/2019

REF: CTE

ASSIGNMENT

From:

Date:

8/01/2019

Veh No:

XD687M

Yr Regn:

9 06

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OE / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

XD687M

Make:

Isuzu

CX250K

c.c.

12068

at Workshop m/s

Kan Kook Sing

Colour:

white/she

A/C:

Insured / Std / NI / NA

of

G1 Defunct 12

Sp. Reading

67283

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JALCX250K 67000102

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

2pm (unit/m)

Mod:

Nil S/Rim / STD A/Rim or

Tyre Size:

F:

295/80 R22.5

R:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Double star

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6/6 6/6

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6/6 6/6

Est. Repairs:

2

days

Res.: Yes or No

D.O.A.

2.1/14/19

D.O.I.

8/1/20

Lum Sum:

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

up

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear Cartridge

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

ATA 7609

19/3/20

according to repainer KFS MR Tan vehicle hasn't send in for repair because parts use cost price he not repairing.

31/3/20

MR Byron from KFS agree cost plus 20% but TP vehicle do not want to repair of KFS only. he said closed case.

submit

(Remark = Vehicle had not sent in to Repair.)

Date/Time, File Pass to:

☐

Prel. Report

Days Of Repair:

2

1)

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time, File Return to:

2/4/20 Typist

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Transportation:

S + RS, \$

Fuels:

Other:

Report Format:

Emp: 200 / 150 / 100

PIP \$48387-50

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt.	Adj Submitted	Ins Auth'd	Status
Main	31 Dec 2019		31 Dec 2019 10:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	DIPICIE CONTRACTORS PTE LTD		
Vehicle Reg. No.:	XD687M	Date of Loss:	21/12/2019 15:00 - :59
Claim Type:	TP / SNM19D206154C02	Policy/Cover Note No.:	DMCVSN30570619011
Vehicle Reg. No. (Insured):	GBG6034C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kan Fook Sing Motor Workshop (Kaki Bukit) Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/01/2020]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2019 15:20
Date Of Accident	21/12/2019 15:15
Exact Location Of Accident	PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD687M
Insured/Policyholder	
Name Of Registered Owner	DIPCIE CONTRACTORS PTE LTD
Co Reg No	XXXXXX508G
Email Address	ADMIN@DIPCIE.COM
Mobile Phone No	
Alternative Phone No	OFFICE-66352155 8180 2037

Vehicle Particulars

Manufacturer	ISUZU
Model	CXZ50K
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DMCPHQ19-001051
Cover Note Number	01/03/19 - 29/02/20

Driver

Name of Driver	KANDASAMY SIVALINGAM
Passport No/FIN	GXXXX800M
Date Of Birth	20/04/1982
Occupation	OUTDOOR
Date Of Driving Pass	01/04/2019
Driving Experience	0 YEAR AND 8 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90818011
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 691B CHOA CHU KANG CRESCENT #03-56 MURAI LODGE II
 Postcode 682691
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions DRIZZLING
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name WOODLANDS EAST N.P.C
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63, POSTCODE: 737890, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT (REPAIR BY KAN FOOK SENG MOTOR WORKSHOP)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG6034C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: W363725
INSURER: EC
DATE & TIME: 21/12/19 12:19

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the G.A. Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insured(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN

8. $8 \times 3 \leq 8 + 8$

8 406 60342

Don't stop!

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ins. Eqs. Vol. No. X5587M Date: 2-12-13 15:15

Refer Police Report

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

/We declare the foregoing particulars are true in every respect

Policyholder Signature _____
Date & Time _____

Driver's Signature _____
 (If driver is not the policyholder)
 Date & Time _____

Reporting Centre Personnel's Signature
Name _____
ARIC/FIN No. _____

() Claim Own Policy () Claim Third Party () Reporting Only
(x) Claim OD/TP at other workshop (than Fault, Term, Major Workshop)



**SINGAPORE
POLICE FORCE**



L/20191221/2102

1 of 2

POLICE REPORT (NP299)

Report No. L/20191221/2102

Police Station Of Origin
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Date/Time Report Made 21/12/2019 22:00	Vide Report No.	Station Diary No. 235
Name Of Informant KANDASAMY SIVALINGAM	Address APT BLK 691B CHOA CHU KANG CRESCENT #03-56 MURAI LODGE II SINGAPORE 682691	
ID Type / ID No. FIN NO / G8342800M	Contact No. Home/Office Mobile 90818011	
Nationality INDIAN	Email Address	
Occupation Building construction engineer	Sex Male	Age 37
Institution/School Name	Date of Birth 20/04/1982	Race Indian
Date/Time Of Incident 21/12/2019 15:15 - 21/12/2019 15:15	Location Of Incident 213 CLEMENTI AVENUE 6 UNNAMED SINGAPORE 120213	

Brief details.

We were working for Dipcie contractors Pte Ltd and tasked by LTA to do some lamppost work.

On the 21/12/2019 at about 1510hrs, We were doing some light changing for lamppost along Clementi Ave 6 - PIE towards Tuas. We had placed some safety barrier at the side of the road, lane 4.

On the 21/12/2019 at about 1515hrs, while we are doing our work at lane 4. There was a lorry knocked

Signature Of Officer Recording The Report: L / SI NG RAYMOND	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 21/12/2019 22:00
Officer In-Charge Of Case: L / Woodlands Police Divisional Investigation Branch / Sgt 2 MUHAMMAD HAFIZH BIN HAMZAH Contact No.:	Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



L/20191221/2102

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20191221/2102

onto our safety barrier. The lorry register plate number XD687M. The driver then came down and provide me his particulars and contact number. At that point of time nobody was injured and no government property damage.

The estimated cost of the safely barrier is S\$25,000/- and the safety barrier belong to my company.

I am lodging this report for my company action.

Signature Of Officer Recording The Report:

L / SI NG RAYMOND

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
L / Woodlands Police Divisional Investigation Branch /
Sgt 2 MUHAMMAD HAFIZH BIN HAMZAH
Contact No.:

Authentication Stamp

Signature Of Informant:

Date/Time:
21/12/2019 22:00

Classification Of Case:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 508G

Vehicle Details

Vehicle No.: XD687M

Vehicle to be Exported: No

Intended Deregistration Date: 08 Jan 2020

Vehicle Make: ISUZU

Vehicle Model: CXZ50K

Primary Colour: White

Manufacturing Year: 2006

Engine No.: 6WA1400399

Chassis No.: JALCXZ50K67000102

Maximum Power Output: -

Open Market Value: \$69,143.00

Original Registration Date: 01 Sep 2006

First Registration Date: 01 Sep 2006

Transfer Count: 1

Actual ARF Paid: \$3,458.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2021

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$23,127.00

COE Rebate Amount: \$7,609.00

Total Rebate Amount: \$7,609.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 08 Jan 2020

OK

Marcus Chua (LKKAUTO)

From: mttan <mttan@kanfs.net>
Sent: Friday, 27 March, 2020 12:32 PM
To: KKLau; Choi Fang Too; Guo Qiang (LKKAUTO); Hsiao Tong (LKKAUTO); Miss Khai Xin; SUR; Marcus Chua (LKKAUTO); Steve Chen (LKK Auto)
Cc: boonsen.chong@sg.cntaiping.com; gina.toh@sg.cntaiping.com; Patricia
Subject: Re: Re: Re: XD687M - SNM19D206154

Dear All

Reference to our various email with regard to mark up percentage(20%) and yet to reach a compromise.

The Owner, Dicipie Contractor Pte Ltd reserve the right to submit the entire claim inclusive repair cost, rental and loss of use from the date of accident due to the delay on your side

Please reply by 27/03/2020 as we had to inform Dicipie Contractor Pte Ltd and his represented lawyer on 27/03/2020.

Thank you

Mr Tan
KFS
67479560

On Fri, 27 Mar 2020 03:45:52 +0000, Chong Boon Sen wrote

> Without Prejudice

>

> Dear Sir,

>

> pls liaise with LKK who will mark accordingly. unfortunately we do not control third party markup prices.

>

> kindly negotiate with LKK who will do the necessary.

>

> Thank you.

>
>
> **Chong Boon Sen**
> Claims Executive
> Department
>
> **China Taiping Insurance (Singapore) Pte. Ltd.**
> 3 Anson Road #16-00 Springleaf Tower Singapore 079909
> DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033
>
> **W:**www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
> DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033
>
>
>

>
>
>
> ----- Forwarded Message -----
> From: "mttan" <mttan@kanfs.net>
> To: boonsen.chong@sg.cntaiping.com, assignments@lkkauto.com
> Cc: gina.toh@cntaiping.com.sg, "Patricia" <patricia@kanfs.net>
> Sent: Thu, 26 Mar 2020 18:08:47 +0800
> Subject: Fw: Re: Re: XD687M - SNM19D206154

>
> Dear All

>
> With reference to our email, to date there wasn't any reply you.

>
> Kindly look into the matter and reply by 27/03/2020.

>
> Failing which to reply, Dipcie Contractor reserve the right to submit the entire
claim inclusive repair cost, rental and loss of use through his lawyer

>
> We will not representing Dipcie Contractors Pte Ltd on this matter

>
> Thank you

>
> Mr Tan

> KFS

> 67479560

>
> ----- Forwarded Message -----

> From: "mttan" <mttan@kanfs.net>

> To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>, assignments

<assignments@lkkauto.com>

> Cc:Gina Toh <gina.toh@cntaiping.comsg.>, "Patricia" <patricia@kanfs.net>, "LKK (survey)" <sur@lkkauto.com>

> Sent:Mon, 23 Mar 2020 09:40:02 +0800

> Subject:Re: Re: XD687M - SNM19D206154

>

> Dear All

>

> Kindly advise on the status on our previous email with regard to the Mark up percentage (20%)

>

> Thank you

>

> Mr Tan

> KFS

> 67479560

>

> On Fri, 21 Feb 2020 06:16:29 +0000, Chong Boon Sen wrote

> > Without Prejudice

> >

> > Dear LKK,

> >

> > can advise on this what is required?

> >

> > Thank you.

> >

> >

> > **Chong Boon Sen**

> > Claims Executive

> > Department

> >

> > **China Taiping Insurance (Singapore) Pte. Ltd.**

> > 3 Anson Road #16-00 Springleaf Tower Singapore 079909

> > DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

> >

> > **W:**www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3

Anson Road #16-00 Springleaf Tower Singapore 079909

> > DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

> >

> >

> >

>

>

> > **From:** mttan <mttan@kanfs.net>

> > **Sent:** Friday, February 21, 2020 2:13 PM

> > **To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

> > **Cc:** Gina Toh <gina.toh@sg.cntaiping.com>; Patricia <patricia@kanfs.net>

>> **Subject:** Re: Re: XD687M - SNM19D206154

>>

>> Dear Boon Sen,

>>

>> As to date we are not able to agree on the cost of repair with your surveyor.

>>

>> To avoid any further delay, please ask your surveyor to recommend a workshop that is able to undertake the repairs at your surveyor's recommended cost of repair.

>>

>> Thank you

>> Mr Tan

>> KFS

>> 6749560

>>

>> On Fri, 21 Feb 2020 06:03:42 +0000, Chong Boon Sen wrote

>>> Without Prejudice

>>>

>>> Dear Mr Tan,

>>>

>>> sorry dont understand. why our surveyor need recommend workshop to you?

>>>

>>> thought you are workshop? also, we dont recommend workshop for repair m.

>>>

>>>

>>> **Chong Boon Sen**

>>> Claims Executive

>>> Department

>>>

>>> **China Taiping Insurance (Singapore) Pte. Ltd.**

>>> 3 Anson Road #16-00 Springleaf Tower Singapore 079909

>>> DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

>>>

>>> **W:**www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平御城 Taiping SG 3

Anson Road #16-00 Springleaf Tower Singapore 079909

>>> DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

>>>

>>>

>>>

>>>

>>>

>

>>> **From:** mttan <mttan@kanfs.net>

>>> **Sent:** Friday, February 21, 2020 9:47 AM

>>> **To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

>>> **Cc:** Gina Toh <gina.toh@sg.cntaiping.com>; Patricia <patricia@kanfs.net>

>>> **Subject:** Fw: Re: XD687M - SNM19D206154

>>>

>>> Dear Boon Sen

Email : ~~25/10/19~~
 not for reply.

TN Safety Pte Ltd

TN Safety Pte Ltd
 1090 Lower Delta Road, #01-03
 Tiong Bahru Industrial Estate, Singapore 169201
 Tel: 6276 7997 Fax: 6272 7261
 Email: tonyngbt@singnet.com.sg
 Reg No: 201806429M

Quotation

GST Reg No: 201806429M

Attach to CR

Date : 18-Oct-19
 Our Ref :
 Your Ref :

M/S :

Attn: i - Operation Director
 Email: 3

Re : Huatong Truck No:XD 762D; TMA 5116A; 5053B, 1579

Qty	Description	Unit Price	Amount
units	To Supply & Install for SafeStop 180 TMA		
1	Cartridge Section A	SGD 19,250.00	SGD 19,250.00
1	Cartridge Section B	SGD 19,250.00	SGD 19,250.00
4	Breakaway Cables Bolt	SGD 15.00	SGD 60.00
1	Impact Frame Plate - reflective	SGD 830.00	SGD 830.00
1	Labour, installation & fixing charges for above and dismantling charges from old unit	SGD 2,350.00	SGD 2,350.00
1	To repair & spray paint Side Guide Bay	SGD 98.00	SGD 98.00
1	To adjust and realign the whole TMA in working condition	SGD 650.00	SGD 650.00
			SGD 42,488.00
	Less : 28% Trade Discount		SGD 11,896.64
			SGD 30,591.36
	Less: Special Discount		SGD 2,447.30
			SGD 28,144.06
	Price : Singapore Dollars; ex-warehouse Singapore		
	Delivery : Ex-stock but subject to goods unsold		
	1st Payment : Deposit 50%		
	Bal Payment : Balance 50% Upon Collection of Your Vehicle		
	Remarks : Subject to 7% GST		
	Total :		SGD 28,144.06

For TN Safety Pte Ltd

Please sign & return as confirmation of order

Tony Ng

Authorised Signature

Company Stamp, Name & Authorised Signature



Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

DATE : 30-12-2019

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE XD687M ISUZU CXZ50K

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
SPECIAL NETT ITEMS			
1	1	CARTRIDGE SECTION A	28000.00
2	1	CARTRIDGE SECTION B	28000.00
3	1	IMPACT FRAME PLATE - REFLECTIVE	1200.00
			57,200.00
LABOUR CHARGES			
1	1	BREAKEAWAY CABLES BOLT	180.00
2	1	TO ADJUST AND ALIGN THE WHOLE TMA	1000.00
3	1	LABOUR , INSTALLATION & FIXING CHARGES FOR ABOVE DISMANTLING CHAR- GES FROM OLD UNIT	4000.00
4	1	TO RESPAIR PAINT SIDE GUIDE RAY	300.00
			5,480.00
			62,680.00

Not Held
2 days.
8/1/20
The above are all

1. The Consultants hence notify the Repairs of the following:

- The reason for the delay in repairing
- The proposed repair method, timing, nature
- The cost of repair (approximate)
- The time taken to complete the repair
- The time taken to complete the repair
- The time taken to complete the repair

Acknowledged by Repairer
 Signature: _____
 Date: _____

TN Safety Pte Ltd

TN Safety Pte Ltd
1090 Lower Delta Road, #01-03
Tiong Bahru Industrial Estate, Singapore 169201
Tel: 6276 7997 Fax: 6272 7261
Email: tonyngbt@singnet.com.sg
Reg No: 201806429M

Quotation

GST Reg No: 201806429M

Date : 30-Dec-19
Our Ref :
Your Ref :

M/S : **Kan Fook Sing Motor Workshop**
61 Defu Lane 12
Singapore 539147
Tel: 6747 9560 Fax: 6748 1006

Attn: Ms Patricia
Email: patricia@kanfs.net

Re : **Truck XD 687M, TMA 5365A, 5296B, Frame 1733 - Dipcie Contractors Pte Ltd**

Qty	Description	Unit Price	Amount
units	To Supply & Install for SafeStop 180 TMA		
1	Cartridge Section A	SGD 19,250.00	SGD 19,250.00
1	Cartridge Section B	SGD 19,250.00	SGD 19,250.00
4	Breakaway Cables Bolt	SGD 15.00	SGD 60.00
1	Impact Frame Plate - reflective	SGD 830.00	SGD 830.00
1	Labour, installation & fixing charges for above and dismantling charges from old unit	SGD 2,350.00	SGD 2,350.00
1	To repair & spray paint Side Guide Bay	SGD 98.00	SGD 98.00
1	To adjust and realign the whole TMA in working condition	SGD 650.00	SGD 650.00
			SGD 42,488.00
Price : Singapore Dollars; ex-warehouse Singapore			
Delivery : 1 unit of Cartridge A&B each ex-stock but subject to goods unsold			
1st Payment : Deposit 50%			
Bal Payment : Balance 50% Upon Collection of Your Vehicle			
Remarks : Subject to 7% GST			
Total :			SGD 42,488.00

For TN Safety Pte Ltd

Please sign & return as confirmation of order

Tony Ng

Authorised Signature

Company Stamp, Name & Authorised Signature