

EXPENSE

ADD. RES. BY

REF: 01INC19022926/Gvd312 | Special Instruction:

Assigned by: Theresa Yim

ASSIGNMENT (Office)

From (Person): Theresa Yim of INC Date/Time: 9:47am @ 3/11/19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 2518C Insured: FU 79612

at Workshop in/s: Vin's Auto Tel: 6453 2121

of 160 Sin Ming Drive # 08-09

Policy No: _____ Claim No: MT/1077530-001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 10:11am @ 3/11/19 Person Contacted: Raymond Vehicle: IN/OUT


Date/Time	Action/Instruction	Estimate	✓
	SLV 2518C - (04/AGM/80/0150/Km 312		
<u>15/1/2020</u>	<u>LS \$ 3750 confirmed by email (Recd 16/12/2019, 30/12)</u>		

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 31 December 2019 1:50 PM
To: 'assignments'
Cc: Theresa Vimala D/O Balagangadharan
Subject: FW: TP CASES FARMED OUT TO LKK ON 31/12/2019

List of OIC, details, thanks

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we proudest as an employer and what we want our people to embody.
Find out more at income.com.sg/careers

IN with you

Hi LKK

Please assist to survey these vehicles. Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
----	-----	-----------	-------------	---------	---------------	------------------	------------------	-------------	--------	-----	--------------------

1.	Alice Low	MT/1077171-002	31/12/2019	SJR808Z	BH AUTO SERVICES PTE LTD	BLK 1 #01-115 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575636	Wen Zheng / 6559 / 8945 / 9621 2084	10:00-13:00	SJP7805X	24/12/2019	This vehicle belong to our MD of ComfortDelGro (REQUESTED-9am to 10am)
2.	Chryllis Quah	MT/1077895-001	31/12/2019	SJM1898I	COMFORTDELGRO ENGINEERING PTE LTD	205 BRADDELL ROAD EAST WING 3RD FLR SINGAPORE 579701	Ngo Toh Wee / 6383 8115 / 6383 7362 / 6383 7656	09:30-10:30	YP400Z	30/12/2019	
3.	Rajeswary	MT/1077719-001	31/12/2019	SLX253T	CP MOTORS PTE LTD	BLK 160 SIN MING DRIVE SIN MING AUTO CITY #05-05	Thomas Tan / 8201 8103	10:00-12:00	SIV6239E	27/12/2019	
4.	Azhari	MT/1077789-001	31/12/2019	SLU7303C	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	CARMEN / 8799 0066 / 6566 2112		SKP2361V	29/12/2019	
5.	Chryllis Quah	MT/1077726-001	31/12/2019	SML358B	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752	10:00-12:00	SIV9565T	29/12/2019	
6.	Serene Lim	MT/1077814-001	31/12/2019	SML3775X	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752	10:00-12:00	SMF7565	28/12/2019	
7.	Huey Huey	MT/1077878-001	31/12/2019	SMK943S	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999		SJ7620Z	30/12/2019	agreeable with the appointment of Mr Lim - LKK

8	Helena	MT/1077820-001	31/12/2019	SLV5356H	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999	SGK1569D	28/12/2019	agreeable with the appointment of Mr Lim - LKK
9	Airwan	MT/1077830-001	31/12/2019	SLV2518C	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722	Raymond Teo / 64532121	FU961Z	29/12/2019	
10	David	MT/1076933-002	31/12/2019	SJ3638U	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722	Raymond Teo / 64532121	SLL1656X	21/12/2019	


Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 15 January 2020 5:25 PM
To: Admin @ VAuG
Cc: SUR
Subject: RE: SLV2518C - NTUC TP - DOA: 29/12/2019 - MT/1077830-001 - Finalization

Dear Raymond,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to NTUC INCOME

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin @ VAuG <admin@vinsautogroup.com.sg>
Sent: Wednesday, 15 January 2020 5:04 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: SLV2518C - NTUC TP - DOA: 29/12/2019 - MT/1077830-001 - Finalization

Good afternoon,

We accept the offer

Please proceed

Thanks!
Best Regards
Raymond Teo

On Wed, Jan 15, 2020 at 11:57 AM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Raymond,

WITHOUT PREJUDICE

Offer Lump Sum \$3750 @ 5 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin @ VAuG <admin@vinsautogroup.com.sg>

Sent: Monday, 13 January 2020 4:09 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: SLV2518C - NTUC TP - DOA: 29/12/2019 - MT/1077830-001 - Finalization

Good afternoon,

Can we finalize?

Thanks!

Best regards

Raymond Teo

--

The logo for Vin's Automotive Group features the word "Vin's" in a stylized, handwritten-style font. To its right, the words "AUTOMOTIVE GROUP" are written in a clean, uppercase, sans-serif font. Below "AUTOMOTIVE GROUP", the hashtag "#VAUG" is written in a smaller, uppercase, sans-serif font.

Sin Ming AutoCity

160 Sin Ming Drive

Singapore 575722

Showroom/Office: #03-03

Workshops: #08-08/09/10

Tel: 64532121 (4 lines)

Fax: 64599795

Website: www.vinsautogroup.com.sg

Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

--
Vin's
AUTOMOTIVE GROUP
#VAUG

Sin Ming AutoCity

160 Sin Ming Drive

Singapore 575722

Showroom/Office: #03-03

Workshops: #08-08/09/10

Tel: 64532121 (4 lines)

Fax: 64599795

Website: www.vinsautogroup.com.sg

Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	803B
Vehicle Details	
Vehicle No.:	SLV2518C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	L15B5460563
Chassis No.:	GK81200469
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,472.00
Original Registration Date:	26 Dec 2017
First Registration Date:	26 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$7,472.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$5,604.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$30,477.00
Total Rebate Amount:	\$36,081.00

The information contained herein is correct as at 02 Jan 2020

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 803B

Vehicle Details

Vehicle No.: SLV2518C
Vehicle to be Exported: No
Intended Deregistration Date: 31 Dec 2019
Vehicle Make: HONDA
Vehicle Model: SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR
Primary Colour: Black
Manufacturing Year: 2017
Engine No.: L15B5460563
Chassis No.: GK81200469
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$17,472.00
Original Registration Date: 26 Dec 2017
First Registration Date: 26 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$7,472.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Dec 2027
PARF Rebate Amount: \$5,604.00

Intended COE Rebate Details

COE Expiry Date: 25 Dec 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,200.00
COE Rebate Amount: \$30,498.00
Total Rebate Amount: \$36,102.00

The information contained herein is correct as at 30 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/12/2019 09:15
Date Of Accident	29/12/2019 17:10
Exact Location Of Accident	PIE TOWARDS TUAS (NEAR EXIT BUKIT BATOK RD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV2518C
Insured/Policyholder	
Name Of Registered Owner	LOW YONG YEE, EUGENE
NRIC No	SXXXX803B
Email Address	EUGENELOWYY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97329772
Alternative Phone No	OFFICE-97329772

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE-1.5 G CVT ABS (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00014833
Cover Note Number	

Driver

Name of Driver	LOW YONG YEE, EUGENE
NRIC No	SXXXX803B
Date Of Birth	06/12/1988
Occupation	INDOOR
Date Of Driving Pass	02/05/2009
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97329772
Fax Number	
Contact Number	OFFICE-97329772
EMail Address	EUGENELOWYY@HOTMAIL.COM

Address	BLK461C BUKIT BATOK WEST AVENUE 8 #08-732
Postcode	653461
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : KWAN GENDER: : FEMALE
Passenger 2	NAME: : LOW GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 JURONG WEST AVENUE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO: 67912972
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FU7961Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOTORCYCLIST

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.





 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/12/2019 18:52	Vide Report No.: J/20191229/0138	Station Diary No.: 42
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: LOW YONG YEE, EUGENE		Address: APT BLK 461C BUKIT BATOK WEST AVENUE 8 #08-732 SINGAPORE 653461	
ID Type / ID No.: NRIC NO / S8848803B		Contact No.: Home/Office: Mobile: 97329772	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 31	Date of Birth: 06/12/1988	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Marine engineer (shore-based)		Driving Licence Information: Class: 2B,2A,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 29/12/2019 17:10	Type of Location: Bend
Location: PAN ISLAND EXPRESSWAY BUKIT BATOK ROAD TUAS NEAR EXIT BT BATOK RD LP 1515S3				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FU7961Z	Motorcycle	YAMAHA		Red	Seriously Damaged	1
SLV2518C	Car	HONDA	SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR	Black	Slightly Damaged	3



Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20191229/2069

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLV2518C	FWD Singapore Pte. Ltd	PNPV2018-00014833-01	26/12/2019	25/12/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	LOW YONG YEE, EUGENE		ID No.	S8848803B
Related Vehicle	NIL		Contact No.	97329772
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 29/12/2019 at about 1708 hrs at PIE exiting to Tuas near exit Bukit Batok Rd, I was driving along the 2nd lane from the right where I stop at a red light then after about six seconds, I felt an impact at the rear of my car (SLV2518C) and saw that a motorcycle (FU7961Z) had self skidded and collided into the back of my car.

My vehicle (SLV2518C) sustained dents and scratches at the left rear of my car. However, I did not sustain any injuries. The motorcycle (FU7961Z) on the other hand sustained damages as it went under my car. I called the ambulance as the rider was bleeding at the rider's forehead. Traffic Police also arrived at the scene to take my statement and I was advised to make a police report. Thus I am here to make a police report. I wish to add that I have an in-car camera at the back of my vehicle. The footage was forwarded to the TP IO in-charge.

The vide report number :J/20191229/0138
TP IO in-charge: Zickie
HP: 65476356



**SINGAPORE
POLICE FORCE**



T/20191229/2069

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

3 of 3

Report No. T/20191229/2069

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 2 ASRUL FADZIL BIN AZMI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 29/12/2019 18:52
Officer In Charge Of Case: TP / GIT / Staff Sgt QHAIRIL BIN ZULKEFLEE Contact No.: 65476187	Classification Of Case:
Authentication Stamp NP168	 <p>SINGAPORE POLICE FORCE REPUBLIC OF SINGAPORE</p> <p></p> <p>SIGNATURE</p>



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00014833 (Comprehensive - Classic Plan)

Car plate number: SLV2518C

Your name (As the policyholder): Low Yong Yee Eugene

Coverage start date: 26/12/2018

Coverage end date: 25/12/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 06/11/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



AUTOMOTIVE GROUP

A. Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T. 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F. 6459 9795 / 6459 0433
E. admin@vinsautogroup.com.sg
W. www.vinsautogroup.com.sg

Our Ref : TP/122019/4200
Accident date: 29/12/2019
Your Ref : FU7961Z

Tax Invoice:
Date : 30/12/2019

MOTOR CLAIM DEPARTMENT
NTUC INCOME INSURANCE CO-OP LTD
75 Bras Basah Road
#05-00 NTUC Income Centre
Singapore 189557

5 Days
Lapsum repair.
After repair photos.
Guo Qiang - 82880282
31/12/19

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SLV2518C
Model : HONDA SHUTTLE-1.5 G CVT ABS (A)

1	pc	Rear Bootlid / buc	\$ 1,193.00 /
1	pc	Rear Bootlid shuttle emblem / dec.	\$ 55.00 /
1	pc	Rear Bootlid inner lock X #N	\$ 157.00 X
1	pc	Rear windscreen glass moulding / dec.	\$ 120.00 /
1	pc	Rear Bumper / dec.	\$ 1,150.60 /
1	pc	Rear Bumper Towing Cover / dec.	\$ 16.50 /
1	pc	Rear bumper LH reflector 2 / ser	\$ 55.00 /
1	pc	Rear bumper LH reflector cover 2 / cut.	\$ 45.00 /
1	pc	Rear bumper LH side retainer X #N	\$ 26.50 X
1	pc	Rear bumper sponge 2 / cut	\$ 56.50 /
1	pc	Rear bumper antenna sensor 2 / #N	\$ 58.10 X
1	pc	Rear bumper buzzie sensor 2 / #N	\$ 80.00 X
1	pc	Rear end panel / buc.	\$ 560.80 487.4
			\$ 3,574.00 3,179
Less 20%			\$ (714.80)
			\$ 2,859.20 2,543.2

1	set	Rear bumper parking sensor / #M	\$ 280.00 N 200
1	pc	Rear windscreen gum / dec.	\$ 60.00 N 40

To remove and refix rear windscreen

To repair rear damages

To spray painting

\$ 180.00 100 240
\$ 680.00 600
\$ 680.00 600
\$ 4,739.20 1300 5362.12

VIN'S MOTOR PTE LTD

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4706.12
20% = 3750



AUTOMOTIVE GROUP

A: Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T: 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F: 6459 9795 / 6459 0433
E: admin@vinsautogroup.com.sg
W: www.vinsautogroup.com.sg

Our Ref : TP/122019/4200
Accident date: 29/12/2019
Your Ref : FU7961Z

Tax Invoice :

Date : 31/12/2019

MOTOR CLAIM DEPARTMENT
NTUC INCOME INSURANCE CO-OP LTD
75 Bras Basah Road
#05-00 NTUC Income Centre
Singapore 189557

SUPPLEMENTARY COST OF REPAIRS TO

Vehicle No. : SLV2518C
Model : HONDA SHUTTLE-1.5 G CVT ABS (A)

1	pc	Rear end panel top trim	<i>Re</i>	\$	155.15	<i>/</i>
1	pc	Rear RH fender inner trimboard	<i>GR PR</i>	\$	455.00	<i>/</i>
1	pc	Rear boot lid rubber	<i>Twi</i>	\$	168.50	<i>/</i>
				\$	778.65	
		Less: 20%		\$	(155.73)	
				\$	<u>622.92</u>	<i>/</i>

VIN'S MOTOR PTE LTD





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: AIRWAN	Ref: CS/INC19022926/Gvd3n2 Date: 16-01-2020 Code: INC	
--	---	---

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FU 7961Z	Veh. Inspected	SLV 2518C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1077830-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	31/12/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE 1.5G	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81200469	Colour	BLACK
Odometer	53349 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	GOODYEAR	6 mm
L/H Front Tyre	185/60 R15	GOODYEAR	6 mm
R/H Rear Tyre	185/60 R15	GOODYEAR	6 mm
L/H Rear Tyre	185/60 R15	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/12/2019	Inspect Date / Time	31/12/2019 (11:20 AM)
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 2518C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	BUCKLED	1,193.00	1,193.00
1	REAR BOOTLID SHUTTLE EMBLEM	NECESSARY	55.00	55.00
1	REAR BOOTLID INNER LOCK	NOT NECESSARY	157.00	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	120.00	120.00
1	REAR BUMPER	DEFORMED	1,150.60	1,150.60
1	REAR BUMPER TOWING COVER	DEFORMED	16.50	16.50
1	REAR BUMPER LH REFLECTOR	SCRATCHED	55.00	55.00
1	REAR BUMPER LH REFLECTOR COVER	CUT	45.00	45.00
1	REAR BUMPER LH SIDE RETAINER	NOT NECESSARY	26.50	-
1	REAR BUMPER SPONGE	CRACKED	56.50	56.50
1	REAR BUMPER ANTENNA SENSOR	NOT NECESSARY	58.10	-
1	REAR BUMPER BUZZIE SENSOR	NOT NECESSARY	80.00	-
1	REAR END PANEL	BUCKLED	560.80	487.40
1	REAR END PANEL TOP TRIM (ADDITIONAL)	DEFORMED	155.15	155.15
1	REAR RH FENDER INNER TRIMBOARD (ADDITIONAL)	BROKEN	455.00	455.00
1	REAR BOOT LID RUBBER (ADDITIONAL)	TWISTED	168.50	168.50
	LESS 20% DISCOUNT		-870.53	-791.53
			3,482.12	3,166.12
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR WINDSCREEN GUM (SN)	NECESSARY	60.00	40.00
			340.00	240.00
LABOUR				
	TO REMOVE AND REFIX REAR WINDSCREEN.		180.00	100.00
	TO REPAIR REAR DAMAGES.		680.00	600.00
	TO SPRAY PAINTING.		680.00	600.00
			1,540.00	1,300.00
GRAND TOTAL			5,362.12	4,706.12

Report Ref No. CS/INC19022926/Gvd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,750.00
--	--	--	----------

Report Ref No. CS/INC19022926/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.