

ASS. REC. BY:

REF:

CS/INC19022936/KvF3 02

Special Instruction:

Survey: Kenneth

ASSIGNMENT (Office)

From (Person): Theresa Virela

of INC

Date/Time: 31/12/19 @ 9.47am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

8ML358B

Insured:

SJV 9565T

at Workshop m/s:

Hui Yang Motor

Tel:

6451 5752

of

176 Sin Ming Drive #04-02

Policy No:

Claim No:

MT/10777 26-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/12/2019

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

10-03am 31/12/19

Person Contacted:

Bel

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate 1

8ML358B X

8/1

83822-64 email. Confirm (Red 41568, 5270)

ASS. REC. BY:

REF: INC/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 1.131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SML 358B Yr Regn: 04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda c.c. 1496

Colour: M. P. White A/C: Insured / Std / NI / NA

Sp. Reading: 9894 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK8 - 2001556

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 29/12/19

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 31/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 09 JAN 2020

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

21/1 - typist

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - R.S. - SI

Fees

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$

3822.64

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 31 December 2019 1:50 PM
To: 'assignments'
Cc: Theresa Vimala D/O Balagangadharan
Subject: FW: TP CASES FARMED OUT TO LKK ON 31/12/2019

List of OIC, details, thanks

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

Hi LKK

Please assist to survey these vehicles. Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
----	-----	-----------	-------------	---------	---------------	------------------	------------------	-------------	--------	-----	--------------------

1	Alice Low	MT/1077171-002	31/12/2019	SIR808Z	BH AUTO SERVICES PTE LTD	BLK 1 #01-115 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575636	Wen Zheng / 6559 8945 / 9621 2084	10:00-13:00	SIP7805X	24/12/2019	
2	Chryllis Quah	MT/1077895-001	31/12/2019	SLM1898I	COMFORTDELGRO ENGINEERING PTE LTD	BRADDELL ROAD EAST WING 3RD FLR SINGAPORE 579701	Ngo Toh Wee / 6383 8115 / 6383 7362 / 6383 7656	09:30-10:30	YP400Z	30/12/2019	This vehicle belong to our MO of ComfortDelGro (REQUESTED- 9am to 10am)
3	Rajeswary	MT/1077719-001	31/12/2019	SLX253T	CP MOTORS PTE LTD	BLK 160 SIN MING DRIVE SIN MING AUTO CITY #05-05	Thomas Tan / 8201 8103	10:00-12:00	SIV6239E	27/12/2019	
4	Athari	MT/1077789-001	31/12/2019	SLU7303C	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	CARMEN / 8799 0066 / 6566 2112		SKP2361Y	29/12/2019	
5	Chryllis Quah	MT/1077726-001	31/12/2019	SML358B	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752	10:00-12:00	SIV9565T	29/12/2019	
6	Serene Lim	MT/1077814-001	31/12/2019	SMI3775X	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752	10:00-12:00	SMF756S	28/12/2019	
7	Huey Huey	MT/1077878-001	31/12/2019	SMK943S	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999		5J2620Z	30/12/2019	agreeable with the appointment of Mr Lim - LKK

8	Helena	MT/1077820-001	31/12/2019	SLV5356H	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999	SGK1569D	28/12/2019	agreeable with the appointment of Mr Lim - LKK
9	Airwan	MT/1077830-001	31/12/2019	SLV2518C	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722	Raymond Teo / 64532121	FU7961Z	29/12/2019	
10	David	MT/1076933-002	31/12/2019	SLJ3638U	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722	Raymond Teo / 64532121	SLL1656X	21/12/2019	

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/12/2019 11:15
Date Of Accident	29/12/2019 20:25
Exact Location Of Accident	ALONG YISHUN CENTRAL IN FRONT OF BLK 202 YISHUN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML358B
Insured/Policyholder	
Name Of Registered Owner	POON SEET KEAT, DAREK
NRIC No	SXXXX006A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92226809
Alternative Phone No	OTHERS-92226809

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29123664QMY
Cover Note Number	

Driver

Name of Driver	POON SEET KEAT, DAREK
NRIC No	SXXXX006A
Date Of Birth	09/12/1988
Occupation	INDOOR
Date Of Driving Pass	16/06/2011
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92226809
Fax Number	
Contact Number	OTHERS-92226809
EMail Address	NOEMAIL

Address BLK 251 CHOA CHU KANG AVENUE 2 #03-302
Postcode 680251
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : IVY HE (FRIEND)
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: CANNOT BE UPLOADED
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV9565T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver MUHAMMAD ASHRRY BIN JA'AFAR
NRIC/Passport Number SXXXX144I
Contact Number 96460985
Address
Postcode
Insurance Company Name
Nature Of Damage

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

* - No.Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:

NRIC/ID No:

NG WING KIN JAMES
admin.vac@vicom.com.sg

30 DEC 2019

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/12/19 @ 8:25pm, my vehicle A (SM1 358B) was stationary along Yishun Central as the traffic light was in Red. Suddenly Vehicle B (SVN 95657) from behind just hit onto the rear of my vehicle A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

30 DEC 2019



Reporting Centre Personnel's Signature
Name: NG WING KIN JAMES
NRIC/FIN No.:
admin.vac@vicom.com.sg

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

29/12/2019

Owner: POON SEET KEAT, DAREK

83822.64

Not Authored

Measuring B4 paint

4-145

ESTIMATE TO REPAIR HONDA SHUTTLE - SML358B

1pc	rear tailgate	By \$	1,193.70	✓
1pc	rear tailgate "H" logo	By \$	58.00	✓
1pc	rear tailgate "SHUTTLE" emblem	By \$	55.00	✓
1pc	rear tailgate chrome	By \$	383.10	X
1pc	rear tailgate windscreen moulding	By \$	195.00	✓
1pc	rear tailgate inner lock	By \$	289.40	X
1pc	rear tailgate inner rubber	By \$	188.50	✓
1pc	rear tailgate inner garnish	By \$	358.50	X
1pc	rear LH taillamp lower bracket	By \$	89.50	X
1pc	rear bumper	By \$	1,150.60	✓
1pc	rear bumper LH side retainer	By \$	38.50	X
1pc	rear bumper LH reflector	By \$	65.00	X
1pc	rear bumper LH reflector garnish	By \$	85.00	X
1pc	rear bumper LH refractor inner sponge	By \$	158.50	X
10pcs	rear bumper clip @\$5.00	By \$	50.00	✓
1pc	rear end panel	By \$	601.50	X
1pc	rear end panel inner garnish	By \$	295.20	X
1pc	rear end panel LH side panel	By \$	385.50	X
1pc	rear fender LH inner garnish	By \$	758.80	X
	less 20%		\$ 6,399.30	
	balance c/f		\$ 1,279.86	
			\$ 5,119.44	
1 set	rear parking sensor	CM s.nett	\$ 280.00	2005m
	remove & refit rear windscreen glass		\$ 120.00	✓
	sealant	By \$	80.00	400m
	wiring		\$ 180.00	201
	tuffkote		\$ 200.00	301
	spray painting		\$ 1,000.00	600d
	labour charges		\$ 1,000.00	500d
	Total		\$ 7,979.44	

Car Parts Consultants hence notify the Repairer of the following:

- To remove before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- (Un)legal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature: CM
Date:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19022936/Kvf3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 10-01-2020



ATTN: CHRYLLIS QUAH

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 9565T	Veh. Inspected	SML 358B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1077726-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	31/12/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK82001556	Colour	METALLIC PEARL WHITE
Odometer	9894 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	8 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	8 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/12/2019	Inspect Date / Time	31/12/2019 (01:33 PM)
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 358B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	1,193.70	1,193.70
1	REAR TAILGATE "H" LOGO	NECESSARY	58.00	58.00
1	REAR TAILGATE "SHUTTLE" EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE CHROME	SERVICEABLE	383.10	-
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	195.00	195.00
1	REAR TAILGATE INNER LOCK	TO REPAIR SEE LABOUR	289.40	-
1	REAR TAILGATE INNER RUBBER	CUT	188.50	188.50
1	REAR TAILGATE INNER GARNISH	SERVICEABLE	358.50	-
1	REAR LH TAILLAMP LOWER BRACKET	SERVICEABLE	89.50	-
1	REAR BUMPER	BENT	1,150.60	1,150.60
1	REAR BUMPER LH SIDE RETAINER	SERVICEABLE	38.50	-
1	REAR BUMPER LH REFLECTOR	SERVICEABLE	65.00	-
1	REAR BUMPER LH REFLECTOR GARNISH	SERVICEABLE	85.00	-
1	REAR BUMPER LH REFLECTOR INNER SPONGE	SERVICEABLE	158.50	-
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	50.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	601.50	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	295.20	-
1	REAR END PANEL LH SIDE PANEL	TO REPAIR SEE LABOUR	385.50	-
1	REAR FENDER LH INNER GARNISH	SERVICEABLE	758.80	-
	LESS 20% DISCOUNT		-1,279.86	-578.16
			5,119.44	2,312.64
SPECIAL NETT ITEMS				
1	SET REAR PARKING SENSOR (SN)	CRACKED	280.00	200.00
1	SEALANT (SN)	NECESSARY	80.00	40.00
			360.00	240.00
LABOUR				
	REMOVE & REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	WIRING.		180.00	20.00

Report Ref No. CS/INC19022936/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFFKOTE.		200.00	30.00
	SPRAY PAINTING.		1,000.00	600.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR TAILGATE INNER LOCK,REAR END PANEL AND REAR END PANEL LH SIDE PANEL.		1,000.00	500.00
			2,500.00	1,270.00
GRAND TOTAL			7,979.44	3,822.64
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,822.64

Report Ref No. CS/INC19022936/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.