

FORM 100

ASS. REC. BY:

Signature: M. P. U. S.

REF: CS/CTI/9022946/USD3¹⁷

Special Instructions:

ASSIGNMENT (Office)

From (Person): Ben Tang

of CTI

Date/Time: 31/12/19 @ 11:12am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP59852

Insured:

S/Q 238944

at Workshop w/s

Poche Auto

Tel:

6886 9097

of

1 kuki Bukit Me 6 #02-50 Autobay

Policy No:

Claim No:

3NM19D20614

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:33am 31/12/19

Person Contacted:

Aidech

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Initiald /</u>
	<u>SLP59852-X</u>
	<u>S/Q 238944-CS/CTI/9005358/Asd 302</u>
	<u>DOA: 22/3/2019</u>

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP 5-9852

Yr Regn:

6.17

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda civic

C.C.

1597

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

33/92

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC 5650H.T 000095

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

31/12/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

nett 22106

15/1/20 1/5 @ 8100 confirmed with MR way
(£ 8,065.84 Red. 50%)

RECEIVED 15 JAN 2020

Date/Time, File Pass to?

15/1/20

1)

Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

12

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS. SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$ 8,100/- 45)

TOTAL

220

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Tuesday, 31 December 2019 11:12 AM
To: assignments@lkkauto.com
Subject: FW: OUR REF: SNM19D206144/SJQ2389H/BEN & YOUR REF: SLP5985Z -PRE SURVEY REPAIR - SLP5985Z & SJQ2389H ACCIDENT ON 27.12.19

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SLP5985Z

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Focus Auto Singapore <claims@focusauto.com.sg>
Sent: Tuesday, December 31, 2019 11:04 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D206144/SJQ2389H/BEN & YOUR REF: SLP5985Z -PRE SURVEY REPAIR - SLP5985Z & SJQ2389H ACCIDENT ON 27.12.19

Dear Ben Tan,

We are please to select Mr Macus Chua as the surveyor. Do let us know early the arrival of Mr Macus to our workshop.

Thank You and wishing you Happy New Year 2020!

Best Regards
Aidah

Focus Auto Pte Ltd
No. 1 Kaki Bukit Avenue 6
#02-50 AutoBay Singapore 417883
Tel: 6886 9097 Fax: 68444625

Office Hours : Mon ~ Sat, 0900 ~ 1800

On Mon, 30 Dec 2019 at 17:18, Ben Tang <Ben.Tang@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 30 December 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, December 30, 2019 5:08 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>; claims@focusauto.com.sg
Subject: OUR REF: SNM19D206144/SJQ2389H/BEN & YOUR REF: SLP5985Z -PRE SURVEY REPAIR - SLP5985Z & SJQ2389H ACCIDENT ON 27.12.19

Dear Ben,

Please conduct PRS –SLP5985Z –soonest possible.

File with officer in charge –Ben Tang –DID: 6389 6175.

Dear Aidah,

*** kindly quote our reference number when replying ***

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Focus Auto Singapore [<mailto:claims@focusauto.com.sg>]

Sent: Monday, 30 December, 2019 2:22 PM

To: Claims Dept of CTI

Subject: PRE SURVEY REPAIR - SLP5985Z & SJQ2389H ACCIDENT ON 27.12.19

Good Day,

Please sent surveyor list to arrange the surveyor down to our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 27/12/2019 at about 0740 hours at Upper Serangoon Road involving our client's SLP5985Z and SLQ2389H driven by your insurer or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client / we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at :

Name of workshop : **FOCUS AUTO PTE LTD**

Address : No. 1 Kaki Bukit Avenue 6

Autobay #02-48/50

Singapore 417883

Telephone No.: 68869097

FAX : 68444625

Best Regards
Aidah

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6
#02-50 AutoBay Singapore 417883
Tel: 6886 9097 Fax: 68444625

Office Hours : Mon ~ Sat, 0900 ~ 1800

Price Range

Depreciation

2017

Vehicle Type

Home > Used Cars > Republic Auto > Honda Civic 1.6A VTi

Honda Civic 1.6A VTi

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

Republic
Auto

 A member of the Jardine Cycle & Carriage Group

Price	\$77,800		
Depreciation	\$9,190 /yr <small>View models with similar depre</small>	Reg Date	04-May-2017 (7yrs 4mths 2days COE left)
Mileage	15,000 km (5.6k /yr)	Manufactured	2017
Road Tax	\$742 /yr	Transmission	Auto
Dereg Value	\$53,685 as of today <small>(change)</small>	OMV	\$20,480
COE	\$52,000	ARF	\$20,672
Engine Cap	1,597 cc	Power	92.0 kW (123 bhp)
Curb Weight	1,249 kg	No. of Owners	1
Type of Vehicle	Mid-Sized Sedan		

Features

1.6L I-VTEC Engine, 123Bhp, 5 Speed Automatic With Paddle Shifters, ABS, SRS Airbags, Eco Assist, Cruise Control, Sports Rims, Leather Seats. [View specs of the Honda Civic \(2016\)](#)

Accessories

17" TSW Sports Rims, Apple CarPlay/Android Auto, Keyless Entry/Start/Stop, Factory Fitted Audio System/Bluetooth, Multi Function Steering, Rear Aircon

Description

1 Owner Agent Unit, Lowest Mileage In The Market. Warranty By Kah Motor, Diligently Serviced And Maintained By Agent, In Pristine Condition. Upgraded 17" TSW Rims, Apple CarPlay, Android Auto. Enjoy Exclusive Low Interest Rates From Authorized Banks At 70% Loan Of The Car Price. Please Call/Whatsapp Now For Viewing.

Category

PARF Car, Low Mileage Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

[Compare](#)



- Price Chart
- Summary

[Click on the point to view the vehicle](#)

- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information

Republic Auto

157 vehicles for sale. 184 sold in past 3 mths

 209 Pandan Gardens Level 3

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	374D
Vehicle Details	
Vehicle No.:	SLP5985Z
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	R16B22000117
Chassis No.:	MRHFC5650HT000095
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,260.00
Original Registration Date:	12 Jun 2017
First Registration Date:	12 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$20,364.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jun 2027
PARF Rebate Amount:	\$15,273.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,489.00
COE Rebate Amount:	\$34,621.00
Total Rebate Amount:	\$49,894.00

The information contained herein is correct as at 31 Dec 2019

OK

MSME19170862 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 28/12/2019 12:09
 SUBMITTED BY: Wan Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/12/2019 12:09
Date Of Accident	27/12/2019 07:40
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP5985Z
Insured/Policyholder	
Name Of Registered Owner	TAN TIEN LEE
NRIC No	SXXXX374D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85189444
Alternative Phone No	OFFICE-85189444

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10760615
Cover Note Number	

Driver

Name of Driver	RASIMA BTE JANTAN
NRIC No	SXXXX082I
Date Of Birth	15/08/1960
Occupation	INDOOR
Date Of Driving Pass	13/07/2001
Driving Experience	18 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96604069
Fax Number	
Contact Number	
Email Address	RASIMABJANTA@GMAIL.COM

Address BLK 254 HOUGANG AVE 3 #01-300
 Postcode 530254
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO POLICE REPORT NO. T/20191227/7021.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJQ2386H
 Vehicle Make/Model/Colour
 Details Of Properties VEH B
 Vehicle Category PRIVATE CAR
 Name of Driver TAN CHIN ENG
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLG5550S
Vehicle Make/Model/Colour
Details Of Properties VEH C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name RASIMA BTE JANTAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLP5985Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode


Accident Sketch Plan Pg. 1


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the value as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared /disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

 28/12/2019
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
SIRIC/PIN No.:

SKETCH PLAN

A

Please refer to police T/20191237/7031

☐ We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature:
Name:
TREC/YS No:

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191227/7021

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No: T/20191227/7021

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/12/2019 21:19	Video Report No.:	Station Diary No.:
--	-------------------	--------------------

Informant's Particulars

Name of Informant: RASIMA BTE JANTAN		Address: APT BLK 254 HOUGANG AVENUE 3 #01-300 SINGAPORE 530254	
ID Type / ID No.: NRIC NO / S14460821		Contact No.:	Mobile: 96604069
Nationality: SINGAPORE CITIZEN		Email: rasimabjanta@gmail.com	
Sex: Female	Age: 59	Date of Birth: 15/08/1960	Type of Informant: Driver
Race: Malay		Language: English	Institution / School Name:
Occupation: Housewife		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 27/12/2019 07:40	Type of Location: Straight Road
Location: UPPER SERANGOON ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 60 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJQ2389H	Car	TOYOTA	Vios	Black	Seriously Damaged	1
SLG5550S	Car	HONDA	Vezel	Brown	Slightly Damaged	1
SLP5985Z	Car	HONDA	Civic	Blue	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191227/7021

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

2 of 4

Report No: T/20191227/7021

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLP5985Z	AVIVA LTD	10760615	12/06/2019	11/06/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MELISSA TJHIA JING JING	ID No.	S9413017D
Related Vehicle	SJQ2389H (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Passenger				
Name	ARUN VINOTH S/O PERUMAL PILLAY	ID No.	S9321759D	
Related Vehicle	SJQ2389H (Car)	Contact No.	81868621	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Driver				
Name	TAN CHIN ENG	ID No.	S0160496A	
Related Vehicle	SLG5550S (Car)	Contact No.	NIL	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191227/7021

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20191227/7021

CONTINUATION OF REPORT

Driver			
Name	RASIMA BTE JANTAN	ID No.	S14460821
Related Vehicle	SLP5985Z (Car)	Contact No.	96604069
Hospital/Clinic	HEALTHCARE MEDICAL @ KOVAN	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	27/12/2019	Date Discharge	27/12/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 27 December 2019 at about 7.40am, I was driving my vehicle, SLP5985Z, along Upper Serangoon Road. As I was slowing down my car gradually due to a queue in front of me to turn right to Hougang st. 21. All of a sudden I was hit hard at my rear by a car bearing the registration number SJQ2389H. The hit was so hard that it pushed my car to hit the car in front of me bearing the registration no SLG5550S. We exchanged particulars. I was given 3 days of MC. I do have an in car camera which the footage was already retrieved but unable to attach as the video is above 2MB. Thats all.

Accident Sketch Plan Pg. 1

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20191227/7021

4 of 4

Report No: T/20191227/7021

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
JUREMAH BINTE AHMAD
Contact No.: 65476219

Authentication Stamp

SP168

Signature Of Informant:

The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
27/12/2019 21:19

Classification Of Case:

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

4/5 \$8100
12/17**M/S : CHINA TAIPING****Estimate No: EST0001082**

Date: 31 Dec 2019

Veh Reg No: **SLP5985Z**

Make/Model: HONDA CIVIC

Chassis No: MRHFC5650HT000095

Engine No: R16B22000117

Reg. Date: 06/12/2017

ATTN: Motor Claim Department

Your Ref No: SLP5985Z HONDA CIVIC

Claim Type: Third Party

Accident Date: 27.12.19

Estimate Repair Cost to Vehicle No :SLP5985Z

PAGE:1/3

Description	U/Price	Quantity	List Price	Amount	
				SS	SS
List Price					
1 Rear Bootlid	831.20	Soled	831.50	1 PC	831.50 ✓
2 Rear Boot Hinge		See	68.00	2 PC	136.00 X
3 Rear Boot Lock		See	112.20	1 PC	112.20 ✓
4 Rear Boot Lock Catch		See	41.00	1 PC	41.00 X
5 Rear Boot Rubber		See	126.20	1 PC	126.20 ✓
6 Rear Boot Emblem (Civic)		See	28.30	1 PC	28.30 ✓
7 Rear Boot Emblem (I-VTEC)		See	31.20	1 PC	31.20 ✓
8 Rear Boot Centre Logo		See	28.40	1 PC	28.40 ✓
9 Rear Boot Centre Garnish		See	327.40	1 PC	327.40 ✓
10 Rear Boot Inner Cover		See	110.20	1 PCS	110.20 ✓
11 Rear Boot Inner Cover Clip		See	5.50	9 PC	49.50 X
12 Rear Boot Lamp		See	269.40	2 PC	538.80 ✓
13 Rear Number Plate Lamp		See	48.00	1 PC	48.00 X
14 Rear Reverse Camera		See	364.40	1 PC	364.40 ✓
15 Rear Spare Tyre Top Cover Board		See	246.20	1 PC	246.20 ✓
16 Rear Spare Tyre Panel		See	656.40	1 PC	656.40 ✓
17 Rear Spare Tyre Side Panel		See	130.40	1 PCS	130.40 ✓
18 Rear Spare Tyre Lock Screw		See	26.20	1 PC	26.20 X
19 Rear Chassis Sub Frame - LH		See	304.20	1 PC	304.20 X
20 Rear Fender		See	877.20	2 PC	1,754.40 X
21 Rear Fender Inner Garnish		See	246.20	2 PC	492.40 X
22 Rear Fender Inner Garnish Clipse		See	5.50	8 PC	44.00 X
23 Rear Fender Dust Cover		See	140.20	2 PC	280.40 X
24 Rear Windscreen Moulding		See	151.30	1 PC	151.30 X
25 Rear Tail Lamp	307.40 X 2 = 614.80	See	385.50	2 PC	771.00 ✓

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

Not Authorized
Halle
31/12/19
The Whistleblower
d/s #8100
12h.

M/S : CHINA TAIPING

Estimate No: EST0001082

Date: 31 Dec 2019

Veh Reg No: SLP5985Z

Make/Model: HONDA CIVIC

Chassis No: MRHFC5650HT000095

Engine No: R16B22000117

Reg. Date: 06/12/2017

ATTN: Motor Claim Department

Your Ref No: SLP5985Z HONDA CIVIC

Claim Type: Third Party

Accident Date: 27.12.19

Estimate Repair Cost to Vehicle No :SLP5985Z

PAGE:2/3

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
26 Rear Tail Lamp Panels	MSBent 96.30	2 PC	192.60	1 PC
27 Rear Tail Lamp Clips	17 5.80	4 PC	23.20	X
28 Rear Tail Lamp Lower Bracket	910 18.00	2 PC	36.00	✓
29 Rear End Panel	Good 385.70	1 PC	385.70	✓
30 Rear End Panel Top Garnish	171 98.40	1 PC	98.40	✓
31 Rear Bumper	617.20 715 683.40	1 PC	683.40	✓
32 Rear Bumper Reinforcement	715 246.20	1 PC	246.20	✓
33 Rear Bumper Lower Spoiler	148.20 715 198.20	1 PC	198.20	✓
34 Rear Bumper Side Cover	171 90.20	2 PC	180.40	✓
35 Rear Bumper Side Retainer	307 28.00	2 PC	56.00	✓
36 Rear Bumper Sensor	shunk 148.30	3 PC	444.90	✓
37 Rear Bumper Lower Clips	30 171 5.50	8 PC	44.00	✓
38 Rear Smart Sensor	811 98.40	1 PC	98.40	X
39 Front Grille	CM 298.20	1 PC	298.20	✓
40 Front Grille Moulding	CM 160.40	1 PC	160.40	✓
41 Front Grille Top Garnish	CM 98.40	1 PC	98.40	✓
42 Front Grille Emblem	171 27.40	1 PC	27.40	✓
43 Front Head Lamp	639.50 x 2 = 1279.00 CM 1,155.80	2 PC	2,311.60	✓
44 Front Headlamp Top Garnish	171 120.80	2 PC	241.60	X
45 Front Headlamp Top Garnish Moulding	171 80.40	2 PC	160.80	X
46 Front Bumper	615.20 70/101 624.20	1 PC	624.20	✓
47 Front Bumper Reinforcement	171 335.80	1 PC	335.80	X
48 Front Bumper Side Retainer	171 22.00	2 PC	44.00	X
			14,619.80	
	Less 20%		2,923.96	11,695.84

86618
20%
6929.44

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : CHINA TAIPING

Estimate No: EST0001082

Date: 31 Dec 2019

Veh Reg No: **SLP5985Z**

Make/Model: HONDA CIVIC

Chassis No: MRHFC5650HT000095

Engine No: R16B22000117

Reg. Date: 06/12/2017

ATTN: Motor Claim Department

Your Ref No: SLP5985Z HONDA CIVIC

Claim Type: Third Party

Accident Date: 27.12.19

Estimate Repair Cost to Vehicle No :SLP5985Z

PAGE:3/3

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Special Net				
49 Rear Number Plate	50.00	1PC	50.00	40
50 Rear Windscreen Gum	80.00	1PC	80.00	X
51 Front Number Plate	50.00	1PC	50.00	40
			180.00	180.00
Labour				
52 Towing	50.00	1PC	50.00	X
53 Panel Beating	2,400.00	1PC	2,400.00	1600
54 Check Wiring	100.00	1 PC	100.00	30
55 Rust Proofing	100.00	1 PC	100.00	90
56 To Remove & Refit Rear Windscreen	160.00	1PC	160.00	X
57 To Remove & Replace Bumper Sensor	80.00	1PC	80.00	50
58 To Spray Painting	1,400.00	1PC	1,400.00	✓
			4,290.00	4,290.00
			Total S\$	16,165.84

TOTAL : SINGAPORE DOLLAR SIXTEEN THOUSAND ONE HUNDRED SIXTY FIVE
AND CENTS EIGHTY FOUR ONLY

3250

For FOCUS AUTO PTE LTD

10179.44

है।

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19022946/USD3N2
Date: 17/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30288419055
Claimant Vehicle No :	SLP5985Z	Insured Vehicle No :	SJQ2389H
Date of Loss:	27/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D206144

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5985Z	Engine No:	R16B22000117
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650HT000095
Reg. Date:	12/06/2017 (Man. Year: 2017)	Odometer:	33192 km
Colour:	Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,875.84	7,009.44	4,866.40	40.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,290.00	3,170.00	1,120.00	26.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,165.84	10,179.44	5,986.40	37.03
Approved Total (Overridden) (S\$)		8,100.00		
(S\$)	16,165.84	8,100.00	8,065.84	49.89
+ GST 7.00/7.00% (S\$)	1,131.61	567.00	564.61	49.89
Nett Amount (S\$)	17,297.45	8,667.00	8,630.45	49.89

INSPECTION

Date of Assignment:	02/01/2020	
Date Inspected:	31/12/2019	Inspected At: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2020)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP5985Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Badly Dented	831.50 FL	*531.20 FL
2	2		*REAR BOOT HINGE	Serviceable	136.00 FL	*- FL
3	1		*REAR BOOT LOCK	Twisted	112.20 FL	*112.20 FL
4	1		*REAR BOOT LOCK CATCH	Not Necessary	41.00 FL	*- FL
5	1		*REAR BOOT RUBBER	Twisted	126.20 FL	*126.20 FL
6	1		*REAR BOOT EMBLEM (CIVIC)	Necessary	28.30 FL	*28.30 FL
7	1		*REAR BOOT EMBLEM (I-VTEC)	Necessary	31.20 FL	*31.20 FL
8	1		*REAR BOOT CENTRE LOGO	Necessary	28.40 FL	*28.40 FL
9	1		*REAR BOOT CENTRE GARNISH	Bent/Cracked	327.40 FL	*327.40 FL
10	1		*REAR BOOT INNER COVER	Deformed/Warped	110.20 FL	*110.20 FL
11	9		*REAR BOOT INNER COVER CLIP	Not Necessary	49.50 FL	*- FL
12	2		*REAR BOOT LAMP	Cracked	538.80 FL	*538.80 FL
13	1		*REAR NUMBER PLATE LAMP	Not Necessary	48.00 FL	*- FL
14	1		*REAR REVERSE CAMERA	Shorted	364.40 FL	*364.40 FL
15	1		*REAR SPARE TYRE TOP COVER BOARD	Torn	246.20 FL	*246.20 FL
16	1		*REAR SPARE TYRE PANEL	Crumpled/Buckled	656.40 FL	*656.40 FL
17	1		*REAR SPARE TYRE SIDE PANEL	Badly Dented	130.40 FL	*130.40 FL
18	1		*REAR SPARE TYRE LOCK SCREW	Serviceable	26.20 FL	*- FL
19	1		*REAR CHASSIS SUB FRAME-LH	Repair	304.20 FL	*- FL
20	2		*REAR FENDER	Repair	1,754.40 FL	*- FL
21	2		*REAR FENDER INNER GARNISH	Not Necessary	492.40 FL	*- FL
22	8		*REAR FENDER INNER GARNISH CLIPSE	Not Necessary	44.00 FL	*- FL
23	2		*REAR FENDER DUST COVER	Not Necessary	280.40 FL	*- FL
24	1		*REAR WINDSCREEN MOULDING	Not Necessary	151.30 FL	*- FL
25	1		*REAR TAIL LAMP PANELS	N/s Bent	192.60 FL	*96.30 FL
26	4		*REAR TAIL LAMP CLIPS	Not Necessary	23.20 FL	*- FL
27	2		*REAR TAIL LAMP LOWER BRACKET	Cracked	36.00 FL	*36.00 FL
28	2		*REAR TAIL LAMP	Cracked	771.00 FL	*614.80 FL
29	1		*REAR END PANEL	Badly Dented	385.70 FL	*385.70 FL
30	1		*REAR END PANEL TOP GARNISH	Twisted	98.40 FL	*98.40 FL
31	1		*REAR BUMPER	Distorted	683.40 FL	*617.20 FL
32	1		*REAR BUMPER REINFORCEMENT	Distorted	246.20 FL	*246.20 FL
33	1		*REAR BUMPER LOWER SPOILER	Distorted	198.20 FL	*145.20 FL
34	2		*REAR BUMPER SIDE COVER	Twisted	180.40 FL	*180.40 FL
35	2		*REAR BUMPER SIDE RETAINER	Bent	56.00 FL	*56.00 FL
36	3		*REAR BUMPER SENSOR	Shorted	444.90 FL	*444.90 FL
37	8		*REAR BUMPER LOWER CLIPS	Necessary	44.00 FL	*30.00 FL
38	1		*REAR SMART SENSOR	Serviceable	98.40 FL	*- FL
39	1		*FRONT GRILLE	Cracked	298.20 FL	*298.20 FL
40	1		*FRONT GRILLE MOULDING	Cracked	160.40 FL	*160.40 FL
41	1		*FRONT GRILLE TOP GARNISH	Cracked	98.40 FL	*98.40 FL
42	1		*FRONT GRILLE EMBLEM	Necessary	27.40 FL	*27.40 FL
43	2		*FRONT HEAD LAMP	Cracked	2,311.60 FL	*1,279.80 FL
44	2		*FRONT HEADLAMP TOP GARNISH	Not Necessary	241.60 FL	*- FL
45	2		*FRONT HEADLAMP TOP GARNISH MOULDING	Not Necessary	160.80 FL	*- FL
46	1		*FRONT BUMPER	Dented/Torn	624.20 FL	*615.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER REINFORCEMENT	Repair	335.80 FL	*- FL
48	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	44.00 FL	*- FL
49	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
50	1		*REAR WINDSCREEN GUM	Not Necessary	80.00 FS	*- FS
51	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	14,799.80	8,741.80
- List Item Discount on L Items 20.00/20.00% (S\$)	2,923.96	1,732.36
Total Parts (S\$)	11,875.84	7,009.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	50.00	0.00
2	PANEL BEATING	New	2,400.00	1,600.00
3	CHECK WIRING	New	100.00	30.00
4	RUST PROOFING	New	100.00	90.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	0.00
6	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
7	TO SPRAY PAINTING	New	1,400.00	1,400.00
Gross Labour Cost (S\$)			4,290.00	3,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >