

ASS. REC. BY:

REF: 3

08/11/1902295/0t d301

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

Munier

From (Person): Subramaniam Arayeshri of

AG

Date/Time: 31/12/19 @ 11:22 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SQF9050G

Insured:

SLW 7199B

at Workshop n/s

San Seng Motor

Tel:

9137 8893

of

Blk 3007 Ubi Road T # 01-404

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:13pm @ 31/12/19

Person Contacted:

Tomy

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate ✓ <u>SQF9050G-NA/INC18019100/h</u>
	<u>SLW 7199B-X</u>
	<u>Submit DAR Report</u>

DOA: 20/10/2018

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SGF9050G  
 at Workshop m/s: Sae Sae  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SGF9050G Yr Regn: 4, 06  
 Type:  Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  
 Truck / Trailer or (A)  
 Make: Toyota Corolla Altis c.c 1598  
 Colour: beige A/C: Insured / Std / NI / NA  
 Sp. Reading: 171707 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MR2537EC107118355  
 Gen. Cond:  Good /  Fair /  Poor /  Burnt  
 Steering:  In order /  Jammed /  Leaked /  Burnt or  
 Brake:  In order /  Jammed /  Leaked /  Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185/70R14  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: A 11K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR • Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: SA 492  
 Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MICT / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 28/12/19 D.O.I. 31/12/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
 No settling. 25-4-2021 SA 195 under

RECEIVED D.B. JAN 2020

Date/Time, File Pass to?  Preli. Report  
 Final Report  
 1) Oli Typist  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format: TP  
 Lump Sum / I.B.I: (\$ - )

Days Of Repair: 7  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: 180  
 Transportation: \_\_\_\_\_  
 Add Fee:  Site Insp (\$ )  S + RS  SI  
 Interview (\$ )  Photos  
 Tech. Invs (\$ )  Others  
 Weekend (\$ )  
 TOTAL 191

PRE-REPAIR INSPECTION REQUEST – SGF9050G vs SLW7199B (OI) on D.O.A.: 28/12/2019

From: Subramaniam, Divyashni  
To: assignments@lkkauto.com, Admin A  
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Hor, Yinrul, Kuru & Co, S  
Sent: 12/31/2019 11:22:06 AM  
Attachments: 

Hi,

Please refer to the enclosed request from **Kuru & Co.**

Claim no : 375556499SG003  
Case Owner : Lee Ming Yao

If you have any queries/concerns, please let us know.  
*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Divyashni Subramaniam  
AIG  
Claim Adjuster II, Singapore FNOL. Claims Operations – Auto  
[Divyashni.Subramaniam@aig.com](mailto:Divyashni.Subramaniam@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Kuru & Co <kurulegal@yahoo.com.sg>  
**Sent:** Tuesday, December 31, 2019 11:06 AM  
**To:** Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>  
**Cc:** Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>  
**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLW7199B AND SGF9050G ON 28/12/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: **MARCUS CHUA: LKK AUTO CONSULTANTS PTE LTD**

Please arrange for your surveyor to survey our client's vehicle at the following address:

**SAN SENG MOTOR ENTERPRISES**  
Blk 3007 Ubi Rd 1  
#01-404  
Singapore 408701  
Contact: Tomy Tan 9137 8893

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards  
Anne

Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

**CONFIDENTIALITY CAUTION:** This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.

On Tuesday, 31 December 2019, 10:44:47 am SGT, Subramaniam, Divyashni <[divyashni.subramaniam@aig.com](mailto:divyashni.subramaniam@aig.com)> wrote:



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-01-06 20:44 CST to read your message. After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**From:** Divyashni.Subramaniam@aig.com  
**To:** kurulegal@yahoo.com.sg  
**Cc:** Andy-SY.Fong@aig.com , Winnie-LW.Fan@aig.com , NoorMariesa.AbuKassim@aig.com , Syazairdina.Azian@aig.com , yokeshi.chan@aig.com , ShengYang.Lim@aig.com , Aashweenjeetkaur.Mithoosingh@aig.com , Theerthan.Parthiban@aig.com , Divyashni.Subramaniam@aig.com , Yinrul.Hor@aig.com  
**Subject:** aigancrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLW7199B AND SGF9050G ON 28/12/2019  
**Date:** Tue, 31 Dec 2019 02:44:40 +0000  
[Without Prejudice](#)

Your Reference : L.19.1584.AT  
Our Reference : 3755556499SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashni Subramaniam  
AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
[Divyashni.Subramaniam@aig.com](mailto:Divyashni.Subramaniam@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Kuru & Co  
**Sent:** Tuesday, December 31, 2019 10:32:23 AM (UTC+08:00) Kuala Lumpur, Singapore  
**To:** Hor, Yinrul  
**Subject:** [EXTERNAL] Our Ref: L.19.1584.AT//Your Ref: SLW 7199B//PRS

This message is from an external sender; be cautious with links and attachments.

Dear Sirs

**ACCIDENT INVOLVING SGF 9050G & SLW 7199B ON 28.12.2019**

**ALONG TANJONG KATONG ROAD TOWARDS CITY PLAZA  
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **Wee Lian Huat**, whose vehicle registration number **SGF 9050G** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards  
Anne

Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

**CONFIDENTIALITY CAUTION:** This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	23-12-2019	<b>Our Ref No.</b> D19008043MFSH
<b>Accident Date</b>	20-12-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC7259P	<b>Third Party Vehicle.</b> SLR3170K
<b>Survey Location</b>	8 KAKI BUKIT AVENUE 4#04-07 PREMIER @ KB	
<b>Contact Person.</b>	TONY	
<b>Contact No.</b>	0/ 97356016	<b>Fax No.</b> 0
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

10:16am @ 31/12/19

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	TONY AUTOMOTIVE PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	RACHELWU LIMEI	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Bootlid           suc —  
 Bootlid emblem x4   rec —  
 Bootlid reflector x2 - scratched —  
 Bootlid outer garnish - cro —  
 Bootlid inner lock   - twisted —  
 Bootlid weatherstrip - twisted —  
 Rear bumper       - 0.5 —  
 Rear bumper bracket - sel —  
 Rear bumper clips - rec —  
 Tail lamps x2       - cracked —  
 Tail lamp apron panel - sel —  
 Tail lamp apron panel rivet - rec —  
 Tail lamp housing panel - Repair X  
 Rear end panel       - 0.9 —  
 Rear end panel top garnish - twisted —  
 Rear floor panel top board - torn —  
 Rear reverse sensor - scratched —  
 Rear licence plate - scratched —

7/1/07

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/12/2019 15:12
Date Of Accident	28/12/2019 23:20
Exact Location Of Accident	TANJONG KATONG ROAD TOWARDS CITYPLAZA
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGF9050G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WEE LIAN HUAT
NRIC No	SXXXX811E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91099068
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5079800413-03
Cover Note Number	

### Driver

Name of Driver	WEE LIAN HUAT
NRIC No	SXXXX811E
Date Of Birth	24/11/1967
Occupation	INDOOR
Date Of Driving Pass	13/08/1990
Driving Experience	29 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91099068
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	NOEMAIL

Address	BLK 450D TAMPINES STREET 42 #04-416
Postcode	524450
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW7199B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

Refer police report

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 28th Dec 10. 22pm  
at tau jang katong Rd when input  
car slowly moving, followed  
suddenly at behind Bang  
on my car boat "

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No.:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 811E

### Vehicle Details

Vehicle No.: SGF9050G

Vehicle to be Exported: No

Intended Deregistration Date: 31 Dec 2019

Vehicle Make: TOYOTA

Vehicle Model: COROLLA 1.6

Primary Colour: Gold

Manufacturing Year: 2006

Engine No.: 3ZZ4561844

Chassis No.: MR053ZEC107118355

Maximum Power Output: 81.0 kW (108 bhp)

Open Market Value: \$15,950.00

Original Registration Date: 26 Apr 2006

First Registration Date: 26 Apr 2006

Transfer Count: 3

Actual ARF Paid: \$17,545.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 25 Apr 2021

COE Category: E - Open Category

COE Period(Years): 5

PQP Paid: \$23,039.00

COE Rebate Amount: \$6,079.00

**Total Rebate Amount: \$6,079.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Dec 2019

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources







Advanced Search

Home » Used Cars » Hong Heng Co. Pte Ltd » Toyota Corolla Altis 1.6A (COE till 11/2021)

## Toyota Corolla Altis 1.6A (COE till 11/2021)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

<b>Price</b>	\$14,800		
<b>Depreciation</b>	\$7,720 /yr	<b>Reg Date</b>	15-Dec-2006 (1yr 10mths 30days COE left)
<b>Mileage</b>	N.A.	<b>Manufactured</b>	2006
<b>Road Tax</b>	\$965 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b>	\$9,904 as of today (change)	<b>OMV</b>	\$15,355
<b>COE</b>	\$25,821	<b>ARF</b>	\$16,891
<b>Engine Cap</b>	1,598 cc	<b>Power</b>	81.0 kW (108 bhp)
<b>Curb Weight</b>	1,115 kg	<b>No. of Owners</b>	2
<b>Type of Vehicle</b>	Mid-Sized Sedan		

## Features

Fuel Efficient, Powerful 1.6L 16 Valves DOHC VVT-i Engine, Smooth Auto Transmission With ECT, Dual SRS Airbags, ABS, Digital Climate Aircon Controls. View specs of the Toyota Corolla Altis (2000-2007)

## Description

Good For Short Term Use, Cheaper Than Rent Car.

## Category

COE Car

## Status

Available

## Resources



## Car Valuation - Free

Find out the market value of your existing car for free. Get started



## Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

## Seller Information

## Hong Heng Co. Pte Ltd

7 vehicles for sale. 7 sold in past 3 mths

33 Sembawang Road #01-01  
Hong Heng Gardens  
Tel: 64521112  
Search cars nearby

Mr Ho  
David Ang

96563239  
92376357

Posted on: 26-Dec-2019 | Last Updated on: 30-Dec-2019

## Upfront Payment

» more Financial Info

<b>Transfer Fee</b>	\$25	
<b>Down Payment</b>	\$4,440 (change)	Maximum 70% Loan
<b>1st Instalment</b>	\$503	Based on 3.75% interest rate

Compare

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Dec 2019 <a href="#">Edit Reg</a>		31 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	-	
Vehicle Reg. No.:	<b>SGF9050G</b>	Date of Loss: 28/12/2019 00:00 - :59 [164 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 3755556499SG</b>	Policy/Cover Note No.: (Comprehensive) Coverage: 28/02/2019 - 27/02/2020
Vehicle Reg. No. (Insured):	<b>SLW7199B</b>	Policy No. (Claimant):
		Excess:
Repairer:	<b>San Seng Motor Enter (HQ)</b> BLK 3006 UBI ROAD 1 #01-374 SINGAPORE 408700, 408700 Ubi - Tel:	
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000	
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 10/01/2020]	
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AIG_SG (02/01/2020): Request to upload TP GIA Report</li> </ul>		
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>
<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>
<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>
<b>Done?</b>	No results.	

### Claim Documents

**\*SGF9050G (3755556499SG)  
[SLW7199B]**

TP

Dec 28 2019 12:00AM

[-]

San Seng Motor Enter

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b>	<a href="#">View in Browser</a> <input type="button" value="v"/>
<b>Photos/Images</b>						3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
2	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
3	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
4	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
5	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
6	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
7	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
8	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
9	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
10	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
11	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
12	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
13	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
14	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
15	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
16	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
17	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
18	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
19	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
20	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
21	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
22	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
23	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
24	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
25	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
26	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
27	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
28	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
29	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
30	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
31	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
32	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
33	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
34	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
35	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
36	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
37	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
38	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
39	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
40	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
41	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
42	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		
43	01/01/20 07:17	General View		Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
45	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
46	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
47	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
48	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
49	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
50	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
51	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
52	01/01/20 07:17	Odometer Reading		<input checked="" type="checkbox"/>
53	01/01/20 07:17	General View		<input checked="" type="checkbox"/>
54	01/01/20 07:18	Chassis Number		<input checked="" type="checkbox"/>
55	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
56	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
57	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
58	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
59	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
60	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
61	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
62	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
63	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
64	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
65	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
66	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
67	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
68	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
69	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
70	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
71	02/01/20 16:28	Reinspection Photo		<input checked="" type="checkbox"/>
72	02/01/20 16:29	Reinspection Photo		<input checked="" type="checkbox"/>
73	02/01/20 16:29	Reinspection Photo		<input checked="" type="checkbox"/>
74	02/01/20 16:29	Reinspection Photo		<input checked="" type="checkbox"/>
75	02/01/20 16:29	Reinspection Photo		<input checked="" type="checkbox"/>
76	02/01/20 16:29	Reinspection Photo		<input checked="" type="checkbox"/>
77	02/01/20 16:29	Reinspection Photo		<input checked="" type="checkbox"/>
78	07/01/20 16:35	After Repair Photo		<input checked="" type="checkbox"/>
79	07/01/20 16:35	After Repair Photo		<input checked="" type="checkbox"/>
80	07/01/20 16:35	After Repair Photo		<input checked="" type="checkbox"/>
81	07/01/20 16:35	After Repair Photo		<input checked="" type="checkbox"/>
82	07/01/20 16:35	After Repair Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/01/20 16:05	OI GIA REPORT		<input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG19022951/UTD3E2

**Date:** 09/01/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**

**Vehicle No :** SGF9050G

**Insured Vehicle No :** SLW7199B

Date of Loss: 28/12/2019

Nature of Claim: TP

Claim No: 3755556499SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGF9050G**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4561844

Reg. Date: 26/04/2006 (Man. Year: 2006)

Chassis No: MR053ZEC107118355

Colour: Beige

Odometer: 171707 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 31/12/2019

Date Inspected: 31/12/2019 Inspected At:

BLK 3006 UBI ROAD 1 #01-404

Repairer : San Seng Motor Enter (HQ)

Estimated Period of Repair: 7.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BOOTLID	Buckled	0.00 F	*- F	
2	4		*BOOTLID EMBLEM	Necessary	0.00 F	*- F	
3	2		*BOOTLID REFLECTOR	Scratched / Cracked	0.00 F	*- F	
4	1		*BOOTLID OUTER GARNISH	Cracked	0.00 F	*- F	
5	1		*BOOTLID INNER LOCK	Twisted	0.00 F	*- F	
6	1		*BOOTLID WEATHERSTRIP	Twisted	0.00 F	*- F	
7	1		*REAR BUMPER	Distorted	0.00 F	*- F	
8	1		*REAR BUMPER BRACKET	Bent	0.00 F	*- F	
9	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
10	2		*TAILLAMPS	Cracked	0.00 F	*- F	
11	1		*TAILLAMP APRON PANEL	Bent	0.00 F	*- F	
12	1		*TAILLAMP APRON PANEL RIVET	Necessary	0.00 F	*- F	
13	1		*TAILLAMP HOUSING PANEL	Repair	0.00 F	*- F	
14	1		*REAR END PANEL	Dented	0.00 F	*- F	
15	1		*REAR END PANEL TOP GARNISH	Twisted	0.00 F	*- F	
16	1		*REAR FLOOR PANEL TOP BOARD	Torn	0.00 F	*- F	
17	1		*REAR REVERSE SENSOR	Shorted	0.00 F	*- F	
18	1		*REAR LICENCE PLATE	Scratched	0.00 F	*- F	
					<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >