



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19022970/Gpa3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:KITTY

Date : 07-10-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 7663B	Veh. Inspected	SLS 5747D
Policy No.	GA304023/1	Coverage (\$)	0.00
Claim No.	S9M02BNX	Excess (\$)	0.00
Assign From		Assign Date	31/12/2019

### 2. Vehicle Particulars & Condition

Make & Model	NISSAN X-TRAIL 2.0	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JN1JANT32Z0010227	Colour	WHITE
Odometer	46388	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R19	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R19	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R19	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R19	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	28/12/2019	Inspection Date	02/01/2020
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------