

ASSIGNMENT

Surveyor:

MARCUS

DOI:

31/12/2019

Date / Time:

31/12/2019

Registered in Meritum:

Pre-assign / CCU / FTE



Insured Vehicle No. GR 9028J

Claim No. : GNM 20 D 200009 / GR 9028J / CBS

Name of Insured : Koh Hock Ann

Policy No. :

Insured Tel No. : HP: _____

Make / Model :

Excess Sec II :SS : D.O.A. : 31/12/2019

Place of Accident :

Is driver the owner? (YES) NO) Nature of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age :

Insured Liability : % Final ? Yes / No

Driver Tel No. :

(V/L: YES / NO)

SMA 7720A



INSRS: WSP: FASTECH
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	SMA 7720A - X	GR 9028J - X	STAGE	DATE / PIC
			Non-Reporting Itr (1st):	
			Non-Reporting Itr (2nd):	
			Non-Reporting Itr (Final):	
			Notification Itr (if non-pickup):	
			Call OI:	
			After call Itr to OI:	05/01/2020 - VIC
			Documentation Check List:	Handler Typist
			Notification Itr (if non-pickup)	<input type="checkbox"/>
			After call Itr to OI:	<input checked="" type="checkbox"/>
			Authorisation To Act:	<input checked="" type="checkbox"/>
			Release Voucher:	<input checked="" type="checkbox"/>
			Final Repair Bill:	<input checked="" type="checkbox"/>
			Car Rental Invoice:	<input checked="" type="checkbox"/>
			Towing Invoice:	<input type="checkbox"/>
			LTA / GIA:	<input type="checkbox"/>
			Medical Bill:	<input type="checkbox"/>
			PIR:	<input type="checkbox"/>
			Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
			LOD:	<input checked="" type="checkbox"/>
			Payment Breakdown Form:	<input type="checkbox"/>
			Post-Repair Photos:	<input type="checkbox"/>
			Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 05/01/2020 Sent By: VIC

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: L/G SS 4,250.00 (4 days) Reduction: FA % Email Call

FINAL SETTLEMENT Date/Time: 12/01/2020 Confirm with: SKOON Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL If NO or B 28, Ass. Lia: (OI BOLA RED LIGHT) TP VIDEO IN

Repair Cost: (w/gov) SS 4,547.00

Loss of Rental (LOR): SS 200.00 (2 days) x \$100.00

Loss of Use (LOU): SS - (5 x days)

Loss of Income (LOI): SS - (5 x days)

LOR only LOU only LOR + LOU LOR + LOI (Tick only one)

GIA/LTA Search: SS 2.00

Medical: SS -

Disbursement: SS - (e.g. Tow/Independent)

Legal Cost: SS -

Total: SS 4,749.50 Global Sum SS: -

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 4,749.50 Name 1: FASTECH AUTO PTB LTD

Payee 2: (Strike if N.A.) SS - Name 2: -

Payee 3: (Strike if N.A.) SS - Name 3: -

COPY SENT

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SMA7720A**
 at Workshop m/s: **H.**
 of: _____
 Insured: **GR 9028Y**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SMA7720A** Yr Regn: **1 09**
 Type: **M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**
 Truck / Trailer or **Q1**
 Make: **Honda Fit** c.c. **1339**
 Colour: **Grey** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **226699** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **GE61158269**
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: **Good / Jammed / Leaked / Burnt or**
 Brake: **Inorder / Jammed / Leaked / Burnt or**
 Modi: **Nil / S/Rim / STD A/Rim or**
 Tyre Size: **F: 205/50 R16**
R: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **38k.**
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **4** days Res.: Yes or No
 Lum Sum: **20** % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS **L1A29637**
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **FALKEN**
 Front **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **31/12/19** D.O.I. **31/12/19**
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
LH O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
31-8-2018 **Dys Sub.**
8/1/20 **4/5 @ 4250 contact with Acc.**
CRSD: 11,961.60 (74%)

Date/Time. File Pass to? : Prell. Report
 : Final Report
 Days Of Repair: _____
 Resurvey No. of Trip: _____ Survey Fee: _____
 Date/Time. File Return to? _____ Transportation: _____
 2) _____
 Report Format : _____
 Lump Sum / I.B.I: (\$) _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)
 Others: _____
 TOTAL _____



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM20D200009/GR9028J/CBS
Our ref: CC6/CTI20000001/Uha3

Date: 05.02.2020

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SMA 7720A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31.12.2019 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	16,211.60
Revised Estimate Amount	: S\$	5,320.80
"Check" Items Amount	: S\$	-
Market Value	: S\$	38,000.00
LTA Reimbursement Value	: S\$	29,637.00
Nett Value	: S\$	8,363.00

Description of Damage:

The vehicle sustained damages at the Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



honda fit Price Range Depreciation 2009 Vehicle Type Submit Advanced Search

Home > Used Cars > Direct Owners > Honda Fit 1.3A G (COE till 02/2029)

Honda Fit 1.3A G (COE till 02/2029)

Overview Financial Insurance Accessories Similar Research Photos Map **DIRECT OWNER**

Price	\$39,999	Reg Date	09-Feb-2009 (9yrs 1mth 8days COE left)
Depreciation	\$4,390 /yr	Manufactured	2008
Mileage	160,000 km (14.7k /yr)	Transmission	Auto
Road Tax	\$590 /yr	OMV	\$13,021
Dereg Value	\$23,450 as of today (change)	ARF	\$13,021
COE	\$25,727	Power	73.0 kW (97 bhp)
Engine Cap	1,339 cc	No. of Owners	4
Curb Weight	1,010 kg		
Type of Vehicle	Hatchback		

Features
View specs of the Honda Fit (2008-2013)

Accessories
New Aircon Compressor And Coil. New Set Of Michelin Tyres And Sports Rim. Reverse Sensor And Camera Installed. Nicely Tinted Windows.

Description
Selling This Car To Upgrade. Car Is Still In A Very Good Condition. Very Spacious Boot. Aircon Is Very Cooling! Call For A Test Drive!

Category
COE Car, Direct Owner Sale

Status
Available

Resources

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Car Valuation - Free
Find out the market value of your existing car for free. Get started

Posted on: 14-Dec-2019 | Last Updated on: 29-Dec-2019

Upfront Payment [+ more Financial info](#)

Transfer Fee \$25



Shortlist Compare Add note
Report Error More Actions

Seller Information

Contact Person(s) Agnes Koh
Contact No. 91594901
Enquiry Contact Seller

ESSENTIAL TRANSACTION FORMS

- Indemnity form
- Receipt
- Ownership Transfer
- Sales agreement
- Hand-over form



GET HELP WITH PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	200I
Vehicle Details	
Vehicle No.:	SMA7720A
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A4173083
Chassis No.:	GE61158269
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,825.00
Original Registration Date:	22 Jan 2009
First Registration Date:	22 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$14,825.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$29,637.00
Total Rebate Amount:	\$29,637.00

The information contained herein is correct as at 31 Dec 2019

OK

Mei Kwan (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 6 January, 2020 9:32 AM
To: Mei Kwan (LKKAuto); Vic (LKKAuto)
Subject: RE: OUR REF: SNM20D200009/GR9028J/CBS - Accident Involving GR9028J (OI : CTI - TBA) AND SMA7720A (TP : LKK REF - CC6/CTI20000001/Uha3) on 31/12/2019
Attachments: INSURED REPORT.PDF
Categories: HMK

Dear Sir,

Pls find insured report.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI
Sent: Friday, January 3, 2020 11:43 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Mei Kwan (LKKAuto <Meikwan@lkkauto.com>); Vic (LKKAuto <vicalpeh@lkkauto.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: SNM20D200009/GR9028J/CBS - Accident Involving GR9028J (OI : CTI - TBA) AND SMA7720A (TP : LKK REF - CC6/CTI20000001/Uha3) on 31/12/2019

Dear Boon Sen,

Please revert LKK.

Note : officer in charge - Boon Sen 63896171.

***** Kindly quote our reference number when replying.**

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	200I
Vehicle Details	
Vehicle No.:	SMA7720A
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A4173083
Chassis No.:	GE61158269
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,825.00
Original Registration Date:	22 Jan 2009
First Registration Date:	22 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$14,825.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$29,637.00
Total Rebate Amount:	\$29,637.00

The information contained herein is correct as at 31 Dec 2019

OK

FASTECH AUTO PTE LTD
 BLK 1 KAKI BUKIT AVE 6
 #01-46/48/50 AUTOBAY
 SINGAPORE 417883

Not Aboard
 31/12/18
 2/5 @ 4250
 4 days

SMA 7720A

1PC	BONNET		2	\$866.20	X
1PC	BONNET LOCK		11	\$199.20	X
1PC	FRONT GRILLE (SPORT)	380	one	\$388.50	✓
1PC	FRONT GRILLE EMBLEM	50	net	\$60.00	✓
1PC	FRONT BUMPER	545.20	20	\$721.30	✓
1PC	FRONT BUMPER CENTRE GRILLE	145.30	To.1	\$188.20	—
2PCS	FRONT BUMPER SIDE RETAINERS	@\$35.00	2nd	\$70.00	—
1SET	FRONT BUMPER CLIPS		All	\$38.00	—
1PC	FRONT BUMPER REINFORCEMENT	264.20	3rd	\$315.00	—
1PC	FRONT BUMPER FOG LAMP O/S	366.50	one	\$380.00	—
1PC	FRONT BUMPER LED LAMP O/S		11	\$285.00	X
1PC	FRONT FENDER O/S		2	\$566.20	X
1PC	FRONT FENDER INNER SHIELD O/S		11	\$182.30	X
1SET	FRONT FENDER INNER SHIELD CLIPS O/S		11	\$38.00	X
2PCS	HEADLAMPS @ \$950.00	627 x 2 = 1254	one	\$1,900.00	—
1PC	FRONT SUPPORT PANEL		2	\$545.00	X
1PC	AIR CON CONDENSER	762.80	half/2nd	\$1,428.20	✓
1PC	RADIATOR		11	\$1,665.30	X
1PC	RADIATOR FAN ASSY		11	\$450.00	X
1PC	WIPER WASHER TANK		11	\$185.00	X
1PC	OIL COOLER		10	\$850.00	X
				\$11,321.60	
				40	

(202)

S.NETT					
1PC	FRONT BUMPER SPOILER		Dis	\$1,280.00	600
1PC	FRONT LICENCE PLATE W/HOLDER		one	\$50.00	40
1BOL	AIR CON OIL		net	\$50.00	30
1BOL	RADIATOR COOLANT		11	\$50.00	X

TO CHECK WIRING		\$80.00	30
TO SPRAY RUST PROOFING		100.00	X
TO REFILL AIR CON GAS		120.00	100
TO MOUNT VEHICLE ON CAR O- LINER		380.00	X
LABOUR FOR PANEL BEATING & REPLACING PARTS		1,280.00	520
TO PUTTY & SPRAY PAINTING		1,500.00	900
	TOTAL	\$16,211.60	40

LCS Auto Consultants hence notify the Repairer of the following:

- To carry out before/after spray painting
- To display damaged part(s) every recovery
- Parts prices are subject to confirmation
- This agreement is on a "Without Prejudice" basis
- No litigation/claim(s) is allowed
- Secondary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P- 3876
 200
 P- 3102.80
 S.N- 67020
 L- 1520
 53208



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20000001/Uha3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 02-03-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GR 9028J	Veh. Inspected	SMA 7720A
Policy No.	DMCVSN3061031901	Coverage (\$)	0.00
Claim No.	SNM20D200009	Excess (\$)	0.00
Assign From		Assign Date	31/12/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT (A)	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GE61158269	Colour	GREY
Odometer	226699	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	FALKEN	6 mm
L/H Front Tyre	205/50 R16	FALKEN	6 mm
R/H Rear Tyre	205/50 R16	FALKEN	6 mm
L/H Rear Tyre	205/50 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/12/2019	Inspection Date	31/12/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 7720A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	TO REPAIR SEE LABOUR	866.20	-
1	BONNET LOCK	NOT NECESSARY	199.20	-
1	FRONT GRILLE (SPORT)	CRACKED	388.50	380.00
1	FRONT GRILLE EMBLEM	NECESSARY	60.00	50.00
1	FRONT BUMPER	DISTORTED	721.30	545.20
1	FRONT BUMPER CENTRE GRILLE	TORN	188.20	145.30
2	FRONT BUMPER SIDE RETAINERS @\$35.00	BENT	70.00	70.00
1	SET FRONT BUMPER CLIPS	NECESSARY	38.00	38.00
1	FRONT BUMPER REINFORCEMENT	BENT	315.00	264.20
1	FRONT BUMPER FOG LAMP O/S	CRACKED	380.00	366.50
1	FRONT BUMPER LED LAMP O/S	NOT NECESSARY	285.00	-
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	566.20	-
1	FRONT FENDER INNER SHIELD O/S	NOT NECESSARY	182.30	-
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NOT NECESSARY	38.00	-
2	HEADLAMPS @\$950.00	CRACKED	1,900.00	1,254.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	545.00	-
1	AIR CON CONDENSER	BENT / PUNCTURE	1,428.20	762.80
1	RADIATOR	NOT NECESSARY	1,665.30	-
1	RADIATOR FAN ASSY	NOT NECESSARY	450.00	-
1	WIPER WASHER TANK	NOT NECESSARY	185.00	-
1	OIL COOLER	NOT NECESSARY	850.00	-
	LESS 20% DISCOUNT		-	-775.20
			11,321.40	3,100.80
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER SPOILER (SN)	DISTORTED	1,280.00	600.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	CRACKED	50.00	40.00
1	BOL AIR CON OIL (SN)	NECESSARY	50.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOL RADIATOR COOLANT (SN)	NOT NECESSARY	50.00	-
			1,430.00	670.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	TO REFILL AIR CON GAS.		120.00	100.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF BONNET, FRONT FENDER O/S AND FRONT SUPPORT PANEL.		1,280.00	520.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			3,460.00	1,550.00
	GRAND TOTAL		16,211.40	5,320.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,250.00

Report Ref No. CC6/CTI20000001/Uha3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.