

22/03/2002

ASS. REC. BY:

REF: CS/EG12000010 / Uqf324 Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Jacelyn Foo of Engo Date/Time: 31.12.11 12.11p.m

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FX 8106D Insured: GBD 127 Z

at Workshop m/s Eofia Motor Trading Tel: 67527740

of 1 Kaki Bukit Ave 6 #02-62

Policy No: Claim No: CDMC 19002380

Sum Insured: Excess:

Make of Veh: D.O.A. 15.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp"

H.O.D. Endorsement:

Date/Time: 21.2.2019 9.54a.m Person Contacted: Ah Kok Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FX 8106D - NA/DAI 1700 3953/14 D.O.A - 26/01/2017
	GBD 127Z - X
03/01/2019	9.46am revised to Jacelyn Foo via Maimmen.

Maimmen

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

MTA 739

Veh No:

FX 8106D

Yr Regn:

3 / 04

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki FD110X c.c 110

Colour

red

A/C:

Insured / Std / NI / NA

Sp. Reading

51224

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

BE49D TH304235

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

B0/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

15/12/19

D.O.I.

2/1/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

loc 31-1-2024 4 yrs. Insh.

re + 261

17/1/20 4/5 @ 1400 Confirmed with hisbe. (Red 22849, 670/0)

RECEIVED 17 JAN 2020

Date/Time. File Pass to?

☐

: Preli. Report

1) 17/1/2024

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

990

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS. SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

1400)

TOTAL

261

Nivitha (LKK Auto)

From: Jacelyn Foo <jacelyn.foo@ergo.com.sg>
Sent: Tuesday, 31 December 2019 12:11 PM
To: admin-d@lkkauto.com; admin-a@lkkauto.com; Meikwan@lkkauto.com
Cc: erofia@singnet.com.sg; Phoebe Xie
Subject: RE: ERGO Claims Ref: CDMCG19002380 | Request pre-repair inspection for accident involving GBD127Z and FX8106D on 15 December 2019
Attachments: FX8106D - DOC.PDF

Data Classification: Confidential, C3

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest Regards,
Jacelyn Foo
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9258
jacelyn.foo@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Erofia Motor - LeeLee Tan [mailto:erofia@singnet.com.sg]
Sent: Tuesday, December 31, 2019 12:07 PM
To: Jacelyn Foo

Subject: RE: ERGO Claims Ref: CDMCG19002380 | Request pre-repair inspection for accident involving GBD127Z and FX8106D on 15 December 2019

Dear Jacelyn

Kindly arrange LKK Auto Consultants Pte Ltd

Thank you

Regards

LeeLee Tan

Erofia Motor Trading Pte Ltd

Tel: 67527740

Fax: 67528669

From: Jacelyn Foo [mailto:jacelyn.foo@ergo.com.sg]

Sent: 31 December, 2019 11:50 AM

To: Erofia Motor - LeeLee Tan <erofia@singnet.com.sg>

Cc: Phoebe Xie <phoebe.xie@ergo.com.sg>

Subject: FW: ERGO Claims Ref: CDMCG19002380 | Request pre-repair inspection for accident involving GBD127Z and FX8106D on 15 December 2019

Data Classification: Confidential, C3

Dear LeeLee Tan,

Please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Warmest Regards,

Jacelyn Foo

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five

Singapore 038985

DID: +65 6829 9258

jacelyn.foo@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Erofia Motor - LeeLee Tan [<mailto:erofia@singnet.com.sg>]

Sent: Monday, December 30, 2019 11:22 AM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Subject: Request pre-repair inspection for accident involving GBD127Z and FX8106D on 15 December 2019

Dear Sir

With reference to the above mentioned, attached necessary documents for your arrangement of pre-repair inspection for our client's

Motorcycle No: FX8106D

Workshop:

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67527740

Thank you

Regards

LeeLee Tan

Erofia Motor Trading Pte Ltd

Tel: 67527740

Fax: 67528669

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 03 Jan 2020

Preliminary Advice

Insured Vehicle No	: GBD127Z	Accident Date	: 15/12/2019
TP Vehicle No	: FX8106D	Assignment Date	: 02/01/2020
Make	: SUZUKI FD110XCSDU	Est. Duration of Repair	: 4.00
Date of Inspection	: 02/01/2020		
Inspection At	: EROFIA MOTOR TRADING PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,249.00
Revised Amount	:S\$	1,807.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,807.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :


> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	791D
Vehicle Details	
Vehicle No.:	FX8106D
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	SUZUKI
Vehicle Model:	FD110XCSDU
Primary Colour:	Red
Manufacturing Year:	2004
Engine No.:	E425TH304235
Chassis No.:	BE49DTH304235
Maximum Power Output:	-
Open Market Value:	\$1,292.00
Original Registration Date:	08 Mar 2004
First Registration Date:	08 Mar 2004
Transfer Count:	2
Actual ARF Paid:	\$194.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,797.00
COE Rebate Amount:	\$739.00
Total Rebate Amount:	\$739.00

The information contained herein is correct as at 02 Jan 2020

OK



100+ Designs, From S\$599

Free Delivery & Quick Gate Installation - Smart Digital Lock Option Available

Bike model

Honda Wave

Type Of Vehicle

Any

Price From

Any

Price To

Any

Class


Any

MORE SEARCH OPTIONS

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Honda Wave 125 (/listing/usedbike/honda-honda-wave-125/15477/)



SGD\$8800

Reg : 26/12/2019

Type: Cubs

125cc

Pre Reg Brand New Wave 125. FY Plate. Double Double Number. Downpayment Fr \$500 Exclude Insurance.

Posted on : 28/12/2019

★ PAID AD

★ DEALER AD

COMARE

DETAILS (/LISTING/USEDBIKE/HONDA-HONDA-WAVE-125/15477/)

(/listing/usedbike/honda-honda-wave-125/15477/)


Number Plates for Sale (/listing/motorcycle/golden-number-plate-for-sale/)

Installment Calculator (/installment_calculator/)

Instant Insurance Quote (/motorcycle-insurance/landing/)

Bounty (/bounty/)

Honda Wave 125 (/listing/usedbike/honda-honda-wave-125/8880/)



SGD\$6000

Reg : 20/02/2002

Type: Cubs

125cc

27314km

Eligible For Nea Cash Rebate Of \$3500 Upon De-Registration. Honda Wave 125 For Sale. Welcome Trade In. Loan Available. Ambra Enterprises Is Located At Block 5034 Ang Mo Kio Industrial Park 2 #0...

Eligible For NEA Cash Rebate Of \$3500

Posted on : 29/11/2019

★ PAID AD

★ DEALER AD

COMARE

DETAILS (/LISTING/USEDBIKE/HONDA-HONDA-WAVE-125/8880/)

(/listing/usedbike/honda-honda-wave-125/8880/)


COE RESULTS

Rd 2, 18 Dec 2019

COE Bidding of Motorcycles

CAT D \$3658

Honda Wave 125 (/listing/usedbike/honda-honda-wave-125/15234/)



SGD\$5000

Reg : 04/12/2002

Type: Cubs

125cc

60000km

NEA Rebate Eligible. Will Get Back 3.5K Upon Scrap. Non Urgent Sale. Brand New Maxxis Tyres. Slight Neg.

Posted on : 07/12/2019

★ DIRECT SELLER


COMARE

DETAILS (/LISTING/USEDBIKE/HONDA-HONDA-WAVE-125/15234/)

(/listing/usedbike/honda-honda-wave-125/15234/)

ROUND-SHAPED LED HEADLIGHT

Honda Wave 125 (/listing/usedbike/honda-honda-wave-125/15304/)



-

Reg : 14/12/2009

Type: Cubs

125cc

69000km

Honda Wave 125 For Sale. Welcome Trade In. Loan Available. Ambra Enterprises Is Located At Block 5034 Ang Mo Kio Industrial Park 2 #01-327.

Posted on : 14/12/2019

★ PAID AD

★ DEALER AD

COMARE


DETAILS (/LISTING/USEDBIKE/HONDA-HONDA-WAVE-125/15304/)

(/listing/usedbike/honda-honda-wave-125/15304/)

Like Page

Learn More

Honda Wave 125 (/listing/usedbike/honda-honda-wave-125/15076/)



-

Reg : 17/08/2009

Type: Cubs

125cc

Honda Wave 125. COE Till Aug 2024. Good Condition. Loan Available, Welcome Trade In. Come Visit Us At Sin Boon Motor. Interested Buyers Are Welcome To Negotiate.

Posted on : 21/11/2019

★ PAID AD

★ DEALER AD


COMARE

DETAILS (/LISTING/USEDBIKE/HONDA-HONDA-WAVE-125/15076/)

(/listing/usedbike/honda-honda-wave-125/15076/)

Be the first of your friends to like this

CALL & ENQUIRE NOW !



1108 & 1110 Serangoon Road

Singapore 328200

Tel: 62939989

Whatsapp: 90224811

源和昌貿易公司

GUAN HOE CHEONG TRADING CO.

https://www.sgbikemart.com.sg/listing/usedbikes/listing/?bike_model=Honda+Wave+&bike_type=&pri... 02-Jan-20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2019 17:23
Date Of Accident	15/12/2019 05:20
Exact Location Of Accident	ALONG PAN ISLAND EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FX8106D
Insured/Policyholder	
Name Of Registered Owner	LIM KOOK SIT
NRIC No	SXXXX791D
Email Address	LIMETHANOL@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98789587
Alternative Phone No	OTHERS-98789587

Vehicle Particulars

Manufacturer	SUZUKI
Model	FD110XCSDU
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5022276183-12
Cover Note Number	

Driver

Name of Driver	LIM KOOK SIT
NRIC No	SXXXX791D
Date Of Birth	17/02/1948
Occupation	OUTDOOR
Date Of Driving Pass	06/09/1975
Driving Experience	44 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98789587
Fax Number	
Contact Number	OTHERS-98789587
Email Address	LIMETHANOL@YAHOO.COM

Address	BLK 704 #11-3602 BEDOK RESERVOIR ROAD
Postcode	470704
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20191226/2049;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD127Z
Vehicle Make/Model/Colour	NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LIM KOOK SIT
Approximate Age	71
Injuries Sustain	
Injured person in which vehicle?	FX8106D
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 704 #11-3602 BEDOK RESERVOIR ROAD
Postcode	470704

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the nature of the accident and speed as the cause of accident.
2. The form must be completed by the Driver/Injured Person or the Authorized Officer.
3. Information provided must be accurate and complete. Any false or misrepresentation, including that of any third party, may result in that company's input and policy liability.
4. The driver's acceptance of the form by means of a stamp or signature shall be taken as an admission of policy liability and the person's insurance company.
5. Any false or untrue may be referred to the Police for investigation.
6. The report will be forwarded by the members of the Road Traffic Management Bureau established by the General Insurance Association of Singapore (GIAS) for administrative purposes of this report. It will not be made available to any individual or by interested parties.
7. By the accident on the report, the driver, the motor vehicle, the driver's license, the report at the scene and the driver's the report being made available to the police.

Consent under the Personal Data Protection Act (PDPA)

I understand, enter a stamp, agree and consent to:

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIAS) may be permitted to collect, use, disclose and/or process my personal data (personal information) set out in this form, and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Information Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s):
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) managing the claims under my claim;
 - (iii) carrying out my claim dealing with my instructions or responding to any enquiry by me;
 - (iv) administering my claims including the making of correspondence, statements, reports, records or reports to me, which could involve disclosure of certain personal data (collective to being about delivery of the same personal data on the external context of collected/not collected) and/or;
 - (v) carrying out my application to law administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIAS to their third party (or its provider) or agent(s) (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to complete claims in order for the purpose of their detection, investigation and management in present and all future claims.
- (e) the information so collected under the above may be shared, disclosed:
 - (i) to all insurers and/or other third parties that assist in settling, investigating, handling or managing claims, negotiations, law enforcement and government agencies or authorities required for the purposes stated; or
 - (ii) for using, using with equipment under the regulations, law and/or consent.

For the driver's signature
Date & Time

For the signature
of the person who is the driver
Date & Time

For the signature
of the person who is the driver
Date & Time

26 DEC 2019



**SINGAPORE
POLICE FORCE**



T/20191226/2049

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20191226/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/12/2019 12:05	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: LIM KOOK SIT			Address: APT BLK 704 BEDOK RESERVOIR ROAD #11-3602 SINGAPORE 470704		
ID Type / ID No.: NRIC NO / S2568791D			Contact No.: Home/Office: Mobile: 98789587		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 71	Date of Birth: 17/02/1948	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: Photogravure cameraman			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/12/2019 05:20	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 PAYA LEBAR ROAD PAN-ISLAND EXPRESSWAY TOWARDS CHANGI				
Weather: Raining		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FX8106D	Motorcycle	SUZUKI	FD110XCSD U	Red		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FX8106D	NTUC Income Insurance Co-Operative Limited	5022276183-12	22/09/2019	21/09/2020

END 1277



SINGAPORE
POLICE FORCE



T/20191226/2049

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20191226/2049

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	LIM KOOK SIT	ID No.	S2568791D
Related Vehicle	FX8106D (Motorcycle)	Contact No.	98789587
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	15/12/2019	Date Discharge	19/12/2019
No. of Days granted Medical Leave	36	Degree of Injury	Serious

Brief Details.

ON THE MENTIONED DATE TIME AND LOCATION,

I WAS RIDING ON THE 3RD LANE GOING TOWARDS CHANGI AIRPORT WHEN THE LORRY FROM BEHIND CAME AND HI MY REAR. THE DRIVER THEN CAME DOWN, APOLOGISED AND SAID HE COUDNT SEE ME. THATS ALL.



SINGAPORE
POLICE FORCE



T/20191226/2049

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20191226/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
NURSADIY ZULFIKAR BIN SHAWAL

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
26/12/2019 12:05

Officer In Charge Of Case:
TP / GIT /
Sgt 2 HO JIEKANG, IVAN
Contact No.: 65476170

Classification Of Case:

Authentication Stamp
NP168

65476256

10 Intan



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5022276183-12

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: **FX8106D**

Chassis Number

: BE49DTH304235

2. Name of Policyholder

: LIM KOOK SIT

3. Effective Date of Insurance

: 22 Sep 2019

4. Expiry Date of Insurance

: 21 Sep 2020

5. Persons or Classes of Persons entitled to drive#

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: LIM KOOK SIT
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : KIMBERLEY INSURANCE AGENCY (00000571380)

Date of Issue : 16 Sep 2019 18:14 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

 Authorised Officer



 Chief Executive

EROFIA MOTOR TRADING PTE LTD.

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

ERG9

Owner : Lim Kook Sit

Accident Date : 15-Dec-19

Vehicle No : FX 8106 D

Vehicle Model : Suzuki FD110

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
2	Fork inner tubes	\$ SLC 180.00 X
2	Fork outer tubes	\$ SLC 190.00 X
1	Fork under bracket	\$ 17 158.00 X
1	Front rim shaft	\$ 17 38.00 X
1	Front brake disc	\$ 17 145.00 X
1	Top cowling inner panel	\$ 17 30.00 X
1	Headlamp	\$ SER 85.00 ✓
1	Handle-bar	\$ Bar 95.00 ✓
1	Handle-bar grip (1 set)	\$ Grip 50.00 ✓
1	Bake lever	\$ CR 22.00 ✓
2	Side mirrors	\$ O/S 90.00 17C
1	Front footrest -R/H	\$ Bar 40.00 ✓
1	Front footrest rubber	\$ Grip 22.00 ✓
1	Brake pedal	\$ Bar 42.00 ✓
1	Exhaust assy	\$ 10/14 355.00 ✓
1	Exhaust protector	\$ NF 35.00 X
1	Rear taillamp	\$ SNO 85.00 ✓
2	Rear footrests	\$ NF 56.00 X
2	Rear footrest brackets	\$ NF 90.00 X
1	Seat lock	\$ 17 55.00 X
1	Swing-arm	\$ SW 245.00
1	Seat	\$ SW 175.00 X
1	Basket	\$ SW 32.00 X
1	Rear fender	\$ CR 65.00 ✓
2	Rear absorbers	\$ SW 220.00 X
1	Fairing cover (1 set)	430 \$ CR 500.00 ✓
		\$ 3,100.00
not Allowed Less 10%		\$ 310.00
		\$ 2,790.00

not Allowed
Less 10%

2/1/20
The price of the up -
H. L. 1400

1336

c/f:	\$	2,790.00
------	----	----------

Special Nett Items

1	Number plate (1 set)	\$ <i>Set</i>	28.00	<i>10</i>
2	Fork oils	\$ <i>17</i>	30.00	<i>X</i>
2	Fork oil seals	\$ <i>17</i>	56.00	<i>9</i>
1	Steering cone (1 set)	\$ <i>17</i>	85.00	<i>X</i>
1	Rear box	\$ <i>647</i>	250.00	<i>100</i>
1	Rear box bracket	\$ <i>Set</i>	100.00	
		\$	549.00	

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service.	\$ 35	50.00
2	To check wiring and reset headlamp focusing	\$ 17	80.00
3	To provide labour.	\$ 280	380.00
4	To repair body frame.	\$ 17	400.00
		<u>\$</u>	<u>910.00</u>

Grand Total

\$ 4,249.00

1607.4

EROFIA MOTOR TRADING PTE LTD










































...CLAIM SUBFOLDER...(Pending for Survey Report)





















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jan 2020 09:45 Edit Reg		31 Dec 2019 00:00 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: LIM KOOK SIT									
Vehicle Reg. No.: FX8106D		Date of Loss: 15/12/2019 00:00 - :59 [189 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CDMCG19002380		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): GBD127Z		Policy No. (Claimant):							
		Excess:							
Repairer: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:									
Handling Insurer: ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199 ... [Handled by Phoebe Xie - 6829 9191]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/01/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FX8106D (CDMCG19002380)
[GBD127Z]
TP
LIM KOOK SIT
Dec 15 2019 12:00AM
[-]
Erofia Motor Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)						Thumbnail			Print		
1	03/01/20 09:46		Adjuster Immediate Advice						 Load HTM					
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)						Thumbnail			Print		
1	17/01/20 08:06		Odometer Reading						 Load JPG			<input checked="" type="checkbox"/>		
2	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
3	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
4	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
5	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
6	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
7	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
8	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
9	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
10	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
11	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
12	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
13	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
14	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
15	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
16	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
17	17/01/20 08:06		General View						 Load JPG			<input checked="" type="checkbox"/>		
18	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
19	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
20	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
21	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
22	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
23	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
24	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
25	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
26	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
27	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
28	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
29	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
30	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
31	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
32	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
33	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
34	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
35	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
36	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
37	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
38	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
39	17/01/20 08:07		General View						 Load JPG			<input checked="" type="checkbox"/>		
40	17/01/20 08:07		General View						 Load JPG					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/01/20 08:07	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/01/20 08:07	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	17/01/20 08:07	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	17/01/20 08:07	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	17/01/20 08:07	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	17/01/20 08:07	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	17/01/20 08:07	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	17/01/20 08:07	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20000010/UQF3E2

Date: 20/01/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : FX8106D

Insured Vehicle No : GBD127Z

Date of Loss: 15/12/2019

Nature of Claim:

TP

Claim No: CDMCG19002380

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FX8106D

Make & Model:

SUZUKI FD110XCSDU, 110cc (M)

Engine No:

E425TH304235

Reg. Date:

08/03/2004 (Man. Year: 2004)

Chassis No:

BE49DTH304235

Colour:

Red

Odometer:

51224 km

Engine Capacity:

110 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

80/90-17

Rear Tyre Size:

80/90-17

Front Left Side:

Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side:

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,339.00	1,492.40	1,846.60	55.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	315.00	595.00	65.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,249.00	1,807.40	2,441.60	57.46
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	4,249.00	1,400.00	2,849.00	67.05

INSPECTION

Date of Assignment:

31/12/2019

Date Inspected:

02/01/2020 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)

1 KAKI BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Jan 2020)	
Parts:	N/A	SUZUKI FD110XCSDU 110cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FX8106D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORK INNER TUBES	Serviceable	180.00 FL	*- FL
2	2		*FORK OUTER TUBES	Serviceable	190.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Not Necessary	158.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	38.00 FL	*- FL
5	1		*FRONT BRAKE DISC	Not Necessary	145.00 FL	*- FL
6	1		*TOP COWLING INNER PANEL	Not Necessary	30.00 FL	*- FL
7	1		*HEADLAMP	Scratched	85.00 FL	*85.00 FL
8	1		*HANDLE-BAR	Bent	95.00 FL	*95.00 FL
9	1		*SET HANDLE-BAR GRIP	Torn	50.00 FL	*50.00 FL
10	1		*BRAKE LEVER	Cracked	22.00 FL	*22.00 FL
11	1		*SIDE MIRRORS	O/S Cut	90.00 FL	*45.00 FL
12	1		*FRONT FOOTREST - R/H	Bent	40.00 FL	*40.00 FL
13	1		*FRONT FOOTREST RUBBER	Torn	22.00 FL	*22.00 FL
14	1		*BRAKE PEDAL	Bent	42.00 FL	*42.00 FL
15	1		*EXHAUST ASSY	Dented / Bent	355.00 FL	*355.00 FL
16	1		*EXHAUST PROTECTOR	Not fitted	35.00 FL	*- FL
17	1		*REAR TAILLAMP	Broken	85.00 FL	*85.00 FL
18	2		*REAR FOOTRESTS	Not fitted	56.00 FL	*- FL
19	2		*REAR FOOTREST BRACKETS	Not fitted	90.00 FL	*- FL
20	1		*SEAT LOCK	Not Necessary	55.00 FL	*- FL
21	1		*SWING-ARM	Serviceable	245.00 FL	*- FL
22	1		*SEAT	Serviceable	175.00 FL	*- FL
23	1		*BASKET	Serviceable	32.00 FL	*- FL
24	1		*REAR FENDER	Cracked	65.00 FL	*65.00 FL
25	2		*REAR ABSORBERS	Serviceable	220.00 FL	*- FL
26	1		*SET FAIRING COVER	Cut	500.00 FL	*430.00 FL
27	1		*SET REAR NUMBER PLATE	Bent	28.00 FS	*10.00 FS
28	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
29	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
30	1		*SET STEERING CONE	Not Necessary	85.00 FS	*- FS
31	1		*REAR BOX	Cut	250.00 FS	*180.00 FS
32	1		*REAR BOX BRACKET	Bent	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,649.00	1,626.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	310.00	133.60
Total Parts (\$\$)	3,339.00	1,492.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	280.00
4	TO REPAIR BODY FRAME	New	400.00	0.00
Gross Labour Cost (\$\$)			910.00	315.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >