

ASS. REC. BY:

REF CS3/CT1 20000011 / Tly f367

Special Instruction:

Surveyor: Taufikn

ASSIGNMENT (Office)

From (Person): Ivan Tay Hui Ping of CT1

Date/Time: 31.12.19 14.10p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKG 4774G

Insured: XD 15912

at Workshop m/s J D E Automobile Service

Tel: 94571616

of 9002 Tampines Industrial Park A #01-44

Policy No: DMCVSR70 488691212

Claim No: SVM19D 206156102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26.12.2019

CA / REV / REP. / REV 24 HRS

"up"

Date/Time: 2.1.2020 10.02a.m

Person Contacted:

Jimmy

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKG 4774G - CC3/AIG 140091376/Any 263
	XD 15912 - X

D.O.A. - 18/03/2019

ASS. REC. BY:

REF: CT1

ASSIGNMENT

From: _____ Date: 3. Jan. 2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKG 4774G

at Workshop m/s J & E Automobile

of 9002 Tampines Industrial Park A #01-44

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 10.00 a.m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$60K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my' PPS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKG 4774G Yr Regn: 2012 Sep

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Lexus GS250 C.O. 2500

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 74947 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHBF15L005001171

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at JRE Automobile.

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No GIA. \$2000 - \$3000, 03 days

need GIA Report O.S

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

3/4/20 Typist

Report Format:

PRS

Lump Sum / L.B.F. (\$)

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Wheel end (\$)

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

190

190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Dec 2019		31 Dec 2019 14:10 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	FOO SEI POH		
Vehicle Reg. No.:	SKG4774G	Date of Loss:	26/12/2019 19:00 - :59
Claim Type:	TP / SNM19D206156C02	Policy/Cover Note No.:	DMCVSN704886191212
Vehicle Reg. No. (Insured):	XD1591Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	J & E AUTOMOBILE SERVICES (HQ) 9002 TAMPINES INDUSTRIAL PARK A #01-44, 528836 Tampines - Tel: 94571616		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/01/2020]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 31 December 2019 12:50 PM
To: jin@tcmg.com.sg
Cc: Admin A; 'assignments'
Subject: FW: OUR REF: SNM19D206156/XD1591Z/IRENE & YOUR REF: TCMG/SKG 4774 G/1219/J&E- SKG4774G - PRE REPAIR INSPECTION NOTICE FOR SKG 4774 G
Attachments: LIST OF INDEPENDENT SURVEYORS.pdf

Dear Sir (LKK),

We refer to the above matter and the email below.

Please get your surveyor to liaise with J & E AUTO to conduct survey.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Rachel Ling [mailto:jin@tcmg.com.sg]
Sent: Tuesday, December 31, 2019 12:03 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: 'Ling Leong Hui' <lhling@tcmg.com.sg>; jenny@tcmg.com.sg
Subject: RE: OUR REF: SNM19D206156/XD1591Z/IRENE & YOUR REF: TCMG/SKG 4774 G/1219/J&E- SKG4774G - PRE REPAIR INSPECTION NOTICE FOR SKG 4774 G

WITHOUT PREJUDICE

Dear Sirs,

We refer to the above matter and to your email of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

Regards,
Rachel Ling

From: Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]

Sent: Tuesday, 31 December, 2019 11:56 AM

To: jln@tcmg.com.sg

Cc: Jason <jason@tcmg.com.sg>

Subject: RE: OUR REF: SNM19D206156/XD1591Z/IRENE & YOUR REF: TCMG/SKG 4774
G/1219/J&E-SKG4774G - PRE REPAIR INSPECTION NOTICE FOR SKG 4774 G

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING

Kelvin Ang

SEE CHEW SENG

MOHD FADHILAH BIN OSMAN

XING QUO QIANG

KENNETH KONG

SIMON HO

CHUA WEIJIE

MARCUS CHUA

HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, December 31, 2019 11:21 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>; jln@tcmg.com.sg

Subject: OUR REF: SNM19D206156/XD1591Z/IRENE & YOUR REF: TCMG/SKG 4774 G/1219/J&E-SKG4774G - PRE REPAIR INSPECTION NOTICE FOR SKG 4774 G

Dear Irene,

Please conduct PRS –SKG4774G –soonest possible

File with Officer in charge –Irene Tay –DID: 6389 6192

Dear Rachel,

*** kindly quote our reference number when replying ***

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6116
Fax (65) 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Rachel Ling [<mailto:jlin@tcmg.com.sg>]
Sent: Monday, December 30, 2019 5:41 PM
To: Claims Dept of CTI
Cc: 'Ling Leong Hui'; 'Jenny'; 'Jimmy Tan'
Subject: PRE REPAIR INSPECTION NOTICE FOR SKG 4774 G | YOUR REF: XD 1591 Z

Our Ref: TCMG/SKG 4774 G/1219/J&E
Your Ref: XD 1591 Z

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Foo Sei Poh**, the owner and/or driver of motor vehicle no. **SKG 4774 G**, which was involved in an accident along Bedok Reservoir Road towards Tampines on 26th December 2019 at 18:55 hrs.

We hereby give you NOTICE that we are claiming against your insured motor vehicle no. **XD 1591 Z** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s J & E Automobile, (9002 #01-44 Tampines Industrial Park A, Singapore 528836 – Jimmy Tan @ 9457 1616).

If we do not hear from you within the next two (2) working days, we shall deem that you have waived the requirement for the pre-repair inspection.

Regards,
Rachel Ling

TOMMY CHOO, MARK GO LLC
151 Chin Swee Road
#14-15/16 Manhattan House
Singapore 169876

Tel: 6532 2455
Fax: 6538 9850



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 121D

Vehicle Details

Vehicle No.: SKG4774G
Vehicle to be Exported: No
Intended Deregistration Date: 03 Apr 2020
Vehicle Make: TOYOTA
Vehicle Model: LEXUS GS250 F SPORT
AUTO

Primary Colour: White
Manufacturing Year: 2012
Engine No.: 4GR0820659
Chassis No.: JTHBF1BL005001171
Maximum Power Output: 154.0 kW (206 bhp)
Open Market Value: \$57,428.00
Original Registration Date: 10 Sep 2012
First Registration Date: 10 Sep 2012
Transfer Count: 0
Actual ARF Paid: \$57,428.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 09 Sep 2022
PARF Rebate Amount: \$34,456.00

Intended COE Rebate Details

COE Expiry Date: 09 Sep 2022
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$93,990.00
COE Rebate Amount: \$21,413.00
Total Rebate Amount: \$55,869.00

The information contained herein is correct as at 03 Apr 2020

OK



H Cross
Spoke Enkei
Racing Matte
Black Rim



Premium
Italy Interior
Leather
Upholstery



Same As New
Refurbished 4
POT Brake Kit



Apple CarPlay
& Android
Auto Retrofit
Service

Post an Advertisement
Sell it yourself! Advertise it at just:
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

BMW 7 Series 730Li (New 10-yr COE).



Priced To Sell! Cheapest In
Market! Could Fine Sale! Low
Mileage, New Suspension
Direct Owner

HR LUNG AUTO
No Fee
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

2 vehicles less

Lexus GS250

Sort by Date Posted 20 results/page

Advanced Search Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Lexus	GS250	Any	Any	2012	Any	Any	Any	Available
	Lexus	GS250	\$59,800	\$17,790 /yr	29-Mar-2012	2,500 cc	-	Luxury	Available
Cheapest In The Market! Almost Perfect Condition, No Repair Needed! Brand Spoke For Itself! Original Black Paintwork Painted With Black Interior + 20 Inch Sport Rim To Give A Sporty Yet Luxurious Feel 100% Accident Free, Highest Trade In Value For Trade In V...									
Car (5) Pte Ltd									
Posted: 28-Mar-2020 Tags: 2012 Lexus GS250, Lexus GS250, Lexus GS250									
	Lexus	GS250 Premium	\$59,800	\$15,300 /yr	11-Jun-2012	2,500 cc	83,000 km	Luxury	Available
Agent Maintained, Call Now For Viewing									
Posted: 25-Mar-2020 Tags: 2012 Lexus GS250, Lexus GS250, Lexus GS250									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OFC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Lexus GS250, Lexus GS250 Singapore, used Lexus GS250 Singapore, used Lexus GS250, used vehicles Singapore or even buy used Lexus GS250 Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/12/2019 13:13
Date Of Accident	26/12/2019 18:55
Exact Location Of Accident	954C TAMPINES ST 96 TAMPINES GREENGEM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG4774G
Insured/Policyholder	
Name Of Registered Owner	FOO SEI POH
NRIC No	SXXXX121D
Email Address	COUFSP@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96640688
Alternative Phone No	OFFICE-96640688

Vehicle Particulars

Manufacturer	LEXUS
Model	GS250

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100313901
Cover Note Number	

Driver

Name of Driver	FOO SEI POH
NRIC No	SXXXX121D
Date Of Birth	02/04/1972
Occupation	INDOOR
Date Of Driving Pass	15/09/1994
Driving Experience	25 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96640688
Fax Number	
Contact Number	OFFICE-96640688

Address	BLK 916 TAMPINES ST 91 #15-65
Postcode	520916
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 6 TAMPINES AVE 4 , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5871999 - FAX NO: 65871699
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO POLICE REPORT NO.G/20191227/2007

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1591Z
Vehicle Make/Model/Colour	
Details Of Properties	VEH B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



G/20191227/2007

1 of 2

POLICE REPORT (NP299)

Report No. G/20191227/2007

Police Station Of Origin
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Date/Time Report Made 27/12/2019 01:41	Vide Report No.	Station Diary No. 14
Name Of Informant FOO SEI POH	Address APT BLK 916 TAMPINES STREET 91 #15-65 SINGAPORE 520916	
ID Type / ID No. NRIC NO / S7211121D	Contact No. Home/Office	Mobile 96640688
Nationality SINGAPORE CITIZEN	Email Address	
Occupation CAR MECHANIC	Sex Male	Age 47
Institution/School Name	Date of Birth 02/04/1972	Race Chinese
Date/Time Of Incident 26/12/2019 18:55	Location Of Incident 954C TAMPINES STREET 96 TAMPINES GREENGEM SINGAPORE 523954	

Brief details.

On the 26/12/19 at about 1855hrs, I was driving along Bedok Reservoir Road towards Tampines. There was a truck which came out from Jalan Lembah Bedok was travelling in front of me at the first lane on the right while I was driving on the second lane from the right. I saw a big stone fell off the truck and it landed on the road at my lane and started rolling towards my vehicle(SKG4774G). Suddenly, I heard some sound coming from the bottom of my car. After a while, the car started surfing to the right even when I was driving straight. The incident happened beside the new BTO flats.

Signature Of Officer Recording The Report: G / Sgt 2 CHIN XUE NI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 27/12/2019 01:41
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Insp VOON PENG SHENG, BENJAMIN Contact No.: 62447200	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



G/20191227/2007

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20191227/2007

I pull over and checked the car and realised that my front right tyre had deflated and the rim also has some dents. My rear right tyre also collided with the stone and there is something budging out from the tyre.

I did not manage to catch up with the truck as my tyre was already flat. I have in car camera in my car however the car plate number captured was not clear enough. The plate number is ~~XD15xxZ~~. The truck drove towards Tampines Ave 1 when I drove towards Tampines Ave 4.

XD1591Z

Tampines P.C.
401-4 Tampines Avenue 4
Singapore 620502
Tel: 6740-3873/39

Signature Of Officer Recording The Report: G / Sgt 2 CHIN XUE NI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 27/12/2019 01:41
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Insp VOON PENG SHENG, BENJAMIN Contact No.: 62447200	Classification Of Case:

Authentication Stamp





CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Foo Sei Poh (Fu Shubao)
 Period of Insurance : 10 Sep 2019 To 09 Sep 2020
 Engine No. : 4GR0820659
 Chassis No. : JTHBF1BL005001171

Vehicle No. : SKG4774G
 Policy No. : 2100313901-07
 Endorsement No. :
 Issued Date : 27 Aug 2019

ABOUT THE COVER

Make/Model : LEXUS GS250
 Engine Capacity/Tonnage : 2,500.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2012
 Insuring with COE/PAF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Foo Sei Poh (Fu Shubao) - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)
 Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1996 (Malaysia).

0502368000

TH INSURANCE SPECIALIST AGENCY
 71 BUKIT BATOK CRESCENT #11-07 PRESTIGE CENTRE
 SINGAPORE 658071
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Tanik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE
 Wong Ling Eileen Goh

AIG Asia Pacific Insurance Pte. Ltd.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Dec 2019		31 Dec 2019 14:10 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
<div>CLAIM SUBFOLDER DETAILS [Created by insurer]</div> <div> <div>Insured: -, Co. Reg. No.: -</div> <div> <div>Main Claimant: FOO SEI POH</div> <div>Vehicle Reg. No.: SKG4774G</div> <div>Claim Type: TP / SNM19D206156C02</div> <div>Vehicle Reg. No. (Insured): XD1591Z</div> </div> <div> <div>Date of Loss: 26/12/2019 19:00 - :59 [87 Months and 16 Days From LTA Reg Date (Man Yr)]</div> <div>Policy/Cover Note No.: DMCVSN704886191212</div> <div>Policy No. (Claimant):</div> <div>Excess: S\$0.00</div> </div> <div> <div>Repairer: J & E AUTOMOBILE SERVICES (HQ) 9002 TAMPINES INDUSTRIAL PARK A #01-44, 528836 Tampines - Tel: 94571616</div> <div>Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]</div> <div>Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/01/2020]</div> <div>Adj Asg. Remarks: PLEASE SURVEY AND REVERT</div> </div> </div> <div> View All Compose Case Mail </div>				

Claim Documents

*SKG4774G (SNM19D206156C02)
[XD1591Z]
TP
FOO SEI POH
Dec 26 2019 7:00PM
[-]
J & E AUTOMOBILE SERVICES

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

3 per page

Photos/Images

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

03/04/20 10:13

Odometer Reading

1 Load JPG

2

03/04/20 10:13

General View

1 Load JPG

3

03/04/20 10:13

Chassis Number

1 Load JPG

4

03/04/20 10:13

General View

1 Load JPG

5

03/04/20 10:13

General View

1 Load JPG

6

03/04/20 10:13

General View

1 Load JPG

7

03/04/20 10:13

General View

1 Load JPG

8

03/04/20 10:13

General View

1 Load JPG

9

03/04/20 10:13

General View

1 Load JPG

10

03/04/20 10:13

General View

1 Load JPG

11

03/04/20 10:13

General View

1 Load JPG

12

03/04/20 10:13

General View

1 Load JPG

13

03/04/20 10:13

General View

1 Load JPG

14

03/04/20 10:31

Photo After Spray

1 Load JPG

15

03/04/20 10:31

Photo After Spray

1 Load JPG

16

03/04/20 10:31

Photo After Spray

1 Load JPG

17

03/04/20 10:31

Photo After Spray

1 Load JPG

18

03/04/20 10:31

Photo After Spray

1 Load JPG

19

03/04/20 10:31

Photo After Spray

1 Load JPG

20

03/04/20 10:31

Photo After Spray

1 Load JPG

21

03/04/20 10:31

Photo After Spray

1 Load JPG

22

03/04/20 10:31

Photo After Spray

1 Load JPG

23

03/04/20 10:31

Photo After Spray

1 Load JPG

24

03/04/20 10:31

Photo After Spray

1 Load JPG

25

03/04/20 10:31

Photo After Spray

1 Load JPG

26

03/04/20 10:31

Photo After Spray

1 Load JPG

27

03/04/20 10:31

Photo After Spray

1 Load JPG

28

03/04/20 10:31

Photo After Spray

1 Load JPG

29

03/04/20 10:31

Photo After Spray

1 Load JPG

30

03/04/20 10:31

Photo After Spray

1 Load JPG

31

03/04/20 10:31

Photo After Spray

1 Load JPG

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
<small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20000011/T1YF3E2
Date: 03/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN704886191212
Claimant Vehicle No: SKG4774G Insured Vehicle No: XD1591Z
Date of Loss: 26/12/2019 Nature of Claim: TP Claim No: SNM19D206156C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG4774G Engine No: 4GR0820659
Make & Model: LEXUS GS250, 2.5 (A) Chassis No: JTHBF1BL005001171
Reg. Date: 10/09/2012 (Man. Year: 2012) Odometer: 74947 km
Colour: White
Engine Capacity: 2500 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R18 Rear Tyre Size: 195/55 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/12/2019
Date Inspected: 03/01/2020 Inspected At: J & E AUTOMOBILE SERVICES (HQ)
9002 TAMPINES INDUSTRIAL PARK A
#01-44
Singapore 528836

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2020)

Parts: 143 LEXUS GS250 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKG4774G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >