

15/5/2010

INS. CASE OWNER:

BONNIE
Chan, Kian Meng

CC4/AIG20000045/Fha3

LKK:

IDAC:

ASSIGNMENT

Surveyor:


RAM

DOI: 30/12/2019

Date / Time : 30/12/2019

Registered in Merimen: 02/01/2020

Pre-assign / CCU / FTE



Insured Vehicle No. : SKG 3333C

Name of Insured : YU KOK LEONG

Insured Tel No. : HP: +65-90239108

Excess Sec II :SS D.O.A : 20/12/2019 12:15

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. : 3450120236SG

Policy No. : 1800022893



Make / Model : MERCEDES-BENZ S320

Place of Accident : ALONG CTE TWDS CITY

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SH 8072Y

INSRS:
WSP: CDGE
Tel: LOYANG
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
	SH 8072Y - CC6/III15018360/Rjb3q2; DOA: 8.10.15	Non-Reporting ltr (1st):	
	- NS/INC15002455/H1qy3d1; DOA: 08.02.15	Non-Reporting ltr (2nd):	
	SKG 3333C - X	Non-Reporting ltr (Final):	
	- FINALISED	Notification ltr (if non-pickup):	
	- ORIGINAL TP LOD IN	Call OI:	
28/01/2020	- FILE PROVIDED. OI REPLY-ENDED TP. SEND LETTER TO OI.	After call ltr to OI:	28/01/2020 - JIC
28/01/2020	- UPLOADED WARRANTS IN IN WORKMEN.	Documentation Check List: Handler	Typist
31/03/2020	- AIG APPROVED WARRANTS	Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
1/4/2020	pending TP acceptance	Car Rental Invoice:	☒
3/4/2020	pending DV signed	Towing Invoice	☐
	File pass MLC to close.	LTA/GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: 46	SS 950.00 (2 days)	Reduction: AIG %	Email ☐ Call ☐

FINAL SETTLEMENT	Date/Time: 3/4/2020	Confirm with: Kazali	Email ☒ Call ☐
------------------	---------------------	----------------------	---

Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No. : 27	If NO or B 28, Ass. Lia :
Repair Cost: (w/gst)	SS 1,016.50		(OI REPLY-ENDED TP)
Loss of Rental (LOR):	SS 156.00 (1.5 days) x 110.67		
Loss of Use (LOU):	SS - (\$ x days)		
Loss of Income (LOI):	SS 75.00 (\$ 50 x 1.5 days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]			

GIA/LTA Search	SS 7.49		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 1,264.99	Global Sum SS: 1,260.00	

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
---------------	------------	---------------	--

Payee 1:	SS 1,260.00	Name 1:	COMFORT DELTA ENGINEERING PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2:	-
Payee 3: (Strike if N.A.)	SS -	Name 3:	-

VIC-gk
03/04/2020

RAM

00481th

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop in/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 2 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SH80724 Yr Regn: 16/07 2015
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Hyundai 1.4D C.C. 1685
Colour: blue A/C: Insured / Std / NI / NA
Sp. Reading: 90299.7 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KMTHLBA10MGU015214
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60 R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 20/12/19 D.O.I. 30/12/19
Survey held at comfortdelgro (loyang)
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>H/o \$950.00</u> <u>(Less: \$815.06 / 46%)</u>
	<u>AG</u>
	<u>LS</u>

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to? _____
2) _____
Report Form 3 _____
Trip Form / M.O.B. _____
Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Insp (\$) ☐ : Wash end (\$)
Survey Fee: _____
Transportation: _____
3 + RS. \$ _____
Photos _____
Other: _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8072Y

MAKE :

MODEL : HYUNDAI i40

DATE 30/12/2019 10:18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>cr</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>rec</i>			\$ 22.00
	Rear Bumper Bracket <i>xm</i>		\$ 35.60	\$ 71.20
	Rear Bumper Under Cover <i>xm</i>			\$ 228.00
	SUB TOTAL			\$ 874.20
	LESS 20%			\$ 174.84
	DISCOUNTED TOTAL			\$ 699.36
	Rear Bumper Reverse Sensor <i>2 avc</i>			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH) <i>rec</i>		\$ 100.00	\$ 200.00
				\$ 335.70
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 730.00
	ESTIMATE TOTAL			\$ 1,765.06

575.00

less 20%

960.00

Nett

Nett 200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$200

\$240

\$200

\$36

\$50

520

\$1,180.00

less 20%

\$944.00

US \$950

after repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ram (LKK)

30/12/19 1320

Paraguram @ LKK Auto

88622728

2 repair days

LIS