


ASS. REC. BY: Wing Kwok REF: CS3/MC/90/9974/GSD3-12 Special Instruction: _____
 Survey: Minimum ASSIGNMENT (Office)
 From (Person): Ler Bernard of ALG Date/Time: 02/01/2020
 Estimated Cost: _____ Bill to: _____
 OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV/CS
 To Inspect Vehicle No: SLH 8713P Insured: SMP 4692M
 at Workshop m/s Choon Hock Auto Tel: 6453 0778
 of BLK 176 Sin Ming #05-03
 Policy No: _____ Claim No: 2407419410SG
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 6/11/2019
 (Client's Record)
 CA / REV / REP. / REV 24 HRS
 Date/Time: 9:44am 11/11/19 Person Contacted: Jade H.O.D. Endorsement: _____
 Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Remarks
	SLH 8713P-X	X
	SMP 4692M-X	
	Dismantle: 12/11/2019	
	\$3850, 5 Days.	
	(\$4,250/- Red - 53%)	
		
	20/1/2020	

RECEIVED 20 JAN 2020

ASSIGNED BY

ALL

REP

ALG

PRS

ASSIGNMENT

From

Date

11/11/19

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLH 8713P

at Workshop m/s

choon hock auto

of

176 Sin Ming Drive # 05-03

Insured

Policy No

Claims No.

Sum insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Liam Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

1/22

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH 8713P

vs Regn:

22 Nov 2016

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Opel Astra 1.4 c.c. B399

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

76764

T/Radio: Insured / Std / NI / NA

Eng/No:

WOLBE6EC4H A00/802

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

225/45R17

R:

11

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

11-11-19

Survey field at

W/S

2pm

Des. of Damages: ☒ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 13 NOV 2019

Date/Time, File Path (if)



Prel. Report

1)



Final Report

Date/Time, File Path (if)

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Imp \$



Interview \$



Tech. Imp \$



Assess. Imp \$

Survey Fee:

Transportation:

1) S + RS: \$

1) Other:

1) Other:

1) Other:

1) Other:

180

11

191

Report Format:

DAR

Image Path / File:

Nivitha (LKK Auto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Thursday, 2 January 2020 10:55 AM
To: Admin A; Admin-D (LKKAuto)
Subject: Paper Adjustment for 2407419410SG-003
Attachments: 2407419410SG.pdf

Dear LKK,

Please assist to complete paper adjustment for the above case.

Relevant documents are in Merimen.

Do let me know if further documents are required.

Thanks!

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

**KM AUTO ASSESSORS PTE. LTD.**

Insurance Loss Assessors / Adjusters

28 Casuarina Walk

Singapore 574086

T 6448 8208

F 6552 7277

E kmautoassessors@gmail.com

Regn. No. 200907140Z

**AUTOMOBILE
INSPECTION REPORT**

NO. 9/11/TP002

To: SEAH HOCK CHYE

2 PASIR RIS LINK #08-01 S'PORE 518184

General Condition: Poor/Fair/Good/Excellent

Reg. No.	SLH 8713 P	Make/Model	OPEL ASTRA HB 1.4 AUTO		Year	2016	
Engine No.	B1162047GSGX0062	Chassis No.	W0LBE6EC4HG001802		Colour	Red	
Condition of Tyres				Speedometer Reading - Km		76764	
Front N/S	B/STONE 225/45R17	worn	10	%	Front O/S	B/STONE 225/45R17	worn 10 %
Rear N/S	B/STONE 225/45R17	worn	10	%	Rear O/S	B/STONE 225/45R17	worn 10 %
As Requested By	YOURSELF		On	11-Nov-19		The Above Vehicle	
Was Inspected At (11-Nov-19) CHOON HOCK AUTOCARE PTE LTD BLK 176 SIN MING DRIVE #05-03 S'PORE 575721							
And The Undermentioned Damage Was Made:							

Tailgate dented and bent, inner frame bent, weatherstrip twisted, kinked and deformed, lock assy. bent and distorted, rear panel dented and bent, both rear lamps dislodged, bumper assy. dented, bent, kinked and deformed, reverse camera and sensors distorted, no. plate dented and bent, fenders bent and distorted, boot floor panel bent.

Photographs:-	131 Copies	were taken at time of inspection and are attached.
The Repairers estimate was for a total amount of	\$	12,815.00
After adjustment the estimate was revised and agreed at	\$	10,166.00

SPECIAL REMARKS

The Repairers were **NOT AUTHORISED** to proceed with the repairs.

Survey was carried out without prejudice.

The above were due to impact to the rear portion of the vehicle.

Alternatively, we recommend that repairs be carried out on a Lump Sum basis instead, @\$8,100/- Nett.


MICHAEL EE Ctr A Eng., AMRTE, AMSAE, AMSOE, AMMI, NSAAA

Date 4-Dec-19



APPENDIX 'A'

TO REPORT NO:

9/11/TP002

REGN. NO:

SLH 8713 P

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
1 pce tailgate	1,659.00	dented & bent	X 1,659.00 RPR
1 pce tailgate inner lock assy.	480.00	not necessary	X - SVC
1 pce tailgate weatherstrip	240.00	twisted, kinked, deformed	X 240.00 SVC
1 pce tailgate emblem	80.00	not necessary	X -
1 pce tailgate "ASTRA" plate	105.00	necessary	/ 105.00 65
1 pce tailgate "TURBO" plate	100.00	necessary	/ 100.00 70
1 pce tailgate glass moulding	90.00	necessary	X 90.00
2 pcs rear lamps assy.	700.00	dislodged, distorted, fasteners snapped	X 700.00 SVC
1 pce rear panel	900.00	dented & bent	/ 900.00
2 pcs rear panel vent grilles	170.00	bent & snapped	/ 170.00
1 pce rear panel inner garnish	240.00	fastener snapped	/ 240.00 120
1 pce rear bumper fascia	1,320.00	dented, bent, deformed, fasteners torn	/ 1,320.00
1 pce rear bumper lower garnish - grey	240.00	dented, bent, deformed, fasteners torn	/ 240.00
2 pcs rear bumper reflectors	116.00	distorted, fasteners snapped	/ 116.00
1 pce rear bumper inner carrier	180.00	bent & cracked	/ 180.00 65
1 pce rear bumper reinforcement	520.00	dented & bent	/ 520.00
2 pcs rear bumper stays	150.00	snapped	X 150.00 SVC
2 pcs rear bumper corner retainers	80.00	fastener snapped	X 80.00
2 pcs rear bumper side retainers	80.00	fastener snapped	/ 80.00
2 pcs reverse sensors	400.00	distorted, s/circuited	X 400.00 SVC
			7,290.00 3066
		less 10%	729.00
	7,850.00		6,561.00 3299.4
S.NETT			
1 pce tailgate glass primer	60.00	necessary	X 60.00 SVC
1 pce tailgate glass sealant	50.00	necessary	X 50.00
1 pce rear panel sealant	60.00	necessary	/ 60.00 40
30pcs rivets	135.00	necessary	/ 135.00 30
1 set reverse camera unit	300.00	distorted, s/circuited	X 300.00 SVC
1 pce rear no. plate with casing	50.00	dented & bent	/ 50.00 120
Transfer tailgate glass assy. to new tailgate assy. and refit.	200.00		X 120.00
Remove tailgate fittings, check, renew damaged fittings, transfer all fittings to new tailgate assy. and refit.	150.00		X 80.00
Remove necessary interior upholsterys and fittings to enable necessary repairs, check and refit same.	200.00		60 120.00
c/f	9,055.00		7,536.00
Total Amount Revised	\$		
Lump Sum Repairs Amount	\$		
It is estimated that the repairs will take		days to complete.	

APPENDIX 'A'

TO REPORT NO:

9/11/TP002

REGN. NO:

SLH 8713 P



KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors / Adjusters

28 Casuarina Walk

Singapore 574086

T 6448 8208

F 6552 7277

E kmautoassessors@gmail.com

Regn. No. 2039073402

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
bif	9,055.00		7,536.00
Renew reverse camera unit and reverse sensors, check, renew if required, transfer same to rear bumper respectively, refit and calibrate both systems.	200.00		80 100.00
Remove lamps, necessary wirings and electrical fittings to enable necessary repairs, check, replace damaged parts, refit same, test electrical-circuit.	60.00		/ 30.00
Remove damaged parts, jack and cut out damaged body panels, jack out, straighten up damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and align whichever parts necessary. (incl. alignment of body structure.)	1,400.00		600 1,000.00
Paint replacement parts and repaint damaged sections with welded portions in and outside.	1,600.00		600 1,200.00
Rustproof replacement parts and touch-up damaged sections.	200.00		60 120.00
Conduct diagnostic programming and calibration.	300.00		X 180.00
			1430
TOTAL	12,815.00		10,166.00
		4849.4 20% 3850 5 Days.	
Total Amount Revised	\$	10,166.00	
Lump Sum Repairs Amount	\$	8,100.00	
It is estimated that the repairs will take	SEVEN	days to complete.	

PHOTOCOPY

Kailis Car Rental

Nº 1940

BLK 15 LORONG 8 TOA PAYOH #02-02 BRADDELL TECH
SINGAPORE 319262 TEL: 6457 8393

OFFICIAL RECEIPT

DATE 18/11/19

Received from Seah Hock Chye
the sum of Dollars One thousand three Hundred & Twenty Only —

being payment of 11640

\$ 1320 /

Bank

Cash/Cheque No. _____

✓ KAILIS CAR RENTAL

[Signature]

BLK 178 SIN MING DRIVE #05-03 SIN MING AUTOCARE
SINGAPORE 575721 TEL: 6453 0781 Co. Reg. No. S2937160W

AGREEMENT / INVOICE NO: 11640

VEHICLE			
VEHICLE NO: S11 4732 Z	MAKE/MODEL: Toyota Altis	ENGINE CAPACITY: 1.5A	
HIRER			
NAME: Seah Rock Chye			
ADDRESS: 2 Pasir Ris Link #18-01			
TEL:	EMAIL:	POSTAL: 518184	
PASSPORT/NRIC NO: S7107096D	DATE OF BIRTH: 5.3.71	NATIONALITY: spone	
DRIVING LICENSE NO: S7107096D	COUNTRY OF ISSUE: spone	EXPIRY DATE:	
ADDITIONAL NAME/DRIVER			
NAME:			
ADDRESS:			
TEL:	EMAIL:	POSTAL:	
PASSPORT/NRIC NO: ✓	DATE OF BIRTH:	NATIONALITY:	
DRIVING LICENSE NO:	COUNTRY OF ISSUE:	EXPIRY DATE:	
CHECK OUT / CHECK IN			
DATE OUT: 7.11.19	TIME OUT: 2:25 PM	KM OUT:	
PETROL LEVEL OUT:	E 1/4 1/2 3/4 (F)		
DATE IN: 18.11.19	TIME IN: 4 PM	KM IN:	
PETROL LEVEL IN:	E 1/4 1/2 (3/4) F		
COLLISION DAMAGE WAIVER		PERSONAL ACCIDENT INSURANCE	
ACCEPT	DECLINE	ACCEPT	DECLINE
\$	PER DAY \$	\$	PER DAY \$
	PER MTH		PER MTH
EXCESS			
HIRER IS RESPONSIBLE FOR THE FIRST \$3500 / 2 EXCESS FOR COLLISION/DAMAGE TO FIRST PARTY (I.E. KAILIS CAR RENTAL'S) VEHICLE (INCLUDING WINDSCREEN) AND ALSO FIRST \$3500 / 2 EXCESS FOR COLLISION/DAMAGE TO THIRD PARTY'S VEHICLE FOR EACH AND EVERY ACCIDENT/DAMAGE.			
VEHICLE TO BE DRIVEN IN SINGAPORE ONLY. PROHIBITED TO ENTER MALAYSIA BY LAW.			
CHARGES			
HOURS	@ \$	PER HOUR	
11 DAYS	@ \$ 120	PER DAY	\$1320
WEEKS	@ \$	PER WEEK	
MONTHS	@ \$	PER MONTH	
SUB TOTAL:			
PETROL			
CDW			
PAI			
EXCESS/NON WAIVERABLE EXCESS			
TOTAL: \$1320			

x

HIRER'S SIGNATURE SIGNIFIES ACCEPTANCE OF AGREEMENT. (PLEASE READ OVERLEAF FOR ADDITIONAL TERMS AND CONDITIONS).



CI - DRIVER'S PARTICULAR Pg. 1

SOMPO Insurance (Private) Limited is a member of the Sompo Group of Companies. The details of the Group's financial performance and other information can be found at www.sompo.com.sg.

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 182)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. D18MTPV01010240
Insured SEAH HOCK CHYE (XIE FUCHAI)
Motor Car (Registration No.) SLH8713P
Cover Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date 22 NOVEMBER 2018 00:00
Policy Expiry Date 21 NOVEMBER 2019 23:59
Maximum Liability (Section I) Market value at time of loss - Excl. COE
Excess* \$400 - Section I
(Waived up to \$51,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* Buy Up : \$200 - Section I
Windscreen Excess* \$5100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use Per Policy Schedule
* Subject to GS1 wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured;
2. Any other person who is driving on the Insured's order or with his permission;
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 8226 3323.

WE HEREBY CERTIFY that the policy is issued in accordance with (i) the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 182) and Part IV of the Road Transport Act, 1987 (Malaysia) and (ii) the Policy terms, conditions and exclusions of the Private Car Policy of MTP27.

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 20 NOVEMBER 2018 14:58

IMPORTANT NOTICE

1. Keep the Certificate in your Motor Car.
2. Under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 182), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
3. On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and this Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 182).
4. This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Insured's Code & Name : 11A14008 & ACCORD INSURANCE AGENCY CI Code: 22A F WODPL1211HOMAA

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2019 13:39
Date Of Accident	06/11/2019 20:35
Exact Location Of Accident	AIRPORT ROAD TOWARDS KPE ENTRANCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH8713P
Insured/Policyholder	
Name Of Registered Owner	SEAH HOCK CHYE
NRIC No	S7107096D
Email Address	JUMMYSEAHHC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98719197
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA HB 1.4 AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE.
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01019240
Cover Note Number	22/11/2018 TO 21/11/2019

Driver

Name of Driver	SEAH HOCK CHYE
NRIC No	S7107096D
Date Of Birth	05/03/1971
Occupation	INDOOR
Date Of Driving Pass	25/03/1997
Driving Experience	22 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98719197
Fax Number	
Contact Number	OFFICE-NOPHONE

Address	2 PASIR RIS LINK #08-01-
Postcode	518184
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE LIN KIW GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMP4692M
Vehicle Make/Model/Colour	KIA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HEJIA
NRIC/Passport Number	S8732159B
Contact Number	97533345
Address	
Postcode	
Insurance Company Name	

No. Of Passenger (Including Driver)

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issuance and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available thereafter.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIC to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

3/11/19 / 1PM

Owner's Signature

[If different from the policyholder]

Date & Time:

Reporting Centre Personnel's Signature


Name:

MIC/APP No.:



3/11/19

Date of accident: 06/11/19 Time: 20 34pm Location: AIRPORT ROAD TOWARDS KPE
 My Vehicle A: SLH 8713P Vehicle B: SMP 4692M Vehicle C: _____
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6/11/19, I was driving along Airport Road toward KPE. Vehicle in front of me stopped and I also stop. My vehicle was stationary for a while and suddenly vehicle B bang onto my vehicle A from behind. The owner of vehicle B admit her veh. and apologise to me.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my file accident report to:
 My workshop:
 Email address: Jimmyseahhe@gmail.com
 & myself:
 Email address: _____

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature: _____
 Date & Time: _____

Driver's Signature: _____
 (If driver is not the policyholder)
 Date & Time: _____

Reporting Centre Personnel's Signature: _____
 Name: grrr
 Date/Time: 7/11/2019



Sompo Insurance (Singapore) Pte. Ltd. (Incorporated in Singapore)
The Straits Times, 22 Nov 2018, Page 100
C/O Hong Kong Insurance Co., Ltd. (Incorporated in Hong Kong)
C/O Hong Kong Insurance Co., Ltd. (Incorporated in Hong Kong)

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. 018MTPV01019240
Insured SEAH HOCK CHYE (XIE FUCAI)
Motor Car (Registration No.) SLH8713P
Cover Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date 22 NOVEMBER 2018 00:00
Policy Expiry Date 21 NOVEMBER 2019 23:59
Maximum Liability (Section I) Market value at time of loss - Excl. COE
Excess* \$400 - Section I
(Waived up to \$51,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* Buy Up: \$200 - Section I
Windscreen Excess* \$5100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use Per Policy Schedule
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP 27.

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue - 20 NOVEMBER 2018 14:58

IMPORTANT NOTICE

1. Keep the Certificate in your Motor Car.
2. Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
3. On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
4. This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name: 11A14006 & ACCORD INSURANCE AGENCY Cl Code: 22A F4100PL12114DMAA

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/11/2019 17:12
Date Of Accident	06/11/2019 20:35
Exact Location Of Accident	BEFORE KPE(TPE)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMP4692M
Insured/Policyholder	
Name Of Registered Owner	TEE HE JIA SHERRAINE
NRIC No	S8732159B
Email Address	HEJIATEE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97533345
Alternative Phone No	Others-97533345
Vehicle Particulars	
Manufacturer	KIA
Model	CERATO-1.6 SUNROOF (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900166850
Cover Note Number	
Driver	
Name of Driver	TEE HE JIA SHERRAINE
NRIC No	S8732159B
Date Of Birth	05/10/1987
Occupation	INDOOR
Date Of Driving Pass	09/11/2007

Gender	FEMALE
Mobile Number	(LOCAL) +65-97533345
Fax Number	
Contact Number	OTHERS-97533345
Email Address	HEJIATEE@GMAIL.COM
Address	BLK 665A PUNGGOL DRIVE #18-514 SINGAPORE
Postcode	821665
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH8713P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TEE HE JIA SHERRAINE

Approximate Age

Injuries Sustain

Injured person in which vehicle? SMP4692M

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

Address

Postcode

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:




- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud/detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 7/11/19 4:24pm


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.:

SKETCH PLAN

	Vehicle A - SMP4692 M B - SLH8713P
	Legend  Vehicle  Motorcycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6/11/19, I was driving towards KFE TPE, Ulu area at around 835pm. SLH 8713P braked and I didn't managed to brake on time, my front hit onto his rear. rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against our policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
 Date & Time: 4:24pm
 7/11/19

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: [Signature]
 NRIC/FIN No.: [Signature]

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG19019974/Gsd3e2-1		
78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 ATTN : LER BERNARD		Date : 21-01-2020		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMP 4692M	Veh. Inspected	SLH 8713P	
Policy No.	1900166850	Coverage (\$)	0.00	
Claim No.	2407419410SG	Excess (\$)	0.00	
Assign From	LER BERNARD	Assign Date	02/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	OPEL ASTRA 1.4	c.c	1399	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	W0LBE6EC4HG001802	Colour	RED	
Odometer	76764	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/11/2019	Inspection Date	11/11/2019	
Survey held at	CHOON HOCK AUTOCARE PTE LTD BLK 176 SIN MING DRIVE #05-03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 8713P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	TO REPAIR SEE LABOUR	1,659.00	-
1	TAILGATE INNER LOCK ASSY	SERVICEABLE	480.00	-
1	TAILGATE WEATHERSTRIP	SERVICEABLE	240.00	-
1	TAILGATE EMBLEM	SERVICEABLE	80.00	-
1	TAILGATE "ASTRA" PLATE	NECESSARY	105.00	65.00
1	TAILGATE "TURBO" PLATE	NECESSARY	100.00	70.00
1	TAILGATE GLASS MOULDING	SERVICEABLE	90.00	-
2	REAR LAMPS ASSY	SERVICEABLE	700.00	-
1	REAR PANEL	DENTED / BENT	900.00	900.00
2	REAR PANEL VENT GRILLES	BENT / SNAPPED	170.00	170.00
1	REAR PANEL INNER GARNISH	FASTENER SNAPPED	240.00	120.00
1	REAR BUMPER FASCIA	DENTED / BENT / DEFORMED / FASTENERS TORN	1,320.00	1,320.00
1	REAR BUMPER LOWER GARNISH - GREY	DENTED / BENT / DEFORMED / FASTENERS TORN	240.00	240.00
2	REAR BUMPER REFLECTORS	DISTORTED / FASTENERS SNAPPED	116.00	116.00
1	REAR BUMPER INNER CARRIER	BENT / CRACKED	180.00	65.00
1	REAR BUMPER REINFORCEMENT	DENTED / BENT	520.00	520.00
2	REAR BUMPER STAYS	SERVICEABLE	150.00	-
2	REAR BUMPER CORNER RETAINERS	SERVICEABLE	80.00	-
2	REAR BUMPER SIDE RETAINERS	FASTENER SNAPPED	80.00	80.00
2	REVERSE SENSORS	SERVICEABLE	400.00	-
	LESS 10% DISCOUNT		-	-366.60
			7,850.00	3,299.40
	SPECIAL NETT ITEMS			
1	TAILGATE GLASS PRIMER (SN)	SERVICEABLE	60.00	-

Report Ref No. CS3/AIG19019974/Gsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE GLASS SEALANT (SN)	SERVICEABLE	50.00	-
1	REAR PANEL SEALANT (SN)	NECESSARY	60.00	40.00
30	RIVETS (SN)	NECESSARY	135.00	30.00
1	SET REVERSE CAMERA UNIT (SN)	SERVICEABLE	300.00	-
1	REAR NO. PLATE WITH CASING (SN)	DENTED / BENT	50.00	50.00
			655.00	120.00
	LABOUR			
	TRANSFER TAILGATE GLASS ASSY. TO NEW TAILGATE ASSY. AND REFIT.	NOT NECESSARY	200.00	-
	REMOVE TAILGATE FITTINGS, CHECK, RENEW DAMAGED FITTINGS, TRANSFER ALL FITTINGS TO NEW TAILGATE ASSY. AND REFIT.	NOT NECESSARY	150.00	-
	REMOVE NECESSARY INTERIOR UPHOLSTERYS AND FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME.		200.00	60.00
	RENEW REVERSE CAMERA UNIT AND REVERSE SENSORS, CHECK, RENEW IF REQUIRED, TRANSFER SAME TO REAR BUMPER RESPECTIVELY, REFIT AND CALIBRATE BOTH SYSTEMS.		200.00	80.00
	REMOVE LAMPS, NECESSARY WIRINGS AND ELECTRICAL FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK, REPLACE DAMAGED PARTS, REFIT SAME, TEST ELECTRICAL-CIRCUIT.		60.00	30.00
	REMOVE DAMAGED PARTS, JACK AND CUT OUT DAMAGED BODY PANELS, JACK OUT, STRAIGHTEN UP DAMAGED BODY PANELS AND REPAIR BODY PARTS AND FITTINGS, WHICHEVER POSSIBLE AND NECESSARY, REPLACE AND WELD NECESSARY DAMAGED PARTS, REFIT AND ALIGN WHICHEVER PARTS NECESSARY. (INCL. ALIGNMENT OF BODY STRUCTURE), INCLUSIVE OF THE REPAIR OF TAILGATE.		1,400.00	600.00
	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE.		1,600.00	600.00
	RUSTPROOF REPLACEMENT PARTS AND TOUCH-UP DAMAGED SECTIONS.		200.00	60.00
	CONDUCT DIAGNOSTIC PROGRAMMING AND CALIBRATION.	NOT NECESSARY	300.00	-
			4,310.00	1,430.00
	GRAND TOTAL		12,815.00	4,849.40



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,850.00
---	--	--	----------

Report Ref No. CS3/AIG19019974/Gsd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.