

ASS. REC. BY:

REF:

es/cr20000066 / Av d3⁵² Special InstructionsSurveyor: Adrian

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of

CTI

Date/Time:

21/11/19 @ 3:33pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBP 7578X

Insured:

7251R
YP7521R

at Workshop m/s

JEC Auto

Tel:

9232 7457.

of

1 Kaki Bukit Ave G # 02-11 Autobay

Policy No:

Claim No:

SNM 20D.200005C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:52pm @ 21/11/2020

Person Contacted:

Ah Xian

Vehicle In / OUT

Date/Time

Action/Instruction

Estimate ✓FBP 7578X - XYP7521R - X26/2/20Adrian confirmed LS \$ 2800 (Red 2308, 451)

ASSIGNMENT

Form

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

FBP7578X

2019 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Honda - CB190X

cc 184

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

10973

T/Radio: Insured / Std / NI / NA

Eng/No

C/No

LWBPC11A0J100A808

Gen. Cond: Goody / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

120/70 R17

R:

140/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CST

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. mm

L/Bal. mm

D.O.A.

D.O.I.

07/01/20

Survey held at

JEL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP Chinn

MV: 8K

PV: 2.61K

Nett: 5.4K

RECEIVED 26 FEB 2020

Date/Time: File Pass to?

☐

: Preli. Report

if

☐

: Final Report

Date/Time: File Return to?

06/2 - typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee

Transportation

2 x PS

Notes

Sign

Report Returned

Comp. Sum of Est. Cost

merimen

4/5 \$2800/2

Add'l Fees:

☐

Site Insp. (S)

☐

Interview (S)

☐

Technical (S)

☐

Contract (S)

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 2 January 2020 3:33 PM
To: alfred_ng@juseq.com.sg; 'assignments'
Subject: RE: ACCIDENT INVOLVING FBP7578X AND YP7251R ON 30 DECEMBER 2019.
Attachments: PRI FBP7578X.PDF

WITHOUT PREJUDICE

Dear Alfred,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: alfred_ng@juseq.com.sg [mailto:alfred_ng@juseq.com.sg]
Sent: Thursday, January 2, 2020 3:04 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: ACCIDENT INVOLVING FBP7578X AND YP7251R ON 30 DECEMBER 2019.

Your ref: SNM20D200005C02

Our ref: JEQ/FP7578X/JEC

Dear Kah Leong,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

Adrian Ling

Please be informed that our client's vehicle is available for inspection at the under stated workshop:-

JEC AUTOSERVICE

1 Kaki Bukit Ave 6

#02-11 Autobay

Singapore 417883

Contact person: Ah Xian

Mobile : 92327457 Fax No. 65096584.

With Regards

Alfred Ng

Executive

Legal Division

On behalf of Mr. Michael Yap

M/s JusEquity Law Corporation

No. 133 New Bridge Road

Chinatown Point

#10-03 Singapore 059413

Tel : 6536 9339

Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/12/2019 12:50
Date Of Accident	30/12/2019 09:30
Exact Location Of Accident	NEYTHAL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP7578X
Insured/Policyholder	
Name Of Registered Owner	GAO XIANG
NRIC No	S8684139H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91880861
Alternative Phone No	OTHERS-94288885

Vehicle Particulars

Manufacturer	HONDA
Model	CBX 200-197CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5110225016
Cover Note Number	07/06/2019 - 06/06/2020

Driver

Name of Driver	GE CHANGQING
Work Permit No	G6867693U
Date Of Birth	06/08/1981
Occupation	INDOOR
Date Of Driving Pass	07/07/2015
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94288885
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	C/O 59 UBI AVE 1 #06-13
Postcode	408938
Was driver an employee of the Insured's Company	NO
If No. Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY MOTORBIKE WAS STOPPED STATIONARY ALONG NEYTHAL ROAD. WHILE WAITING FOR MAIN TRAFFIC CLEARANCE. I SAW VEHICLE B TURNING IN AT A NARROW ANGLE. I SOUNDED MY HORN AT VEHICLE B BUT STILL VEHICLE B HIT ONTO MY MOTORBIKE FRONT PORTION. I THEN FELL TO THE RIGHT SIDE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP7251R
Vehicle Make/Model/Colour	
Details Of Properties	RIGHT PORTION
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ALAM MOHAMMAD SHAHIN
NRIC/Passport Number	G2135039M
Contact Number	85394429
Address	96171701
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Report No: M1

D.O.A

Vehicle No:

Make / Model:

Report Date: 30/12/2019 Start Time: 1:03 PM

Reporting Type: TP End Time:

FBP7578X

HTCB200

30/12/19

IMPORTANT NOTICE

SKETCH PLAN

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.

30/12/2019 13:02


30/12/2019 13:02

Policyholder's Signature
Date & Time:

Driver's Signature (if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Chen JunLiang
NRIC/ Fin No: S990765

SKETCH PLAN



MY MOTORBIKE WAS STOPPED STATIONARY ALONG NEYTHAL ROAD. WHILE WAITING FOR MAIN TRAFFIC CLEARANCE, I SAW VEHICLE B TURNING IN AT A NARROW ANGLE. I SOUNDED MY HORN AT VEHICLE B BUT STILL VEHICLE B HIT ONTO MY MOTORBIKE FRONT PORTION. I THEN FELL TO THE RIGHT SIDE.

DECLARATION

We declare the foregoing particulars are true in every respect.

30-12-2019 13:02

Policyholder's Signature
Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder)
Date & Time

30-12-2019 13:02

Reporting Centre Personnel's Signature
Name: Chen JunLiang
NRIC/ Fin No: S990765

[Signature]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	139H
Vehicle Details	
Vehicle No.:	FBP7578X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	CB190X MANUAL
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	WH161FMK18M00029
Chassis No.:	LWBPCL1A0J1004808
Maximum Power Output:	-
Open Market Value:	\$2,970.00
Original Registration Date:	06 Jun 2019
First Registration Date:	06 Jun 2019
Transfer Count:	1
Actual ARF Paid:	\$446.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jun 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,202.00
COE Rebate Amount:	\$2,561.00
Total Rebate Amount:	\$2,561.00

The information contained herein is correct as at 07 Jan 2020

OK

Advertisement



Home > Motorbikes > Motorbikes for Sale > Class 2B



nifster



Chat

Make Offer

\$S\$7,000

Share

35

Cb190x Tourism up for sale

Blk18, Teck Whye Lane

Mailing · Meetup

Used

Honda cb 190x for sale

COE Expiry: May 2028

read more

3 weeks ago in Class 2B

✓ Honda

✓ Sports Tourer

Insurance

Meet-up

Blk18, Teck Whye Lane

Drop me a call if you want to view the bike

Shipping

Listed by nifster

Very Responsive



Check seller profile

Reviews for nifster



weech72

2020 Jan

Sincere and punctual buyer. Thks!

Read all 21 reviews



Advertisement

all roads



You may also like

FBP7578X 2019 June.

TP China
Veron

Honda CB190X 184cc

LWBPCLI1A0J1004808

Front Number Plate Sticker.	Ner	10(SN)	✓
Front Windshield.	ut	125	✓
Headlamp	cracked	455	✓
Headlamp Stay.	Ner	135	X
Headlamp Panel.	cracked	215	✓
Front Fender.	cracked	90	✓
Front Fork X02 Bent		450 X 2 = 900.	✓
Front Fork Under Bracket	cracked	235	✓
Steering Cone and Bearing.	Ner	90(SN)	✓
Fork Oil	Ner	30(SN)	✓
Handle Bar	Bent	190	✓
Front Brake Disc	Ner	185.	X
Front RH Signal Lamp	ut	60	✓
Balancer RH	ut	38	✓
Lever Protector RH.	ut	140	✓
Slider RH	ut	110(SN)	✓
Front RH Wing Mirror	ut	55	✓

FBP7578X

Front RH Footrest	} Cut	55 ✓
Rear RH Footrest		55 ✓
Rear Exhaust Pipe	Rejs	550 +
Rear Exhaust Protector	ut	65 ✓
Rear Box	ut	280(SN) 200(SN)
Rear Box Bracket.	N/P NM	150(SN) X
2553	S.N 440	
2297.70		

Labour	300 250
Spry Painting.	250 250
Wiring.	50 30
To straighten chassis body	250 200
Towing Charges.	<u>40</u> ✓ 770

5108*

Total 3507.70

h/s/ 2.8k

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jan 2020		02 Jan 2020 16:44 Edit Adj Rpt	S\$2,800.00 Edit Estimates	S\$2,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:	-, Co. Reg. No.: -			
Main Claimant:	GAO XIANG , ID: S8684139H			
Vehicle Reg. No.:	FBP7578X	Date of Loss:	30/12/2019 09:00 - :59 [6 Months and 24 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM20D200005C02	Policy/Cover Note No.:	DMCVSN30619819000	
Vehicle Reg. No. (Insured):	YP7251R	Policy No. (Claimant):	5110225016	
		Excess:	S\$450.00	
Repairer:	Jec Autoservice (HQ) 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY, 417883 Kaki Bukit - Tel: 92327457			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/01/2020]			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS			View All	Search Tasks
Due Date	Priority	Type	Task Group	Subject
Handler	Assigned By	Completed On	Created On	Done?
No results.				






























Claim Documents































































































***FBP7578X (SNM20D200005C02)**
[YP7251R]
























TP
GAO XIANG
Dec 30 2019 9:00AM
[-]
Jec Autoservice

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼


Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	30/12/19 13:13	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	30/12/19 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/02/20 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
19	26/02/20 08:44	General View	 Load JPG	
20	26/02/20 08:44	General View	 Load JPG	
21	26/02/20 08:44	General View	 Load JPG	
22	26/02/20 08:44	General View	 Load JPG	
23	26/02/20 08:44	General View	 Load JPG	
24	26/02/20 08:44	General View	 Load JPG	
25	26/02/20 08:44	General View	 Load JPG	
26	26/02/20 08:44	General View	 Load JPG	
27	26/02/20 08:44	General View	 Load JPG	
28	26/02/20 08:44	General View	 Load JPG	
29	26/02/20 08:44	General View	 Load JPG	
30	26/02/20 08:44	General View	 Load JPG	
31	26/02/20 08:44	General View	 Load JPG	
32	26/02/20 08:44	General View	 Load JPG	
33	26/02/20 08:44	General View	 Load JPG	
34	26/02/20 08:44	General View	 Load JPG	
35	26/02/20 08:44	General View	 Load JPG	
36	26/02/20 08:44	General View	 Load JPG	
37	26/02/20 08:44	General View	 Load JPG	
38	26/02/20 08:44	General View	 Load JPG	
39	26/02/20 08:44	General View	 Load JPG	
40	26/02/20 08:44	General View	 Load JPG	
41	26/02/20 08:44	General View	 Load JPG	
42	26/02/20 08:44	General View	 Load JPG	
43	26/02/20 08:44	General View	 Load JPG	
44	26/02/20 08:44	General View	 Load JPG	
45	26/02/20 08:44	General View	 Load JPG	
46	26/02/20 08:44	General View	 Load JPG	
47	26/02/20 08:44	General View	 Load JPG	
48	26/02/20 08:44	General View	 Load JPG	
49	26/02/20 08:44	General View	 Load JPG	
50	26/02/20 08:44	General View	 Load JPG	
51	26/02/20 08:44	General View	 Load JPG	
52	26/02/20 08:44	Reinspection Photo	 Load JPG	
53	26/02/20 08:44	Reinspection Photo	 Load JPG	
54	26/02/20 08:44	Reinspection Photo	 Load JPG	
55	26/02/20 08:44	Reinspection Photo	 Load JPG	
56	26/02/20 08:44	Reinspection Photo	 Load JPG	
57	26/02/20 08:44	Reinspection Photo	 Load JPG	
58	26/02/20 08:44	Reinspection Photo	 Load JPG	
59	26/02/20 08:44	Reinspection Photo	 Load JPG	
60	26/02/20 08:44	Reinspection Photo	 Load JPG	
61	26/02/20 08:44	Reinspection Photo	 Load JPG	
62	26/02/20 08:44	Reinspection Photo	 Load JPG	
63	26/02/20 08:44	Reinspection Photo	 Load JPG	
64	26/02/20 08:44	Reinspection Photo	 Load JPG	
65	26/02/20 08:44	Reinspection Photo	 Load JPG	
66	26/02/20 08:44	Reinspection Photo	Load JPG	

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
67	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	26/02/20 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/01/20 13:52	Pre-Repair Survey	 Load PDF	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	30/12/19 13:11	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View <input data-bbox="1321 1323 1492 1346" type="button" value="View in Browser"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	1 per page ▼ <input checked="" type="checkbox"/>
1	30/12/19 13:13	Accident Statement	 Load HTM
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail
1	30/12/19 12:54	Accident Photo	 Load JPG
2	30/12/19 12:54	Accident Photo	 Load JPG
3	30/12/19 12:54	Accident Photo	 Load JPG
4	30/12/19 12:54	Accident Photo	 Load JPG
5	30/12/19 12:54	Accident Photo	 Load JPG
6	30/12/19 12:54	Accident Photo	 Load JPG
7	30/12/19 12:54	Accident Photo	 Load JPG
8	30/12/19 12:54	Accident Photo	 Load JPG
9	30/12/19 12:54	Accident Photo	 Load JPG
10	30/12/19 12:54	Accident Photo	 Load JPG
Documentation			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail Print
1	30/12/19 13:11	Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20000066/AVD3S2
Date: 27/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30619819000
 Claimant Vehicle No: FBP7578X Insured Vehicle No: YP7251R
 Date of Loss: 30/12/2019 Nature of Claim: TP Claim No: SNM20D200005C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP7578X**
 Make & Model: HONDA CBX 200, 197cc Engine No: WH161FMK18M00029
 Reg. Date: 06/06/2019 (Man. Year: 2018) Chassis No: LWPCL1A0J1004808
 Colour: White Odometer: 10973 km
 Engine Capacity: 184 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 140/70 R17
 Front Left Side: CST 6 mm Rear Left Side: CST 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,218.00	2,850.20	1,367.80	32.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	890.00	770.00	120.00	13.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,108.00	3,620.20	1,487.80	29.13
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	5,108.00	2,800.00	2,308.00	45.18

INSPECTION

Date of Assignment: 02/01/2020
 Date Inspected: 07/01/2020 Inspected At: Jec Autoservice (HQ)
 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Feb 2020)	
Parts:	N/A	HONDA CBX 200 197cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP7578X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSHIELD	Cut	125.00 F	*125.00 FL
2	1		*HEADLAMP	Cracked	455.00 F	*455.00 FL
3	1		*HEADLAMP STAY	Not Necessary	135.00 F	*- FL
4	1		*HEADLAMP PANEL	Cracked	215.00 F	*215.00 FL
5	1		*FRONT FENDER	Cracked	90.00 F	*90.00 FL
6	2		*FRONT FORK	Bent	900.00 F	*900.00 FL
7	1		*FRONT FORK UNDER BRACKET	Damaged	235.00 F	*235.00 FL
8	1		*HANDLE BAR	Bent	190.00 F	*190.00 FL
9	1		*FRONT BRAKE DISC	Not Necessary	185.00 F	*- FL
10	1		*FRONT RH SIGNAL LAMP	Cut	60.00 F	*60.00 FL
11	1		*BALANCER RH	Cut	38.00 F	*38.00 FL
12	1		*LEVER PROTECTOR RH	Cut	140.00 F	*140.00 FL
13	1		*FRONT RH WING MIRROR	Cut	55.00 F	*55.00 FL
14	1		*FRONT RH FOOTREST	Cut	55.00 F	*55.00 FL
15	1		*REAR RH FOOTREST	Cut	55.00 F	*55.00 FL
16	1		*REAR EXHAUST PIPE	Repair	550.00 F	*- FL
17	1		*REAR EXHAUST PROTECTOR	Cut	65.00 F	*65.00 FL
18	1		*FRONT NUMBER PLATE STICKER	Necessary	10.00 FS	*10.00 FS
19	1		*STEERING CONE AND BEARING	Necessary	90.00 FS	*90.00 FS
20	1		*FORK OIL	Necessary	30.00 FS	*30.00 FS
21	1		*SLIDER RH	Cut	110.00 FS	*110.00 FS
22	1		*REAR BOX	Cut	280.00 FS	*200.00 FS
23	1		*REAR BOX BRACKET	Not Necessary	150.00 FS	*- FS
				Sub Total (\$\$)	4,218.00	3,118.00
				- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	267.80
				Total Parts (\$\$)	4,218.00	2,850.20

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR.	New	300.00	250.00
2	SPRAY PAINTING.	New	250.00	250.00
3	WIRING.	New	50.00	30.00
4	TO STRAIGHTEN CHASSIS BODY.	New	250.00	200.00
5	TOWING CHARGES.	New	40.00	40.00
Gross Labour Cost (\$\$)			890.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >