COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

Via Fax

Date

Your Insured

Time of Fax:

Date of Acc

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- Our initial estimate of repairs of the damaged vehicle;
- Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

 Lim Kwok Eng Jumani Bin Masudin 	Tel: 6214 8316 or HP: 9824 0811 Tel: 6214 8315 or HP: 9635 5305	jumanibm@cdge.com.sg
 Lim Tien Siong 	Tel: 6214 8398 or HP: 9635 8546	Fax no. 6546 8156
 Chiang Liat Choon 	Tel: 6214 8314 or HP: 9296 6006	(
 Larry Ng Nyuk Phin , 	Tel: 6214 8315 or HP: 9230 2824	
 Fauzy Bin Mokhtar 	Tel: 6214 8319 or HP: 8125 9176)

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President Crash Repairs & Claims Recovery

OMFORIDELGRO ENGINEERING

member of **ComfortDelgro**

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755 Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 509286 320 Ubi-Road 3 Singapore 509286 321 Ubi-Road 3 Singapore 509286 320 Ubi-Road 3 Singapore 509286 321 1:59 Pt.

24 Senoko Loop Singapore 758156 7 Sungai Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

Page: 1

Team: ARC Repair TP(CFSO)1	JOB CARD	Sales Order: 3980060	JC NO.: 305369733
FOMER CITEVISIA DEEL LED		REGN NO.: SHA8660S	MILEAGE
AS CITYCAB PTE LTD FOMER NO. 7010070	超	MAKE: HYUNDAI	FUEL EF
RESS 383 SIN MING DRIVE Singapore SINGAPORE 57 (B) 65551188	5717	MODEL I-40	DATE/TIME IN 24.12.2019 17:25
(R) 65551188 (O)		YR OF MANU. 14.07.2016	TARGET DATE
OUNT CARD NO.		CHASSIS CODE KMHLB41UMGU09228	COMPLETION DATE/TIME:
Accident Date: 24.12.2019 NATURE: 3P 24.12.19	JOB DESCRIPTION		-
S/NO LABOR CODE 23-01	DESCR TOWING FEE	RIPTION	FRONT SIDE
XED & PASSED OUT BY:		CUSTOMER'S SIG	SNATI IDE
	9	COSTOWER'S SIG	AIVAI UKE
dgement Slip	Exit Pass	# %	

Service Advisor urned to Service Reception upon collection

SHA8660S

JU AIG

Signature/Date

0.:

Name of Service Advisor

Vehicle No.:

Date

To be kept by Security Guard

SHA8660S

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 8660S

MAKE :

MODEL : HYUNDAI i40

DATE 26/12/2019 9:30

MODEL	: HYUNDAI i40			_			
Qty	Parts Description/ Labour	Type		Unit Price		Amount]
	Rear Bumper				\$	553.00	1
	Rear Bumper Reinforcement				\$	428.40	
1	Rear Bumper Reinforcement Bracket (LH/RH)		\$	80.30	\$	160.60	
	Rear Bumper Clip 10 pcs				\$	22.00	
1	Rear Bumper Bracket		\$	35.60	\$	71.20	1
	Rear Bumper Sponge				\$	103.50	
	Rear Bumper Under Cover				\$	228.00	
	SUB TOTAL				\$	1,566.70	ĺ
	LESS 20%				\$	313.34]
	DISCOUNTED TOTAL				\$	1,253.36	ĺ
					1		
1	Rear Bumper Reverse Sensor			2	\$	135.70	Nett
	Rear Bumper Advertisement Logo				\$	50.00	Nett
	Rear Bumper Rubber Mat				\$	50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$	100.00	\$		Nett
	Team Tender Travertisement Logo (Librar)		Ψ	100.00	"	200.00	nen
	3				\$	435.70	1
					4	433.70	1
	ale de						
	9.						
,	T V CI						
	Labour Charge						
	Panel Beating				\$	350.00	
1	Spray Painting Charge				\$	250.00	
	Wiring Charge				\$	50.00	
	Remove/Refix Reverse Sensor				\$	80.00	
	TOWING				W	60.00	
	TOTAL LABOUR				\$	730.00	
	ESTIMATE TOTAL	1			\$	2,419.06	
	This is an initial estimate based on a visual inspection of the	e ahove vel	nicle	The final renair of	llant	um will	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.						
L	to prepared after the vehicle is surveyed by a motor Survey	or appointe	u os	ule insurance con	upan	у.	

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline +65 6383 6280 Facsimile +65 6280 9755

Verallinie + 50 6050 200 Patisimilie + 50 5260 9750 Service Centres 256 Braddell Road Singapore 57971 45 Pandan Road Singapore 509285 7 Sungel Kadut Way Singapore 728791 24 Senoko Loop Singapore 758156





JOB REQUISITION FOR	BREAKDOWN / TOWING SER	VICE
Job Requisition		
1. Date: 74 11 Time Received: 1743 2. New SPARK Kakis Name of Customer: Contact No.: 96605081 Vehicle No.: SHA8660S	3. Vehicle Type: Private Taxi (CTPL/CCPL) Fleet STK (Boon Lay)	4. Type of Towing: Normal Tow King Dolly Flat Bed Crane-up
Make / Model / Colour: Email	5. Nature of Service: Jumpstart Recovery Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: 9. Preferred Workshop: Braddell	Smol	
10. Odometer Reading : Fuel Level : F 1/4 1/2 3/4 E Job Attended	11. Radio / CD Player OK Faulty Not tested	THORE AND ADDRESS OF THE PROPERTY OF THE PROPE
12. Tow Truck / Recovery Van : VRS QA GAC Name of Driver : GACAT Vehicle No. : Y3556C Time Dispatch : L43 Time of Arrival : L86	TZ YISHUN OTHERS	#: Cracked X: Dented /: Scatched O: Missing
Time Completed :	*	Signature of Customer
Cash Invoice Details (if applicable)		
13. Cash Invoice No.		
Customer Acknowledgement		
a. I have been advised to remove all valuable items in my vehicle, includin cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK oc. Surcharge: Towing fee will be levied if the customer decides neither to be decided by the customer d	Car Care™ will not be held liable for such los tow nor proceed with the repairş in SPARK C	eses.
14. <u>WORKSHOP</u>		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	26/12/2019 11:30
Date Of Accident	24/12/2019 17:25
Exact Location Of Accident	BRADDEL RD THOMSON RD
Country/State of Loss	SINGAPORE
FIRST STEEL STATE	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHA8660S
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer **HYUNDAI** Model 140

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number D-18088937MFSH

Cover Note Number

Driver

Name of Driver YEO HOOI CHYE NRIC No SXXXX042D Date Of Birth 28/12/1962 Occupation **OUTDOOR** Date Of Driving Pass 05/03/1980

Driving Experience 39 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96605081

Fax Number

Contact Number

EMail Address DONYEO89@GMAIL.COM Address

BLK 879 YISHUN STREET 81

#04-249

Postcode

760879

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

8 +

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SLD7797A

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TOH LYE HENG

NRIC/Passport Number

Contact Number

97438293

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

Name

YEO HOOI CHYE

Approximate Age

Injuries Sustain

NECK AND BACK

Injured person in which vehicle?

SHA8660S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

NO

Address Postcode

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal Information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CO. REG. NO. 199502839G

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Jan 26/12

Name:

NRIC/FIN No.:

GIARMS SketchPlanCorp., 93

die 4

Sketch Plan Pg. 2

SKETCH PLAN		37
	Road Leading to	
	amp to Larme highway	
Braddel		A SHARE
Kaad -		+
DESCRIBE CIRCUMSTANCES	construction sure	
DESCRIPCE CIRCUIVISTANCES		19 @_ 1705 hu
	J Vert @ SA	low down and stop
	Due to infrat	velvele Boake.
	Sudderly VeH (R)	Kom tu Rear
	hut vest (4) Rea	v- or the point
	of accident	vert & femy or lemane
	my toe sup	in .
	<u> </u>	
CLARATION		
CLARATION Ve declare the foregoing particula	rs are true in every respect.	2 2
CITYCAE PTE LTD CO. REG. NO. 199602830G	X	J. Marg. soli
cyholder's Signature e & Time:	Driver's Signature (If driver is not the policyholder)	Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

eigende skaathpinform vil

Date & Time: