

A.S.S. REC. BY:

REF: 083/FWD 200000-70

Special Instruction:

Surveyor: Taufik H

ASSIGNMENT (Office)

From (Person): Vanessa Chan

of

PUD

Date/Time: 21/2020 @ 11:43am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCZ 3399H

Insured:

FW 2468D

at Workshop m/s

Han Car Repairs

Tel:

9777 7266

of

BLK 1001 Bukit Merah Lane 3 # 01-49

Policy No:

PNMC 2019-0000 3957

Claim No:

1201900042692

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:12pm @ 21/2020

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time	Action/Instruction
	Isimall (X)
	SCZ 3399H - NBA / INC / 19022742 / Y
	FW 2468D - NBA / INC / 19022742 / Y
	Disassemble - 8/1/2020
10/1/2020	Submit PRS, repair range \$3000 - \$4000

DUA: 26/12/2019

DUA: 26/12/2019

ASS. FED. BY:

Taufik

REF:

PWD

## ASSIGNMENT

From

Date:

6/1/2020

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SCZ 3399H

at Workshop m/s

Han Car Repair

of BLK 1001 #01-49 Bukit Merah Lane 3

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

9140K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

imp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SCZ 3399H

Yr Regn:

2019 Jan

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Peugeot 5008

c.c

1598

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

20434

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF3M45G2W.JL052367

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

6/1/20

Survey held at

Han Car Repair

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

93000-94000, 4 days.

RECEIVED 10 JAN 2020

8/1/2020

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2) 10/1 - typist

Report Format:

PRS

Lump Sum / LE: (\$)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

80

Transportation:

50

3 + RS, SI

Folio:

Others:

TOTAL

130

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2020 <a href="#">Edit Reg</a>		02 Jan 2020 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	Muhammad Ghaffuri Bin Rohan, ID: S8701228Z								
Main Claimant:	FOK EN CI, KELVIN (HUO EN'CI), ID: S8524692E								
Vehicle Reg. No.:	SCZ3399H	Date of Loss:	26/12/2019 00:00 - :59						
Claim Type:	TP / 1201900042692	Policy/Cover Note No.:	PNMC2019-00003957 (Comprehensive) Coverage: 27/08/2019 - 26/07/2020						
Vehicle Reg. No. (Insured):	FW2468D	Policy No. (Claimant):							
		Excess:							
Repairer:	Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/01/2020]								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** venessa.chan@fwd.com  
**Sent:** Thursday, 2 January 2020 11:43 AM  
**To:** 'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'  
**Cc:** motorclaims.sg@fwd.com; eileen.bay@fwd.com  
**Subject:** ACCIDENT INVOLVING SCZ 3399H AND FW 2468D ALONG SELETAR EXPRESSWAY TOWARDS TAMPINES EXPRESSWAY ON 26th DECEMBER 2019 AT ABOUT 1730 HRS

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen .

Kindly upload all correspondence emails/documents sent to you into Merimen.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




**FWD Singapore Pte. Ltd.**

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



---

**From:** Venessa Chan - SGUser

**Sent:** Thursday, January 2, 2020 11:42 AM

**To:** 'Winston Low'

**Cc:** weeyuweed@gmail.com; Motor Claims SG - SG Common; Eileen Bay - SGUser

**Subject:** ACCIDENT INVOLVING SCZ 3399H AND FW 2468D ALONG SELETAR EXPRESSWAY TOWARDS TAMPINES EXPRESSWAY ON 26th DECEMBER 2019 AT ABOUT 1730 HRS

WITHOUT PREJUDICE

Dear Winston,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/S **LKK Auto Consultants** to conduct the pre-repair survey (PRS) on your client's vehicle,

SCZ3399H. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

***\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com).***

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




**FWD Singapore Pte. Ltd.**

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



---

**From:** Winston Low [<mailto:winstlow@singnet.com.sg>]

**Sent:** Thursday, January 2, 2020 11:33 AM

**To:** Venessa Chan - SGUser

**Cc:** [weeyuweed@gmail.com](mailto:weeyuweed@gmail.com); Motor Claims SG - SG Common; Eileen Bay - SGUser

**Subject:** RE: ACCIDENT INVOLVING SCZ 3399H AND FW 2468D ALONG SELETAR EXPRESSWAY TOWARDS TAMPINES EXPRESSWAY ON 26th DECEMBER 2019 AT ABOUT 1730 HRS

Our Ref: SCZ 3399H Your Ref: FW 2468D

Dear Sirs

Our client objects appointing your surveyors as a single joint expert.

We propose on the following surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

- 1) Michael Yap Teck Chye (Mc-Coy Appraiser Pte Ltd)
- 2) Dixon Yeo (Treasure Appraisal Services)
- 3) Dennis Yap Teck Wee (Pal's Appraiser Pte Ltd)
- 4) Andy Yap Teck Lee (LCW Appraiser Pte Ltd)

Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Regards

M/s Winston Low & Partners

cc: clients

---

**From:** [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com) [<mailto:venessa.chan@fwd.com>]

**Sent:** 02 January 2020 11:19

**To:** [winstlow@singnet.com.sg](mailto:winstlow@singnet.com.sg)

**Cc:** [weeyuweed@gmail.com](mailto:weeyuweed@gmail.com); [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com); [eileen.bay@fwd.com](mailto:eileen.bay@fwd.com)

**Subject:** ACCIDENT INVOLVING SCZ 3399H AND FW 2468D ALONG SELETAR EXPRESSWAY TOWARDS TAMPINES EXPRESSWAY ON 26th DECEMBER 2019 AT ABOUT 1730 HRS

WITHOUT PREJUDICE

Dear Winston,

Refer to your email dated on 02.01.2020 of the PRI Notice of your client's vehicle SCZ3399H;

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

\*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

**\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com).**

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E : [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W : [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** Winston Low [<mailto:winstlow@singnet.com.sg>]

**Sent:** Thursday, January 2, 2020 10:04 AM

**To:** Motor Claims SG - SG Common

**Cc:** 'weeyuweed weeyuweed'

**Subject:** ACCIDENT INVOLVING SCZ 3399H AND FW 2468D ALONG SELETAR EXPRESSWAY TOWARDS TAMPINES EXPRESSWAY ON 26th DECEMBER 2019 AT ABOUT 1730 HRS

Our Ref: SCZ 3399H

Your Ref: FW 2468D

Dear Sirs

1. We act for Mr Fok En Ci, Kelvin, owner of vehicle no. SCZ 3399H.
2. We are instructed to claim damages against you in connection with the above accident.
3. Pursuant to the State Courts NIMA Protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -

Venue: **Han Car Repairs**  
Address: 1001 Bukit Merah Lane 3  
#01-49, Alexandra Village  
Singapore 159718  
Contact: Ms. Susan Chin @ 9777 7266

4. TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Regards

Winston Low  
M/s Winston Low & Partners  
111 North Bridge Road  
#11-03 Peninsula Plaza  
Singapore 179098  
Tel: 6338 8722  
Fax: 6339 9722

cc : client (SCZ 3399H)

---

Notice & Disclaimer:

The information contained in this email (including all attachments) is both confidential and protected by

legal professional privilege. It is intended for the use only of the addressee named. If you are not the intended recipient, you are hereby notified that any dissemination, distribution, publication or copying of this email is strictly prohibited. If you have received this email in error, please accept our apologies, delete the original email from your system including all copies made, and notify us by return email at [winstlow@singnet.com.sg](mailto:winstlow@singnet.com.sg)

Winston Low & Partners do not guarantee the integrity and security of Internet communications. Although we have taken reasonable precautions to scan outgoing and incoming emails and attachments for viruses, we cannot guarantee this communication to be free of all viruses nor are we responsible for any consequences caused by viruses.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	692E
<b>Vehicle Details</b>	
Vehicle No.:	SCZ3399H
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2020
Vehicle Make:	PEUGEOT
Vehicle Model:	5008 ALLURE 1.6 E-THP EAT6
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	10FJCS2475613
Chassis No.:	VF3M45GZWJL052367
Maximum Power Output:	121.4 kW (162 bhp)
Open Market Value:	\$32,445.00
Original Registration Date:	16 Jan 2019
First Registration Date:	16 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$37,423.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jan 2029
PARF Rebate Amount:	\$28,067.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 Jan 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$30,851.00
COE Rebate Amount:	\$27,832.00
<b>Total Rebate Amount:</b>	<b>\$55,899.00</b>

The information contained herein is correct as at 07 Jan 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/12/2019 10:15
Date Of Accident	26/12/2019 17:30
Exact Location Of Accident	SLE TOWARDS TPE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCZ3399H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FOK EN CI, KELVIN (HUO EN'CI)
NRIC No	SXXXX692E
Email Address	JONATHANFOK@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-81813945
Alternative Phone No	OTHERS-81813945

### Vehicle Particulars

Manufacturer	PEUGEOT
Model	5008
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106926368
Cover Note Number	

### Driver

Name of Driver	JONATHAN FOK EN HAO
NRIC No	SXXXX033D
Date Of Birth	08/01/1992
Occupation	INDOOR
Date Of Driving Pass	29/04/2011
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81813945
Fax Number	
Contact Number	OTHERS-81813945
EMail Address	JONATHANFOK@OUTLOOK.COM

Address	124 YUNNAN CRESCENT
Postcode	638330
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FW2468D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 27/12/2019 12:22 PM


Reporting Centre Personnel's Signature  
Name: Kardi Lim  
NRIC/FIN No.:

### SKETCH PLAN

Site Lowpass TPE



Burger-Domäne



Left side  
Bumper Damage

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Motorcyclist did not manage to break in time and collided to the bumper of the vehicle.

[illegible]

I/We declare the foregoing particulars are true in every respect.

Driver's Signature: \_\_\_\_\_  
(if driver is not the policyholder)  
Date & Time: 22/12/2023 10:28 AM

Reporting Centre Personnel's Signature  
Name: Rohit  
IRAC/FIN No.:

## Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE

**IMPORTANT NOTE** : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

#### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: 2/11/19/170087 Vehicle Registration No: 9KZ 3399 H  
Name(as shown in NRIC): Jonathan Fok Fa Hoo  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
NRIC/Passport No: S9703033 D  
Address: 124 Yunnan Crescent (S) 638330  
Contact (Tel): 91913945 (H/P): \_\_\_\_\_  
(Email): \_\_\_\_\_  
Date of Accident: 26-12-2019 Time of Accident: 17:30  
Place of Accident: SLE TOLLROAD TPE  
Insurance Company: NTUC Ins.

#### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

① The vehicle in front of me slowed down and stopped.  
I also followed suit.  
Vehicle (B) behind me could not stop in time and hit  
my car (A)

② To change from 2 party to 3 party claim.



Signature of Vehicle Owner / Driver

Date:

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : +65 6224 0010 Fax : +65 6224 0030  
Operating Hours : Monday to Friday 9am to 5pm

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jan 2020 <a href="#">Edit Reg</a>		02 Jan 2020 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>Muhammad Ghaffuri Bin Rohan</b> , ID: S8701228Z									
Main Claimant: <b>FOK EN CI, KELVIN (HUO EN'CI)</b> , ID: S8524692E									
Vehicle Reg. No.: <b>SCZ3399H</b>		Date of Loss: 26/12/2019 00:00 - :59 [11 Months and 10 Days From LTA Reg Date (Man Yr)]	Policy/Cover Note No.: PPMC2019-00003957 (Comprehensive) Coverage: 27/08/2019 - 26/07/2020						
Claim Type: <b>TP / 1201900042692</b>		Policy No. (Claimant):	Excess:						
Vehicle Reg. No. (Insured): <b>FW2468D</b>		Repairer: <b>Han Car Repairs (HQ)</b> BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275							
Handling Insurer: <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Eileen Bay</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 13/01/2020]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SCZ3399H (1201900042692)  
[FW2468D]  
TP  
FOK EN CI, KELVIN (HUO EN'CI)  
Dec 26 2019 12:00AM  
[Muhammad Ghaffuri Bin Rohan]  
Han Car Repairs

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
2	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
3	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
4	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
5	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
6	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
7	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
8	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
9	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
10	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
11	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
12	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
13	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
14	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
15	10/01/20 09:40	General View	Load JPG	<input checked="" type="checkbox"/>
16	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	10/01/20 09:41	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>



Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
49	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	10/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/01/20 16:41	EMAIL TO ARRANGE FOR SURVEY		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	02/01/20 16:50	FW2468D OI GIA		Load PDF	
2	02/01/20 16:50	SCZ3399H TP GIA		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD20000070/T1VD3E2

Date: 15/01/2020

## REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2019-00003957

## Claimant

Vehicle No : SCZ3399H

Insured Vehicle No : FW2468D

Date of Loss: 26/12/2019

Nature of Claim: TP

Claim No: 1201900042692

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SCZ3399H

Make &amp; Model: PEUGEOT 5008, 1.6 (A)

Engine No: 10FJCS2475613

Reg. Date: 16/01/2019 (Man. Year: 2018)

Chassis No: VF3M45GZWJL052367

Colour: White

Odometer: 20434 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 02/01/2020

Date Inspected: 06/01/2020 Inspected At:

Han Car Repairs (HQ)  
BLK 1001 BUKIT MERAH LANE 3  
#01-49 ALEXANDRA VILLAGE  
Singapore 159718

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2020)
<b>Parts:</b>	M1-MPV	PEUGEOT 5008 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCZ3399H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >