

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305370546
REGN NO : SHC8242E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 02.04.2015
DATE/TIME IN : 30.12.2019 10:40
ACCIDENT DATE : 23.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0578-G	I40V2 COVER-FR BUMPER#	1	544.50	20.00	435.60	cut / def
0002 04-01-0103-0574-G	I40VC PANEL-FENDER LH#	1	566.30	20.00	453.04	20.00 DD
0003 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	XNN
SUB-TOTAL :						938.64

JOB NATURE

0000 PB	PANEL BEATING	600.00	\$560
0001 SP	SPRAYPAINT CHARGE	500.00	\$400
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	—
0003 20-05	RENEW ADVERTISEMENT STICKER-	100.00	rec —
SUB-TOTAL : 1,250.00			

TOTAL : 2,188.64

Jumani

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Ram (LKK)
30/12/19 1300hrs
para suram@lkkauto.com
88622778
(3) repairs
after repair photo
(LIS)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305370546
REGN NO : SHC8242E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 02.04.2015
DATE/TIME IN : 30.12.2019 10:40
ACCIDENT DATE : 23.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0578-G	I40V2 COVER-FR BUMPER#	1	544.50	20.00	435.60	Cut / Def
0002 04-01-0103-0574-G	I40VC PANEL-FENDER LH#	1	566.30	20.00	453.04	566.30 DD
0003 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	Xnn

SUB-TOTAL : 938.64

JOB NATURE

0000 PB	PANEL BEATING	600.00	\$560
0001 SP	SPRAYPAINT CHARGE	500.00	\$400
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	
0003 20-05	RENEW ADVERTISMENT STICKER-	100.00	rec

SUB-TOTAL : 1,250.00

TOTAL : 2,188.64

Jumani

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED : YES / NO

Ram (LKK)
30/12/19 1300hrs
parasuram@lkkauto.com
88622778
(3) repairs
after repair photo
(LIS)