Surveyor: Guo Qiang

REF: CS3/ASM18017024/Gtd3e2

Special Instruction:
L/S: $5600.00

ASSIGNMENT (Office)

From (Person): Xin Yi of Sea Hong Date/Time: 11/12/2019

Estimated Cost: Bill to:

Third Parties:
Claimant:
Surveyor: PAR Automotive
Workshop: Twincar Automotive

OR TP Re-inspection Evaluation

To Inspect Vehicle No: SLS 9720D Insured: SFB 5166R

at Workshop m/s Twincar Automotive Tel: 68420051

of 2 Kaki Bukit Ave 2 #01-18 Autohub

Policy No: GA342154/1 Claim No: 19.27384

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 15/09/2018

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red $ / %; Original 7 days)

Date/Time: 4/2 Submit Final Fig 2900 , 5 days (Red $ 2700 / 48 %; Original 7 days)

Date/Time	Action/Instruction
	SLS9720D-CS3/ASM18017024/Gtbe2 DOA: 15/09/2018
	SFB 5166R-CS3/ASM18017024/Gtbe2 DOA: 15/09/2018

4/2/2020

RECEIVED 05 FEB 2020

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	Date:
Basic & Add	150
Transport	
Photos	
Others	
Total	150

1) Date/Time 4/2/2020 File Pass to Typist 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to