



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 30/12/2019

User ID : JeongCH

Section A - Accident Details

Registration Number	SG5774E
Case Reference Number	BUS/12/19/5039
Registration Date	8/18/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Lim Chye Kiosk
Type of Accident	Head to Rear
Accident Date and Time	12/23/2019 7:50 AM
Accident Reported Date and Time	12/23/2019 9:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24105076
Special Instruction to ARC, if any	SG5774E-REAR RIGHT PORTION FBL2843J (TP) INSURED WITH EQ
Prepared Date and Time	12/27/2019 12:46 PM
Chassis Number	WMAA95ZZ7G7003250
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$432.00	\$262.00
Total Spare Part Cost	\$1,739.38	\$822.02
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,701.38	\$1,349.02
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	27/12/2019 1:36 PM	30/12/2019 2:27 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/12/2019

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$530.00				\$265.00			
Total Labour		\$530.00				\$265.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TO PUTTY & RESPRAY		\$432.00				\$262.00			
Total Spray Painting & Panel Beating		\$432.00				\$262.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298	VE	88-25225-6039	LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	Replace
6010299	VE	88-25320-6008	LAMP,INDICATOR:LED (MAN BUS)	0.00	\$1,274.10	0.00	\$0.00	Replace	Not Given
Total					\$2,415.80		\$1,027.53		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day 1 day

Lump Sum Repair
After paint photo.

Sun Pm (LKK)

30/12/2019.

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: