




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CC4/FCI20000108/Dea3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-08-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6387P		Veh. Inspected	SHA 9104A
Policy No.	D-19092580MFSH		Coverage (\$)	0.00
Claim No.	D20000040MFSH		Excess (\$)	0.00
Assign From	JOANNE YONG		Assign Date	30/12/2019
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS		c.c	1798
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	JTDKB3FU003561196		Colour	YELLOW
Odometer	-		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DAVANTI	5 mm
	L/H Front Tyre	195/65 R15	DAVANTI	5 mm
	R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
	L/H Rear Tyre	195/65 R15	DAVANTI	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/12/2019	Inspection Date	30/12/2019
	Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	