

Mechanical Inspection Report Request

Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>

Thu 12/12/2019 5:58 PM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; SPF-TP FAIT <SPF-TP_FAIT@spf.gov.sg>; Tiak Yee PHUA (SPF) <PHUA_Tiak_Yee@spf.gov.sg>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **9 vehicles** below: [The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]

- a) **Case IAFP-IB-20191211 - Mechanical Inspection of Motor Taxi, SHB1982D (TP/IP/74669/2019)**
- b) **Case IAFP-IB-20191211 - Mechanical Inspection of Motor Lorry, YP2418K (TP/IP/74669/2019)**
- c) **Case IAFP-IB-20191211 - Mechanical Inspection of Motor Scooter, FBG9070C (TP/IP/74669/2019)**

On 2 December 2019 (Monday) at about 7.37 p.m., the 1st Involved Party was travelling straight along Ayer Rajah Expressway towards Tuas, on lane 2 of the 4-lanes road while the 2nd Involved Party was travelling straight on lane 3, abreast of the 1st Involved Party. A while later, the Deceased who was travelling directly behind both Involved Parties, collided into the rear portions of both vehicles. It cannot be determined which vehicle the Deceased had collided into first. As a result of the accident, the Deceased sustained head injury and was reported to be unconscious. He was conveyed to the National University Hospital by ambulance. However, upon the Deceased's arrival in hospital, he suffered a traumatic arrest, succumbed to his injuries and was pronounced dead on the same day, at 8.57 p.m. by Dr Gene.

Vehicles to be inspected: SHB1982D - Driver (1st Involved Party)
YP2418K - Driver (2nd Involved Party)
FBG9070C - Rider (Deceased)

IO In-Charge: SIO Kamaliah

- d) **Case IAFP-IB-20191211 - Mechanical Inspection of Motor Car, SDV8101B (TP/IP/75659/2019)**

On 7 December 2019 (Saturday) at about 6.02 a.m., the Accused was travelling straight along Farrer Road towards Queensway, on lane 2 of the 4-lanes road when he veered towards the left side into lane 3 followed by lane 4 and subsequently mounted the left kerb, collided into the Deceased, who was walking along the sheltered footpath. After the collision, the Accused drove off without stopping. As a result of the accident, the Deceased sustained head injury and was pronounced dead at the scene, at 6.20 a.m. by the attending paramedic.

Vehicles to be inspected: SDV8101B - Driver (Accused)

SIO In-Charge: SIO Kamaliah

- e) **Case IAFP-IB-20191211 - Mechanical Inspection of Motorcycle, FBM4089B (TP/IP/72439/2019)**

On 21 November 2019 sometime before 10.45 a.m., the accused was riding his motorcycle on lane 1 of 2-lanes along Woodlands Avenue 2 at the slip road into SLE(CTE) when he lost control and skidded. Rider was conveyed to KTHP where he succumbed to his injuries and was pronounced dead on the same day at 11.37am.

Vehicles to be inspected: FBM4089B - Rider (Deceased)

SIO In-Charge: SIO Adrian Lim

- f) **Case IAFP-IB-20191211 - Mechanical Inspection of Motor Car, SKE1231L (TP/IP/72425/2019)**
- g) **Case IAFP-IB-20191211 - Mechanical Inspection of Bicycle (TP/IP/72425/2019)**

On 21 November 2019 sometime before 8.13 a.m., the accused was driving his motor car on lane 2 of 2-lanes along Tampines Avenue 3 when he collided onto the Cyclist who was crossing the road from his right to left at the Pedestrian Crossing in front of Block 831. Cyclist was conveyed to CGH where she succumbed to his injuries and was pronounced dead on the same day at 9.27am.

Vehicles to be inspected: SKE1231L - Rider (Accused)
Bicycle - Pedal Cyclist (Deceased)

SIO In-Charge: SIO Adrian Lim

- h) **Case IAFP-IB-20191211 - Mechanical Inspection of Motor Taxi, SHA8079X (TP/IP/73519/2019)**

On 27 November 2019 (Wednesday) at about 12.30 a.m., the Potential Defendant was driving motor taxi SHA 8079 X, travelling along lane 3 of 4 lanes along Bukit Timah Road towards the direction of Woodlands Road. Before the non-signalised T-junction of Mayne Road, the signalised pedestrian crossing was showing green signal for the Potential Defendant's direction of travel. As he was approaching the said signalised pedestrian crossing, the Deceased had pushed a trolley across the signalised pedestrian at a fast pace, from the the Potential Defendant's right to left, when he collided into the the Deceased. As a result of the accident, the Deceased sustained serious t injuries. She was conveyed to Tan Tock Seng Hospital (TTSH) by the ambulance. On the same day, the Deceased succumbed to her injuries and was pronounced dead at TTSH at 1.04 a.m.

Vehicles to be inspected: SHA8079X - Driver (Potential Defendant)

SIO In-Charge: SIO Raziz

- i) **Case IAFP-IB-20191211 - Mechanical Inspection of Motorcycle, FX8357X (TP/IP/74937/2019)**

On the 3 December 2019 (Tuesday) sometime around 5.46 p.m., the rider was riding along TPE (SLE) on left of 4 lanes in which he claimed that the piston of his motorcycle was jammed. The rider was unable to control his motorcycle and the motorcycle's rear wheel locked causing his motorcycle to lost control. The said motorcycle then side-swiped onto another motorcycle.

Vehicles to be inspected: FX8357X - Rider (Potential Defendant)

SIO In-Charge: IO Phua Tiak Yee

2. These request has been approved by my management.

3. Thank you Sirs.

cc: FAIT Team & IO Phua, fyip

Best regards,

Kamaliah Kamis (Miss)
Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352



