SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	02/10/2019 14:02
Date Of Accident	02/10/2019 02:35
Exact Location Of Accident	BEDOK SOUTH AVE 1 BLK 2A MSCP
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHA1388A
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	

Driver

Name of Driver TAN CHIN HOCK NRIC No S0024309D Date Of Birth 08/06/1953 Occupation **OUTDOOR Date Of Driving Pass** 01/11/1975

Driving Experience 43 YEARS AND 11 MONTHS

MALE Gender

Mobile Number (LOCAL) +65-94483893

Fax Number

Contact Number

EMail Address TCHINHOCK@YAHOO.COM Address BLK 308 HOUGANG AVENUE 5 #12-335

Postcode 53030

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

•

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] BEDOK NORTH N.P.C

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / POLICE REPORT: T/20191002/2052 / Type Of Accident: HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJB8875K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage LEFT FRT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION FTE LTD CO. REG. NO. 199303821R

Policyholder's Signature

Driver's Signature (If driver is not the policyholder) Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIARMC SketchPlanForm_V3





Sketch Plan Pg. 2



GIARMC SketchPlanForm_V3

Page 4 of 15





Police Station Of Origin: Bedok North N.P.C

30 Bedok North Road SINGAPORE 469676

Tel No: 1800-2449999

1 of 3

Report No. T/20191002/2052

REPORT OF	A TRAFFIC	ACCIDENT				
Date/Time Report Made: 02/10/2019 12:17		ade:	Vide Report No.: G/20191002/0020	Station Diary No.: 44		
Informant	's Particul	ars				
Name of Informant: TAN CHIN HOCK			Address: APT BLK 308 HOUGANG AVENUE 5 #12-335 SINGAPORE 530308			
ID Type / ID No.: NRIC NO / S0024309D			Contact No.: Home/Office: Mobile: 94483893			
Nationality SINGAPOR		 N	Email:			
Sex: Male	Age: 66	Date of Birth: 08/06/1953	Type of Informant: Driver			
Race: Chinese			Language: English	Institution / School Name:		
Occupation Taxi driver	1:		Driving Licence Information: Class: 2B,2A,2,3,4	Date of Ex	piry:	

General Informat	ion of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: Yes	Date/Time of Accident: 02/10/2019 01:0)()	Type of Location: Car Park
Location: Along Road 1 BEDOK SOUTH AVENUE 1 BLK 2A MULTI STOREY CARPARK					
Weather: Clear		Road Surface: Dry		Road	d Speed Limit:
Traffic Flow: Traffic Control: Traffic Vol Two Way Not Controlled No Traffic			ic Volume: raffic		
Type of Collision: Between Moving Vehicles - Head To Side		ide		1 -	one conveyed by ulance:

Details of V	ehicle Invo	lved				
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SHA1388A	Car	HYUNDAI	AE IONIQ HEV 1.6 DCT	Blue	Slightly Damaged	0
SJB8875K		KIA	CERATO 1.6(A)	Red	Slightly Damaged	1

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA		

Sketch Plan Pg. 4



Police Station Of Origin: Bedok North N.P.C

30 Bedok North Road SINGAPORE 469676

Tel No: 1800-2449999

2 of 3

Report No. T/20191002/2052

Driver						
Name	TAN CHIN HOCK			ID No	•	S0024309D
Related Vehicle	SHA1388A (Car)			Conta	ct No.	94483893
Hospital/Clinic	NIL			Class Drivin Licend Expiry	g	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	Sligh	t

CONTINUATION OF REPORT

Brief Details.

On the 02 October 2019 at about 0130hrs, I was driving my taxi bearing plate number SHA1388A. I was entering the multi story carpark of Blk 2A when I saw another car bearing the plate number, SJB8875K, suddenly stopped. At that time, it was in front of me. I had no time to react and I collided with the said vehicle. The front of my taxi collided with the left side of the said car. I wish to that that my front left portion was slightly damaged. I am not injured. The other driver did not provided his particulars. He called for ambulance. I am lodging this report for recording purposes. I wish to state that I have an in car camera.





Police Station Of Origin: Bedok North N.P.C 30 Bedok North Road SINGAPORE 469676 Tel No: 1800-2449999 3 of 3 Report No. T/20191002/2052

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 3 NAZEEHA BINTE MOHAMAD NASSIR //	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/10/2019 12:17
Officer In Charge Of Case:	
TP / GIT / Sgt 3 MUHAMMAD RIZWAN BIN KAMALUDIN Contact No.: 65476185	Classification Of Case:
Authentication Stamp	
SIGNATURE	















