

ASS. REC. BY:

REF:

083/FWD20000136/71yd3^{SP}

Special Instruction:

Surveyor: Tan FitchASSIGNMENT (Office)From (Person): Vanessa Chen

of

FWD

Date/Time:

2/1/2020

Estimated Cost:

Bill to:

CD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 3587Y

Insured:

SLW 3184U

at Workshop m/s

Topmax Auto

Tel:

G744 853

of

Blk 3007 Ubi Road 1 #01-410

Policy No:

PNPV2019-00011815

Claim No:

1202000000112

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:15pm @ 2/1/2020

Person Contacted:

CarmenVehicle IN / OUT

Date/Time	Action/Instruction
	<u>Rehman (X)</u>
	<u>SJL 3587Y - X</u>
	<u>SLW 3184U - X</u>
	<u>After repair: 9/1/2020</u>

ASS. REC. BY: *Tough*

REF:

FWD

ASSIGNMENT

CoE 2023 Nov

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJL 3587Y Yr Regn: 2008 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda R1 cc 1337

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 174684 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GE 61085483

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front: 6 mm Rear: 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____ D.O.I. 02/01/2008 530pm

Survey held at Topmax

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or *

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>Range, Repairs</i>
	\$6000 - \$7000 <i>8 days</i>
	\$4K - \$5K <i>6 days</i>
	RECEIVED 11 FEB 2020

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 6

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Rep. Form: PRS

Lump Sum / TP R/C

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2020 Edit Reg		03 Jan 2020 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Tan Yew Chuan Eber, ID: S7045812H		
Main Claimant:	SOH KOK CHONG		
Vehicle Reg. No.:	SJL3587Y	Date of Loss:	31/12/2019 13:00 - :59
Claim Type:	TP / 1202000000112	Policy/Cover Note No.:	PNPV2019-00011815 (Third Party Only) Coverage: 05/08/2019 - 04/08/2020
Vehicle Reg. No. (Insured):	SLW3184U	Policy No. (Claimant):	
		Excess:	
Repairer:	Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410, 408701 Ubi - Tel: 90622722		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Thursday, 2 January 2020 11:52 AM
To: 'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: motorclaims.sg@fwd.com; lionel.tan@fwd.com; service.sg@fwd.com
Subject: PRE-REPAIR SURVEY ACCIDENT INVOLVING SJL3587Y & SLW3184U [1912-7552(TOP)(PD)] OUR REF: 1202000000112
Attachments: PRI - RS SOLOMON LLC.PDF

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen .

Kindly upload all correspondence emails/documents sent to you into Merimen.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Venessa Chan - SGUser

Sent: Thursday, January 2, 2020 11:51 AM

To: 'Wendy Jiang'

Cc: Natalie Ng; Lua Siew Hui; Lionel Tan Tian Pei - SGUser; Motor Claims SG - SG Common

Subject: PRE-REPAIR SURVEY ACCIDENT INVOLVING SJL3587Y & SLW3184U [1912-7552(TOP)(PD)] OUR REF: 1202000000112

WITHOUT PREJUDICE

Dear Wendy,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/S **LKK Auto Consultants** to conduct the pre-repair survey (PRS) on your client's vehicle,

SJL3587Y. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.*

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]

Sent: Thursday, January 2, 2020 11:43 AM

To: Venessa Chan - SGUser

Cc: Natalie Ng; Lua Siew Hui; Lionel Tan Tian Pei - SGUser; Motor Claims SG - SG Common

Subject: RE: PRE-REPAIR SURVEY ACCIDENT INVOLVING SJL3587Y & SLW3184U [1912-7552(TOP)(PD)] OUR REF: 120200000112

Dear Venessa,

We refer to your email of even date.

We write to inform that our client will be appointing his own Surveyors.

In this respect, please arrange your surveyors to contact Carmen Chang of Topmax Auto Body Shop at Tel No. 6744 2653 for a pre-repair survey of our client's vehicle located at Block 3007 Ubi Road 1 #01-410 Singapore 408701.

Thank you and Best Regards

Yours sincerely

Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

From: venessa.chan@fwd.com [<mailto:venessa.chan@fwd.com>]

Sent: Thursday, 2 January 2020 11:25 am

To: Wendy Jiang <wendy_jiang@rssolomon.com>

Cc: Natalie Ng <natalie_ng@rssolomon.com>; Lua Siew Hui <lua_siewhui@rssolomon.com>; lionel.tan@fwd.com; motorclaims.sg@fwd.com

Subject: PRE-REPAIR SURVEY ACCIDENT INVOLVING SJL3587Y & SLW3184U [1912-7552(TOP)(PD)] OUR REF: 1202000000112

WITHOUT PREJUDICE

Dear Wendy,

Refer to your email dated on 02.01.2020 of the PRI Notice of your client's vehicle SJL3587Y;

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**

Thank you.

Best Regards,

Venessa Chan


Administrative Assistant, Claims



FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com



From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]
Sent: Thursday, January 2, 2020 10:02 AM
To: Motor Claims SG - SG Common
Cc: Natalie Ng; Lua Siew Hui
Subject: PRE-REPAIR SURVEY ACCIDENT INVOLVING SJL3587Y & SLW3184U [1912-7552(TOP)(PD)]

Dear Sirs,

We act for the owner ('our Client') of vehicle no. SJL3587Y.

Our Client's vehicle was involved in the aforesaid accident with your insured's vehicle no. SLW3184U at the material time. As a result, our Client's vehicle was damaged and before our Client proceeds to repair its vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of our Client's vehicle within the stipulated timeline, our Client will proceed to repair its vehicle without further reference to you.

Please see below, the following documents for your necessary action:-

1. Our letter of even date; and
2. GIA Report lodged by our Client.

Let us hear from you soonest.

Thank you and best regards,

Yours sincerely
Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/12/2019 13:56
Date Of Accident	31/12/2019 13:15
Exact Location Of Accident	CTE TOWARDS CITY NEAR ANG MO KIO AVE 1 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL3587Y
Insured/Policyholder	
Name Of Registered Owner	SOH KOK CHONG
NRIC No	SXXXX296Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97676719
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	FIT-1.3 G (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company


Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5113709359
Cover Note Number	

Driver

Name of Driver	SOH KOK CHONG
NRIC No	SXXXX296Z
Date Of Birth	31/01/1979
Occupation	INDOOR
Date Of Driving Pass	28/08/1999
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97676719
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	NOEMAIL

Sketch Plan

SKETCH PLAN



A - SJL35874
B - SLW31840

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 5/12/19 at around 1:15pm @ CTE towards city before
Ang Mo Kio Ave 1 exit. The traffic was slow and I was
following the vehicle in front of me. Suddenly vehicle
SLW31840 collided onto my rear side

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

Report No. T/20191231/2153

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/12/2019 21:02	Vide Report No.:	Station Diary No.: 42
--------------------------------------------	------------------	--------------------------

Informant's Particulars

Name of Informant: SOH KOK CHONG			Address: APT BLK 154 HOUGANG STREET 11 #04-196 SINGAPORE 530154		
ID Type / ID No.: NRIC NO / S7904296Z			Contact No.: Home/Office: Mobile: 97676719		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 40	Date of Birth: 31/01/1979	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: OUTDOOR SALES			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 31/12/2019 13:15	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY Along CTE towards CITY, before Ang Mo Kio Ave 1.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJL3587Y	Car	HONDA	FIT 1.3G A	White	Slightly Damaged	1
SLW3184U	Car	HONDA	FIT	White	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJL3587Y	NTUC Income Insurance Co-Operative Limited	5113709359	17/12/2019	16/12/2020



**SINGAPORE
POLICE FORCE**



T/20191231/2153

3 of 4

Report No. T/20191231/2153

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

CONTINUATION OF REPORT

government property damaged and nobody was conveyed by ambulance nor Traffic Police was activated.

I wish to state that my vehicle was equipped with camera focusing the front only and the footage revealed there was a jerk after the collision.

My passenger and I consulted doctor from Mt Alvernia Hospital and was granted 5 days of MC dated 01/01/2020 until 05/01/2020 by Dr Tan Sen Tai, Timothy. (MC: M19000033013 and M19000033014 respectively).



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 296Z

Vehicle Details

Vehicle No.: SJL3587Y
Vehicle to be Exported: No
Intended Deregistration Date: 03 Jan 2020
Vehicle Make: HONDA
Vehicle Model: FIT 1.3G A
Primary Colour: White
Manufacturing Year: 2008
Engine No.: L13A4094785
Chassis No.: GE61085483
Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$11,703.00
Original Registration Date: 25 Nov 2008
First Registration Date: 25 Nov 2008
Transfer Count: 4
Actual ARF Paid: \$11,703.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 24 Nov 2023
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$14,835.00
COE Rebate Amount: \$11,546.00
Total Rebate Amount: \$11,546.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Jan 2020

OK

honda fit Price Range Depreciation > 10 year(s) ol Vehicle Type Search

Advanced Search

Home » Used Cars » 88 Motor Trading » Honda Fit 1.3A G (COE till 11/2023)

Honda Fit 1.3A G (COE till 11/2023)

Overview Financial Insurance Accessories Similar Research Photos Map



Price	\$22,800		
Depreciation ⓘ	\$5,860 /yr	Reg Date	25-Nov-2008 (3yrs 10mths 21days COE left)
Mileage	N.A.	Manufactured ⓘ	2008
Road Tax ⓘ	\$708 /yr	Transmission	Auto
Dereg Value ⓘ	\$11,551 as of today (change)	OMV ⓘ	\$14,133
COE ⓘ	\$14,835	ARF ⓘ	\$13,315
Engine Cap	1,339 cc	Power	73.0 kW (97 bhp)
Curb Weight ⓘ	1,010 kg	No. of Owners ⓘ	2
Type of Vehicle	Hatchback		

Features
View specs of the Honda Fit (2008-2013)

Description
Full Loan Available At \$700 Plus, We Can Help To Conver To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Weekend From 10.30 A.M. To 6.30 P.M.! All Our Vehicles Has Undergone A 120 Points Check By Our In House Workshop!

Category
COE Car, Premium Ad Car

Status
Available

Resources

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Car Valuation - Free
Find out the market value of your existing car for free. Get started

Posted on: 28-Dec-2019 | Last Updated on: 28-Dec-2019

Upfront Payment		» more Financial info
Transfer Fee ⓘ	\$25	
Down Payment ⓘ	\$6,840 (change)	Maximum 70% Loan
1st Instalment ⓘ	\$397	Based on 3.75% interest rate
Insurance	\$638 onwards (Get a quote) Extra 15% Off for MINDEF, MHA & POGIS policyholders Quote assumes a standard profile. "Get a quote" for exact figure.	Powered by
Total Upfront Payment ⓘ	\$7,900	Check with seller for exact figure

Compare



Shortlist Compare Add note
Report Error More Actions

Seller Information

88 Motor Trading
142 vehicles for sale. 147 sold in past 3 mths

📍 200 Jalan Sultan #02-38/Level 7 Carpark
Textile Centre
Tel: 62911187
Search cars nearby

🌐 88motortrading.com

👤 Lek	87555787 📞
Yap	83287973 📞
Mr Soh	82327232 📞
Yang	87798127 📞

View our: Used Car List / Company Profile

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2020 Edit Reg		02 Jan 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Tan Yew Chuan Eber, ID: S7045812H		
Main Claimant:	SOH KOK CHONG		
Vehicle Reg. No.:	SJL3587Y	Date of Loss:	31/12/2019 13:00 - :59 [133 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1202000000112	Policy/Cover Note No.:	PNPV2019-00011815 (Third Party Only) Coverage: 05/08/2019 - 04/08/2020
Vehicle Reg. No. (Insured):	SLW3184U	Policy No. (Claimant):	
		Excess:	
Repairer:	Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410, 408701 Ubi - Tel: 90622722		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL3587Y (1202000000112)

[SLW3184U]

TP

SOH KOK CHONG




































Dec 31 2019 1:00PM




[Tan Yew Chuan Eber]

Topmax Auto Body Shop

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
2	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
3	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
4	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
5	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
6	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
7	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
8	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
9	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
10	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
11	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
12	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
13	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
14	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
15	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
16	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
17	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
18	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
19	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
20	13/01/20 18:26	General View	 Load JPG	<input checked="" type="checkbox"/>
21	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
22	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
23	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
24	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
25	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
26	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
27	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
28	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
29	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
30	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
31	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
32	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
33	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
34	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
35	13/01/20 18:46	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	03/01/20 12:08	PRI - RS SOLOMON LLC	 Load PDF	
2	03/01/20 12:08	SLW3184U OI GIA	 Load PDF	
3	03/01/20 12:08	SJL3587Y TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD20000136/T1YD3S2
Date: 12/02/2020

REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2019-00011815
Claimant Vehicle No :	SJL3587Y	Insured Vehicle No :	SLW3184U
Date of Loss:	31/12/2019	Nature of Claim:	TP
		Claim No:	1202000000112

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL3587Y	Engine No:	L13A4094785
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61085483
Reg. Date:	25/11/2008 (Man. Year: 2008)	Odometer:	174684 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/01/2020		
Date Inspected:	02/01/2020	Inspected At:	Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410 Singapore 408701
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
- THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2020)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL3587Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >