

CC4/FCI20000137/Fka3

Registered in Merimen: \_\_\_\_\_

Place of Accident : \_\_\_\_\_

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :	%	Final ? Yes / No
1. General Liability		
2. Professional Liability		
3. Directors and Officers Liability		
4. Employment Practices Liability		
5. Fidelity and Bonding		
6. Commercial Auto		
7. Commercial Property		
8. Marine		
9. Aviation		
10. Other		

INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/ Time			STAGE	DATE / PIC
	SHD 8593L - CS/FCI18010473/Avd3n2; DOA: 29.03.18		Non-Reporting ltr (1st):	
	- NA/INC18005870/h4; DOA: 28.03.18		Non-Reporting ltr (2nd):	
	SHC 6576E - NS/INC18001247/Sqd3e2; DOA: 11.01.18		Non-Reporting ltr (Final):	
	OINR		Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			<b>Documentation Check List: Handler Typist</b>	
			Notification ltr (if non-pickup)	<input type="checkbox"/>
			After call ltr to OI:	<input type="checkbox"/>
			Authorisation To Act:	<input type="checkbox"/>
			Release Voucher:	<input type="checkbox"/>
			Final Repair Bill:	<input type="checkbox"/>
			Car Rental Invoice:	<input type="checkbox"/>
			Towing Invoice	<input type="checkbox"/>
			LTA / GIA :	<input type="checkbox"/>
			Medical Bill:	<input type="checkbox"/>
			PIR:	<input type="checkbox"/>
			Mandate/Reject Instruction:	<input type="checkbox"/>
			LOD	<input type="checkbox"/>
			Payment Breakdown Form:	<input type="checkbox"/>
			Post-Repair Photos:	<input type="checkbox"/>
			Others:	<input type="checkbox"/>
<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:		
<b>FINALIZATION</b>	Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	S\$	( days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time:	Confirm with	Email <input type="checkbox"/>	Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :	
Repair Cost:	S\$			
Loss of Rental (LOR):	S\$	( days)		
Loss of Use (LOU):	S\$	(\$ x days)		
Loss of Income (LOI):	S\$	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	S\$		1) Claim status: Normal/Reject/Private Settle	
Medical:	S\$		2) Report Format:	
Disbursement:	S\$	(e.g. Tow/ Independent )	3) Survey fee:	
Legal Cost	S\$			
<b>Total:</b>	S\$	<b>Global Sum S\$:</b>		
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Email <input type="checkbox"/>	Call <input type="checkbox"/>
Payee 1:	S\$	Name 1:		
Payee 2: (Strike if N.A.)	S\$	Name 2:		
Payee 3: (Strike if N.A.)	S\$	Name 3:		

$$BA \parallel CB$$

31.  $\frac{1}{2} \ln 4$

The U/C / Chassis frame / Body Structure affected due to collision.

LS

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	27 Feb 2015 / 09:20:58	Receipt No.:	AACCK001-AX239-150227-000007
Asset Type:	Vehicle	Transaction Amount:	\$66,712.00
Asset ID:	SHC6576E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150227092058997744		

Vehicle No.:	SHC6576E
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	27 Feb 2015
Original Registration Date:	27 Feb 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5578297
Engine No.:	D4FDEH313331
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$20,834.00
Minimum PARF Benefit:	\$8,200.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	27 Feb 2015 09:20:58
COE No.:	2015022701001616M
COE Expiry Date:	26 Feb 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$52,904.00
Lifespan Expiry Date:	26 Feb 2023



# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

27-Dec-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6576 E

1 pc	Bonnet grille X (R)	\$	385.00
1 pc	Front bumper X (R)	\$	531.00
1 pc	Front bumper emblem rec	\$	44.00
1 pc	Front bumper centre grille Xnr	\$	174.00
1 pc	Front bumper lower stiffer Xnr	\$	134.00
1 pc	Front bumper tow hook cover Xnr	\$	14.00
1 pc	Front bumper inner sponge ?	\$	110.00
1 pc	Front bumper reinforcement ?	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 Xnr	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 Xnr	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 Xnr	\$	32.00
		\$	1,816.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### S/NETT

1 pc	Front no. plate with casing B	\$	50.00
1 pc	Front bumper clips Xnr	\$	48.00

Sundry

To check for wiring and to focus head lamps

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. knock-out, straighten, repair, reshape and adjust of the support panel etc

To putty and spray painting on front bumper, bonnet grille,

To apply rustproofing on the repaired and replaced panels.

\$	181.60
\$	1,634.40
\$	50.00
\$	48.00
\$	50.00 \$30
\$	80.00 Xnr
\$	180.00 Xnr
\$	750.00 \$300
\$	400.00 \$360
\$	120.00 \$50
\$	3,312.40

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ram (LKK)  
06/01/2020 1645hrs  
Para Sumana@LKKauto.co  
aft repair photo  
LIS  
2 repair days