

ASS. REC. BY:

REF: CS3/AIG 20000147/T19/327 Special Instruction:

Survivor: Tan Seng

ASSIGNMENT (Office)

From (Person): Willie Fan

of

AIG

Date/Time: 3.1.2020 11.37 a.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBJ 2296Z

Insured:

GBG 292M

at Workshop m/s

Messrs Derrick Motor

Tel:

96333593

of

Bik 9002 Tampin St 93 #01-72

Policy No:

Claim No:

556217986556

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19-Dec-2019

CA / REV / REP. / REV 24 HRS

Date/Time:

3.1.2020 1.14 p.m.

Person Contacted:

Jeremy

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate



GBJ 2296Z - X

GBG 292M - NA / TMI 19006925/h4 Don: 18/04/2019

10/01/20

Submit DRP.

RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBG292M AND GBJ22...

From: Fan, Winnie-LW
To: Admin A, assignments
Cc: Fong, Andy-SY
Sent: 1/3/2020 11:37:38 AM
Attachments:  

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Thursday, 2 January, 2020 9:06 AM

To: 'Hor, Yinrul'

Cc: 'Lily.Tan@aig.com'; 'Andy-SY.Fong@aig.com'; 'Lee-Ying.Chin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'ShengYang.Lim@aig.com'; 'Syazairdina.Azlan@aig.com'; 'yokeshi.chan@aig.com'; 'Aashweenjeetkaur.Mithoosingh@aig.com'; 'Parthiban, Theerthan'; 'nurmariahhuibrechts.mohdrizal@aig.com'

Subject: PRE REPAIR-INSPECTION --- YOUR REF: GBG 292 M --- ACCIDENT INVOLVING GBJ 2296 Z AND GBG 292 M ON 19 DECEMBER 2019 ALONG CLEMENTI AVENUE 6 SLIP ROAD TO TOH TUCK AVENUE AT ABOUT 1025 HOURS

Importance: High

Our Ref: GBJ 2296 Z (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by **GUO RUI CHENG PTE LTD** to notify you of a road traffic accident on 19 December 2019 along Clementi Avenue 6 slip road to Toh Tuck Avenue at about 1025 hours involving our client's vehicle registration number GBJ 2296 Z and vehicle registration number GBG 292 M driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose **DENNIS YAP - PAL'S APPRAISER PTE LTD** for appointment as Single Joint Expert for your consideration.

Please be informed that the said vehicle can be inspected at:

Messrs Derrick Motor Works
Blk 9002 Tampines St 93
#01-72, Tampines Ind Park A
Singapore 528836
Attention: Mr Jeromy – HP 9633 3593 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

FOR SURVEYOR
Please initial here after completion of pre-repair inspection.
Thank you.

Appointed surveyor
(Name & Signature)

Date & Time of Inspection:

Thank you.

Regards,
Elaine Toh (Secretary)

Singapore 059413
Tel: 65342811 (Ext. 122) / Fax: 65356802

cc: GBJ 2296 Z – By email only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|-------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 808M |
| Vehicle Details | |
| Vehicle No.: | GBJ2296Z |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 08 Jan 2020 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | HIACE VAN TURBO 5DR MT |
| Primary Colour: | Silver |
| Manufacturing Year: | 2018 |
| Engine No.: | 1KD2841072 |
| Chassis No.: | JTFHT02P700247608 |
| Maximum Power Output: | - |
| Open Market Value: | \$28,136.00 |
| Original Registration Date: | 20 Feb 2019 |
| First Registration Date: | 20 Feb 2019 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$1,407.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 19 Feb 2029 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| QP Paid: | \$26,230.00 |
| COE Rebate Amount: | \$23,911.00 |
| Total Rebate Amount: | \$23,911.00 |

The information contained herein is correct as at 08 Jan 2020

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
GBJ2296Z

Make / Model
TOYOTA / HIACE VAN TURBO 5DR MT

Vehicle Type :
A50 - Goods (Closed) Van/Van Panel (Delivery)

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
JTFHT02P700247608

Propellant :
Diesel

Engine No. :
1KD2841072

Motor No. :
-

Engine Capacity :
2982 cc

Power Rating :
-

Maximum Power Output :
-

Maximum Laden Weight :

2800 kg

Unladen Weight :

1700 kg

Year Of Manufacture :

2018

Original Registration Date :

20 Feb 2019

Lifespan Expiry Date :

19 Feb 2039

COE Category :

C - Goods Vehicle & Bus

Quota Premium :

\$26,230.00

COE Expiry Date :

19 Feb 2029

Road Tax Expiry Date :

19 Feb 2020

PARF Eligibility Expiry Date :

-

Inspection Due Date :

19 Feb 2020

Intended Transfer Date :

08 Jan 2020

CO2 Emission :

210.00 (g/km)

CEV/VES Rebate Utilised Amount :

-

CO Emission :

0.066000 (g/km)

HC Emission :

0.002653 (g/km)

NOx Emission :

0.107000 (g/km)

PM Emission :

1.600000 (mg/km)

Fees To Be Paid For Transfer

| | |
|---|---------|
| Transfer Fees | \$25.00 |
| Road Tax Renewal - 6 months (20 Feb 2020 to 19 Aug 2020) | \$0.00 |
| Road Tax Renewal - 12 months (20 Feb 2020 to 19 Feb 2021) | \$45.00 |

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner.

This vehicle has a road tax Over Payment of \$16.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Print

OK →

Save as PDF

Copy as Text

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 20/12/2019 13:14
Date Of Accident 19/12/2019 10:25
Exact Location Of Accident CLEMENTI AVE 6 SLIP RD TO TOH TUCK AVE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ2296Z
Insured/Policyholder
Name Of Registered Owner GUO RUI CHENG PTE LTD
Co Reg No 2XXXXX808M
Email Address GRCTRADING@SINGNET.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-67795738

Vehicle Particulars

Manufacturer TOYOTA
Model HIACE-3.0 D TURBO 5 DR (M)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMCVSN1903061900
Cover Note Number

Driver

Name of Driver DU LIWU
Passport No/FIN GXXXXX693K
Date Of Birth 04/05/1986
Occupation OUTDOOR
Date Of Driving Pass 27/02/2015
Driving Experience 4 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98456869
Fax Number
Contact Number
Email Address NOEMAIL

Address N/A
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: DID NOT BRING DURING REPORTING
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG292M
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver MUHAMMAD SYIMIR BIN MOHD DAUD
NRIC/Passport Number SXXXX114H
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

GUO RUI CHENG PT. LTD.

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Clements Ave 6


On 19/12/19 @ around 10:25 hrs, I was travelling along a & exit to
 Joh Tuck Ave. While at the slip RD to Joh Tuck Ave & the
 vehicle at my front had stop & I also stopped behind him
 but however I felt an impact on my rear then I went down
 to check & found that Vehicle B had collided onto my rear:

DECLARATION


I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

GIAP/AC Sketch Plan Form V3


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

☐ Claim own policy
☐ Claim third party
☒ Claim OD / FFS Other workshop TBA.
☐ For record purpose
 Policy No. DM/VL/A03061900
 Insurer Clutch Veh. No. XBJ72962.


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



(1) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (NC)

Rear Portion

Vehicle No: 6BJ2296Z

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-------------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate | | | |
| 1138 | 993627 | Rear Number Plate Base | | | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper | de | ✓ | |
| 1142 | 993085 | Rear Bumper Upper | | | |
| 1143 | 993017 | Rear Bumper Lower | | | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993103 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips | all | ✓ | |
| 1147 | 992976 | Rear Bumper Bracket | all | ✓ | 2 |
| 1148 | 993068 | Rear Bumper Side Retainer | | | |
| 1149 | 993045 | Rear Bumper Reinforcement | | | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Pad | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1156 | 993044 | Rear Bumper Reflector | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1158 | 994023 | Reverse Sensor | nw | ✓ | |
| 1159 | 993327 | Rear End Panel | bt | ✓ | |
| 1160 | 993339 | Rear End Panel Top Garnish | | | |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp | | | |
| 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | | | |
| 1171 | 991328 | Bootlid Emblem | | | |
| 1172 | 990356 | Bootlid Handle | | | |
| 1173 | 995250 | Bootlid Moulding | | | |
| 1174 | 990376 | Bootlid Reflector | | | |
| 1175 | 995222 | Bootlid Lamp LH | | | |
| 1176 | 992899 | Bootlid Lamp RH | | | |
| 1177 | 995243 | Bootlid Lock | | | |
| 1178 | 990377 | Bootlid Rubber | | | |
| 1179 | 990382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | bt | ✓ | |
| 1182 | 991328 | Tailgate Emblem | nac | ✓ | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp sticker 'HIACE' | all | ✓ | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | all | ✓ | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | bt | ✓ | |
| 1198 | 994651 | Tailgate Rubber | tn | ✓ | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |
| 1201 | 994613 | Tailgate Inner Board | | | |

| NAC | INC | Item | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 995323 | Triangle Breakdown Sign | | | |
| 1208 | 990507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | | | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | | | |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | | | |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993401 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1136 | 990247 | Sticker | | | |

No of Items: _____ Assessor: _____

06 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 21 Dec 2019 Edit Reg | | 03 Jan 2020 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | GRID TECH CONSULTANT PTE. LTD., Co. Reg. No.: 200209277G | | | | | | | | |
| Main Claimant: | GUO RUI CHENG PTE LTD | | | | | | | | |
| Vehicle Reg. No.: | GBJ2296Z | Date of Loss: | 19/12/2019 00:00 - :59 [9 Months and 29 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 5562179865SG | Policy/Cover Note No.: | (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | GBG292M | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Messrs Derrick Motor Works (HQ) BLK 9002 TAMPINES ST 93, #01-72, TAMPINES IND PARK A, 528836 Tampines - Tel: | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/01/2020] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (06/01/2020): TP GIA report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*GBJ2296Z (5562179865SG)
[GBG292M]
TP
GUO RUI CHENG PTE LTD
Dec 19 2019 12:00AM
[GRID TECH CONSULTANT PTE. LTD.]
Messrs Derrick Motor Works

| | | | | | | |
|------------------|--|---------------|--------------------|--------------|--------------|---|
| Upload Documents | | Upload Photos | Compose New Letter | Upload Video | Upload Audio | View View in Browser ▼ |
|------------------|--|---------------|--------------------|--------------|--------------|---|

| Video | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------|----------------|---|---------------------------|-------------------------------------|
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 06/01/20 15:45 | Video - Accident | Load AVI | |

| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
|----------------------|-----------------|-----------------------------------|---------------------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 10/01/20 10:54 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 10/01/20 10:54 | Chassis Number | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 10/01/20 10:54 | General View | Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|----------------------|----------------|---|---------------------------|-------------------------------------|
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 06/01/20 15:45 | OI GIA REPORT | Load PDF | |

Documents Checklist

| | | | | |
|--|--|-------|------|-------|
| DOCUMENTS CHECKLIST | | Reset | Save | Print |
| There are no document checklists configured. | | | | |

| | |
|--|--|
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | |
| <div style="border: 1px solid black; width: 100%; height: 100%;"></div> | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20000147/T1QF3E2

Date: 15/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : GBJ2296Z

Insured Vehicle No : GBG292M

Date of Loss: 19/12/2019

Nature of Claim: TP

Claim No: 5562179865SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ2296Z

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No: 1KD2841072

Reg. Date: 20/02/2019 (Man. Year: 2018)

Chassis No: JTFHT02P700247608

Colour: Silver

Odometer: 20649 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 Inspected At:

Messrs Derrick Motor Works (HQ)
BLK 9002 TAMPINES ST 93, #01-72,
TAMPINES IND PARK A
Singapore 528836

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|--------------------------|-------------|------------|--------|
| 1 | 1 | | *REAR BUMPER | Deformed | 0.00 F | *- F |
| 2 | 1 | | *REAR BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 3 | 2 | | *REAR BUMPER BRACKET | Necessary | 0.00 F | *- F |
| 4 | 1 | | *REVERSE SENSOR | Not Working | 0.00 F | *- F |
| 5 | 1 | | *REAR END PANEL | Bent | 0.00 F | *- F |
| 6 | 1 | | *TAILGATE | Bent | 0.00 F | *- F |
| 7 | 1 | | *TAILGATE EMBLEM | Necessary | 0.00 F | *- F |
| 8 | 1 | | *TAILGATE STICKER HIACE | Necessary | 0.00 F | *- F |
| 9 | 1 | | *TAILGATE GLASS MOULDING | Necessary | 0.00 F | *- F |
| 10 | 1 | | *TAILGATE LOCK | Bent | 0.00 F | *- F |
| 11 | 1 | | *TAILGATE RUBBER | Torn | 0.00 F | *- F |
| Total Parts (S\$) | | | | | 0.00 | 0.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >