

ASS. REC. BY:

REF: CS/A1G2000048/UVf302 Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Hor Yinnal

of A1G

Date/Time: 12.2020 4:29p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 80685

Insured: SLL 4262D

at Workshop m/s Imperium Automotive

Tel: 97489940

of 25 Kaki Bukit Road 4 #01-49 Symray

Policy No:

Claim No: 6251 337431 SG003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27. Dec. 2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.1.2020 1:51p.m

Person Contacted: Shawn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLL 4262D - CS/LPC 14022865 / Kqd3 DOA - 27/12/2019

GBG 80685 - CS/LPC 14022865 / Kqd3 DOA - 27/12/2019

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Aca/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TRWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

L7A 37767 No 2017 S.G. 00000000.

20/2/20 1/5 #4300 confirmed with Shown. (Red 7589.15, 6490)

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 21 FEB 2020

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 21/2 - typist

Report Format:

Lump Sum / I.B.I. (\$

☐: Preli. Report☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐: Site Insp (\$☐: Interview (\$☐: Tech. Invs (\$☐: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

290

11

261

PRE-REPAIR INSPECTION REQUEST – GBG8068S vs SLL4262D (OI) on D.O.A.: 27/12/2019

From: Hor, Yinrul

To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)

Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashn

Sent: 1/2/2020 4:29:07 PM

Attachments:  PRI GBG8068S.pdf  PRI GBG8068S.pdf

Hi,

Please refer to the enclosed request from **JusEquity Law Corporation**.

Claim no : 6251337431SG003

Case Owner : Norsiah Bte Md Noor

If you have any queries/concerns, please let us know.

*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: alfred_ng@juseq.com.sg <alfred_ng@juseq.com.sg>

Sent: Thursday, January 2, 2020 2:53 PM

To: Hor, Yinrul <Yinrul.Hor@aig.com>

Subject: [EXTERNAL] ACCIDENT INVOLVING GBG8068S AND SLL4262D ON 27 DECEMBER 2019.

This message is from an external sender; be cautious with links and attachments.

Your ref: SLL4262D

Our ref: JEQ/GBG8068S/IMP

Dear Sirs,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

Mr. Marcus Chua- LKK Auto Consultants Pte Ltd

Please be informed that our client's vehicle is available for inspection at the under stated workshop:-

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4

#01-49, Synergy@KB

Singapore 417800

Tel: 97489940 Fax: 63467213

Mr. Shawn Tan

With Regards

Alfred Ng

Executive

Legal Division

On behalf of Mr. Michael Yap

M/s JusEquity Law Corporation

No. 133 New Bridge Road

Chinatown Point

#10-03 Singapore 059413

Tel : 6536 9339

Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

From: Yinrul.Hor@aig.com

To: zul@juseq.com.sg, alfred_ng@juseq.com.sg

Cc: Andy-SY.Fong@aig.com, Winnie-LW.Fan@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL4262D AND GBG8068S ON 27/12/2019

Date: Thu, 2 Jan 2020 05:48:51 +0000

Without Prejudice

-

Your Reference : JEQ/GBG8068S/IMP (zl)
Our Reference : SLL4262D

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002208
Yinrui.Hor@aig.com | www.aig.sg

From: zul <zul@juseq.com.sg>
Sent: Friday, December 27, 2019 5:56 PM
To: Hor, Yinrui <Yinrui.Hor@aig.com>
Cc: 'Alfred Ng' <alfred_ng@juseq.com.sg>
Subject: [EXTERNAL] ACCIDENT INVOLVING GBG8068S & SLL4262D ON 27.12.2019 Our Ref: JEQ/GBG8068S/IMP (zl)

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Please refer to our notice of accident.

Regards,

Zul
JusEquity Law Corporation
133 New Bridge Road #10-03
Chinatown Point
Singapore 059413
Tel: 6536 9339
Fax: 6536 5368
E-mail: zul@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 279G

Vehicle Details

Vehicle No.: GBG8068S

Vehicle to be Exported: No

Intended Deregistration Date: 10 Feb 2020

Vehicle Make: ISUZU

Vehicle Model: NHR85AUE4AA

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 4JJ13A9243

Chassis No.: JAANHR85EH7100232

Maximum Power Output: -

Open Market Value: \$24,680.00

Original Registration Date: 01 Nov 2017

First Registration Date: 01 Nov 2017

Transfer Count: 0

Actual ARF Paid: \$1,234.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$48,902.00

COE Rebate Amount: \$37,767.00

Total Rebate Amount: \$37,767.00

The information contained herein is correct as at 10 Feb 2020

OK



BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

START SEARCH NOW!

Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Volkswagen Scirocco 1.4A TSI



Car Ideal For COE Renewal As Major Wear And Tear Parts Have Been Replaced!
Direct Owner StarAd



click here to view our **PRISTINE USED CARS** at **GREAT PRICES**

Browse by Category

Sort by Date Posted





20 results/page

4 vehicles

Isuzu NHR85A

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Isuzu NHR85A		Any	Any	2016	Any	Any	Any	Available
	Isuzu NHR85A		\$42,800	\$6,600 /yr	05-Aug-2016	2,999 cc	-	Truck	Available
Fuel Type: Diesel Cheaper In Market. Lower Depre In 10ft Truck. Heavy Duty Brand. New Condition. Full Loan Available, High Trade In, Don't Miss It, Call... ABWIN (1994) Pte Ltd Posted: 05-Feb-2020 Tags: 2016 Isuzu NHR85A, 2016 isuzu nhr85a, Isuzu NHR85A, isuzu nhr85a, Isuzu, NHR85A, nhr85a, Used Isuzu									
	Isuzu NHR85A		\$39,488	\$6,400 /yr	13-Apr-2016	2,999 cc	-	Truck	Available
Fuel Type: Diesel Extremely Good Condition Isuzu Nhr85a. Full Loan Available At \$764 Monthly. Payload Up To 1.7 Ton. Suitable For All Type Of Business.... ABWIN Bus Pte Ltd Posted: 21-Jan-2020 Tags: 2016 Isuzu NHR85A, 2016 isuzu nhr85a, Isuzu NHR85A, isuzu nhr85a, Isuzu, NHR85A, nhr85a, Used Isuzu									
	Isuzu NHR85A		\$37,800	\$6,220 /yr	08-Mar-2016	2,999 cc	63,000 km	Truck	Available
Fuel Type: Diesel Cheaper In Market, Condition As Good As New. Very Well Maintained And Low Usage. Full Loan Can Be Arrange. Posted: 26-Dec-2019 Tags: 2016 Isuzu NHR85A, 2016 isuzu nhr85a, Isuzu NHR85A, isuzu nhr85a, Isuzu, NHR85A, nhr85a, Used Isuzu									
	Isuzu NHR85A		\$40,800	\$6,370 /yr	07-Jul-2016	2,999 cc	-	Truck	Available
Fuel Type: Diesel With Retractable Canopy & HDB Parking. New Paint. Just Serviced, All Wear & Tear Parts Replaced With Workshop Receipt. Excellent Co... Posted: 25-Dec-2019 Tags: 2016 Isuzu NHR85A, 2016 isuzu nhr85a, Isuzu NHR85A, isuzu nhr85a, Isuzu, NHR85A, nhr85a, Used Isuzu									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2019 15:20
Date Of Accident	27/12/2019 11:30
Exact Location Of Accident	MARINA BOULEVARD TOWARDS SHEARES AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG8068S
Insured/Policyholder	
Name Of Registered Owner	AGAPE LOGISTICS PTE LTD
Co Reg No	2XXXXX279G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65729247

Vehicle Particulars

Manufacturer	ISUZU
Model	NHR85AUE4AA-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	ON THE WAY FOR DELIVERY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z19VC00104896
Cover Note Number	

Driver

Name of Driver	SONG JIANGTAO
Passport No/FIN	GXXXX829X
Date Of Birth	06/12/1982
Occupation	OUTDOOR
Date Of Driving Pass	23/01/2013
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87556539
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	30 SENOKO SOUTH ROAD
Postcode	758088
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 27/12/2019 AT ABOUT 1130 HOURS, I WAS TRAVELLING IN LANE 3 ALONG MARINA BOULEVARD TOWARDS SHEARES AVENUE. LANES 3 IS GOING STRAIGHT AND TURN LEFT LANE. WHILE LANES 4 AND 4 ARE ALL LEFT TURN ONLY LANES. AT THAT TIME, THE TRAFFIC LIGHTS WERE GREEN. WHEN I REACHED THE JUNCTION OF MARINA BOULEVARD AND SHEARES AVENUE, I SIGNALLED LEFT AND SLOWED DOWN THEN TURNED LEFT INTO SHEARES AVENUE. JUST THEN, A VEHICLE (REGN NO: SLL4262D) TRAVELLING ON MY LEFT IN LANE 4 SUDDENLY WENT STRAIGHT WHILST IN THE TURN LEFT ONLY LANE. AS A RESULT, THE ENTIRE RIGHT PORTION OF SLL4262D HIT ONTO THE FRONT LEFT PORTION OF MY MOVING VEHICLE (REGN NO: GBG8068S).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4262D
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	RIGHT PORTION DAMAGED
Vehicle Category	PRIVATE HIRE
Name of Driver	QUEK GUAN SEAH
NRIC/Passport Number	SXXXX422B
Contact Number	83574883
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

RIGHT PORTION DAMAGED

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

27/12/19
1550 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

27/12/19
1550 hrs



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFOR To Report

DECLARATION

U/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature _____
 Date & Time 27/12/19 1550 hrs

Driver's Signature *[Signature]*
(If driver is not the policyholder)
Date & Time: 2/12/19
1550 Hrs

Report of _____ Personnel's Signature _____
Name _____
NRIC# _____

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

27 Dec 2019

Vehicle No.: GBG 8068 S

Model: ISUZU LORRY

JAA NHAR

Not Authorized
10/1/20
4/5 of 4300
4 days.
the sh. after rep

QTY	DESCRIPTION	AMT S\$
<u>List Items</u>		
1	Front headlamp -L/H 545.00	\$ 019 585.00 ✓
1	Front headlamp side bracket	\$ 11 160.00 X
1	Front headlamp lower rubber seal 48.00	\$ 11 110.00 ✓
1	Front side lamp 188.00	\$ 320 355.00 ✓
1	Front corner panel -L/H 366.00	\$ cut 425.00 ✓
1	Front side mirror -L/H	\$ 11 243.00 X
1	Front side mirror stay	\$ 11 200.00 X
1	Front bumper 745.00	\$ 25 1,383.00 ✓
1	Front bumper side bracket H	\$ 56 255.00 ✓
1	Front bumper reinforcement	\$ 25 380.00 X
1	Front door -L/H 1265.00	\$ 20 1,595.00 ✓
1	Front door checker	\$ 11 105.00 X
1	Front door glass outer moulding	\$ 11 115.00 X
1	Front door hinges 115.00	\$ 32 156.00 ✓
1	Front door inner board	\$ 11 235.00 X
1	Front door lock	\$ 11 185.00 X
1	Front door outer garnish -Front 166.00	\$ 32 199.00 ✓
1	Front door regulator	\$ 11 238.00 X
1	Front door regulator motor	\$ 11 265.00 X
1	Front door rubber	\$ 11 165.00 ✓
1	Wheel arch panel	\$ 2 425.00 X
1	Wheel arch panel outer garnish	\$ 32 195.00 ✓
1	Front step panel garnish	\$ 32 325.00 ✓
		\$ 8,299.00
		Less 15% \$ 1,244.85
		\$ 7,054.15


4378
152
371.30

Special Nett Items

1	Front tyre	\$ 11 400.00 X
1	Front wheel rim -L/H	\$ 11 550.00 X
1	Front door lettering sticker	\$ 25 45.00 35
1	Front door company sticker	\$ 25 280.00 200
		\$ 1,275.00

<u>S/N.</u>	<u>Labour Charges</u>	
1	To check wiring and reset headlamps focussing.	\$ 80.00 30
2	To conduct wheel alignment.	\$ 11 180.00 X
3	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$ 200.00 60
4	To apply undercoating.	\$ 200.00 50
5	Panel beating.	\$ 1,500.00 600
6	To respray painting on the affected areas.	\$ 1,400.00 680
		\$ 3,560.00

Grand Total : \$ 11,889.15



P-3721-30
S.N-235.00
L-1420.00
5376.30
20%
4301.04

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jan 2020 Edit Reg		01 Feb 2020 00:00 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	ANDRIC AGENCIES PTE LTD , Co. Reg. No.: 200804611D								
Main Claimant:	AGAPE LOGISTICS PTE LTD								
Vehicle Reg. No.:	GBG8068S	Date of Loss:	27/12/2019 00:00 - :59 [25 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6251337431SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLL4262D	Policy No. (Claimant):							
		Excess:							
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (06/01/2020): TP GIA report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBG8068S (6251337431SG)
[SLL4262D]**






































TP































AGAPE LOGISTICS PTE LTD

Dec 27 2019 12:00AM

[ANDRIC AGENCIES PTE LTD]

Imperium Automotive - Kaki Bukit

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	10/02/20 15:25	Chassis Number														Load JPG	<input checked="" type="checkbox"/>			
2	10/02/20 15:26	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>			
3	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
4	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
5	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
6	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
7	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
8	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
9	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
10	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
11	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
12	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
13	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
14	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
15	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
16	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
17	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
18	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
19	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
20	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
21	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
22	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
23	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
24	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
25	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
26	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
27	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
28	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
29	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
30	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
31	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
32	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
33	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
34	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
35	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
36	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			
37	10/02/20 15:28	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
56	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
57	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
58	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
59	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
60	10/02/20 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
61	21/02/20 13:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/02/20 13:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/02/20 13:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/02/20 13:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	21/02/20 13:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/20 10:03	TP GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/01/20 15:55	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20000148/UVF3E2

Date: 24/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBG8068S

Insured Vehicle No : SLL4262D

Date of Loss: 27/12/2019

Nature of Claim: TP

Claim No: 6251337431SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG8068S

Make & Model: ISUZU NHR85AUE4A, 3.0 D (M)

Reg. Date: 01/11/2017 (Man. Year: 2017)

Colour: White

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 4JJ13A9243

Chassis No: JAANHR85EH7100232

Odometer: 124566 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 165 R13 (D)

Front Left Side: Yokohama 6 mm

Rear Left Side: Delium 6/6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Delium 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,329.15	3,956.30	4,372.85	52.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,420.00	2,140.00	60.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,889.15	5,376.30	6,512.85	54.78
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	11,889.15	4,300.00	7,589.15	63.83

INSPECTION

Date of Assignment: 01/02/2020

Date Inspected: 10/02/2020 Inspected At:

Imperium Automotive - Kaki Bukit (HQ)

25 Kaki Bukit Road 4, #01-49

Synergy@KB

Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP SIDE BRACKET	Not Necessary	160.00 FL	*- FL
2	1		*FRONT HEADLAMP LOWER RUBBER SEAL	Torn	110.00 FL	*48.00 FL
3	1		*FRONT SIDE LAMP	Broken	355.00 FL	*188.00 FL
4	1		*FRONT CORNER PANEL - L/H	Cut	425.00 FL	*366.00 FL
5	1		*FRONT SIDE MIRROR - L/H	Not Necessary	243.00 FL	*- FL
6	1		*FRONT SIDE MIRROR STAY	Not Necessary	200.00 FL	*- FL
7	1		*FRONT BUMPER	Distorted	1,383.00 FL	*745.00 FL
8	1		*FRONT BUMPER SIDE BRACKET LH	Bent	255.00 FL	*255.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	No such part	380.00 FL	*- FL
10	1		*FRONT DOOR - L/H	Badly Dented	1,595.00 FL	*1,265.00 FL
11	1		*FRONT DOOR CHECKER	Not Necessary	105.00 FL	*- FL
12	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	115.00 FL	*- FL
13	1		*FRONT DOOR HINGES	Bent	156.00 FL	*115.00 FL
14	1		*FRONT DOOR INNER BOARD	Not Necessary	235.00 FL	*- FL
15	1		*FRONT DOOR LOCK	Not Necessary	185.00 FL	*- FL
16	1		*FRONT DOOR OUTER GARNISH - FRONT	Grazed	199.00 FL	*166.00 FL
17	1		*FRONT DOOR REGULATOR	Not Necessary	238.00 FL	*- FL
18	1		*FRONT DOOR REGULATOR MOTOR	Not Necessary	265.00 FL	*- FL
19	1		*FRONT DOOR RUBBER	Twisted	165.00 FL	*165.00 FL
20	1		*WHEEL ARCH PANEL	Repair	425.00 FL	*- FL
21	1		*WHEEL ARCH PANEL OUTER GARNISH	Grazed	195.00 FL	*195.00 FL
22	1		*FRONT STEP PANEL GARNISH	Grazed	325.00 FL	*325.00 FL
23	1		*FRONT TYRE	Not Necessary	400.00 FS	*- FS
24	1		*FRONT WHEEL RIM - L/H	Not Necessary	550.00 FS	*- FS
25	1		*FRONT DOOR LETTERING STICKER	Necessary	45.00 FS	*35.00 FS
26	1		*FRONT DOOR COMPANY STICKER	Necessary	280.00 FS	*200.00 FS
27	1		*FRONT HEADLAMP - L/H	Cracked	585.00 FL	*545.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,574.00	4,613.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,244.85	656.70
Total Parts (\$\$)	8,329.15	3,956.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	30.00
2	TO CONDUCT WHEEL ALIGNMENT	New	180.00	0.00
3	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	200.00	60.00
4	TO APPLY UNDERCOATING	New	200.00	50.00
5	PANEL BEATING	New	1,500.00	600.00
6	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	680.00
Gross Labour Cost (\$\$)			3,560.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >