



Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
138 Robinson Road #07-09
The Corporate Office
Singapore 068906
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS

Original Report No : MOR119123751 Vehicle Registration No : FBQ124M
Name(as shown in NRIC) : MOHAMMAD NUR HUSYAM BIN ROSLAN
NRIC/Passport No : S9013796D
Address :
Contact (Tel) : (H/P) : 90702044
(EMail) :
Date Of Accident : 6/09/2019 Time Of Accident : 22:00
Place Of Accident : STEVEN ROAD
Insurance Company : AXA Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:-

AMEND TO INDICATE VIDEO CAPTURED


SIGNATURE OF VEHICLE OWNER/DRIVER
DATE: 18/09/2019

GS/19/5004/PMR/PDPI/jn/hk

**THIS IS A NON-SCANNABLE EXHIBIT ATTACHED,
(CD-R CONTAINING THE ACCIDENT VIDEO FOOTAGE)**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2019 09:10
Date Of Accident	16/09/2019 22:00
Exact Location Of Accident	ALONG STEVENS RD AFTER YMCA T-JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8591Y
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	TAN AIK HAN
NRIC No	S0054788C
Address	BLK 119 SIMEI STREET 1 #09-504

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBQ124M
Vehicle Make/Model/Colour	MOTORCYCLE
Name of Driver	UNKNOWN
Insurance Company Name	

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMPETENT TRANSPORTATION LTD LTD
10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 17 SEP 2019

GIA/NAF SketchPlanForm_V3



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 16/9/19 @ 2200hrs I was travelling on Stevens Road in Centre lane of a two lane Road, upon reaching location the road that opened up to three lane. I was at the middle lane. Upon hearing a sound at the rear of my taxi and I saw a person waving at me, like calling for help. I then change lane to the left lane and stop along the T-junction of Stevens Rd after the Ymer. Then I realised a Motorcycle of FBQ 124M was skidded. The rider suffer slight bruises on his hand. I am sure there is no contact between our vehicle.

I am Filling this report for reporting purpose.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CONTACT NO: 159092218

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 17 SEP 2019
NRIC/FIN No.:

COMFORT TRANSPORTATION PTE LTD


Annex E

NOTICE OF REPORTING

This is to confirm that Tan Aik Han NRIC/FIN: S0054788C, residing at 119 Simei St 1 #09-54 TEL: 96812173, has reported to the Police, a non-injury traffic accident which occurred along Stevens Road on 16/09/2019 at about 2200hrs involving the following vehicles:

- i) SHC8591Y (complainant)
- ii) FBQ124M (Other party)

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.



Rank/ Name of Issuing Officer: ASP Nigel Lim

Date: 17/09/2019

Time: 0200hrs

Police Post/ Unit: Changi Neighbourhood Police Centre

Original - to be issued to informant

Duplicate - to be submitted to Traffic Police

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SCENE



SCENE



SCENE



Enquire Vehicle & Owner Information (Vehicle No. SHC8591Y As At 16 Sep 2019 / 22:00:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: FBQ124M/PMR/JN/HK

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717
Current Vehicle Details

Vehicle No.: SHC8591Y
Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Insurance Company Name: INDIA INT'L INS PTE LTD

Print

OK



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220

Tel: 9101 7844

Fax: 6996 6442

Business Reg. No.: 53387981K

Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/1909/FBQ124M/PR

Mr Mohammad Nur Husyam Bin Roslan

Bill No.: LA19110005

C/O KSCGP Juris LLP
10 Hoe Chiang Rd
#13-03 Keppel Towers
Singapore 089315

Bill Date : 18 Nov 2019

To our services rendered in connection with the below matters:-

<u>Description</u>	<u>Amount</u>
Survey fees	\$ 260.00
Transportation	\$ 180.00
Photographs (38) Copies	\$ 38.00
Total:	\$ 478.00

Dollars: Four Hundred And Seventy Eight Only.

Please quote our Bill No. or return a copy of our bill with your remittance.

Cheque should be made payable to "Lee Appraisal Services",

or via PayNow Corporate to UEN "53387981K".

LEE APPRAISAL SERVICES



Lee Kah Pang

Dip Mech Engr, BCompSc



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220

Business Reg. No.: 53387981K

Tel: 9101 7844

Fax: 6996 6442

Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/1909/FBQ124M/PR

VEHICLE APPRAISAL REPORT

Mr Mohammad Nur Husyam Bin Roslan

Report Date : 18 Nov 2019

C/O KSCGP Juris LLP
10 Hoe Chiang Rd
#13-03 Keppel Towers
Singapore 089315

REFERENCE

Your Reference No	: Not Advised	Date of Inspection	: 26 Sep 2019
Type of Appraisal	: Third Party	Date of Re-inspection 1	: 08 Nov 2019
Date of Accident	: 16 Sep 2019	Date of Re-inspection 2	: 11 Nov 2019

PARTICULARS OF VEHICLE

Registration No.	: FBQ124M	First Reg Date	: 12 Jul 2019
Make	: Yamaha	COE Expiry	: 11 Jul 2029
Model	: Aerox GDR155 CVT ABS	Odometer	: 4321
Color	: Black	Engine No.	: G3J8E0110689
Manufacturing Year	: 2019	Chassis No.	: MH3SG4640KJ058196

CONDITIONS OF VEHICLE (STATIC CHECK AT TIME OF INSPECTION ONLY)

Front Brake	: Serviceable	Steering	: Distorted
Rear Brake	: Serviceable	Modification	: None

TYRE / CONDITION

Location	Make & Size	Thread
Front	IRC 110/80 R14	5 mm
Rear	IRC 140/70 R14	6 mm

DAMAGE PROFILE

The vehicle sustained damages on front & left side.

Please refer to photographs and assessment of repairs for details.

ASSESSMENT SUMMARY

Repair cost to the vehicle is assessed as **\$3,000.00** on **lump sum basis**

Estimated period required for repairs: **(3) days**

Survey conducted at: **Primero Racing**

Enclosed (38) photographs depicting damages to the vehicle

The survey was conducted on a *WITHOUT PREJUDICE* basis.



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220

Business Reg. No.: 53387981K

Tel: 9101 7844

Fax: 6996 6442

Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/1909/FBQ124M/PR

ASSESSMENT FOR REPAIR : FBQ124M

Qty	Description	Condition	Repairer's Estimate	Our Assessment
1 pc	Handle bar	Distorted	122.00	122.00 <i>x sue</i> ✓ Δ
1 set	Handle grip	Cut	30.00	30.00
1 pc	Lever LH	Cut	46.00	46.00
2 pcs	Front body cowling @141.00	LH Cut	282.00	141.00 <i>x sue</i>
2 pcs	Front body cowling emblem set @75.00	LH Necessary	150.00	75.00 <i>x sue</i>
1 pc	Front lower cover, carbon fibre	Grazed	74.00	74.00
2 pcs	Fork assy @377.00	Distorted	754.00	754.00
1 pc	Fork under bracket	Distorted	215.00	215.00
1 pc	Front fender, carbon fibre	Cut	195.00	195.00
1 pc	Front wheel	Deformed	346.00	346.00 <i>x sue</i>
1 pc	Front wheel axle	Bent	38.00	38.00 <i>x sue</i>
1 pc	Side cover mole LH	Cut	68.00	68.00
1 pc	Footrest board LH	Cut	83.00	83.00
1 pc	Footrest mat LH	Warped	54.00	54.00
1 pc	Side stand	Bent	86.00	86.00 <i>x sue</i>
1 pc	Main stand	Cut	144.00	144.00
			2,687.00	2,471.00 <i>1663</i>
		Less 10%	268.70	247.10 <i>10%</i>
			2,418.30	2,223.90 <i>1496.70</i>

Special Nett Items				
1 pc	IU unit	Cut	156.00	156.00
1 set	Lever guard	Cut	150.00	120.00 <i>60</i>
1 set	Steering cone & bearing	Necessary	150.00	120.00 <i>80</i>
			456.00	396.00 <i>296</i>

Total Parts	2,874.30	2,619.90
-------------	----------	----------

Labour Charges

1	Align steering components	250.00	180.00 <i>100</i>
2	Service leaking crankcase and renew gasket	250.00	200.00 <i>x</i>
3	Workmanship to renew damaged parts	400.00	350.00 <i>250</i>
		900.00	730.00 <i>350</i>

Total Parts & Labours Concluded	3,774.30	3,349.90
---------------------------------	----------	----------

Lump Sum Repair Adjustment (new bike less 10%)		3,000.00
--	--	----------

1496.70
 296.00
 350.00
 2142.70
 10%
 1928.43
 415-1,900
 3 days



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220

Business Reg. No.: 53387981K

Tel: 9101 7844

Fax: 6996 6442

Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/1909/FBQ124M/PR

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment above.

Yours faithfully,
LEE APPRAISAL SERVICES



Lee Kah Pang

Dip Mech Engr, BCompSc




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III19016661/R1yd3s2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 14-01-2020		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8591Y	Veh. Inspected	FBQ 124M	
Policy No.	MC0M0015	Coverage (\$)	0.00	
Claim No.	MCT19090370	Excess (\$)	0.00	
Assign From	STANLEY LAI	Assign Date	30/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA GDR155A	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MH3SG4640KJ058196	Colour	MULTI-COLOUR	
Odometer	4321	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/80-14	IRC	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70-14	IRC	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/09/2019	Inspection Date	27/09/2019	
Survey held at	PRIMERO RACING 20 BUKIT BATOK CRESCENT #01-19 ENTERPRISE CENTRE SINGAPRE 658080			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 124M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR	SERVICEABLE	122.00	-
1	SET HANDLE GRIP	CUT	30.00	30.00
1	LEVER LH	CUT	46.00	46.00
2	FRONT BODY COWLING @ \$141.00	SERVICEABLE	282.00	-
2	SET FRONT BODY COWLING EMBLEM @ \$75.00	NOT NECESSARY	150.00	-
1	FRONT LOWER COVER, CARBON FIBRE	GRAZED	74.00	74.00
2	FORK ASSY @ \$377.00	DISTORTED	754.00	754.00
1	FORK UNDER BRACKET	DISTORTED	215.00	215.00
1	FRONT FENDER, CARBON FIBRE	CUT	195.00	195.00
1	FRONT WHEEL	SERVICEABLE	346.00	-
1	FRONT WHEEL AXLE	SERVICEABLE	38.00	-
1	SIDE COVER MOLE LH	CUT	68.00	68.00
1	FOOTREST BOARD LH	CUT	83.00	83.00
1	FOOTREST MAT LH	WARPED	54.00	54.00
1	SIDE STAND	SERVICEABLE	86.00	-
1	MAIN STAND	CUT	144.00	144.00
	LESS 10% DISCOUNT		-268.70	-166.30
			2,418.30	1,496.70
SPECIAL NETT ITEMS				
1	IU UNIT (SN)	CUT	156.00	156.00
1	SET LEVER GUARD (SN)	CUT	150.00	60.00
1	SET STEERING CONE & BEARING (SN)	NECESSARY	150.00	80.00
			456.00	296.00
LABOUR				
	ALIGN STEERING COMPONENTS.		250.00	100.00
	SERVICE LEAKING CRANKCASE AND RENEW GASKET.	NOT NECESSARY	250.00	-
	WORKMANSHIP TO RENEW DAMAGED PARTS.		400.00	250.00
			900.00	350.00
GRAND TOTAL			3,774.30	2,142.70

Report Ref No. CS3/III19016661/R1yd3s2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	----------

Report Ref No. CS3/III19016661/R1yd3s2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.