

ASS. REC. BY:

REF: 033

III 20000786/Gq d 302

Special Instruction:

Assigner: GA

ASSIGNMENT (Office)

From (Person):

MEMMEN Gabriel Wee

of

III

Date/Time:

2/1/2020 @ 3:04pm

Estimated Cost:

Bill to:

OP / EP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SKV 6666T

Insured:

SHD 3991D

at Workshop m/s

Mega Swift

Tel:

97511604

of

176 Sin Ming Drive #05-11

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:52am @ 3/1/2020

Person Contacted:

Alan

Vehicle IN / OUT

Date/Time

Action/Instruction Estimate (X)

SKV 6666T-X

SHD 3991D - CS/SM07003991/M/H/3m2

AVA: 2/1/2020

03/1/20

Submit pas.

Nivitha (LKK Auto)

From: Gabriel Wee <Gabriel@iii.com.sg>
Sent: Thursday, 2 January 2020 3:04 PM
To: 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: Acc invl SHD3991D (III) & SKV6666T on 31.12.19
Attachments: shd3991d_20200102144104.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SKV6666T
III INSURED VEHICLE NO. : SHD3991D
DATE OF LOSS : 31.12.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Aida**.

We will forward you the workshop details once we receive the same.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

We started using audatex since 1st dec 2019. Please do adjustments throught Audatex and upload the report onto Merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this

information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

K. K. CHENG & CO

Advocates and Solicitors
 101 Upper Cross Street #05-21
 People's Park Centre
 Singapore 058357
 Tel: 6227 1272 Fax: 6227 5563



Our Ref: MEGA/SKV 6666T
 Your Ref: SHD 3991D
 (Please quote our reference number when replying)

2 January 2020

INDIA INTERNATIONAL INSURUAN CE
 Singapore

By fax only: 6224-4174

Dear Sirs

NOTICE OF ACCIDENT

Claimant: TAN SENG CHIN FINIAN

Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident occurring on or after 1st April 2016 ["Protocol"]

We refer to your letter dated 2 January 2020.

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 2 January 2020.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 2 January 2020.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, *for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.*

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:

Name of Workshop	:	Mega Swift Auto
Address	:	Block 176 Sin Ming Drive #05-11 Sin Ming Autocare Singapore 575721
Contact person	:	Alan
Telephone No	:	9751 1604

Yours faithfully

CHENG KIM KUAN

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/12/2019 14:15
Date Of Accident	31/12/2019 10:05
Exact Location Of Accident	AFTER SENTOSA GANTRY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV6666T
Insured/Policyholder	
Name Of Registered Owner	TAN SENG CHIN FINIAN
NRIC No	SXXXX713Z
Email Address	IVY.CHIN@VICKERSVENTURE.COM
Mobile Phone No	(LOCAL) +65-91193388
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	TOGUAN
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTVO1013382
Cover Note Number	16/11/2019 TO 15/11/2020

Driver

Name of Driver	ANTONIO JOANLEY MARIANO
Passport No/FIN	GXXXX839N
Date Of Birth	28/03/1990
Occupation	INDOOR
Date Of Driving Pass	11/09/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91193388
Fax Number	
Contact Number	

Address 293 OCEAN DRIVE #13-17
 Postcode 098533
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : BJ
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD3991D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver WONG CHIN ANN
 NRIC/Passport Number SXXXX790F
 Contact Number 83861476
 Address
 Postcode
 Insurance Company Name

Sketch Plan Pg. 1
SKETCH PLAN

Sompo
Vehicle : SKV 6666T

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

Date of accident: 31/12/19 Time: 10:05 Location: After Lentosa Gantry
 My Vehicle A: SKV6666T Vehicle B: SHD3991D Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 31 Dec 2019 at 10.05am.

I was driving at Lentosa Gantry's resident lane after gantry; Comfort taxi SHD3991D cut into my lane and hit the passenger's side portion

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop : MESO SWIFT AUTO
 Email address : meso.swift0511@gmail.com
 & myself : _____
 Email address : NIL

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Vehicle: -SKV 6666T

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

31/12/19 10:05 AM





Sompo Insurance Singapore Pte. Ltd.

59 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6464 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg No: 198905400E | GST Reg No: M200903196

Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D19MTPV01013382
Insured : TAN SENG CHIN FINIAN
Motor Car (Registration No.) : SKV6666T
Cover : Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date : 16 NOVEMBER 2019 00:00
Policy Expiry Date : 15 NOVEMBER 2020 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$400 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : Buy Up : \$100 - Section I
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP-27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 13 SEPTEMBER 2019 15:00

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11G05800 & GREAT EASTERN FINANCIAL ADVISERS PTE LTD CI Code: 22A RADZOW2KKMDYCIAJ

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **G2591839N**
 Name: **ANTONIO JOANLEY MARIANO**

Birth Date: **28 Mar 1990**
 Issue Date: **11 Sep 2018**
 Valid Till: **10/09/2023**

002844484E



WORK PERMIT
 Employment of Foreign Manpower Act (Chapter 91A)
 Republic of Singapore

Employer Location:
FRAN TAJI SENG CHH
293 OCEAN DRIVE #13-17 S(098533)

Name:
ANTONIO JOANLEY MARIANO

Work Permit No: **0 27081886** Sector: **DOMESTIC**

11133141



STRICTLY FOR WORKSHOP USAGE
 USE FOR ACCIDENT REPORTING ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3A Motor cars without clutch pedals (Auto) with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight <= 2500kg

EFFECTIVE DATE
 11 Sep 2018

License No: G2591839N

NP 428A

STRICTLY FOR WORKSHOP USAGE
 USE FOR ACCIDENT REPORTING ONLY

VISIT PASS
Immigration Regulations

29-01-2019

Name: ANTONIO JOANLEY MARIANO

PN
G2591839N

Date of Birth: **28-03-1990** Sex: **F**

Nationality: **FILIPINO**

Download SGWorkPass App to check status



MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

ANTONIO JOANLEY MARIANO



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	713Z
Vehicle No.:	SKV6666T
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jan 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TIGUAN 1.4 TSI AT BMT 5N22QY
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	CTH230424
Chassis No.:	WVGZZZ5NZGW025031
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$26,894.00
Original Registration Date:	05 Nov 2015
First Registration Date:	05 Nov 2015
Transfer Count:	0
Actual PARF Paid:	\$29,652.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Nov 2025
PARF Rebate Amount:	\$22,239.00
COE Expiry Date:	04 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Quota (Years):	10
QIP Price:	\$59,889.00
COE Rebate Amount:	\$34,905.00
Total Rebate Amount:	\$57,144.00

The information contained herein is correct as at 06 Jan 2020

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2020 10:43 Edit Reg		02 Jan 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SKV6666T	Date of Loss:	31/12/2019 00:00 - :59 [49 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHD3991D	Policy No. (Claimant):	
		Excess:	
Repairer:	Mega Swift Auto (HQ) 176 Sin Ming Drive, #05-11 Sin Ming Autocare, 575721 Sin Ming - Tel: 6459 2321, 6459 4077		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/01/2020]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SKV6666T
[SHD3991D]
TP
-
Dec 31 2019 12:00AM
[-]
Mega Swift Auto

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
2	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
3	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
4	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
5	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
6	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
7	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
8	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
9	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
10	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
11	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
12	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
13	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
14	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
15	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
16	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
17	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
18	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
19	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
20	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
21	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
22	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
23	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
24	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
25	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
26	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
27	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
28	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
29	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
30	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
31	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
32	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
33	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
34	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
35	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
36	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
37	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
38	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
39	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
40	08/01/20 10:25	General View		Load JPG	<input checked="" type="checkbox"/>					
41	08/01/20 10:25	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
42	08/01/20 10:25	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/20 10:23	ASSIGNMENT FROM III	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/01/20 08:43	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III20000186/GQD3E2**Date:** 09/01/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant
Vehicle No : SKV6666T**Insured Vehicle No :** SHD3991D

Date of Loss: 31/12/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKV6666T**

Make & Model: VOLKSWAGEN TIGUAN, 1.4 TSI (A)

Engine No: CTH230424

Reg. Date: 05/11/2015 (Man. Year: 2015)

Chassis No: WVGZZZ5NZGW025031

Colour: Silver

Odometer: 58962 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/40Z R19 Rear Tyre Size: 255/40Z R19

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/01/2020

Date Inspected: 06/01/2020 Inspected At:

Mega Swift Auto (HQ)
176 Sin Ming Drive, #05-11 Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2020)	
Parts: M1-SUV	VOLKSWAGEN TIGUAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKV6666T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >