

request

ASS. REC. BY:

REF: CS/INCR0000219 / Byd3er

Special Instructions

Singer: Mtim

ASSIGNMENT (Office)

From (Person): Theresa Yimala

of INC

Date/Time: 3/1/2020 @ 9:55am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 7157L

Insured:

at Workshop m/s

Team AutoPro

Tel:

6258 1955

of

160 Sin Ming Drive # 01-14

Policy No:

Claim No:

MT/1078094-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:00am @ 3/1/2020

Person Contacted:

Peach

Vehicle IN / OUT

Date/Time

Action/Instruction

To inspect

SLF 7157L-X

Jord

INC

ASSIGNMENT

From: Date: 3/1/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 7157L

at Workshop m/s

Team Autopro

of 160 Sin Ming Drive #01-14

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball. or Market Value: 71,000/2

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res. Yes or No

Lum Sum: % 3 Vol. Yes or No

CA / REV / REP. / 24 HRS lup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLF 7157L Regn: 7/9/2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen C4 Picasso 1.6 cc 1598

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 51481 T/Radio: Insured / Std / NI / NA

Eng/No: 10JBHD3053723

C/No: VF7DBH2TQJ666997

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60/16

R: 205/60/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 31/12/19 D.O.I. 3/1/2020

Survey held at Team Autopro 0231 PM

Des. of Damages: Fit / Real / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 3,000/2 - 10,000/2

need GIA OK

RECEIVED 03 FEB 2020

HS 9,200/2 Team Lin 16/1/2020 (Red \$13946-75, 60%)

MV 71,000/2 29/01/2020 - CR reviewed. Too high adjustment
PV 42,312/2 with no clear photos showing
NV 28,688/2 damages - To submit as per adjustment.

Date/Time, File Path (if)

☐ : Prel. Report

j)

☐ : Final Report

Date/Time, File Path (if)

31/1/20 Typist

Report Format:

Long Form U.S.G. \$9200/2

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Insp. (\$)☐ Workshop (\$)

Survey Fee:

Transportation

Fuel

Other

Other

Other

Total

250

250

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Friday, 3 January 2020 9:55 AM
To: 'assignments'
Cc: Theresa Vimala D/O Balagangadharan; Thio Tse Kiat
Subject: RE: TP CASES FARMED OUT TO LKK ON 3/1/2020

Dear LKK

Please assist to survey the following vehicles :

SN	OIC	Claim No.	Appt Type	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1			TP	3/1/2020	JPT7907	AUTOEXCEL ENGINEERING PTE LTD	160 SIN MING DRIVE SIN MING AUTOCTY #06-01	Ryan Soh / 93825367				
2	JAREJ	MT/1078094-001	TP	3/1/2020	SLF7157L	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999				
3		MT/10777727-002	TP	3/1/2020	SMC6867G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295				
4		MT/1077764-002	TP	3/1/2020	SLH8755T	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295				

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/12/2019 16:21
Date Of Accident	31/12/2019 12:50
Exact Location Of Accident	BKE TOWARDS PIE (CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF7157L
Insured/Policyholder	
Name Of Registered Owner	NUR ELFANIE BINTE ABDUL SAMAD
NRIC No	SXXXX459D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97435009
Alternative Phone No	OFFICE-97435009

Vehicle Particulars

Manufacturer	CITROEN
Model	C4 PICASSO-1.6 BLUEHDI EAT6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 28823792 QMY
Cover Note Number	

Driver

Name of Driver	MOHAMAD HALIM SHAH BIN ABDUL RAHMAN
NRIC No	SXXXX468B
Date Of Birth	23/04/1982
Occupation	OUTDOOR
Date Of Driving Pass	10/11/2004
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97435009
Fax Number	
Contact Number	OFFICE-97435009
Email Address	NOEMAIL

Address	APT BLK 546B SEGAR ROAD #07-53 SINGAPORE
Postcode	672546
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NUR ELFANIE BINTE ABDUL SAMAD GENDER: : FEMALE
Passenger 2	NAME: : MD ARIFF GENDER: : MALE
Passenger 3	NAME: : HANA SUFFIA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC4207E
Vehicle Make/Model/Colour	VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature

Date & Time: 31/12/19, 2:15 pm


 Driver's Signature

(If driver is not the policyholder)

Date & Time: 31/12/19


1415


 Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle SLF 7157L was travelling on the stated venue. I was travelling straight in my lane. the car in front brake, as such I applied my brakes and came to a stop. A few seconds later, I felt an impact on my vehicle rear portion shortly I got out and realised vehicle 'B' GBC 4207E unable to brake in time, had collided against my stationary vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 31/12/19, 3:15pm

Continued on next page, if any

Driver's Signature

(If driver is not the policyholder)

Date & Time: 31/12/19, 14:15

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 31/12/2019 (dd/mm/yy) Time of Accident: 12:50 (24-HR-FORMAT)
 Vehicle No.: SLF 7157 L Vehicle Make & Model: CITROEN C4 PICASSO 1.6 BLUEHDI EAT6
 Exact location of Accident: BKE TOWARDS PIE CHANGI
 Policyholder's Name / IC No.: NUR ELFIANIE BINTE ABDUL SAMAD S8418459D
 Driver's Name / IC No.: MOHAMAD HALIM SHAH BIN ABDUL RAHMAN S8210468B (As Above) ☐
 Driver's Contact No.: 9743 5009 Company Contact No.: _____
 Driver's Address: 546B SEGAR ROAD #07-53 S672546
 Insurance Company: MSIG Email address (if any): _____

Relationship between Owner & Driver: SPOUSE

or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

**Exact purpose for which the vehicle
Was being used at time of accident?**

☒ Private use / ☐ Work purpose

Occupation (nature of job) ☐ Indoor / ☒ Outdoor

No. of Passengers (Including Driver): 04

Passenger Name : NUR ELFIANIE

Gender : Female

Passenger Name : MD ARIFF

Gender : Male

Hana Sofia

Gender : Female

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: GBC 4207 E

Driver's Contact No: _____ Insurance Company (If any): _____


2. Driver's Name / IC No: _____ Vehicle No: _____

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle SLF7157L was travelling on the stated venue. I was travelling straight in my lane. the car in front brake, as such I applied my brakes and came to a stop. A few seconds later, I felt a impact on my vehicle rear portion. shortly I got out and realised vehicle 'B' GBC 4207E unable to brake in time, had collided against my stationary vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 31/12/19, 2:15pm


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 31/12/19, 1415

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	459D
Vehicle Details	
Vehicle No.:	SLF7157L
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jan 2020
Vehicle Make:	CITROEN
Vehicle Model:	C4 PICASSO 1.6 BLUEHDI EAT6
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	10JBHD3053723
Chassis No.:	VF73DBHZTGJ666997
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$22,863.00
Original Registration Date:	07 Sep 2016
First Registration Date:	07 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$9,009.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Sep 2026
PARF Rebate Amount:	\$6,756.00
Intended COE Rebate Details	
COE Expiry Date:	06 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,334.00
COE Rebate Amount:	\$35,556.00
Total Rebate Amount:	\$42,312.00

The information contained herein is correct as at 06 Jan 2020

OK

MV 66,000/2

PV 42,312/2

NV 23,688/2

TCU M
16/1/2020

Google Home Mini

Buy Google Home Mini for hands-free control of your smart home. Shop i

Citroen Price Range Depreciation 2016 Vehicle Type

Advanced Search

Home » Used Cars » Classic Credit Pte Ltd » Citroen Grand C4 Picasso Diesel 1.6A BlueHDI

Citroen Grand C4 Picasso Diesel 1.6A BlueHDI

Overview Financial Insurance Accessories Similar Research Photos Map

CLASSIC CREDIT SGCARMART'S PREMIUM DEALER 2011 / 2014 / 2015 / 2016 / 2017

Price	\$67,800	Fuel Type	Diesel (Euro 5 Engine and Above)
Depreciation	\$8,970 /yr View models with similar depre	Reg Date	08-Nov-2016 (5yrs 9mths 17days COE left)
Mileage	N.A.	Manufactured	2016
Road Tax	\$1,244 /yr	Transmission	Auto
Dereg Value	\$44,926 as of today (change)	OMV	\$26,192
COE	\$50,991	ARF	\$13,669
Engine Cap	1,560 cc	Power	88.0 kW (118 bhp)
Curb Weight	1,359 kg	No. of Owners	1
Type of Vehicle	MPV		

Features

1.6L Turbo Diesel, 6 Speed Full Auto With Paddle Shift, Traction Control, 6 x Airbags, Speed Limiter/Cruise Control And Keyless Entry & Start/Stop. View specs of the Citroen Grand C4 Picasso Diesel (2014-2017)

Accessories

Keyless Entry/Start/Stop, Reverse Camera, LED Daytime Running Lights, Auto Headlights And Wipers, Navigation, Panoramic Roof.

Description

Best Deal. 1 Owner. Bidded Golden Plate Number '808'. Grand Luxury 7 Seater Mpv. Facelift Model. Skyroof Edition. 100% Accident Free. Hurry!View Now. Free Extended Warranty. Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaed Warranty. Meet Our Friendly Consultant For An Non Obligation Advised.

Category

MPV Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more




Car Valuation - Free

Find out the market value of your existing car for free. Get started

Compare



Price Chart



Click on the point to view the vehicle

Shortlist Compare Add note
Report Error More Actions

Seller Information

Classic Credit Pte Ltd

57 vehicles for sale. 22 sold in past 3 mths

61 Ubi Avenue 2 #03-11, #03-18, #04-05
Automobile Megamart
Tel: 68412076 / 68481203 / 68414849
Search cars nearby

Mr Chen
Roland

90044461
97479331

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SLF 7157 L**
 Model : Citroen C4
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 3,852.60	3,852.60
2	Tailgate outer Garnish	1	\$ 647.20	647.20
3	Tailgate logo	1	\$ 201.30	201.30
4	Tailgate emblem 'Citroen'	1	\$ 183.20	183.20
5	Tailgate emblem 'PICANCO' <i>PICASSO</i>	1	\$ 146.30	146.30
6	Tailgate emblem 'BLUEHD'	1	\$ 173.50	173.50
7	Tailgate emblem 'C&C'	1	\$ 203.40	203.40
8	Tailgate emblem 'C4'	1	\$ 184.60	184.60
9	Tailgate weather strip	1	\$ 437.20	437.20
10	Tailgate inner trim board	1	\$ 493.20	493.20
11	Tailgate inner lock	1	\$ 438.60	438.60
12	Tailgate lock sensor	1	\$ 354.80	354.80
13	Tailgate antenna	1	\$ 300.00	300.00
14	Tailgate lamp	2	\$ 950.00 1,786.20	1,644.00 3,572.40
15	Rear windscreen moulding top	1	\$ 186.30	186.30
16	Rear windscreen moulding bottom	1	\$ 175.10	175.10
17	Rear windscreen moulding side	1	\$ 116.20	116.20
18	Rear bumper	1	\$ 2,674.90	2,674.90
19	Rear bumper side retainer	2	\$ 268.40	536.80
20	Rear bumper bracket	2	\$ 185.00 186.70	370.00 373.40
21	Rear bumper reflector	2	\$ 276.50 482.60	553.00 965.20
22	Rear bumper lower lid	1	\$ 684.20	684.20
23	Front bumper reinforcement	1	\$ 658.30	658.30
24	Rear end panel	1	\$ 1,058.40	1,058.40
25	Rear end panel top garnish	1	\$ 385.80	385.80
26	Rear bumper tow cap	1	\$ 204.60	204.60

Parts Sub Total : \$10,027.90 19,207.50
 Discount : \$1,002.79 1,920.75
PARTS TOTAL : \$9,025.11 17,286.75

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 60.00	\$ -60.00
2	Tailgate outer garnish clips	1	\$ 60.00	\$ 30.00 60.00
3	Rear bumper clips	1	\$ 60.00	\$ 30.00 60.00
4	Rear bumper lower lid clips	1	\$ 60.00	\$ 30.00 60.00
5	Tailgate sealant	1	\$ 100.00	\$ 100.00
6	Tailgate lamp sealant	2	\$ 80.00	\$ 60.00 160.00
7	Rear windscreen sealant	1	\$ 80.00	\$ 50.00 80.00
8	Rear windscreen clips	1	\$ 60.00	\$ 30.00 60.00
9	Tailgate windscreen inner seal	1	\$ 80.00	\$ -80.00
10	Rear end panel sealant	1	\$ 100.00	\$ 50.00 100.00
11	Rear number plate w/casing	1	\$ 80.00	\$ 80.00
12	Reverse camera	1	\$ 380.00	\$ 380.00
13	Reverse sensor	4	\$ 250.00	\$ 1,000.00
SPECIAL NETT TOTAL :				\$ 680.00 2,280.00

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 50.00 100.00
2	R&R reverse sensor	\$ 60.00 100.00
3	R&R rear windscreen	\$ 120.00 250.00
4	Disconnect wire harness to facilitate repair, reconnect and test function	\$ 30.00 80.00
5	R&R upholstery	\$ 200.00
6	Panel beat	\$ 800.00 1,200.00
7	Reset fault code	\$ 300.00
8	Rust proofing	\$ 150.00
9	Spray painting	\$ 900.00 1,200.00
LABOUR TOTAL :		\$ 1860.00 3,580.00

Survey
3/1/2020

Trim lin

Lump sum repair

Resurvey 6/1/2020

1600 hrs

Trim lin

Repair days 7

PARTS TOTAL : \$ 9025.11 17,286.75
SPECIAL NETT TOTAL : \$ 680.00 2,280.00
LABOUR TOTAL : \$ 1860.00 3,580.00
GRAND TOTAL : \$ 23,146.75

@ 20%

11,565.11
2313.02
9252.08

L/S 9,200/2

Trim lin
16/1/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000219/Byd3e2

73 BRAS BASAH ROAD

Date: 03-02-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : JARED

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 4207E	Veh. Inspected	SLF 7157L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078094-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	03/01/2020

2. Vehicle Particulars & Condition

Make & Model	CITROEN C4 PICASSO 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF73DBHGTGJ668997	Colour	RED
Odometer	51481 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	MICHELIN	6 mm
L/H Front Tyre	205/60 R16	MICHELIN	6 mm
R/H Rear Tyre	205/60 R16	MICHELIN	6 mm
L/H Rear Tyre	205/60 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/12/2019	Inspect Date / Time	03/01/2020 (02:31 PM)
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7157L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	CUT	3,852.60	2,215.00
1	TAILGATE OUTER GARNISH	TO REPAIR SEE LABOUR	647.20	-
1	TAILGATE LOGO	NECESSARY	201.30	98.60
1	TAILGATE EMBLEM 'CITROEN'	NECESSARY	183.20	97.50
1	TAILGATE EMBLEM 'PICASSO'	NECESSARY	146.30	92.00
1	TAILGATE EMBLEM 'BLUEHDI'	NECESSARY	173.50	97.40
1	TAILGATE EMBLEM 'C&C'	NECESSARY	203.40	45.00
1	TAILGATE EMBLEM 'C4'	NECESSARY	184.60	92.00
1	TAILGATE WEATHER STRIP	NOT DAMAGED	437.20	-
1	TAILGATE INNER TRIM BOARD	TORN	493.20	493.20
1	TAILGATE INNER LOCK	NOT DAMAGED	438.60	-
1	TAILGATE LOCK SENSOR	NOT DAMAGED	354.80	-
1	TAILGATE ANTENNA	NOT DAMAGED	300.00	-
2	TAILGATE LAMP @\$1786.20	CUT	3,572.40	1,640.00
1	REAR WINDSCREEN MOULDING TOP	NO SUCH PARTS	186.30	-
1	REAR WINDSCREEN MOULDING BOTTOM	NO SUCH PARTS	175.10	-
1	REAR WINDSCREEN MOULDING SIDE	NO SUCH PARTS	116.20	-
1	REAR BUMPER	CUT	2,674.90	1,580.00
2	REAR BUMPER SIDE RETAINER @\$268.40	NECESSARY	536.80	320.00
2	REAR BUMPER BRACKET @\$186.70	BENT	373.40	370.00
2	REAR BUMPER REFLECTOR @\$482.60	BROKEN	965.20	553.00
1	REAR BUMPER LOWER LID	CUT	684.20	684.20
1	FRONT BUMPER REINFORCEMENT	BROKEN	658.30	611.00
1	REAR END PANEL	DENTED	1,058.40	1,039.00
1	REAR END PANEL TOP GARNISH	NOT DAMAGED	385.80	-
1	REAR BUMPER TOW CAP	NOT DAMAGED	204.60	-
	LESS 10% DISCOUNT		-1,920.75	-1,002.79
			17,286.75	9,025.11
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS/INC20000219/Byd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER LOWER LID CLIPS (SN)	NECESSARY	60.00	30.00
1	TAILGATE SEALANT (SN)	NOT NECESSARY	100.00	-
2	TAILGATE LAMP SEALANT @\$80.00 (SN)	NECESSARY	160.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR WINDSCREEN CLIPS (SN)	NECESSARY	60.00	30.00
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	50.00
1	REAR NUMBER PLATE W/CASING (SN)	NOT DAMAGED	80.00	-
1	REVERSE CAMERA (SN)	NOT DAMAGED	380.00	-
4	REVERSE SENSOR @\$250.00 (SN)	CUT	1,000.00	400.00
			2,280.00	680.00
	LABOUR			
	R&R TAILGATE COMPONENT.		100.00	50.00
	R&R REVERSE SENSOR.		100.00	60.00
	R&R REAR WINDSCREEN.		250.00	120.00
	DISCONNECT WIRE HARNESS TO FACILITATE REPAIR, RECONNECT AND TEST FUNCTION.		80.00	30.00
	R&R UPHOLSTERY.	NOT NECESSARY	200.00	-
	PANEL BEAT. INCLUSIVE OF THE REPAIR OF TAILGATE OUTER GARNISH.		1,200.00	800.00
	RESET FAULT CODE.	NOT NECESSARY	300.00	-
	RUST PROOFING.	NOT NECESSARY	150.00	-
	SPRAY PAINTING.		1,200.00	800.00
			3,580.00	1,860.00
GRAND TOTAL			23,146.75	11,565.11
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				9,200.00

Report Ref No. CS/INC20000219/Byd3e2

LIM TEOW GUAN

Automotive Assessor

K.K. LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.