

22/03/2002

ASS. REC. BY:

REF: CS 3/LPC 2000243/GY 13<sup>22</sup>

Special Instruction:

Surveyor: GQ

**ASSIGNMENT (Office)**

From (Person): Ong Li Li

of

LPC

Date/Time: 6 Jan. 2020 10.28A.m

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 507R

Insured:

Ym 7488R

at Workshop m/s

Pek Trong Auto

Tel:

6755 0688

of

B1K 1017 Yishun Industrial Park A 704258

Policy No:

Claim No:

191 20/20 / VC05 / 022860

Sum Insured:

Excess:

Make of Veh:

D.O.A 3-01-2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

11up1

H.O.D. Endorsement:

Date/Time:

6-1-2020 10.41A.m

Person Contacted:

Pek Trong

Vehicle IN/OUT

Date/Time

Action/Instruction ( X ) Estimate.

GBC 507R - CS3/MSG 1904796/3cd302 Port - 29/04/2019

Ym 7488R - X

ASS. REG. BY:

REF:

LP

## ASSIGNMENT

(2021)

From:

Date:

6 Jan 2020

Veh No:

GBC 507R

Yr Regn:

10 Mar 2011

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBC 507R

Make:

Fiat Fiorino 1.3 c.c 1248

at Workshop m/s Pek Tiong Muto

Colour:

Silver

A/C: Insured / Std / NI / NA

of Bkt 1017 Yishun Industrial Park A #01-250

Sp. Reading:

161479

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

2FA225 00000 160033

Policy No:

C/No: Gen. Cond: Good / Fair / Poor / Burnt

Claims No:

Steering: In order / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

Brake: In order / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / PS/Rim / STD A/Rim or

Make of Veh:

Tyre Size:

F:

175/70 R14

R:

11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Eigenlander

IDAC Accident Report:

Consistent? : Yes or No

Front

Rear

GIA / PR Seen:

Consistent? : Yes or No

R/Bal.

R/Bal.

Est. Repairs:

5

days

Res.: Yes or No

L/Bal.

L/Bal.

Lum Sum:

%

3 Val.: Yes or No

D.O.A.

D.O.I.

06-01-2020

Survey held at

W/S

4pm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

COC: 3408

RECEIVED 17 JAN 2020

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

5

1)



Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

17/1/20 Typist

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Wheel end (\$)

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Rep. Form:

Lump Sum / F.R. / C.

## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 6 January 2020 10:28 AM  
**To:** Florence KOH; assignments@lkkauto.com; Admin-D (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Your Ref: PT/GBC507R Our Ref: 19/20/20/VC05/022860 Accident involving YM7488R and GBC507R on 03/01/2020 [External General]

### Lonpac External - General

Without Prejudice  
Save as to Costs

Dear Florence

We note that you have breached the NIMA protocol by not providing a list of at least 10 surveyors. Therefore we urge you to agree to our appointed surveyor as a Single Joint Expert.


We are not agreeable with your list of 4 surveyors and we shall appoint LKK Auto Consultants Pte Ltd to conduct the survey.

Meanwhile, all our rights are expressly reserved.

Dear Nivitha

FYA

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse  
Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

---

**From:** Florence KOH [mailto:florencekohef@yahoo.com.sg]  
**Sent:** Monday, 6 January 2020 10:02 AM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG  
**Subject:** Your Ref: PT/GBC507R Our Ref: 19/20/20/VC05/022860 Accident involving YM7488R and GBC507R on 03/01/2020 [External General]

Dear Li Li

We refer to your email dated 6th January 2020.

**Firstly**, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 3rd January 2020.

**Secondly**, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 3rd January 2020.

**Thirdly**, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

**Fourthly**, *for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.*

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

**Finally**, the location and contact person of the workshop are as follows:

Name of Workshop	:	<b>Pek Tiong Auto Services</b>
Address	:	Block 1017 Yishun Industrial Park A #01-258 Singapore 768759
Contact person	:	Pek Tiong
Telephone No	:	6755-0688

Regards

Florence

K K CHENG & CO

Tel: 6227 1272

Fax: 6227 5563

On Monday, 6 January 2020, 09:43:14 am GMT+8, ONG LI LI <[llong@lonpac.com](mailto:llong@lonpac.com)> wrote:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/01/2020 14:08
Date Of Accident	03/01/2020 09:00
Exact Location Of Accident	SLE (BKE) NEAR TO WOODLANDS AVE 12 EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC507R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SOIL DYNAMICS (SINGAPORE) PTE LTD
Co Reg No	1XXXXX585Z
Email Address	VARAN@SOILDYNAMICS.SG
Mobile Phone No	(LOCAL) +65-82960260
Alternative Phone No	OFFICE-63625211

### Vehicle Particulars

Manufacturer	FIAT
Model	FIORINO
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28894417MKC (COMP)
Cover Note Number	

### Driver

Name of Driver	JEGASEELAN VARALAKSON
NRIC No	GXXXX322X
Date Of Birth	08/10/1990
Occupation	OUTDOOR
Date Of Driving Pass	29/10/2018
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82960260
Fax Number	
Contact Number	OTHERS-96883699
Email Address	VARAN@SOILDYNAMICS.SG

Address	BLK 332 #02-277 SERANGOON AVE 3
Postcode	550332
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT ATTACHED.

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM7488R
Vehicle Make/Model/Colour	ISUZU
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GURPREET SINGH
NRIC/Passport Number	GXXXX109R
Contact Number	98923531
Address	SAMLAIN EQUIPMENT SERVICES PTE LTD
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was drive on slow lane near to SLE(BKE) Woodlands Ave 12 Exit. Due to traffic (heavy) I slowdown the vehicle to exit woodlands Ave 12. But Back lorry couldn't ~~slow~~ slowdown. due to brake issues. so lorry hit me at the back. Driver ~~claim~~ his claim his ~~brake~~ brake is not good.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

03 JAN 2020

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

IC 70400 SketchPlan Form\_1/3



## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

03 JAN 2020

*Abdul Rahman*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	585Z
Vehicle No:	GBC507R
Vehicle In-Use Exempt:	No
Intended Registration Date:	06 Jan 2020
Vehicle Make:	FIAT
Vehicle Model:	FIORINO 1.3MJTD (225.2L20)
Primary Colour:	Silver
Model Year:	2010
Engine No:	199A20003604947
Chassis No:	ZFA22500000160033
Maximum Power Output:	-
Open Market Value:	\$16,614.00
Original Registration Date:	10 Mar 2011
First Registration Date:	10 Mar 2011
Transfer Count:	0
Across State PPA:	\$831.00
PARF Eligible:	No
PARF Eligibility Expiry Date:	-
PARF Rate Amount:	\$0.00
COE Expiry Date:	09 Mar 2021
COE Category:	C - Goods Vehicle & Bus
COE Period (Years):	10
QP Price:	\$29,011.00
COE Rebate Amount:	\$3,408.00
Total Rebate Amount:	\$3,408.00

The information contained herein is correct as at 06 Jan 2020

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

**PRE-REPAIR INSPECTION REPORT**

LONPAC INSURANCE BHD

Ref: CS3/LPC20000243/Gyf3s2

300 BEACH ROAD

Date: 17-01-2020

#17-04/07 THE CONCOURSESINGAPORE 199555



Code: LPC2

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

Insured Veh.	YM 7488R	Veh. Inspected	GBC 507R
Policy No.		Coverage (\$)	0.00
Claim No.	19/20/20/VC05/022860	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	06/01/2020

**2. Vehicle Particulars & Condition**

Make & Model	FIAT FIORINO 1.3	c.c	1248
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	ZFA22500000160033	Colour	SILVER
Odometer	161479 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	175/70 R14	GRENLANDER	6 mm
L/H Front Tyre	175/70 R14	GRENLANDER	6 mm
R/H Rear Tyre	175/70 R14	GRENLANDER	6 mm
L/H Rear Tyre	175/70 R14	GRENLANDER	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	--

**5. General Information**

Accident Date	03/01/2020	Inspect Date / Time	06/01/2020 ( 04:00 PM )
Survey held at	PEK TIONG AUTO SERVICES BLK 1017 YISHUN INDUSTRIAL PARK A #01-258 SINGAPORE 768759		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No: CS3/LPC20000243/Gyf3s2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.