

ASS. REC. BY:

REF: CS/INC20060303/6/d3<sup>3</sup>

Special Instruction:

Surveyor: S/VC

ASSIGNMENT (Office)

From (Person): Theresa Vimala of INC Date/Time: 10:04am @ 6/1/2020

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP  WS  TP RES  OD RES  EVA  INV  MV  CS

To Inspect Vehicle No: PC950E Insured: SFA 60A

at Workshop m/s Connect 3 Tel: 9850 9666

of No. 566 Woodlands Road

Policy No: \_\_\_\_\_ Claim No: MT/1078404-001

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 02/01/2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 10:33am @ 6/1/2020 Person Contacted: Winnie Vehicle IN  OUT

Date/Time	Action/Instruction	Initials	✓
	PC950E-X		
	SFA 60A-X		

Surveyor *Steve*

REF:


### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP.RES/OD.RES/EVA/INV/MY  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: *PC 950C* Yr Regn: *20/12/11*  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Traller or  
 Make: *Nissan URVAN* c.c. *2953*  
 Colour: *SILV* AC: Insured / Std / NI / NA  
 Sp. Reading: *38337.2* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: *JN1164E2S2 2791891*  
 Gen. Cond: Good / Fal / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD / R/Rim or  
 Tyre Size: F: \_\_\_\_\_ R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR. Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front Rear  
 R/Bal. *5* mm R/Bal. *5* mm  
 L/Bal. *5* mm L/Bal. *5* mm  
 D.O.A. *2/1/20* D.O.I. *6/1/20* U-102w

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Survey held at *Conrad 3*  
 Dos. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
*Frt LH*  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>13/1/20</i>	<i>Finalize \$2150, 4 days (Winnie)</i>
<i>13/1/20</i>	<i>Steve</i>
<i>13/1/20</i>	<i>pls check parts prices</i>
<i>13/1/20</i>	<i>cred: 5686-30% 72%</i>

RECEIVED 14 JAN 2020

*[Signature]*  
*9/11*

Date/Time, File Pass to?  : Proll. Report  
 : Final Report  
 1) *14/1 Typist*  
 Date/Time, File Return to?

Days Of Repair: *4*  
 Resurvey No. of Trip: *1*

Survey Fee:	
Transportation:	
Site Insp:	
Interview:	
Tech Inv:	
Weekend:	
Others:	
TOTAL	

Report Format: *TP*  
 Lump Sum / I.B.I: (\$) *2150/-*

Add Fee:  : Site Insp (\$)   
 : Interview (\$)   
 : Tech Inv (\$)   
 : Weekend (\$)

## **Nivitha (LKK Auto)**

**From:** Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>  
**Sent:** Tuesday, 7 January 2020 8:45 AM  
**To:** Nivitha (LKK Auto); 'assignments'  
**Cc:** sur@lkkauto.com; Theresa Vimala D/O Balagangadharan  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 6/1/2020

Details of the OIC . Thank you

**Theresa Vimala**  
Senior Administrator  
Operations, Motor & Personal Lines (PL)  
T +65 6430 7898  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [income.com.sg/careers](http://income.com.sg/careers)

**in** with you

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Monday, 6 January 2020 5:12 PM  
**To:** Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; 'assignments' <assignments@lkkauto.com>  
**Cc:** Thio Tse Kiat <tsekiat.thio@income.com.sg>; sur@lkkauto.com  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 6/1/2020

Dear Sir/Mdm,

Please be informed that the owner for SKN 7952C couldn't make it for the survey today therefore workshop will rearrange for the survey.

**“Wishing you a Happiness and Prosperity New Year”**

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Theresa Vimala D/O Balagangadharan [mailto:[thrsvim.bala@income.com.sg](mailto:thrsvim.bala@income.com.sg)]  
**Sent:** Monday, 6 January 2020 9:51 AM

**To:** 'assignments' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** Thio Tse Kiat <[tsekiat.thio@income.com.sg](mailto:tsekiat.thio@income.com.sg)>; Theresa Vimala D/O Balagangadharan <[thrsvim.bala@income.com.sg](mailto:thrsvim.bala@income.com.sg)>  
**Subject:** TP CASES FARMED OUT TO LKK ON 6/1/2020

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	JEFF	MT/1078653-001	6/1/2020	SLJ8914R	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		G8G772U	27/12/19	
2	DAVID	MT/1076716-002	6/1/2020	G8D6155C	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SJV2117A	20/12/19	
3	SERENE	MT/1077934-001	6/1/2020	SLW9889E	BORNEO MOTORS (S) PTE LTD	2 PANDAN CRESCENT SINGAPORE 128462	Carine Yeo / 9699 6192	10:00-12:00	SMG9970A	30/12	
4	HELENA	MT/1078404-001	6/1/2020	PC950C	CONNECT 3 CYCLE & CARRIAGE INDUSTRIES PTE LTD	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00-16:00	SFA60A.	2/1/2020	
5	FIONA	MT/1058395-001	6/1/2020	SKU7412H	CYCLE & CARRIAGE INDUSTRIES PTE LTD	188 PANDAN LOOP SINGAPORE 128378	Kerlyn Ong / 67714420 / 91865113	10:30-16:00	SL18542U	13/8/19	

6	CHRYLLIS 002	MT/1062729- 002	6/1/2020	SKN7952C	HUA HONG PTE LTD	250 SUNGAI KADUT STREET 1 SINGAPORE 729332	Jerleen/Mrs Tan / 6661 9688	14:00- 16:00	SKC6103B	14/9/19
---	-----------------	--------------------	----------	----------	---------------------	--	-----------------------------------	-----------------	----------	---------

**Theresa Vimala**  
Senior Administrator  
Operations, Motor & Personal Lines (PL)  
**T +65 6430 7898**  
[www.income.com.sg](http://www.income.com.sg)




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)



**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## Steve Chen (LKK Auto)

---

**From:** Winnie Chai <connect3winnie@gmail.com>  
**Sent:** Monday, January 13, 2020 11:57 AM  
**To:** Steve Chen (LKK Auto)  
**Cc:** Denise Tay (LKKAuto)  
**Subject:** Re: Finalization for PC950C

Yes, please proceed.

On Mon, Jan 13, 2020 at 9:10 AM Steve Chen (LKK Auto) <[SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com)> wrote:

Dear Winnie,

Kindly refer our finalize \$2150 (L/S, before GST). 4 repair days.

Kindly confirm.

Thanks

Best Regards,

**Steve Chen | Assistant Automotive Assessor**

**LKK Auto Consultants**

Phone: 6256 3561 | Email: [SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/01/2020 14:22
Date Of Accident	02/01/2020 11:20
Exact Location Of Accident	AT BLK 202 ANG MO KIO ST 22 CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC950C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	METRO COACH SERVICES PTE LTD
Co Reg No	2XXXXX324M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94550531

### Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN MICROBUS 3.0 4DR 5M/T ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI19V14078/VBS/R03
Cover Note Number	

### Driver

Name of Driver	DANIEL CHUA SENG CHOON
NRIC No	SXXXX732B
Date Of Birth	26/01/1951
Occupation	OUTDOOR
Date Of Driving Pass	06/10/1986
Driving Experience	33 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96208748
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address APT BLK 572A WOODLANDS AVE 1 #04-814  
 Postcode 731572  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - MAJOR/MINOR RD  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name KEBUN BARU NPP  
 Police Station Address ROAD: 111 ANG MO KIO AVE 4 , POSTCODE: 560111 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER POLICE REPORT

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SFA60A  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Signer.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be stored / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:



  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:


  
 Reporting Centre Personnel's Signature

Name:  
 SMC/VW No.:



Accident Sketch Plan

SKETCH PLAN



A = PC 950C  
B = SFA 60A.

coffee shop.


BIK 203  
open space  
carpark  
Arg mo Kio St 22

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


\* PIR OF TO POLICE REPORT \*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:  


  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NIC/PIN No.:

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20200102/2071

Police Station Of Origin:  
Kebun Baru NPP  
111 Ang Mo Kio Avenue 4 SINGAPORE  
560111  
Tel No: 1800-4589999

1 of 3  
Report No. T/20200102/2071

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 02/01/2020 13:47		Vide Report No.: F/20200102/0083		Station Diary No.: 10	
<b>Informant's Particulars</b>					
Name of Informant: DANIEL CHUA SENG CHOON			Address: APT BLK 572A WOODLANDS AVENUE 1 #04-814 SINGAPORE 731572		
ID Type / ID No.: NRIC NO / S0432732B			Contact No.: Home/Office: Mobile: 96208748		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 68	Date of Birth: 28/01/1951	Type of Informant: Driver		
Race: Chinese		Language: Chinese		Institution / School Name:	
Occupation: DELIVERY DRIVER			Driving Licence Information: Class: 2B,2A,2,3,4,5 Date of Expiry:		

<b>Details of the Accident</b>				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/01/2020 11:20	Type of Location: Car Park
Location: Along Road 1 ANG MO KIO STREET 22  BLK 202 ANG MO KIO OPEN SPACE CARPARK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

PC	Make	Model	Color	Damage	Count
PC950C	Van	NISSAN	Grey	Seriously Damaged	0
SFA60A	Car		Gold	Slightly Damaged	0

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Scanned with  
CamScanner

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20200102/2071

Police Station Of Origin:  
Kebun Baru NPP  
111 Ang Mo Kio Avenue 4 SINGAPORE  
560111  
Tel No: 1800-4589999

2 of 3  
Report No. T/20200102/2071

## CONTINUATION OF REPORT

Driver			
Name	DANIEL CHUA SENG CHOON		ID No. S0432732B
Related Vehicle	PC950C (Van)		Contact No. 96208748
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 02/01/2020 at about 1120hrs, I was driving my Nissan grey van reg: PC950C, at the open space carpark of Blk 202 Ang Mo Kio Street 22. At that time, I was going out of the said carpark gantry. The weather is clear and the road is dry.

When I was approaching the carpark gantry about one car length, suddenly there was one gold colour car reg: SFA80A, came from my left side and hit my front left door. The said car did not stop at the stop line and hit my car. After the accident, the female Chinese driver, aged about 60 plus years old, continued to stay in her car. My car front left tyre was punctured and I approached the said driver. I asked the said driver why she never brake. The said driver admitted that she was in the wrong.

After that, there was slight obstruction and I reversed my car a bit to give way to other vehicles. Subsequently, the said lady driver suddenly drove out of the carpark to the main road and drove off towards to Blk 226 direction. I was unable to give chase and I called for police ref: F/20200102/0083 (incharge TPIP Hiaoyu tel: 65476423). After the traffic police came and they advised me to lodge a accident report. I wish to inform that my van did not install any in-car camera. My car sustained was badly dented on my front left door and front left tyre was punctured. No one was injured during the



Scanned with  
CamScanner

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20200102/2071

Police Station Of Origin:  
Kebun Baru NPP  
111 Ang Mo Kio Avenue 4 SINGAPORE  
560111  
Tel No: 1800-4589999

3 of 3


Report No. T/20200102/2071

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sr Staff Sgt CHER KOK KENG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 02/01/2020 13:47
Officer In Charge Of Case: TP / GIT / SI VILTON HIA WEE SIANG Contact No.: 65476228	Classification Of Case:

Authentication Stamp  
NP168



Scanned with  
CamScanner

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	324M
Vehicle Details	
Vehicle No.:	PC950C
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	URVAN MICROBUS 3.0 4DR 5M/T ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	ZD30292427K
Chassis No.:	JN1TG4E25Z0791891
Maximum Power Output:	-
Open Market Value:	\$34,918.00
Original Registration Date:	20 Dec 2011
First Registration Date:	20 Dec 2011
Transfer Count:	0
Actual ARF Paid:	\$1,746.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Dec 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$37,011.00
COE Rebate Amount:	\$7,223.00
<b>Total Rebate Amount:</b>	<b>\$7,223.00</b>

The information contained herein is correct as at 06 Jan 2020

OK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

**CONNECT 3**

566 Woodlands Road ( Mandai Estate ) Singapore 728697

Tel: (65) 9850-9666 Email: [Connect3winnie@gmail.com](mailto:Connect3winnie@gmail.com)

ROC:53360061L

GST:53360061L

*Steve (LKK) wtl Nil*

QT19/PC950C/TPC

*6/1/20 11.15am*

NTUC Income Insurance Cooperative Ltd

*4 days*

1 Maritime Square

*L/S*

#10-01 Harbourfront Centre

*MJ AL SJ*

Singapore 099253

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC950C

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper X R	1	1,395.10	1,395.10
2.	Front bumper bracket LH X NA	1	105.00	105.00
3.	LH step panel garnish / cut	1	622.80	622.80
4.	LH sidelamp X NA	1	248.50	248.50
5.	Front LH door / DD	1	2,532.90	2,532.90
6.	Front LH door hinge X NA	2	348.50	697.00
7.	Front Lh rim cover / cut (Nptt)	1	155.00	155.00
8.	Transfer LH door fittings	1	300.00	300.00
9.	Labour charges	1	1,000.00	1,000.00
10.	Spray painting	1	500.00	500.00
<b>SUB-TOTAL</b>				<b>S\$7,556.30</b>

• Price before 7% gst

Thank you.

Yours faithfully,

*Winnie Chai*

Winnie Chai  
HP: 9850-9666



*1425  
-10%  
P-1282.50  
M-80  
L-1100  
Syd-196*

*2658.50  
L/S-2126.80  
= 2150*

*7336.30\**

**C O N N E C T 3**

566 Woodlands Road ( Mandai Estate ) Singapore 728697

Tel: (65) 9850-9666 Email: [Connect3winnie@gmail.com](mailto:Connect3winnie@gmail.com)

ROC:53360061L

GST:53360061L

QT19/PC950C/TPC

**NTUC Income Insurance Cooperative Ltd**

1 Maritime Square

#10-01 Harbourfront Centre

Singapore 099253

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC950C ( sup item )

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front LH tyre ✓ TN (Repaired) 7.0% (Nett)	1	280.00	280.00 196 ✓
			<b>SUB-TOTAL</b>	<b>S\$280.00</b>

- Price before 7% gst

Thank you.

Yours faithfully,



Winnie Chai

HP: 9850-9666





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000303/Etd3s2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 15-01-2020



ATTN: HELENA

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFA 60A	Veh. Inspected	PC 950E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078404-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	06/01/2020

#### 2. Vehicle Particulars & Condition

Make & Model	NISSAN URVAN	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JN1TG4E25Z0791891	Colour	SILVER
Odometer	383372 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	5 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	5 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	5 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	02/01/2020	Inspect Date / Time	06/01/2020 ( 11:10 AM )
Survey held at	NO.566 WOODLANDS ROAD		
Repairer	CONNECT3		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 950E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,395.10	-
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	105.00	-
1	LH STEP PANEL GARNISH	CUT	622.80	192.00
1	LH SIDELAMP	NOT NECESSARY	248.50	-
1	FRONT LH DOOR	DENTED	2,532.90	1,233.00
2	FRONT LH DOOR HINGE @ \$348.50 LESS 10% DISCOUNT	NOT NECESSARY	697.00 -	- -142.50
			5,601.30	1,282.50
<b>SPECIAL NETT ITEMS</b>				
1	FRONT LH RIM COVER (SN)	CUT	155.00	80.00
1	FRONT LH TYRE (@ \$280.00 DISC 70%) (SN) (ADDITIONAL)	TORN	280.00	196.00
			435.00	276.00
<b>LABOUR</b>				
TRANESFER LH DOOR FITTINGS.			300.00	50.00
LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.			1,000.00	600.00
SPRAY PAINTING.			500.00	450.00
			1,800.00	1,100.00
<b>GRAND TOTAL</b>			<b>7,836.30</b>	<b>2,658.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>2,150.00</b>

Report Ref No. CS/INC20000303/Etd3s2

CHEN TSUE YEE  
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.