

SK AUTOMOBILE PTE LTD

Roc.No. 201500047H

23 Kaki Bukit Ave 4 #03-01 Vicom Inspection Centre

(South Wing) Singapore 415933

Tel: 67895155 Fax : 67835155

Date: 03/01/20

To: AIG Asia Pacific Insurance Pte Ltd

By Fax & Email

Attn: Motor Claims Department.

Re: Accident involving motor vehicle nos. SGY 3982 G and GR 7327 J
Along Jln Eunos After Exit From PLE on 31/12/19

We refer to the above matter.

Under the new practice directions, we the repairers of motor vehicle no SGY 3982 G
Hereby give you the insurer of motor vehicle no GR 7327 J **2 working days.**
Whether you are appointing your own surveyors to conduct a pre-repair inspection on our customers vehicle.

If we do not hear from you after 2 working days, we shall carry out to appoint our own surveyors on behalf of our said customer to conduct the said pre-repair inspection and proceed to repair the said vehicle thereafter.

Thank You.

Regards


Huey Lee
E-mail: admin@skauto.com.sg

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed Surveyor: _____
(Name & Signature)

Date & Time of Inspection: _____

****8 Kaki Bukit Ave 4 #08-46**

Premier@Kaki Bukit

Singapore 415875

**** Pls contact: Xiong - 8121 0478**

Operations address: 23 Kaki Bukit Ave 4, #03-01 (South Wing) Singapore 415933

Tel: +65 6789-5155 Fax: +65 6783-5155