

22/03/2002

ASS. REC. BY:

REF: CS/U01 20000351 / kyf3 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Felix

of

U01Date/Time: 6.1.2020

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMN 6524M

Insured:

PA 8052Cat Workshop m/s Heng Yap Seng Auto

Tel:

919 33008of 160 Sn ring #08-13 Auto cityPolicy No: DHOM110152001602

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25. Dec. 2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 7.1.2020 9:44a.m

Person Contacted:

Mr chungVehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMN 6524M - X
	PA 8052C - CC6 / AXA 14019266 / mlue 392 DOA - 08/10/2014

ASS. REC. BY: Kenneth

REF: UOI

ASSIGNMENT

From:

Date:

7 Jan. 2020

Estimated Cost:

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMN 6524 M

at Workshop m/s

Hing YAP Seng Auto

of

160 on my #08-13 Highway.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMN 6524 M

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Opel

Astra

C.C

1598

Colour

n. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

33959

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W0VBD8EG4K8031215

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

25/12/19

D.O.I.

7/1/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Est not ready

1/4/20 call to ask for estimate (No Estimate)

4s \$3950/- (Red \$6992.00, 63%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

25/8/20 Typist

Report Form:

Imp Sum / B/L / C

\$3950/-

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL



MEMBER OF THE UOB GROUP

United Overseas Insurance Limited
3 Anson Road #28-01 Springleaf Tower
Singapore 079909
Tel (65) 6222 7733
Fax (65) 6327 3869 / 6327 3870
Email: ContactUs@uoi.com.sg
uoi.com.sg
Co. Reg. No. 197100152R

To :	Kurup & Boo	Fax : 62257248
From :	Josephine Wong	Fax : 63273869
Date :	6.1.2020	Our ref: PA8052C (DHOM110152001602) Yr ref : SMN6524M(BMC.3450.20.wh)

FACSIMILE MESSAGE

WITHOUT PREJUDICE

**REQUEST FOR PRE-REPAIR SURVEY – SMN6524M
ACCIDENT INVOLVING PA8052C AND SMN6524M ON 25.12.2019**

We refer to your email dated 6.1.2020.

In this case you have proposed to appoint M/s LKK Auto Consultants Pte Ltd from our list, to conduct the pre-repair survey on without prejudice basis.


Please forward us a copy of the estimated cost of repair for our reference.

Please seek your client's instruction for the repair after the inspection has been completed.

We reserve all our rights in this matter.

Thank you.

Regards


Josephine Wong
Claims Division

cc. LKK Auto Consultants Pte Ltd
Fax: 62564315
Attn : Summer

For your immediate attention.
fy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2019 17:25
Date Of Accident	25/12/2019 20:30
Exact Location Of Accident	JUNCTION OF GRANGE ROAD / TANGLIN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN6524M
Insured/Policyholder	
Name Of Registered Owner	COSMO AUTOMOBILES RENTAL PTE LTD
Co Reg No	2XXXXX129M
Email Address	ANDREW@COSMOAUTOMOBILES.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-90990920

Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA ST 1.6 TURBO DIESEL (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107813422
Cover Note Number	

Driver

Name of Driver	HANS ANDERSEN UNTONO @WEN WEI HAN
NRIC No	SXXXX477H
Date Of Birth	08/11/1971
Occupation	OUTDOOR
Date Of Driving Pass	04/07/1994
Driving Experience	25 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97583698
Fax Number	
Contact Number	OFFICE-97583698
Email Address	NOEMAIL

Address	APT BLK 757 WOODLANDS AVENUE 4 #10-267 SINGAPORE
Postcode	730757
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHEW AI HOON GENDER: : FEMALE
Passenger 2	NAME: : LAURENTIA NICOLE UNTONO GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA8052C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	WANG YUANQING

NRIC/Passport Number 0XXXX9850
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name HANS ANDERSEN UNTONO
Approximate Age 48
Injuries Sustain REFER POLICE REPORT
Injured person in which vehicle? SMN6524M
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address APT BLK 757 WOODLANDS AVENUE 4
#10-267 SINGAPORE
Postcode 730757

DETAILS OF INJURED PERSON 2

Name CHEW AI HOON
Approximate Age
Injuries Sustain REFER POLICE REPORT
Injured person in which vehicle? SMN6524M
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address NA
NA
Postcode NA

DETAILS OF INJURED PERSON 3

Name LAURENTIA NICOLE UNTONO
Approximate Age
Injuries Sustain REFER POLICE REPORT
Injured person in which vehicle? SMN6524M
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address NA
NA
Postcode NA


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop, and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A... 3MN5524M
E PF 8052-C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MS PER POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Not Authorized
11 Pmp @ 3950/hr
Resurvey After Paint

4 days

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722
Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SMN6524M
Vehicle Model : Opel Astra

Estimate Repair Cost

No.	Qty	Parts List Items
1	1	Front bumper 1840
2	2	Front bumper retainers
3	2	Front bumper brackets
4	1	Front bumper fog lamp assy LH
5	1	Front bumper lower grille
6	1	Front bumper sensor
7	1 set	Front bumper clips
8	1	Head lamp LH
9	1	Front support panel
10	1	Front fender LH
11	1	Front fender inner shield LH
12	1	Front fender reflector LH
13	1	Front wheel rim LH

CM	\$	1,980.00	✓
MSD	\$	110.00	✓
	\$	140.00	X
Sm	\$	480.00	X
	\$	690.00	X
	\$	420.00	X
nn	\$	760.00	50 SM
CM	\$	1,290.00	✓
	\$	920.00	X
nn	\$	760.00	✓
	\$	230.00	X
	\$	92.00	X
CM	\$	590.00	✓
Total		\$ 8,462.00	

107

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,200.00	400
2	To putty and respray painting on affected areas.	\$ 800.00	400
3	To remove, replace front fender fittings to facilitate repair.	nn \$ 300.00	X
4	To remove, replace front tyre and wheel rim.	\$ 100.00	20
5	To check wiring and lightings.	\$ 80.00	20

Total Labour \$ 2,480.00

Total Parts and Labour \$ 10,942.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: