

ASS. REC. BY:

REF: CS/MSG 20000352/Uqf3

Special Instruction:

Surveyor:

MARCUS

ASSIGNMENT (Office)

From (Person):

ONG Zi Hui

of

MSG

Date/Time:

6. Jan. 2020 4.09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 61224

Insured:

SJH 3128K

at Workshop m/s:

Zoom AUTOWARE

Tel:

94507920

of

130 Bedok Reservoir Road #08-1339

Policy No:

A804682072MY

Claim No:

617079

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time:

7.1.2020 9.30am

Person Contacted:

Elin

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate Inspec: BLK 15 Kallie Bukit Road 4, Banyu Biz #01-53

SMC 61224 - NA

MSG 20000352/24

DCA - 04/01/2020

SJH 3128K - NA

MSG 20000352/24

RON - 04/01/2020


08/01/20 @ 4.09pm Informed Zi Hui, we are pending estimate from repairer.
 14/01/20 @ 11.58a revised to Monica Chung via text mes.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: *SMC 61224*
 at Workshop m/s: *2000*
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: *3k.*
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est Repairs: *4* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction *L7A966*
asking 2k. car 30-4-2020 4wks.

14/1/20 2/5 2000 confirmed with Elin (had 7503.12, 79%)

RECEIVED 14 JAN 2020

Date/Time, File Pass to? ☐ : Prell. ReportDate/Time, File Return to? ☐ : Final Report

2)

Report Format: *MEP-TP*Lump Sum / I.B.I. (\$) *2000*Veh No: *SMC 61224* Yr Regn: *2 / 92*Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or *CA /*Make: *Honda civic* *44 1590*Colour: *Black* A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: *44286* T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: *JHMEH968005001427*Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: *195/50 R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: *6* mm R/Bal: *6* mmL/Bal: *6* mm L/Bal: *6* mmD.O.A. *4/1/20* D.O.I. *7/1/20*

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

LP NIS.

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) *2000*Days Of Repair: *4*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) \$ + RS. \$

) Photos

) Others

TOTAL

150

11

161

14/1/20

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 14 Jan 2020

Preliminary Advice

Insured Vehicle No	: SJH3128K	Accident Date	: 04/01/2020
TP Vehicle No	: SMC6122Y	Assignment Date	: 10/01/2020
Make	: HONDA CIVIC	Est. Duration of Repair	: 4.00
Date of Inspection	: 07/01/2020		
Inspection At	: ZOOM AUTOWERKS PTE LTD (BEDOK) 130 BEDOK RESERVOIR ROAD, #08-1339 SINGAPORE 470130		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,503.12
Revised Amount	:S\$	2,655.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,655.20
Lump Sum Repair	:S\$	2,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Monday, 6 January 2020 4:02 PM
To: assignments; Admin-D (LKKAuto)
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned
Attachments: T_20200104_7025_.pdf; SMC 6122 Y.pdf

Pre-Repair Inspection for SMC6122Y against SJH3128K (MSIG) // Accident on 04/01/2020 @ 16:45HR at along Blk 512 Mapletree Industrial (Chai Chee Lane) involving Vehicle Number SMC 6122 Y & SJH 3128 K

Manual Assigned

Dear LKK,

Refer to the email below, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Monday, 6 January 2020 3:18 PM
To: Zoom Autowerks <zoomautowerks@gmail.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: Pre-Repair Inspection for SMC6122Y against SJH3128K (MSIG) // Accident on 04/01/2020 @ 16:45HR at along Blk 512 Mapletree Industrial (Chai Chee Lane) involving Vehicle Number SMC 6122 Y & SJH 3128 K

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Zoom Autowerks <zoomautowerks@gmail.com>

Sent: Monday, 6 January 2020 11:38 AM

To: Helene Phua <helene_phua@sg.msig-asia.com>

Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>

Subject: Re: Pre-Repair Inspection for SMC6122Y against SJH3128K (MSIG) // Accident on 04/01/2020 @ 16:45HR at along Blk 512 Mapletree Industrial (Chai Chee Lane) involving Vehicle Number SMC 6122 Y & SJH 3128 K

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

Kindly arrange LkK

On Mon, Jan 6, 2020, 11:32 Helene Phua <helene_phua@sg.msig-asia.com> wrote:

Hi,

We refer to your email dated 06/01/2020.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd

- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1. Xing Guo Qiang	6) Chow Bo Xiong
2. Kenneth Kong	7) Siew Meng Hui
3. Marcus Chua	8) Daniel Chan
4. Ng You Han	9) Victor Png
5. Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- a. ***Fast lane settlement is not applicable for cases that liability is in dispute***
- b. If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com





Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg    



From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: Monday, January 06, 2020 12:13 AM

To: Claims <claims@sg.msig-asia.com>

Subject: Pre-Repair Inspection for SMC 6122 Y // Accident on 04/01/2020 @ 16:45HR at along Blk 512 Mapletree Industrial (Chai Chee Lane) involving Vehicle Number SMC 6122 Y & SJH 3128 K

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir/Madam,

We are instructed by Cheok Wei Sheng, Gabriel to notify you of a road traffic accident on 04/01/2020

at about 16:45HR at along Blk 512 Mapletree Industrial (Chai Chee Lane) involving our client's vehicle registration number SMC 6122 Y and vehicle registration number SJH 3128 K driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178 08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 8 January 2020 4:09 PM
To: 'Ong Zi Hui'; assignments; SUR
Cc: 'Crystal Lee'
Subject: RE: Survey Request - Manual Assigned

Dear Zi Hui,

Please be informed that we have inspected the vehicle SMC 6122Y on 07/01/2020.

We are pending for estimate from repairer.

Wishing you a Happiness and Prosperity New Year

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 7 January 2020 9:42 AM
To: 'Ong Zi Hui' <zihui_ong@sg.msig-asia.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Crystal Lee' <crystal_lee@sg.msig-asia.com>
Subject: RE: Survey Request - Manual Assigned

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Monday, 6 January, 2020 4:02 PM
To: assignments <assignments@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>
Subject: Survey Request - Manual Assigned

Pre-Repair Inspection for SMC6122Y against SJH3128K (MSIG) // Accident on 04/01/2020 @ 16:45HR at along Blk 512 Mapletree Industrial (Chai Chee Lane) involving Vehicle Number SMC 6122 Y & SJH 3128 K

SGC8888M

BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Audi A3 Sedan 1.0A TFSI S-Tronic Virtual Cockpit.



5 Year Service, 7 Years
Warranty, Road Tax 2020
Include Low Mileage
Immaculate
Direct Owner

ABWIN

ONE-STOP



Browse by Category

Sort by Date Posted

5 vehicles

civic esi

Advanced Search

	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	civic esi	Any	Any	Any	Any	Any	Any
	Honda Civic ESI EH9 (New 5-yr COE)	\$22,800	\$4,560 /yr	04-May-1992	1,590 cc	180,000 km	Sedan
Posted: 30-Dec-2019 Tags: 1992 Honda Civic, 1992 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							
	Honda Civic ESI 3M (COE till 04/2029)	\$42,800	\$4,600 /yr	04-Sep-1992	1,590 cc	-	Hatchback
Head Turner Classic Jdm Sports Car. Well Taken Care By Owner, Accident Free. Low Depreciation In Mint Condition. Loan Available. No Low Baller And Dealer, Only For Sincere Buyer Please. Whatsapp Or Call To View This Beauty. Posted: 28-Dec-2019 Tags: 1992 Honda Civic, 1992 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							
	Honda Civic ESI EH9 (COE till 03/2029)	\$44,444	\$4,820 /yr	10-May-1993	1,590 cc	-	Sedan
The Best 1993 Civic In Town.Value For Money With Full Modification. Drive Every Bit Like A Race Car.New IU Unit & Brake Pump,Aircon Just Serviced,Very Cold,New Meter,Low Fuel Consumption 13-14km/litre.Will Be Changing New ECU For The Next Buyer.Probably The B... Posted: 10-Dec-2019 Tags: 1993 Honda Civic, 1993 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							
	Honda Civic ESI EH9 (COE till 04/2029)	\$43,888	\$4,710 /yr	02-Oct-1992	1,590 cc	-	Sedan
Powerful VTEC Engine.No Repairs Needed.High Paper Value. Only Owners So Far!Supersprint Exhaust With Cert.SSCUS Reclinable Pair Seats.Suspension Tomei Gold.New Battery,Camber Kit,Pump & Fan!The One & Only ESI In The Market!This Is Your Last Chance To Own... Posted: 09-Dec-2019 Tags: 1992 Honda Civic, 1992 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda							

Brembo GT6 Front GT4 Rear Big 6 POT Brake Kit

GT6 Big 6 POT for Toyota Alphard, Vellfire, Harrier / BMW F10 (5 Series Sedan), F30 (3 Series Sedan) / Honda Civic.

More info about this product

Honda Civic ESI EH9 (COE till 04/2029) **\$42,000** **\$4,590 /yr** **14-May-1992** **1,590 cc** **360,000 km** **Sedan**

ent Code: A325. Flexible And Attractive Loan Available. Trade-In Available For Your Car! No Hidden Costs. For Further In Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 009C

Vehicle Details

Vehicle No.: SMC6122Y

Vehicle to be Exported: No

Intended Deregistration Date: 09 Jan 2020

Vehicle Make: HONDA

Vehicle Model: CIVIC ESI 4A

Primary Colour: Grey

Manufacturing Year: 1991

Engine No.: D16Z61704282

Chassis No.: JHMEH96800S001427

Maximum Power Output: -

Open Market Value: \$18,252.00

Original Registration Date: 17 Feb 1992

First Registration Date: 17 Feb 1992

Transfer Count: 8

Actual ARF Paid: \$27,378.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Apr 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

PQP Paid: \$21,421.00

COE Rebate Amount: \$966.00

Total Rebate Amount: \$966.00

The information contained herein is correct as at 09 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/01/2020 11:37
Date Of Accident	04/01/2020 16:45
Exact Location Of Accident	BLK 512 MAPLETREE INDUSTRIAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC6122Y
Insured/Policyholder	
Name Of Registered Owner	CHEOK WEI SHENG
NRIC No	SXXXX009C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97872037
Alternative Phone No	OFFICE-97872037

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC ESI 4A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5111191939
Cover Note Number	

Driver

Name of Driver	CHEOK WEI SHENG, GABRIEL
NRIC No	SXXXX009C
Date Of Birth	16/04/1990
Occupation	INDOOR
Date Of Driving Pass	16/04/2009
Driving Experience	10 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97872037
Fax Number	
Contact Number	OFFICE-97872037
Email Address	NOEMAIL

Address	BLK 686A JURONG WEST CENTRAL 1 #16-124
Postcode	641686
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CYNTHIA KONG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20200104/7025.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH3128K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3

DETAILS OF INJURED PERSON 1

Name CHEOK WEI SHENG, GABRIEL

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SMC6122Y

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name CYNTHIA KONG

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SMC6122Y

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please fill in correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may render your claim inoperative to repudiate policy liability.
4. Completion or acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurer(s).
5. Any case reporting may be referred to the Police for investigation.
6. This form is issued by the insurers of the GIA Records Management Centre established by The General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon request to the insurers.
7. The completion of this report by the insured, you hereby consent to the archiving of this report at the insurer's and to comply with the provisions of the Insurance Act.
8. I warrant under the Personal Data Protection Act (PDPA)
 - (a) I am/are the insured, agree and consent that:
 - (i) the insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (forms) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the G.I. Industry Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (a) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (b) investigating the accident and/or my claims;
 - (c) ensuring compliance with my insurance policy or responding to any enquiries by me;
 - (d) proper management (including the mailing of correspondence, statements, reports, reports or notices to me) and/or delivery of certain personal data stand-ins to bring about delivery of the goods to such claims and/or delivery of insurance claim packages; and/or
 - (e) complying with applicable law in administering, processing, handling and/or dealing with my claims (including the "Purpose(s)").
 - (ii) all parties who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s); and
 - (iii) Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or representatives (their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purpose(s);
 - (iv) Personal Information will also be collected and used to compile claims history for the purpose of fraud detection and insurer and management in present and all future claims;
 - (v) Personal Information collected under (d) above may be shared / disclosed
 - (vi) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing motor accidents, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (vii) for complying with requirements under any regulations, laws or court orders.


 Insured's Signature
 (If driver, sign for policyholder)


 Insured's Signature
 (If driver, sign for policyholder)
 Date & Time:



 Reporting Centre's Signature
 Name
 (Print in full)

Accident Sketch Plan

SKETCH PLAN

Vehicle A: SNL6122Y

Vehicle B: JCH312BK



DETAILED CIRCUMSTANCES OF THE ACCIDENT

- Refer to police report -

DECLARATION

[Signature]
 I declare that the foregoing particulars are true and correct.
 Date & Time:

[Signature]
 I declare that the particulars are true and correct.
 Date & Time:

[Signature]
 Reporting Centre Personnel
 Name:
 NRIC ID No:

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20200104/7025

1 of 3

Report No. T/20200104/7025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/01/2020 23:26		Vide Report No.: G/20200104/0222		Station Diary No.:	
Informant's Particulars					
Name of Informant: CHEOK WEI SHENG, GABRIEL			Address: APT BLK 686A JURONG WEST CENTRAL 1 #16-124 SINGAPORE 641686		
ID Type / ID No.: NRIC NO / S9012009C			Contact No.: Home/Office: Mobile: 97872037		
Nationality: SINGAPORE CITIZEN			Email: gabrielcheok2010@gmail.com		
Sex: Male	Age: 29	Date of Birth: 16/04/1990	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/01/2020 16:45	Type of Location: Car Park
Location: CHAI CHEE LANE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJH3128K	Car	TOYOTA			Slightly Damaged	2
SMC6122Y	Car	HONDA	CIVIC ESI 4A	Silver	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMC6122Y	NTUC Income Insurance Co-Operative Limited	5111191939	17/07/2019	16/07/2020

Police Report



**SINGAPORE
POLICE FORCE**



T/20200104/7025

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No: T/20200104/7025

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	CYNTHIA KONG	ID No.	S9429249B
Related Vehicle	SMC6122Y (Car)	Contact No.	97111673
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	04/01/2020	Date Discharge	04/01/2020
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	CHEOK WEI SHENG, GABRIEL	ID No.	S9012009C
Related Vehicle	SMC6122Y (Car)	Contact No.	97872037
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	04/01/2020	Date Discharge	04/01/2020
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details:

ON 04/01/2020 AT ABOUT 16.45HR, I WAS DRIVING MY VEHICLE - SMC6122Y, ALONG MAPLETREE INDUSTRIAL. I WAS STATIONARY WHEN VEHICLE NUMBER - SJH3128K, REVERSED ONTO MY VEHICLE'S FRONT LEFT PORTION. I WISH TO STATE THAT THE VEHICLE WAS EXITING FROM THE CAR PARK LOT.

SUBSEQUENTLY, I WAS CONVEYED TO CHANGI GENERAL HOSPITAL & WAS GIVEN 3 DAYS MC, AND MY GIRLFRIEND SEEK MEDICAL ATTENTION AT UNIHEALTH CLINIC @ BEDOK AND WAS GIVEN 3DAYS MC.

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20200104/7025

3 of 3

Report No. T/20200104/7025

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP1B /
THABAGESH JEYATHESH
Contact No.: 65476232

Authentication Stamp

SP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
04/01/2020 23:26

Classification Of Case:



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

8 January 2020

not Authorized
date
7/1/20
The photo of the car
1/5 ~~2000~~ 2000/2
4 day.

REG NO.: SMC 6122 Y
MAKE/MODEL: HONDA CIVIC

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Front bonnet	\$ 12 510.90 X
2	Front bonnet hinges	\$ 17 70.60 X
1	Front bonnet lock	\$ 17 139.80 X
1	Front bonnet rubber	\$ 17 47.80 X
1	Front bonnet logo	\$ 22 48.00 ✓
1	Front headlamp AL5 38.00	\$ 520 748.80 ✓
1	Front headlamp lower brackets AL5 485.30	\$ 17 225.00 X
1	Front sidelamp AL5 145.20	\$ 110 227.80 ✓
1	Front bumper 466.20	\$ 703 538.20 ✓
1	Front bumper clip (1 set) 30.00	\$ 22 45.00 ✓
1	Front bumper reinforcement	\$ 12 318.00 X
2	Front bumper side retainers 20.50	\$ 150 45.00 1PC
2	Front fenders 407.40	\$ 340 814.80 1PC
2	Front fender inner shields 63.90	\$ 70 127.80 1PC
1	Front support panel	\$ 12 374.40 X
1	Air con condenser	\$ 17 539.50 X
1	Air con condenser electric fan	\$ 17 277.50 X
1	Radiator	\$ 17 1,109.90 X
1	Radiator fan blade	\$ 17 50.60 X
1	Radiator fan cowl	\$ 17 93.20 X
1	Radiator fan motor	\$ 17 276.30 X
2	Radiator top mountings	\$ 17 50.00 X
		\$ 6,678.90
Less 20%		\$ 1,335.78
		\$ 5,343.12

1657.50
202
1325.20

SPECIAL NETT ITEMS

1	Front bumper lower spoiler	\$	12	550.00	X
1	Front number plate with holder	\$	11	50.00	X
		\$		600.00	

<u>S/N</u>	<u>LABOUR CHARGES</u>
------------	-----------------------

1	To check wiring and reset headlamps focusing.	\$	80.00	20
2	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00	X
3	To apply undercoating.	\$	200.00	30
4	Panel beating.	\$	1,600.00	600
5	To re-spray painting on the affected areas.	\$	1,500.00	680
		\$	3,560.00	

GRAND TOTAL :

\$ 9,503.12

P-1325-20

L-1330.00

2653.20

254

2124.16.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20000352/UQF3N2

Date: 17/01/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80468207QMY
Claimant Vehicle No :	SMC6122Y	Insured Vehicle No :	SJH3128K
Date of Loss:	04/01/2020	Nature of Claim:	TP
		Claim No:	617079

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC6122Y	Engine No:	D16Z61704282
Make & Model:	HONDA CIVIC, 1.6 ESI (3A) (A)	Chassis No:	JHMEH96800S001427
Reg. Date:	17/02/1992 (Man. Year: 1991)	Odometer:	44286 km
Colour:	Black		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,943.12	1,325.20	4,617.92	77.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,330.00	2,230.00	62.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,503.12	2,655.20	6,847.92	72.06
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	9,503.12	2,000.00	7,503.12	78.95

INSPECTION

Date of Assignment:	10/01/2020		
Date Inspected:	07/01/2020	Inspected At:	Blk 15 Kaki Bukit Road 4 , Bartley Biz #01-53 Repairer: Zoom Autowerks Pte Ltd
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2020)
Parts:	144	HONDA CIVIC 1.6 ESI (3A) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC6122Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	510.90 FL	*- FL
2	2		*FRONT BONNET HINGES	Not Necessary	70.60 FL	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	139.80 FL	*- FL
4	1		*FRONT BONNET RUBBER	Not Necessary	47.80 FL	*- FL
5	1		*FRONT BONNET LOGO	Necessary	48.00 FL	*38.00 FL
6	1		*FRONT HEADLAMP N/S	Broken	748.80 FL	*485.30 FL
7	1		*FRONT HEADLAMP LOWER BRACKETS N/S	Not Necessary	225.00 FL	*- FL
8	1		*FRONT SIDELAMP N/S	Cracked	227.80 FL	*145.20 FL
9	1		*FRONT BUMPER	Distorted	538.20 FL	*466.20 FL
10	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FL	*30.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	318.00 FL	*- FL
12	1		*FRONT BUMPER SIDE RETAINERS	N/s Cracked	45.00 FL	*20.50 FL
13	1		*FRONT FENDERS	N/s Buckled	814.80 FL	*407.40 FL
14	1		*FRONT FENDER INNER SHIELDS	N/s Torn	127.80 FL	*63.90 FL
15	1		*FRONT SUPPORT PANEL	Repair	374.40 FL	*- FL
16	1		*AIR CON CONDENSER	Not Necessary	539.50 FL	*- FL
17	1		*AIR CON CONDENSER ELECTRIC FAN	Not Necessary	277.50 FL	*- FL
18	1		*RADIATOR	Not Necessary	1,109.90 FL	*- FL
19	1		*RADIATOR FAN BLADE	Not Necessary	50.60 FL	*- FL
20	1		*RADIATOR FAN COWLING	Not Necessary	93.20 FL	*- FL
21	1		*RADIATOR FAN MOTOR	Not Necessary	276.30 FL	*- FL
22	2		*RADIATOR TOP MOUNTINGS	Not Necessary	50.00 FL	*- FL
23	1		*FRONT BUMPER LOWER SPOILER	Repair	550.00 FS	*- FS
24	1		*FRONT NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	7,278.90	1,656.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,335.78	331.30
Total Parts (\$\$)	5,943.12	1,325.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE,REPLACE AIR-CON CONDENSER,REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	0.00
3	TO APPLY UNDERCOATING	New	200.00	30.00
4	PANEL BEATING	New	1,600.00	600.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	680.00
Gross Labour Cost (S\$)			3,560.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >