

Form 100

ASS REC BY:

REP CS/CTI 2000364/USF312

Special Instruction:

Surveyor: NARCUS

ASSIGNMENT (Office)

From (Person): Adeline chng

of CTI

Date/Time: 7 Jan 2020 11:49 am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SGY 2203D

Insured: GBJ 6445J

at Workshop n/s: Kaizen Motors

Tel: 9150 0670

of 68 Kati Bukit Ara 6 #02-12

Policy No:

Claim No: SNM20 670005 2 / GBJ6445J / 12KRL

Sum Insured:

Excess:

Make of Vch:

D.O.A 23.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 7 Jan 2020 11:30 am

Person Contacted: Shawn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGY 2203D - NA / (17 Nov 2019) / R3 Non - 23/12/2019
	GBJ 6445J - NA / CTI 190 2026 / R3 Non - 23/12/2019

DMV 1/13 wel
ASS. REC. BY: Marcus

REF:

CT. /

ASSIGNMENT

From: Date: Vch No: 564 2203D Yr Regn: 9 / 07
Estimated Cost: Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MY Truck / Trailer or CA /
To inspect Vehicle No: 564 / 2203D Make: Honda civic CC: 1799
at Workshop m/s: 1001 Zen Colour: silver A/C: Insured / Std / NI / NA
of Sp. Reading: 20 / 096 T/Radio: Insured / Std / NI / NA
insured: Eng/No:
Policy No: C/No: FDI 11 03396
Claims No: Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: Steering: In order / Jammed / Leaked / Burnt or
(Client's Record) Brake: In order / Jammed / Leaked / Burnt or
Make of Veh: Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205 / 55 R16
R:

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 19
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

17A1356f

Vehicle: IN / OUT

Date: Person Contacted:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: 6 Rear: 6
R/Bal: mm R/Bal: mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: 23/12/19 D.O.I: 7/1/20
Survey held at

Des. of Damage: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R/L
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18-9-2022 2yrs. 9m.

15/1/20 1/5 & 2350 Conf. with shown.
(\$ 8,225.90 Red 78%)

RECEIVED 16 JAN 2020

Date/Time: File Pass to?

16/01/20
Typ. 4

Date/Time: File Return to?

2)

☐ : Prell. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

5 + RS (\$)

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ 2,350/- 45)

TOTAL

220

Nivitha (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Tuesday, 7 January 2020 11:08 AM
To: assignments@lkkauto.com
Cc: ct-admin@visionlawllc.com; Claims Dept of CTI; claims@kaizenmotors.com.sg; Irene Tay
Subject: OUR REF: SNM20D200052/GBJ6445J/IRENE & YOUR REF: AM.JT.INS.K88.SGY2203D.20(SJ) -TO CONDUCT PRS -SGY2203D
Attachments: 1848_001.pdf; RE: OUR REF: SNM20D200052/GBJ6445J/IRENE & YOUR REF: AM.JT.INS.K88.SGY22... (95.3 KB)

Without Prejudice

Dear LKK

Please refer to the attached letter and liaise with third party workshop accordingly.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]
Sent: Tuesday, 7 January 2020 10:26 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>; claims@kaizenmotors.com.sg
Subject: Scan Image

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
ANG KIM NOI DIANE
RAVENORA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
SONIA LIM WEI LEI

Unique Entity Number :200721148H

✓ **HEAD OFFICE:** 133 New Bridge Road

#18-01/02 Chinatown Point

Singapore 059413

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)

FAX ✓ : (65) 65356802 (General)

: (65) 65355905 (Litigation)

E-mail : jactan@visionlawllc.com

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM,jt.Ins.K88.112588.20 (sj)

Your Ref: SNM20D200052/GBJ6445J/IRENE

07 January 2020

CHINA TAIPING INSURANCE (S'PORE) PTE LTD

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attention: Motor Claims Department

BY FAX: 6224 7175

email: claimsdept@sg.cntaiping.com

email: adeline.chng@sg.cntaiping.com

Dear Sirs,

ACCIDENT INVOLVING SGY 2203 D & GBJ 6445 J ON 23 DECEMBER 2019 ALONG KAKI BUKIT AVENUE AT ABOUT 1405 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 06 January 2020 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus Chua as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Kaizen Motors Pte Ltd
68 Kaki Bukit Avenue 6
#02-12 ARK@KB
Singapore 417896
Contact Person: Shawn Yap 9150-0670

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor
(Name & Signature)

2nd Survey on _____
Appointed surveyor
(Name & Signature)

3rd Survey on _____
Appointed Surveyor
(Name & signature)

cc: **SGY 2203 D** – by Email claims@kaizenmotors.com.sg only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

ANNOUNCING Creative Auto

as sgCarMart Premium Dealer for the 8th Consecutive Year

CREATIVE

Civic

Price Range

Depreciation

> 10 years

Vehicle Type



Home » Used Cars » Hua Hong Motoring » Honda Civic 1.6A VTi (COE till 11/2022)

Honda Civic 1.6A VTi (COE till 11/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$20,700		
Depreciation	\$7,210 /yr	Reg Date	22-Nov-2007 (2yrs 10mths 13days COE left)
Mileage	178,000 km (14.7k /yr)	Manufactured	2007
Road Tax	\$962 /yr	Transmission	Auto
Dereg Value	\$12,057 as of today (change)	OMV	\$18,405
COE	\$20,997	ARF	\$20,246
Engine Cap	1,595 cc	Power	92.0 kW (123 bhp)
Curb Weight	1,220 kg	No. of Owners	5
Type of Vehicle	Mid-Sized Sedan		

Features

1.6L I-VTEC Engine, SRS Airbags, Reverse Sensors, Auto Climatic Aircon Control, Knockdown Rear Seats. View specs of the Honda Civic (2006-2012)

Accessories

Sports Rims, DVD Car Stereo System, Electrical Retractable Side Mirrors, Leather Seats.

Description

Cheapest Unit Avail In Market. Easy Maintain Popular Honda Civic, Powerful And Spacious. Perfectly Maintain By Previous Owner. Extended Warranty On Gear Box And Engine. Easy In House Loan Available, 100% Approval Rate, Call Us To Discuss.

Category

COE Car

Status

Available

Related

Compare



Location Map

Shortlist

Compare

Report Error

More Action

Seller Information

Hua Hong Motoring

16 vehicles for sale. 16 sold in past 3

210 Turf Club Road Lot C20
Car Mall @ The Grandstand
Search cars nearby

Randy Chan
Terence

96

81

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	139A
Vehicle Details	
Vehicle No.:	SGY2203D
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8B A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	R18A1033541
Chassis No.:	FD11103396
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,980.00
Original Registration Date:	19 Sep 2007
First Registration Date:	19 Sep 2007
Transfer Count:	1
Actual ARF Paid:	\$20,878.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,178.00
COE Rebate Amount:	\$13,568.00
Total Rebate Amount:	\$13,568.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2019 11:54
Date Of Accident	23/12/2019 14:05
Exact Location Of Accident	KAKI BUKIT AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY2203D
Insured/Policyholder	
Name Of Registered Owner	CHUA YEW TECK
NRIC No	SXXXX139A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88233366
Alternative Phone No	OFFICE-88233366

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	19-MU003380-R02
Cover Note Number	

Driver

Name of Driver	CHUA YEW TECK
NRIC No	SXXXX139A
Date Of Birth	21/11/1956
Occupation	OUTDOOR
Date Of Driving Pass	20/10/1976
Driving Experience	43 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88233366
Fax Number	
Contact Number	OFFICE-88233366
EMail Address	NOEMAIL

Address	BLK 652 HOUGANG AVE 8 #08-363
Postcode	1953
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ON KAKI BUKIT AVE 4. SUDDENLY, A VEHICLE SWERVE IN AND HIT ME ON MY LEFT SIDE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ6445J
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAY SENG HUAT
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) All insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mali packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement, and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NIC/FIN No:

PAREAS MOTOR

SKETCH PLAN

A - SGY2203D

B - GBJ6445J



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ON KAKI BUKIT AVE 4.
SUDDENLY A VAN SWERVE IN & HIT ME ON
MY ~~RIGHT~~ ^{LEFT} SIDE.
Law

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Law
Policyholder's Signature
Date & Time:

Law
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
Unit/Line No.:

KAIZEN MOTORS

KAIZEN MOTORS PTE. LTD.

68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896

UEN: 201502816H GST Reg No. 201502816H

Tel: (+65) 6384 1956 Fax: (+65) 6384 1957

Webpage: <https://www.kaizenmotors.com.sg>

 kaizenmotorsingapore

 kaizen_motors

 kaizenmotors

Date : 26/12/2019

Vehicle No : SGY2203D

Model : Honda Civic

Mileage :

Accident Damaged Parts

No	Job Description	Qty	Price / Unit	Amount
1	FRONT L/H FENDER	1	\$ 450.00	\$ 450.00
2	FRONT L/H FENDER SIDE SIGNAL LAMP	1	\$ 96.00	\$ 96.00
3	FRONT BUMPER	1	\$ 631.30	\$ 631.30
4	FRONT L/H HEADLAMP	1	\$ 912.10	\$ 912.10
5	FRONT L/H HEADLAMP BRACKET	1	\$ 32.90	\$ 32.90
6	FRONT L/H BUMPER BRACKET	1	\$ 18.90	\$ 18.90
7	FRONT L/H ABSORBER	1	\$ 650.70	\$ 650.70
8	FRONT L/H WHEEL BEARING	1	\$ 116.30	\$ 116.30
9	FRONT L/H WHEEL KNUCKLE	1	\$ 258.60	\$ 258.60
10	FRONT L/H WHEEL TIE ROD	1	\$ 96.70	\$ 96.70
11	FRONT L/H WHEEL TIE ROD END	1	\$ 99.80	\$ 99.80
12	FRONT L/H LOWER ARM	1	\$ 233.70	\$ 233.70
13	FRONT L/H LOWER ARM BALLJOINT	1	\$ 117.80	\$ 117.80
14	FRONT L/H SIDE MIRROR	1	\$ 494.30	\$ 494.30
15	FRONT L/H SIDE MIRROR COVER	1	\$ 79.80	\$ 79.80
16	FRONT L/H INNER FENDER GUARD	1	\$ 96.70	\$ 96.70
17	FRONT L/H MUD FLAP	1	\$ 140.60	\$ 140.60
18	FRONT L/H FENDER PROTECTOR	1	\$ 130.80	\$ 130.80
19	FRONT L/H DOOR ASSY	1	\$ 30.50	\$ 30.50
20	FRONT L/H DOOR HINGE	2	\$ 56.70	\$ 113.40
21	FRONT L/H DOOR JACK	1	\$ 88.90	\$ 88.90
22	FRONT L/H DOOR PROTECTOR	1	\$ 98.10	\$ 98.10
23	FRONT L/H RIM	1	\$ 850.00	\$ 850.00
24	FRONT L/H TIRE	1	\$ 250.00	\$ 250.00
25	BUMPER & FENDER CLIPS	20	\$ 3.90	\$ 78.00
26	LABOUR FOR CHECKING ON WIRING		\$ 120.00	\$ 120.00
27	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF FRONT L/H SIDE FENDER, BUMPER, PANEL, TRIMMING		\$ 2,200.00	\$ 2,200.00
28	LABOUR FOR DISMANTLE & REPLACING OF FRONT L/H SIDE UNDERCARRIAGE		\$ 650.00	\$ 650.00
29	SPRAYPAINTING & PUTTY OF FRONT BUMPER, FRONT L/H FENDER		\$ 1,200.00	\$ 1,200.00
30	4 WHEEL ALIGNMENT CHECKING	2	\$ 120.00	\$ 240.00

P-1288

S.N-430

L-1220

2938

2/1/20

P-1610

20%

P. 1288

Sub-Total \$ 10,575.90

GST 7% \$ 740.31

Grand Total \$ 11,316.21

Stamford Tyres International Pte Ltd

23 Kaki Bukit Road 4

#01-12/13 Synergy@KB

Singapore 417801

Phone Number: 6702 3355

Fax Number: 6341 6993

Customer:		Date:	12/24/2019 4:08 PM
Company:		VIN	
License NO:	SGY2203D	Technician:	
Odometer:	200'694KM	Order NO:	

VEHICLE ALIGNMENT REPORT

HONDA, CIVIC, 05-10, FD1, FD2

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	5°55'	7°55'	---
		Right	---	5°55'	7°55'	---
	Camber	Left	-1°00'	-0°30'	0°30'	-0°48'
		Right	-0°42'	-0°30'	0°30'	-0°42'
	Toe	Left	0°03'	-0°05'	0°05'	-1°27'
		Right	0°03'	-0°05'	0°05'	-0°03'
Total		0°06'	-0°11'	0°11'	-1°30'	
Rear	Camber	Left	-0°48'	-2°10'	-0°20'	-1°12'
		Right	-2°12'	-2°10'	-0°20'	-2°12'
	Toe	Left	0°03'	0°00'	0°08'	0°06'
		Right	0°00'	0°00'	0°08'	0°00'
		Total	0°03'	0°00'	0°16'	0°06'
	Max Thrust Angle		-0°01'	---		-0°03'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	---	12°50'	12°50'	---
		Right	---	12°50'	12°50'	---
Included Angle		Left	---	---	---	---
		Right	---	---	---	---
Toe Out On Turns		Left	---	---	---	---
		Right	---	---	---	---
Max Turn Inside		Left	---	---	---	---
		Right	---	---	---	---
Toe Curve Change		Left	---	---	---	---
		Right	---	---	---	---
Setback		Front	-1mm	---	---	-5mm
		Rear	-12mm	---	---	-11mm
Track Width Diff.			-13mm			-13mm
Wheel Base Diff.			11mm			6mm
Front Ride Height		Left	---	---	---	---
		Right	---	---	---	---
Rear Ride Height		Left	---	---	---	---
		Right	---	---	---	---
Frame Angle						---

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20000364/USF3N2

Date: 17/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19270919000
Claimant Vehicle No :	SGY2203D	Insured Vehicle No :	GBJ6445J
Date of Loss:	23/12/2019	Nature of Claim:	TP
		Claim No:	SNM20D200052C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY2203D	Engine No:	R18A1033541
Make & Model:	HONDA CIVIC, 1.8 (A)	Chassis No:	FD11103396
Reg. Date:	19/09/2007 (Man. Year: 2007)	Odometer:	201096 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,165.90	1,718.00	4,447.90	72.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	1,220.00	3,190.00	72.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,575.90	2,938.00	7,637.90	72.22
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	10,575.90	2,350.00	8,225.90	77.78
+ GST 7.00/7.00% (S\$)	740.31	164.50	575.81	77.78
Nett Amount (S\$)	11,316.21	2,514.50	8,801.71	77.78

INSPECTION

Date of Assignment:	07/01/2020	
Date Inspected:	07/01/2020 Inspected At:	Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT Singapore 417896
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2020)
Parts:	143	HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY2203D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H FENDER	Badly Dented	450.00 F	*450.00 FL
2	1		*FRONT L/H FENDER SIDE SIGNAL LAMP	Cracked	96.00 F	*96.00 FL
3	1		*FRONT BUMPER	Not Necessary	631.30 F	*- FL
4	1		*FRONT L/H HEADLAMP	Not Necessary	912.10 F	*- FL
5	1		*FRONT L/H HEADLAMP BRACKET	Not Necessary	32.90 F	*- FL
6	1		*FRONT L/H BUMPER BRACKET	Not Necessary	18.90 F	*- FL
7	1		*FRONT L/H ABSORBER	Not Necessary	650.70 F	*- FL
8	1		*FRONT L/H WHEEL BEARING	Necessary	116.30 F	*116.30 FL
9	1		*FRONT L/H WHEEL KNUCKLE	Bent	258.60 F	*258.60 FL
10	1		*FRONT L/H WHEEL TIE ROD	Not Necessary	96.70 F	*- FL
11	1		*FRONT L/H WHEEL TIE ROD END	Not Necessary	99.80 F	*- FL
12	1		*FRONT L/H LOWER ARM	Not Necessary	233.70 F	*- FL
13	1		*FRONT L/H LOWER ARM BALLJOINT	Not Necessary	117.80 F	*- FL
14	1		*FRONT L/H SIDE MIRROR }	Cracked	494.30 F	*494.30 FL
15	1		*FRONT L/H SIDE MIRROR COVER }		79.80 F	*- FL
16	1		*FRONT L/H INNER FENDER GUARD	Distorted	96.70 F	*96.70 FL
17	1		*FRONT L/H MUD FLAP	Not Necessary	140.60 F	*- FL
18	1		*FRONT L/H FENDER PROTECTOR	Not Necessary	130.80 F	*- FL
19	1		*FRONT L/H DOOR ASSY	Repair	30.50 F	*- FL
20	2		*FRONT L/H DOOR HINGE	Not Necessary	113.40 F	*- FL
21	1		*FRONT L/H DOOR JACK	Not Necessary	88.90 F	*- FL
22	1		*FRONT L/H DOOR PROTECTOR	Necessary	98.10 F	*98.10 FL
23	1		*FRONT L/H TIRE	Serviceable	250.00 F	*- FL
24	1		*FRONT L/H RIM	Cut	850.00 FS	*400.00 FS
25	20		*BUMPER & FENDER CLIPS	Necessary	78.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	6,165.90	2,040.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	322.00
Total Parts (\$\$)	6,165.90	1,718.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR CHECKING ON WIRING	New	120.00	20.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING WELDING,KNOCKING,REPAIRING,STRAIGHTENING,RESHAPE & ADJUSTMENT OF FRONT L/H SIDE FENDER,BUMPER,PANEL,TRIMMING	New	2,200.00	400.00
3	LABOUR FOR DISMANTLE & REPLACING OF FRONT L/H SIDE UNDERCARRIAGE	New	650.00	120.00
4	SPRAYPAINTING & PUTTY OF FRONT BUMPER,FRONT L/H FENDER	New	1,200.00	600.00
5	4 WHEEL ALIGNMENT CHECKING	New	240.00	80.00
Gross Labour Cost (S\$)			4,410.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >