

ASS. REC. BY:

REF:

083/III 20000402 /Hvd302

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Gabriel Wee

of

III

Date/Time:

7/1/2020 @ 11:14am

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJW 41892

Insured:

SHB 43452

at Workshop in/s

Wee Hoe Auto

Tel:

68580019

of

19 Kim Chuan Terrace

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/01/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

12:15pm @ 7/1/2020

Person Contacted:

Ah Kiat

H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction	Signature
	SJW 41892 - NA/MSG 20000290/h4	DOA: 1/1/2020
	SHB 43452 - NA/MSG 20000290/h4	DOA: 4/1/2020
13/1/2020	Submit PRS, repair range \$5000 - \$6000 (Est)	
	Dismantle: 08/01/2020 0303PM	
	After repair: 10/01/2020 0202PM	

REG. REC. BY: H. ANN

REF: III

PRS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: 5JW 4189Z
 at Workshop n/s Auto correct
 of 19 Kim Chuay TERRACE
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: MR KIAT - 68580019

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs. _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: 5JW 4189Z Yr Regn: 17/03/2009
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota corolla B415 c.c. 1598
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 243904km T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053ZEE106141348
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65/15
 R: 195/65/15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 5 mm 5 mm 5 mm
 R/Bal. 5 mm R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 3 mm L/Bal. 3 mm L/Bal. 3 mm
 D.O.A. 4/1/20 D.O.I. 7/1/20 0418PM
 Survey held at Auto correct / wee Hoe Ave
 Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range → 5 - 6k</u>
	<u>upr Rys → 5 day</u>
	<u>mv - 41000</u>
	<u>pv - 23459</u>
	<u>nv - 17500</u>

RECEIVED 13 JAN 2020

Date/Time File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: _____

13/1 - typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)

Survey Fee:
 Transportation: _____
 S + RS. SI
 Fines
 Other
 TOTAL

120
11
131

Report Fee: _____
 Long Term / Other: _____

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 7 January 2020 11:14 AM
To: ct-admin@visionlawllc.com; Anna Tan; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Manivel Priyadarshini
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJW4189Z (Accident involving SJW4189Z and SHB4345Z on 04.01.2019)
Attachments: 1838_001.pdf; 1812_001.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SJW4189Z
III INSURED VEHICLE NO. : SHB4345Z
DATE OF LOSS : 04.01.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **PRIYA**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

We started using audatex since 1st dec 2019. Please do adjustments through Audatex and upload the report onto Merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Motor Claim - III
Sent: 07 January, 2020 9:20 AM

To: 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'Anna Tan' <annatan@visionlawllc.com>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJW4189Z (Accident involving SJW4189Z and SHB4345Z on 04.01.2019)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

We started using audatex since 1st dec 2019. Please submit your estimate/quotation through Audatex so that our surveyors can make the adjustments according.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: 07 January, 2020 9:04 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
CHEONG YUNHUI, CLARISSA
SONIA LIM WEI LEI

Unique Entity Number: 200721148H

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Main
TEL : (65) 6534 2811 (Hunting)
FAX : (65) 6535 6802
E-MAIL : annatan@visionlawllc.com

Conveyancing & Family Law Practices
TEL : (65) 6358 0703
Fax: : (65) 6358 0448

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE

OUR REF: AW1-atv-INS-W30-SJW4189Z-2020 – please reply to: annatan@visionlawllc.com
YOUR REF: SHB4345Z

7 January 2020

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04/06-00 IOB Building
Singapore 049711
Attn: Motor Claims Department

BY FAX: 6224 4174 Only
motorclaim@iii.com.sg

Dear Sirs

NAME OF CLAIMANT: CHANG ZHENG AUTO AGENCY
VEHICLE NUMBER: SJW 4189 Z
YOUR INSURED VEHICLE NUMBER: SHB 4345 Z
ACCIDENT AT ALONG TANJONG PAGAR ROAD ON 4 JAN 2020 AT ABOUT 1735HOURS

We refer to your email dated 7 January 2020 wherein there is no agreement to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

WEE HOE AUTO SERVICE
19 KIM CHUAN TERRACE
SINGAPORE 537041
TEL: 6858-0019 (KIAT)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Audrey Wong
(Head Office)

cc. **SJW 4189 Z** – By fax 6858-0195 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	617M
Vehicle Details	
Vehicle No.:	SJW4189Z
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	3ZZ4869511
Chassis No.:	MR053ZEE106141348
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,990.00
Original Registration Date:	17 Mar 2009
First Registration Date:	17 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$16,990.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Mar 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$25,525.00
COE Rebate Amount:	\$23,459.00
Total Rebate Amount:	\$23,459.00

The information contained herein is correct as at 07 Jan 2020

OK

SQUARESPACE

WEBSITES & ONLINE STORES
FOR ENTREPRENEURS

Connect with Facebook

HOME NEW CARS USED CARS COMMERCIAL VEH RENTAL CARS SELL CARS MOTOR DIRECTORY


Home > Used Cars > Toyota Corolla Altis 1.6A Elegance (COE till 08/2029)

TOYOTA COROLLA ALTIS 1.6A ELEGANCE (COE TILL 08/2029)

OVERVIEW

GALLERY

Share



Price	\$45,888
Registration Date	26-Aug-2009
COE Remaining	9yrs 7mths 18days
Manufactured	2009
Mileage	108,188 km
No. of Owners	2
Transmission	Auto
Engine Capacity	1,598 cc
COE	\$29,328
OMV	\$17,853
Paper Value	\$28,267
Depreciation	\$4,760 / year
Type	Mid-Sized Sedan

Meticulously Well Maintained Unit With No Repair Needed! Low Mileage Done Yet Always Sheltered Park. Guaranteed Accident Free! Buy With Assurance From A Reputable Dealer! Our Company Provided Loan Scheme With Easy Approval Rate! Hurry Contact Us Now For A Viewing Appointment Today Before It's Gone!

Features: 1.6L DOHC 16V VVT-I Engine, Smooth 5-Speed Auto Transmission With ECT, Dual SRS Airbags, ABS, Digital Climatic Control Aircon, Knockdown Rear Seats.

Accessories: Premium Leather Seats, Upgraded Pioneer Touchscreen DVD Audio With Reverse Camera/Steering Controls, Fog Lamps, Retractable Side Mirrors.

More info on Toyota Corolla Altis(2008-2013) |

77 user reviews

For full set of photos and payment break-down, <http://www.sgcarmart...=852392&DL=1277>

Status: Available | Category: COE Car

Date Posted: 04-Jan-2020 | Date Updated: 04-Jan-2020

SELLER INFORMATION

Creative Auto

61 Ubi Avenue 2 #04-02/03/18/19/20 (map)



-



ALVIN CHUA

84488354



ALEX TAN

97556887

" SAY YOU SAW THIS AD ON STCARS.SG! "

RELATED DISCUSSION

+ View All "Corolla" Discussion

Topic Title	Replies	Last Action
2019 12th Gen Toyota Corolla Sedan	990	06-Jan-2020
2014 Corolla Altis - Technical, Features & Use	1715	24-Dec-2019
Honda civic 2012 1.6L or Toyota Corolla Altis 2012	13	21-Dec-2019
2017 Toyota Corolla Altis new Facelift	1259	20-Dec-2019

SELL BY
CONSIGNMENT
SELL DIRECT AT THE PRICE YOU WANT

NO SALE = NO CHARGE



USED CAR SEARCH

Car Make / Car Model

Category	Car Type
Transmission	Engine Capacity
Min Price	Max Price
Min Depreciation	Max Depreciation
From Reg Year	To Reg Year

VEHICLE TOOLS

Get expert assessment on the condition of this car with STA Evaluation

COE Results	Loan Calc
Post an Ad	Road Tax
Carpark Rates	Car Insurance

CARPARK RATES

Find cheapest carpark location



LIFESTYLE

Food & Beverage	Health & Beauty
Home Needs	IT Products

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/01/2020 16:28
Date Of Accident	04/01/2020 17:35
Exact Location Of Accident	TANJONG PAGAR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW4189Z
Insured/Policyholder	
Name Of Registered Owner	CHANG ZHENG AUTO AGENCY
Co Reg No	- 52815617 m
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65471511
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29115466 MCX
Cover Note Number	
Driver	
Name of Driver	CHOW CHEE CHUNG
NRIC No	SXXXX089B
Date Of Birth	10/07/1968
Occupation	OUTDOOR
Date Of Driving Pass	29/01/1993
Driving Experience	26 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93473030
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 89 REDHILL CLOSE #10-480
Postcode	150089
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	AFTER RAINED
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB4345Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHOW CHEE CHUNG
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SJW4189Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

I WAS TRAVELLING ALONG TG PAGAR RD ON THE RIGHT LANE, WHILE APPROACHING JUNC WITH TRAS LINK, SUDDENLY THE TAXI FROM THE LEFT LANE MAKE A RIGHT TURN, I MANGE TO STOP BUT STILL HIT ONTO THE TAXI RIGHT HAND SIDE.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jan 2020 17:20 Edit Reg		07 Jan 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SJW4189Z	Date of Loss:	04/01/2020 00:00 - :59 [129 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHB4345Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Wee Hoe (HQ) 19 KIM CHUAN TERRACE, 537041 Tai Seng - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 16/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJW4189Z
[SHB4345Z]












































TP























































-





Jan 4 2020 12:00AM

[-]

Wee Hoe

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/01/20 08:49	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	08/01/20 08:49	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
4	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
5	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
6	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
7	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
8	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
9	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
10	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
11	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
12	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
13	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
14	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
15	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
16	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
17	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
18	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
19	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
20	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
21	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
22	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
23	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
24	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
25	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
26	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
27	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
28	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
29	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
30	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
31	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
32	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
33	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
34	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
35	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
36	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
37	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
38	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
39	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
40	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
41	08/01/20 08:50	General View		Load JPG	<input checked="" type="checkbox"/>
42	09/01/20 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	09/01/20 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	09/01/20 11:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
90	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
91	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
96	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	14/01/20 18:22	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
99	14/01/20 18:22	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	14/01/20 18:22	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/01/20 15:43	EMAIL FROM III TO ARRANGE FOR SURVEY	 Load PDF	
2	07/01/20 15:46	WORKSHOP DETAILS	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	08/01/20 08:52	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20000402/HVD3E2

Date: 15/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJW4189Z

Insured Vehicle No : SHB4345Z

Date of Loss: 04/01/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJW4189Z

Make & Model: KIA RIO, 1.6 (M)

Engine No: 3ZZ4869511

Reg. Date: 17/03/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106141348

Colour: Blue

Odometer: 243904 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: CST TIRE 5 mm

Rear Left Side: CST TIRE 5 mm

Front Right Side: CST TIRE 5 mm

Rear Right Side: CST TIRE 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/01/2020

Date Inspected: 07/01/2020 Inspected At:

Wee Hoe (HQ)
19 KIM CHUAN TERRACE
Singapore 537041

Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jan 2020)

Parts: 143 KIA RIO 1.6 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJW4189Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >