

ASS. REC. BY:

REF: CS/TM1 20000414/FvF32

Special Instruction:

Survivor: Ram

ASSIGNMENT (Office)

From (Person): Francis Ng Kwai Lay of TMZ Date/Time: 7. Jan. 2020 15:40p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 3408m

Insured: SKF 84x

at Workshop m/s Comfortdelgro
of 59 Luyang Drive

Tel: 6214 8300

Policy No: MT 109162

Claim No: M 2000027

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 1/1/2020

CA / REV / REP. / REV 24 HRS

"mp"

H.O.D. Endorsement:

Date/Time: 7.1.2020 4:09 p.m

Person Contacted: Juman

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 3408m - CS/FCI 19019683/UVf3 R.O.A - 04/11/2019
	SKF 84x - CCB/AIG 17006811/Lug392 R.O.A - 06/04/2017
8/1/2020	Send preli revised via merimen


Rem

ASSIGNMENT

Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop in/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHA 3408M** Regn: **10/03/2016**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / **Taxi** / Prime Mover /
 Truck / Trailer or
 Make: **Hyundai 140** C.C: **1685**
 Colour: **Blue** A/C: Insured / Std / NI / NA
 Sp. Reading: **.537 365** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **14MHLB41UMG08SS38**
 Gen. Cond: Good / **Fair** / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / **STD A/Rim** or
 Tyre Size: F: **205/60 R14**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **westlake**
 Front Rear
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **01/01/2020** D.O.I. **07/01/2020**
 Survey held at **comfort delgro (loyang)**
 Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or
rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 10 JAN 2020

Thi

L/S

L/S: \$850/= with 2 repair days
 confirm on 15/1/2020 with chary. (Red 1050.62, 5570)

Date/Time: File Pass to:

☐

: Preli. Report

☐

: Final Report

Date/Time: File Return to:

16/1 typist

merimen

L/S \$850

Days Of Repair: **2**

Resurvey No. of Trip: **1**

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Teach type (\$)

☐

Final report (\$)

Survey Fee:

Transportation

Site Insp (\$)

Interview

Teach type

Final report

250

11

261

Our Job Ref No : 305372512

Date : 14/01/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

: SHA3408M

01/01/20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: TOKIO SKF84X

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$850.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Ram

Date : 15/1/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

	for Fed	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2020 15:09 Sendback Est	07 Jan 2020 15:19 S\$1,902.62	07 Jan 2020 15:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				
Insured:	CTPL, Co. Reg. No.: 199303821R			
Main Claimant:	CTPL			
Vehicle Reg. No.:	SHA3408M	Date of Loss:	01/01/2020 07:00 - :59 [45 Months and 22 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / M2000027	Policy/Cover Note No.:	MT109162 (TP, Fire & Theft) Coverage: 06/11/2019 - 05/11/2020	
Vehicle Reg. No. (Insured):	SKF84X	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300			
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/01/2020]			
ASSOCIATED MAIL RECEIVED				
				View All Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS <input type="checkbox"/>				
View All Search Tasks Create New Task Complete				
Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd 20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Ng Kwai Kay Francis	Date: 08 Jan 2020
<u>Preliminary Advice</u>	

Insured Vehicle No	: SKF84X	Accident Date	: 01/01/2020
TP Vehicle No	: SHA3408M	Assignment Date	: 07/01/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 2
Date of Inspection	: 7/1/2020		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,902.62
Revised Amount	:S\$	1,081.00
Check Items (Estimated)	:S\$	469.36
Total	:S\$	1,550.36
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2020 14:07
Date Of Accident	01/01/2020 07:20
Exact Location Of Accident	YISHUN AVE X AVE 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3408M
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	ABDUL WAHID BIN ABU BAKARABDUL WAHID BIN ABU BAKAR
NRIC No	SXXXX919C
Date Of Birth	16/08/1959
Occupation	OUTDOOR
Date Of Driving Pass	02/01/1991
Driving Experience	28 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87799553
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 269B YISHUN STREET 22 #07-559
Postcode	762269
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKF84X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LER LI SHIANG ALCINA
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ABDUL WAHID BIN ABU BAKAR
Approximate Age	
Injuries Sustain	SHOULDER AND NECK
Injured person in which vehicle?	SHA3408M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1/1/20 at about 0720hrs when I Veh A was stationary waiting at the traffic junction (Red), Veh B suddenly collided onto the rear of my vehicle. I felt pain on the shoulder and neck. I will be consulting the doctor.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305372512

CUSTOMER

MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755
(R) (O)
(P)


COUNT CARD NO.

REGN NO.: SHA3408M	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 07.01.2020 10:35
YR OF MANU 10.03.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU085538	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 01.01.2020
NATURE: 3P 01.01.2020

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acceptance Slip

Exit Pass

No.: SHA3408M CHIANG

Vehicle No.: SHA3408M

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM			
----------------------	--	--	--

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/01/2020
Vehicle Reg. No.:	DHA3408M	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	10/03/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDFU596161	Chassis No:	KMHLB41UMGU085538
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,181.62
Miscellaneous Items	11.00
Labour	710.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,902.62
+ GST 7.00% (S\$)	133.18
Nett Amount (S\$)	2,035.80

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS***Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/DHA3408M/07/01/2020 15:19**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER <i>cut</i>	20.00	0.00	*553.00 FL
2	1		*REAR BUMPER REINFORCEMENT <i>Pxnn</i>	20.00	0.00	*420.30 FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET LH /RH <i>Pxnn</i>	20.00	0.00	*166.40 FL
4	1		*REAR BUMPER UNDER COVER <i>xnn</i>	20.00	0.00	*83.20 FL
5	10		*REAR BUMPER CLIPS <i>hec</i>	20.00	0.00	*22.00 FL
6	1		*REAR BUMPER MAT <i>hec</i>	0	0.00	*50.00 FS
7	1		*REAR REVERSE SENSOR <i>xnn</i>	0	0.00	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,430.60
- List Item Discount on L Items (\$)	248.98
Total Parts (\$)	1,181.62

ComfortDelGro Engineering Pte Ltd/DHA3408M/07/01/2020 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	\$280 350.00
2	SPRAY PAINTING	New	\$200 250.00
3	WIRING	New	\$30 \$100 50.00
4	REMOVE,REFIX REVERSE SENSOR	New	\$50 60.00
Gross Labour Cost (S\$)			710.00

ComfortDelGro Engineering Pte Ltd/DHA3408M/07/01/2020 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Handwritten notes:
8/1/2020
Ram (LCC)
07/01/2020 1620ms
Paresnam@lkkauto.com
88622728 (LIS)
2 days
aft repair photo

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jan 2020 15:09 Sendback Est	07 Jan 2020 15:19 S\$1,902.62	07 Jan 2020 15:40 Edit Adj Rpt	S\$850.00 Edit Estimates	S\$850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199303821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHA3408M	Date of Loss:	01/01/2020 07:00 - :59 [45 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2000027	Policy/Cover Note No.:	MT109162 (TP, Fire & Theft) Coverage: 06/11/2019 - 05/11/2020
Vehicle Reg. No. (Insured):	SKF84X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 16/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.



































ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA3408M (M2000027)
[SKF84X]
TP
CTPL
Jan 1 2020 7:00AM
[CTPL]
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	07/01/20 15:19	Repairer Estimates		 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/01/20 11:57	Adjuster Immediate Advice		 Load HTM	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	07/01/20 15:41	Accident Photo From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
2	07/01/20 15:41	Accident Photo From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
3	07/01/20 15:41	Accident Photo From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
4	07/01/20 15:41	Accident Photo From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
5	07/01/20 15:41	Accident Photo From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
6	07/01/20 15:41	Accident Photo From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
7	07/01/20 15:41	SCENE From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
8	07/01/20 15:41	SCENE From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
9	07/01/20 15:41	SCENE From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
10	07/01/20 15:41	SCENE From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
11	07/01/20 15:41	SCENE From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
12	07/01/20 15:41	SCENE From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD		 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
2	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
3	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
4	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
5	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
6	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
7	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
8	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
9	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
10	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
11	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
12	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
13	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
14	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
15	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
16	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
17	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
18	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
19	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
20	13/01/20 17:57	General View		 Load JPG	<input checked="" type="checkbox"/>
21	13/01/20 17:57	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
22	13/01/20 17:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	16/01/20 09:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	16/01/20 09:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	16/01/20 09:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	07/01/20 15:41	Sketch Plan From:TP - Reg. No: SHA3408M, Claimant: COMFORT TRANSPORTATION PTE LTD	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20000414/FVF3E2

Date: 16/01/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MT109162
Claimant
Vehicle No : SHA3408M **Insured Vehicle No :** SKF84X
Date of Loss: 01/01/2020 **Nature of Claim:** TP **Claim No:** M2000027

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA3408M**
 Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDFU596161
 Reg. Date: 10/03/2016 (Man. Year: 2015) Chassis No: KMHLB41UMGU085538
 Colour: Blue Odometer: 537365 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,181.62	510.00	671.62	56.84
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	710.00	560.00	150.00	21.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,902.62	1,081.00	821.62	43.18
Approved Total (Overridden) (S\$)		850.00		
(S\$)	1,902.62	850.00	1,052.62	55.32
+ GST 7.00/7.00% (S\$)	133.18	59.50	73.68	55.32
Nett Amount (S\$)	2,035.80	909.50	1,126.30	55.32

INSPECTION

Date of Assignment: 07/01/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
 Date Inspected: 07/01/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3408M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Cut	553.00 FL	-	*553.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	420.30 FL	-	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET LH /RH	Not Necessary	166.40 FL	-	*- FL
4	1		*REAR BUMPER UNDER COVER	Not Necessary	83.20 FL	-	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*REAR BUMPER MAT	Necessary	50.00 FS	-	*50.00 FS
7	1		*REAR REVERSE SENSOR	Not Necessary	135.70 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,430.60	625.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	248.98	115.00
Total Parts (\$\$)	1,181.62	510.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	280.00
2	SPRAY PAINTING	New	250.00	200.00
3	WIRING	New	50.00	30.00
4	REMOVE,REFIX REVERSE SENSOR	New	60.00	50.00
Gross Labour Cost (\$\$)			710.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >