



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000505/Hsf3e2

73 BRAS BASAH ROAD

Date: 16-04-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : HELENA

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLZ 4828Z	Veh. Inspected	SMP 3605Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078980-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	08/01/2020

#### 2. Vehicle Particulars & Condition

Make & Model	RENAULT GRAND SCENIC	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	VF1RFA00X62852038	Colour	BLUE
Odometer	32586 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R20	GOODYEAR	6 mm
L/H Front Tyre	195/55 R20	GOODYEAR	6 mm
R/H Rear Tyre	195/55 R20	GOODYEAR	6 mm
L/H Rear Tyre	195/55 R20	GOODYEAR	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	05/01/2020	Inspect Date / Time	08/01/2020 ( 01:54 PM )
Survey held at	1 DEFU LANE 6		
Repairer	TAN LIM MOTOR PTE LTD		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------